

CARTIMES

autolution

Not Arthair
Resurvey B&Pain
1.1.1

2 days

Kennerth
96910683

Vehicle no: SLZ 4885 H

MODEL: HONDA FIT

QTY	DESCRIPTION	REPAIRER'S ESTIMATE(\$\$)	SURVEYORS ADJUSTMENT
PARTS (LIST ITEMS)			
1	Front bumper	650.00	✓
1	Front reinforcement bar	270.00	X
2	Front Rh & LH bumper side retainer	50.00	X
1	Front LHS headlamp	1030.00	✓
1	Front headlamp bracket LHS	45.00	✓
1	Front grille	395.00	X
1	Front bumper LHS side garnish	185.00	X
		2625.00	0.00
		20% 525.00	20%
		2100.00	
SPECIAL NETT ITEMS			
1	Front bumper clips	50.00	✓
1	Front number plate w/holder	60.00	X
	special nett item	110.00	
	TOTAL PARTS	2210.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle No.SLZ 4885 H

MODEL:HONDA FIT

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYORS ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	500.00 200	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	300.00 220	
3	To remove and refix wiring and check all electrical components at damaged areas for proper functions	120.00 201	
4	To provide anti-rust treatment on affected areas	100.00 X	
	Labour Total :	1020.00	
	TOTAL (PARTS & LABOUR):	3230.00	