



## SPORT MODE

### REPAIR / ACCIDENT QUOTATION

DATE : 7/6/2018  
OWNER NAME : PANG HUI CHIN  
REGN NO : SFP2403C  
MODEL : MINI COOPER  
CHASSIS NO : WMWRE32090TK75613  
REGN DATE : 16/11/2004

#### MATERIALS:- PART DESCRIPTION

S\$

1	Carrier (51111494431 )	520.00 x
2	Mount bracket LH (31116757911)	85.00 x
4	Fog lamp cover LH (51711481436)	38.00 x
5	Front panel (51647200800)	550.00 x
6	Splash wall reinforcement LH (41117070655 )	102.00 x
7	Cover panel wheel house (41117049301)	35.00 x
8	Supporting strut (41247070653)	189.00 ✓
9	Interior column A LH (41137035315)	110.00 <
10	Lower apron (41137035417)	145.00 <
11	Guide left bottom (51236800799)	33.00 ✓
12	Guide left TOP (51236800797)	11.00 ✓
13	Front bumper (51111177877)	670.00 ✓
14	Trim strip (51111400063)	99.00 x
15	Centre finisher (51117127931)	89.00 x
16	Grille (51117068396)	45.00 x
17	Centre spoiler (51117130315)	97.00 x
18	Left spoiler (51117130311)	42.00 x
19	Trim panel (51111504252)	75.00 x
20	Spoiler left (51111479090 )	75.00 x
21	Wheel arch LH (51131505867)	73.00 x
22	Engine Hood (41617067754)	1,100.00 R x
23	Headlamp LH (63127198737)	1,650.00 x
24	Fog lamp LH (63176925049)	185.00 x
25	Control unit xenon (63127176068)	630.00 x
26	Xenon bulb (63217160806)	375.00 x
27	Left turn indicator (63137165861)	77.00 x
28	Wheel housing cover LH (51711486198)	93.00 x
		<b>7,193.00</b>
LESS 10%		<b>(719.30)</b>
		<b>6,473.70</b>

**SPECIAL NET ITEMS**

1 FRONT NUMBER PLATE WITH FRAME

50.00 X

**TOTAL MATERIALS****6,523.70****LABOUR****DESCRIPTION****S\$**

1 RENEW ACCIDENT DMAGED PARTS ON FRT BUMPER,BONNET

900.00 300

2 RESPRAY PAINT ACCIDENT DMAGED PORTION ON FRT BUMPER, BONNET,

600.00 400

3 CHECK WIRING AND ELECTRICAL SYSTEM

30.00 ✓

4 TO CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM

200.00 100

5 TO APPLY SEALANT FOR ACCIDENT AFFECTED AREA

120.00 X

6 TO RENEW FRT UNDER CARRIAGE

300.00 X

8 TO CONDUCT WHEELALIGNMENT

120.00 X

9 SUNDRY

20.00 ✓

**TOTAL LABOUR****2,290.00****GRAND TOTAL****8,813.70**

Prepare By : JEFFERY SEET

Survey by :

Tanpin 97495749

Date:

21/8/18 C 1630

Authorised / Not Authorised

97495749

62563561 affie.

THE ABOVE IS ONLY BASED ON OUR PRELIMINARY INSPECTION , IN THE PROCESS OF SUCH REPAIR ADDITIONAL WORK OR WORKS OR PARTS MAY BE REQUIRE. PART PRICE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

Resumy after repair

03 days

sure lkkauto.com

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: