

22/03/2002

ASS. REC. BY:

REF:

es/FCI18011071/Tlrd302

Special Instruction:

Surveyor: Taukh

ASSIGNMENT (Office)

*From (Person): Lurene jaw

of

FCI

Date/Time: 19/6/18 @ 12.42pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLA 2344Y

Insured: SHB 2248J

at Workshop m/s Ding Auto

Tel: 9239 4128

of Blk 10, 8in Ming Ind. Est. Sec. C # 01-20

Policy No:

Claim No: D18004774MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 16/06/2018

(Insp. 249 Jalan Boon Lay

CA / REV / REP. / REV 24 HRS (wpi)

H.O.D. Endorsement:

Date/Time: 12:58pm @ 19/6/18

Person Contacted:

Ah poh

Vehicle (IN) / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLA 2344Y - EC3 / LCR / 7013195 / Swb Bq 2 DOA: 5/7/17
	SHB 2248J - NS / INC / 7023698 / K / vbn 2 DOA: 11/12/2017
	Revert poli thru email.

Taufik

REF:

FC1

INSURANCE

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop in s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No


GIA / PP Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS _____

Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: SLA2344Y Yr Regn: 2016 Feb.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Alh's. cc 1598

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 146214 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRC053KEH104538634

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / SRim / STD A/Rim or _____

Tyre Size: F: 205/55R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Triangle

Front		Rear	<u>6</u>
R/Bal.	<u>6</u> mm	R/Bal.	<u>6</u> mm
L/Bal.	<u>6</u> mm	L/Bal.	<u>6</u> mm
D.O.A.		D.O.I.	<u>20/6/18</u>

Survey held at: Ding Auto Shu Branley

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

confirm L/S \$3550 @ 7 days
Red: \$10843.10, 75%.

RECEIVED 12 JUL 2018

Enter Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 7
Resturvey No. of Trip: 1

Add Fee: Site Insp. \$5
 Inter. Insp. \$5
 Tech. Insp. \$5
 Man. Insp. \$5

Survey Fee	1704.90
Transportation	50
...	50
...	69
...	13118
429	

Report Format: TP
Lump Sum / ... 3550

MOTOR SURVEY ASSIGNMENT

Date 18-06-2018 **Our Ref No.** D18004774MFSH
Accident Date 16-06-2018 **Claim Type.** Third Party
Insured Vehicle SHB2248J **Third Party Vehicle.** SLA2344Y
Survey Location BLK 10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-20
Contact Person. DUAN HONGBO
Contact No. 64589523/ 92394128 **Fax No.** 62652690
Survey Type WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:
Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD
Contact Person NA **Fax No.** 68416315
Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop DING AUTO PTE LTD **Attention.** NIL
Cc : TP Solicitor NA **TP Solicitor Fax No.** NA
Officer Incharge LURENE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241502)



PRI Documents



Close



PRI Header Details

Claim No	D18004774MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & DING AUT
Workshop Name	DING AUTO PTE LTD (Contact Person : DUAN HONGBO)	Survey Location & Contact Details	BLK 10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-2 Mobile: 92394128 , Phone: 64589523 , Fax: 62652690 EmailId: DUAN.HONGBO@DINGAUTO.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB2248J	TP Vehicle No	SLA2344Y
PRI Recieved Date	18-06-2018 09:34:38 PM	Surveyor Appointed Date	19-06-2018 12:41:16 PM	Surveyor Accept Date	

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	19-06-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Your Ref: D18004774MFSHOur Ref: CS/FCI18011071/T1rd3The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLA 2344Y .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20.06.2018 at the premises of M/s DING AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 10,393.10</u> .
Revised Estimate Amount	: <u>S\$ 4,490.82</u> .
“Check” Items Amount	: <u>S\$ 834.66</u> .
Market Value	: <u>S\$ -</u> .
LTA Reimbursement Value	: <u>S\$ -</u> .
Nett Value	: <u>S\$ -</u> .

Description of Damage:
The vehicle sustained damages
at rear portion.



Yours faithfully
TAUFIKH
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/06/2018 13:51
Date Of Accident	16/06/2018 13:20
Exact Location Of Accident	ALONG HAVELOCY LINK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA2344Y
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31584255

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 CLASSIC CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995145
Cover Note Number	

Driver

Name of Driver	NEO CHENG YONG
NRIC No	S7622870A
Date Of Birth	26/07/1976
Occupation	OUTDOOR
Date Of Driving Pass	17/02/2004
Driving Experience	14 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92394128
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 249 JALAN BOON LAY
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHB2248J
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category TAXI
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
(e) the information so collected under (d) above may be shared / disclosed:
(i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
(ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: [Signature]

Driver's Signature
Date & Time: [Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: [Signature]



SKETCH PLAN



A: SLA2344Y

B: SHB2248J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16/6/2018 Around 1220HRS, I was driving along Havelock Link, at the Junction; I was stop on the lane, suddenly Rear veh hit my veh rear

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

19/06/2018 10:43

JOB-NO: 85008386

OWNER'S PARTICULARS

Page 1 of 2

NAME: LION CITY RENTALS PTE. LTD CONTACT: 0
ADDRESS: 50 UBI AVENUE 3 0
#01-12 NIL
SINGAPORE 408866

VEHICLE DETAILS

LICENSE NO: SLA2344Y TRANS: AUTO CHASSIS: MR053REH104538634
MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A) ENGINE: 1ZRY208377
OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.
JOB-CODE: TP SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,500.00	0.00	1,500.00	Y		900 ✓
2 R&R REAR REVERSE SENSOR AND PAINTING	1.00	120.00	0.00	120.00	Y		30 ✓
3 R&R SPARE TYRE ,BOARD ,CARPET AND TRIM	1.00	180.00	0.00	180.00	Y		40 ✓
4 R&R BOOTLID COMPONENTS	1.00	150.00	0.00	150.00	Y		X ✓
5 CHECK WIRING	1.00	100.00	0.00	100.00	Y		30 ✓
6 RUST PROOFING	1.00	100.00	0.00	100.00	Y		30 ✓
7 TO PUTTY & SPRAY PAINTING REAR BUMPER ,REAR END PANEL , REAR FENDER LH/RH , SPARE TYRE PANEL , BOOTLID	1.00	1,500.00	0.00	1,500.00	Y		1000 ✓
8 TO MOUNTWORK BENCH&RE-ALIGN REAR CHASSIS	1.00	350.00	0.00	350.00	Y		X ✓
TOTAL:		4,000.00	0.00	4,000.00			
MATERIALS							
1 REAR BUMPER	1.00	586.55	146.64	439.91 ✓	L	Y	de ✓
2 REAR BUMPER RETAINER LH SHORT	1.00	79.20	19.80	59.40 ✓	L	Y	neu ✓
3 REAR BUMPER RETAINER LH LONG	1.00	104.40	26.10	78.30	L	Y	X } X ✓
4 REAR BUMPER RETAINER RH LONG	1.00	104.40	26.10	78.30	L	Y	X } X ✓
5 REAR BUMPER RETAINER RH SHORT	1.00	79.20	19.80	59.40 ✓	L	Y	neu ✓
6 REAR BUMPER REINF	1.00	478.42	119.61	358.81 ✓	L	Y	bg ✓
7 REAR BUMPER REINF ARM LH	1.00	101.97	25.49	76.48	L	Y	? } X ✓
8 REAR BUMPER REINF RH	1.00	101.97	25.49	76.48	L	Y	? } X ✓
9 REAR BUMPER REFLECTOR RH	1.00	79.70	19.93	59.77	L	Y	X } X ✓
10 REAR BUMPER REFLECTOR LH	1.00	79.70	19.93	59.77	L	Y	X } X ✓
11 REAR END PANEL	1.00	790.45	197.61	592.84 ✓	L	Y	bg ✓
12 REAR END PANEL TOP GARNISH	1.00	150.10	37.53	112.57 ✓	L	Y	de ✓
13 TAIL LAMP RH	1.00	427.80	106.95	320.85	L	Y	? } X ✓
14 TAIL LAMP LH	1.00	427.80	106.95	320.85	L	Y	? } X ✓
15 BOOTLID	1.00	879.60	219.90	659.70	L	Y	Rp } X ✓
16 BOOTLID LOCK	1.00	424.79	106.20	318.59	L	Y	X } X ✓
17 BOOTLID EMBLEM LOGO	1.00	58.70	14.68	44.02 ✓	L	Y	neu ✓
18 BOOTLID EMBLEM ALTIS	1.00	58.70	14.68	44.02 ✓	L	Y	neu ✓
19 BOOTLID EMBLEM COROLLA	1.00	58.70	14.68	44.02 ✓	L	Y	w ✓
20 BOOTLID LAMP LH	1.00	427.80	106.95	320.85	L	Y	X } X ✓
21 BOOTLID LAMP RH	1.00	427.80	106.95	320.85	L	Y	X } X ✓

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
22 REAR FENDER LH	1.00	1,084.90	271.23	813.67	L	Y	X R } x nn
23 REAR FENDER RH	1.00	1,084.90	271.23	813.67	L	Y	X R
24 SPARE TYRE PANEL	1.00	372.20	93.05	279.15	L	Y	Ry
25 SPARE TYRE BOARD	1.00	342.77	85.69	257.08	L	Y	am
26 REAR END PANEL WEATHERSTRIP	1.00	185.00	46.25	138.75	L	Y	ant
27 REAR FENDER INNER PANEL TRIM LHS	1.00	390.00	97.50	292.50	L	Y	X } x nn
28 REAR FENDER INNER PANEL TRIM RHS	1.00	390.00	97.50	292.50	L	Y	X
29 REAR BUMPER CLIP	1.00	35.00	0.00	35.00	S	Y	nt
30 REAR END PANEL TOP GARNISH CLIPS	1.00	35.00	0.00	35.00	S	Y	nt
31 TAIL LAMP RH CLIP	1.00	20.00	0.00	20.00	S	Y	?
32 TAIL LAMP LH CLIP	1.00	20.00	0.00	20.00	S	Y	?
33 BOOTLID INSULATOR CLIP	1.00	35.00	0.00	35.00	S	Y	X } x nn
34 REAR FENDER LH INNER TRIM CLIP	1.00	35.00	0.00	35.00	S	Y	X
35 REAR FENDER RH INNER TRIM CLIP	1.00	35.00	0.00	35.00	S	Y	X
36 SPARE TYRE PANEL SEALANT	1.00	50.00	0.00	50.00	S	Y	X
37 REAR END PANEL SEALANT	50.00	2,500.00	0.00	2,500.00	S	Y	40 nt
38 REVERSE SENSOR	1.00	260.00	0.00	260.00	S	Y	200 am
39 REAR FENDER INNER PANEL TRIM CLIP	1.00	35.00	0.00	35.00	S	Y	X } x nn
TOTAL:		12,837.52	444.42	10,393.10			
TOTAL PARTS & LABOUR:		16,837.52	2,444.42	14,393.10			

EXCESS/LOADING: \$\$ 0.00

No. Of Day: 7

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: \$\$

DATE OF SURVEY: 20 / 6 / 18

SURVEYED BY: Taufiq

CONTACT NO: 9749574 FAX NO: 6

WP'
sur@lkkauto.com

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED
DAuto001
Ding Auto User 1

ESTIMATOR
STA AUTOCENTRE
TEL: FAX:

[Signature]
22/6/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

19/06/2018 10:43

OWNER'S PARTICULARS

JOB-NO: 85008386

NAME: LION CITY RENTALS PTE. LTD CONTACT: 0
ADDRESS: 50 UBI AVENUE 3 0
#01-12 NIL
SINGAPORE 408866

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SLA2344Y TRANS: AUTO CHASSIS: MR053REH104538634
MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A) ENGINE: 1ZRY208377
OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.
JOB-CODE: TP SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,500.00	0.00	1,500.00		Y	900
2 R&R REAR REVERSE SENSOR AND PAINTING	1.00	120.00	0.00	120.00		Y	30
3 R&R SPARE TYRE ,BOARD ,CARPET AND TRIM	1.00	180.00	0.00	180.00		Y	40
4 R&R BOOTLID COMPONENTS	1.00	150.00	0.00	150.00		Y	X
5 CHECK WIRING	1.00	100.00	0.00	100.00		Y	30
6 RUST PROOFING	1.00	100.00	0.00	100.00		Y	30
7 TO PUTTY & SPRAY PAINTING REAR BUMPER ,REAR-END PANEL , REAR FENDER LH/RH , SPARE TYRE PANEL , BOOTLID	1.00	1,500.00	0.00	1,500.00		Y	1000
8 TO MOUNTWORK BENCH&RE-ALIGN REAR CHASSIS	1.00	350.00	0.00	350.00		Y	X
TOTAL:		4,000.00	0.00	4,000.00			
MATERIALS							
1 REAR BUMPER	1.00	586.55	146.64	439.91	L	Y	de
2 REAR BUMPER RETAINER LH SHORT	1.00	79.20	19.80	59.40	L	Y	new
3 REAR BUMPER RETAINER LH LONG	1.00	104.40	26.10	78.30	L	Y	X
4 REAR BUMPER RETAINER RH LONG	1.00	104.40	26.10	78.30	L	Y	X
5 REAR BUMPER RETAINER RH SHORT	1.00	79.20	19.80	59.40	L	Y	new
6 REAR BUMPER REINF	1.00	478.42	119.61	358.81	L	Y	new
7 REAR BUMPER REINF ARM LH	1.00	101.97	25.49	76.48	L	Y	?
8 REAR BUMPER REINF RH	1.00	101.97	25.49	76.48	L	Y	?
9 REAR BUMPER REFLECTOR RH	1.00	79.70	19.93	59.77	L	Y	X
10 REAR BUMPER REFLECTOR LH	1.00	79.70	19.93	59.77	L	Y	X
11 REAR END PANEL	1.00	790.45	197.61	592.84	L	Y	new
12 REAR END PANEL TOP GARNISH	1.00	150.10	37.53	112.57	L	Y	new
13 TAIL LAMP RH	1.00	427.80	106.95	320.85	L	Y	?
14 TAIL LAMP LH	1.00	427.80	106.95	320.85	L	Y	?
15 BOOTLID	1.00	879.60	219.90	659.70	L	Y	Ry
16 BOOTLID LOCK	1.00	424.79	106.20	318.59	L	Y	X
17 BOOTLID EMBLEM LOGO	1.00	58.70	14.68	44.02	L	Y	new
18 BOOTLID EMBLEM ALTIS	1.00	58.70	14.68	44.02	L	Y	new
19 BOOTLID EMBLEM COROLLA	1.00	58.70	14.68	44.02	L	Y	new
20 BOOTLID LAMP LH	1.00	427.80	106.95	320.85	L	Y	X
21 BOOTLID LAMP RH	1.00	427.80	106.95	320.85	L	Y	X

\$2000

\$2150.82

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
22 REAR FENDER LH	1.00	1,084.90	271.23	813.67	L	Y	XR
23 REAR FENDER RH	1.00	1,084.90	271.23	813.67	L	Y	XR
24 SPARE TYRE PANEL	1.00	372.20	93.05	279.15	L	Y	RY
25 SPARE TYRE BOARD	1.00	342.77	85.69	257.08	L	Y	AM
26 REAR END PANEL WEATHERSTRIP	1.00	185.00	46.25	138.75	L	Y	AM
27 REAR FENDER INNER PANEL TRIM LHS	1.00	390.00	97.50	292.50	L	Y	X
28 REAR FENDER INNER PANEL TRIM RHS	1.00	390.00	97.50	292.50	L	Y	X
29 REAR BUMPER CLIP	1.00	35.00	0.00	35.00	S	Y	NI
30 REAR END PANEL TOP GARNISH CLIPS	1.00	35.00	0.00	35.00	S	Y	NI
31 TAIL LAMP RH CLIP	1.00	20.00	0.00	20.00	S	Y	?
32 TAIL LAMP LH CLIP	1.00	20.00	0.00	20.00	S	Y	?
33 BOOTLID INSULATOR CLIP	1.00	35.00	0.00	35.00	S	Y	X
34 REAR FENDER LH INNER TRIM CLIP	1.00	35.00	0.00	35.00	S	Y	X
35 REAR FENDER RH INNER TRIM CLIP	1.00	35.00	0.00	35.00	S	Y	X
36 SPARE TYRE PANEL SEALANT	1.00	50.00	0.00	50.00	S	Y	X
37 REAR END PANEL SEALANT	50.00	2,500.00	0.00	2,500.00	S	Y	40
38 REVERSE SENSOR	1.00	260.00	0.00	260.00	S	Y	200
39 REAR FENDER INNER PANEL TRIM CLIP	1.00	35.00	0.00	35.00	S	Y	X
TOTAL:		12,837.52	444.42	10,393.10			

TOTAL PARTS & LABOUR : 16,837.52 2,444.42 14,393.10

EXCESS/LOADING:SS 0.00

No. Of Day: 7

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: SS

DATE OF SURVEY: 20 / 6 / 18

SURVEYED BY: Tanpin

CONTACT NO: 97495744 FAX NO: 8

WP'
sur@ (kkanato.com)

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001
Ding Auto User 1

ESTIMATOR
STA AUTOCENTRE
TEL: FAX:

Labour = \$2030.00
Special = \$310
Part = \$2150.82
TOTAL = \$4490.82

TOTAL - 20% = \$3592.65

310

Janice Lee (LKKAuto)

From: Dd hashim <dd.hashim@dingauto.sg>
Sent: Tuesday, June 26, 2018 2:17 PM
To: Taufikh (LKKAuto)
Cc: SUR; Kenneth Ding; Accounts Ding Auto; Carlor Chan; You jingfeng; Duan Hongbo
Subject: 85008386/SLA2344Y~FINALIZE AMOUNT&AFTER PAINT PHOTO
Attachments: estimate finalize.pdf; READY (3).JPG; READY (4).JPG; READY (5).JPG; READY (6).JPG; READY (1).JPG; READY (2).JPG

Hello.

Dear Taufikh,

Please refer to the attachment for the finalize estimate and after paint photo.

Finalize amount is based on surveyor marked and approved.

Kindly calculate and confirm the figure amount.

Finalize:

Total Repair =07Day
Type Repair =L/S

Total Labour =\$2030.00
Total Special Nett =\$310.00
Total Part =\$2150.82
Total Labour+S/N+Part =\$4490.82
Total - 20% =\$3592.65

Total Amount =\$3592.65

Kindly confirm the amount and close this file for us to submit our claims.

Have a great day to you ahead..

Thank you
SINCERELY
DD HASHIM
DING AUTO PTE LTD
TEL Office : 92394128
FAX :62652690



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18011071/T1rd3e2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 19-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 2248J	Veh. Inspected	SLA 2344Y
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18004774MFSH	Excess (\$)	0.00
Assign From	LURENE JAW	Assign Date	19/06/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104538634	Colour	SILVER
Odometer	146214	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	TRIANGLE	6 mm
L/H Front Tyre	205/55 R16	TRIANGLE	6 mm
R/H Rear Tyre	205/55 R16	TRIANGLE	6 mm
L/H Rear Tyre	205/55 R16	TRIANGLE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/06/2018	Inspection Date	20/06/2018
Survey held at	249 JALAN BOON LAY		
Repairer	DING AUTO PTE LTD		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 2344Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	586.55	586.55
1	REAR BUMPER RETAINER LH SHORT	NECESSARY	79.20	79.20
1	REAR BUMPER RETAINER LH LONG	NOT NECESSARY	104.40	-
1	REAR BUMPER RETAINER RH LONG	NOT NECESSARY	104.40	-
1	REAR BUMPER RETAINER RH SHORT	NECESSARY	79.20	79.20
1	REAR BUMPER REINF	BENT	478.42	478.42
1	REAR BUMPER REINF ARM LH	NOT NECESSARY	101.97	-
1	REAR BUMPER REINF RH	NOT NECESSARY	101.97	-
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	79.70	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	79.70	-
1	REAR END PANEL	BENT	790.45	790.45
1	REAR END PANEL TOP GARNISH	DEFORMED	150.10	150.10
1	TAIL LAMP RH	NOT NECESSARY	427.80	-
1	TAIL LAMP LH	NOT NECESSARY	427.80	-
1	BOOTLID	TO REPAIR SEE LABOUR	879.60	-
1	BOOTLID LOCK	NOT NECESSARY	424.79	-
1	BOOTLID EMBLEM LOGO	NECESSARY	58.70	58.70
1	BOOTLID EMBLEM ALTIS	NECESSARY	58.70	58.70
1	BOOTLID EMBLEM COROLLA	NECESSARY	58.70	58.70
1	BOOTLID LAMP LH	NOT NECESSARY	427.80	-
1	BOOTLID LAMP RH	NOT NECESSARY	427.80	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,084.90	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,084.90	-
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	372.20	-
1	SPARE TYRE BOARD	CRACKED	342.77	342.77
1	REAR END PANEL WEATHERSTRIP	CUT	185.00	185.00
1	REAR FENDER INNER PANEL TRIM LHS	NOT NECESSARY	390.00	-
1	REAR FENDER INNER PANEL TRIM RHS	NOT NECESSARY	390.00	-

Report Ref No. CS/FCI18011071/T1rd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-	-716.95
			9,777.52	2,150.84
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLIP (SN)	NECESSARY	35.00	35.00
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	35.00	35.00
1	TAIL LAMP RH CLIP (SN)	NOT NECESSARY	20.00	-
1	TAIL LAMP LH CLIP (SN)	NOT NECESSARY	20.00	-
1	BOOTLID INSULATOR CLIP (SN)	NOT NECESSARY	35.00	-
1	REAR FENDER LH INNER TRIM CLIP (SN)	NOT NECESSARY	35.00	-
1	REAR FENDER RH INNER TRIM CLIP (SN)	NOT NECESSARY	35.00	-
1	SPARE TYRE PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
50	REAR END PANEL SEALANT (SN)	NECESSARY	2,500.00	40.00
1	REVERSE SENSOR (SN)	NOT WORKING	260.00	200.00
1	REAR FENDER INNER PANEL TRIM CLIP (SN)	NOT NECESSARY	35.00	-
			3,060.00	310.00
	LABOUR			
	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF BOOTLID, REAR FENDER LH, REAR FENDER RH AND SPARE TYRE PANEL.		1,500.00	900.00
	R&R REAR REVERSE SENSOR AND PAINTING.		120.00	30.00
	R&R SPARE TYRE, BOARD, CARPET AND TRIM.		180.00	40.00
	R&R BOOTLID COMPONENTS.	NOT NECESSARY	150.00	-
	CHECK WIRING.		100.00	30.00
	RUST PROOFING.		100.00	30.00
	TO PUTTY & SPRAY PAINTING REAR BUMPER, REAR END PANEL, REAR FENDER LH / RH, SPARE TYRE PANEL, BOOTLID.		1,500.00	1,000.00
	TO MOUNTWORK BENCH & RE-ALIGN REAR CHASSIS.	NOT NECESSARY	350.00	-
			-	-
			-	-
			4,000.00	2,030.00
	GRAND TOTAL		16,837.52	4,490.84

Report Ref No. CS/FCI18011071/T1rd3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,550.00
---	--	--	----------

Report Ref No. CS/FCI18011071/T1rd3e2

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.