



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 28/8/2018

### Survey Details:

Date of loss	5-Jun-18
Date of appointment	18-Jun-18
Date of survey	19-Jun-18
Location of survey	CHENG MOTOR WORK CO

### Vehicle Details:

Claim Type:	Third party
Vehicle number	GY 301S
Make and Model	TOYOTA DYNA 3.0M 2982cc
Date of registration	Sep-14
Excess	
Market Value	\$ 45,000.00
Parf Rebate	\$ 32,564.00
Nett Loss	\$ 12,436.00

### Repair details:

Initial Estimate	\$ 4,332.98
------------------	-------------

### Proposed/Revised repair cost:

Parts	\$ 1,142.21
Check items (estimate)	\$0
Labour	\$ 750.00
<b>Total</b>	<b>\$ 1,892.21</b>
<b>Lump Sum(if applicable)</b>	<b>\$ -</b>

<b>Number of days for repair</b>	<b><u>3 days</u></b>
----------------------------------	----------------------



**Remarks:**

*The Insured Driver (transcab) reported that he was from minor road turning out towards the main road when the accident happened. TP vehicle was turning in from main road towards the minor road. A letter was sent out to the Insured to notify of the TP claim and NCD issue. No feedback from Insured till date. BOLA 10a - OI from minor road. TP LOD IN. TP scene photos show OI vehicle had crossed the stop line.*

**Mandate:**

Liability(TP)		100%
Proposed Repair Cost	\$	1,892.21
Loss of Use	\$	600.00
Loss of Rental (w/gst)	\$	-
Loss of Income	\$	-
GIA/LTA search fees	\$	7.45
Others	\$	-
<b>Proposed Total</b>	<b>\$</b>	<b>2,499.66</b>