

ASS. REC. BY:

REF: es/FCI18011079

R1sd3

02

Special Instructions:

Surveyor:
CWS

Rasul

ASSIGNMENT (Office)

From (Person):

Lurene jaw

of

FCI

Date/Time:

19/6/18 @ 1:02pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 7003C

Insured:

SHA 9154E

at Workshop m/s

Wearnes Automotive

Tel:

8126 1237

of

249 Alexandra Road

Policy No:

Claim No:

D18004802MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/06/2018

CA / REV / REP. / REV 24 HRS

(wp)

21-06-2018 @ after 10am at 45 Leng Kee Rd

H.O.D. Endorsement:

Date/Time:

1:55pm @ 19/6/18

Person Contacted:

paul

Vehicle IN ☒ OUT

Date/Time	Action/Instruction	Estimate
	SLE 7003C - X	
	SHA 9154E - CS / QW11013508 / Rfs2	DOA: 8/07/2011
22/06/18	@ 16:33 p.m. revised PA to wear via email.	
12/11/18	Confirmed P/P \$ 8,365.73 @ 5 days with Rasul.	
	(\$ 5,835.37 Real - 41%)	

Surveys

REF:

3606A

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLE 7003C
at Workshop m/s: W6ARNES
of: 45, LEACH KERR RD
Insured: PCI
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.


Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLE 7003C Yr Regn: 2016 / July
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: INFINITI Q50 2-OTA c.c. 1991
Colour: BLACK A/C: Insured / Std / NI / NA
Sp. Reading: 8093 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JN1BCAV3720480667
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Order / Jammed / Leaked / Burnt or
Brake: Order / Jammed / Leaked / Burnt or
Modi: Nil / STD A/Rim or
Tyre Size: F: 225/50R18
R: 18
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 16/06/18 D.O.I. 21/06/18
Survey held at: W6ARNES
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
REAR N/S
The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

RECEIVED 12 NOV 2018

Date/Time, File Pass to?

1) 12/11/18
7p.54

Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation

) S + RS \$

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 8,365.73 r/p

4x15 = 60

170 + 60

50

50

41

371



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18011079/R1sd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 19-06-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9154E	Veh. Inspected	SLE 7003C
Policy No.		Coverage (\$)	0.00
Claim No.	D18004802MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	19/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/06/2018	Inspection Date
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004802MFSH

Date: 22 June 2018

Our Ref: CS/FCI18011079/R1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLE 7003C .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/06/2018 at the premises of M/s Wearnes Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>12,501.10</u> .
Revised Estimate Amount	: S\$ <u>6,929.70</u> .
"Check" Items Amount	: S\$ <u>624.20</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 5 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	18-06-2018	Our Ref No.	D18004802MFSH
Accident Date	16-06-2018	Claim Type.	Third Party
Insured Vehicle	SHA9154E	Third Party Vehicle.	SLE7003C
Survey Location	BODY AND PAINT DEPT 249 ALEXANDRA ROAD		
Contact Person.	PAUL ONG		
Contact No.	63789336/ 81261237	Fax No.	0
Survey Type	DIRECT SETTLEMENT:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEARNES AUTOMOTIVE PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	LURENE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241534)



PRI Documents



Close



PRI Header Details

Claim No	D18004802MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & WEARNES
Workshop Name	WEARNES AUTOMOTIVE PTE LTD (Contact Person : PAUL ONG)	Survey Location & Contact Details	BODY AND PAINT DEPT 249 ALEXANDRA ROAD Mobile: 81261237 , Phone: 63789336 , Fax: 0 EmailId: PAUL.ONG@WEARNES.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9154E	TP Vehicle No	SLE7003C
PRI Recieved Date	18-06-2018 09:53:54 PM	Surveyor Appointed Date	19-06-2018 01:01:06 PM	Surveyor Accept Date	19-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	19-06-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 12 November 2018 10:14 AM
To: 'Paul Ong Qing Yong'
Cc: Rasul (LKKAuto); SUR
Subject: FW: SLE7003C Finalise
Attachments: SLE7003C Finalise (3.19 MB)

Sensitivity: Confidential

Dear Paul,

Confirmed final fig of \$8,365.73 @ 5 days of repairs before GST.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Paul Ong Qing Yong <paul.ong@wearnes.com>

Sent: Thursday, 8 November 2018 10:24 AM

To: Admin A <admin-a@lkkauto.com>

Cc: Rasul (LKKAuto) <Rasul@lkkauto.com>

Subject: RE: SLE7003C Finalise

Sensitivity: Confidential

Can help send to handling officer to close case

Best Regards,

Paul Ong

Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd

249 Alexandra Road Singapore 159935

M (65) 8126 1237 D (65) 6378 9336

www.wearnesauto.com paul.ong@wearnes.com

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Paul Ong Qing Yong
Sent: Monday, 5 November, 2018 8:48 AM
To: 'Rasul (LKKAUTO)'
Subject: RE: SLE7003C Finalise
Sensitivity: Confidential

Can I close case

Best Regards,

Paul Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 8126 1237 D (65) 6378 9336
www.wearnesauto.com paul.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Paul Ong Qing Yong
Sent: Wednesday, 31 October, 2018 10:08 AM
To: 'Rasul (LKKAUTO)'
Subject: RE: SLE7003C Finalise
Sensitivity: Confidential

Can close

Best Regards,

Paul Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 8126 1237 D (65) 6378 9336
www.wearnesauto.com paul.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Paul Ong Qing Yong
Sent: Tuesday, 23 October, 2018 8:48 AM
To: 'Rasul (LKKAUTO)'
Subject: SLE7003C Finalise
Sensitivity: Confidential

Attached

Best Regards,

Paul Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 8126 1237 D (65) 6378 9336
www.wearnesauto.com paul.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 22 June 2018 4:38 PM
To: 'Nivitha (LKK Auto)'; 'Claim Workflow System'; ASSIGNMENTS@LKKAUTO.COM
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; "SUR"
Subject: RE: SURVEY ASSESSMENT - D18004802MFSH/1
Attachments: SLE 7003C - Preli Advise.pdf

Dear Lurene,

Enclosed preliminary revised for SLE 7003C.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 19 June 2018 2:00 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; "SUR" <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004802MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 19 June 2018 1:01 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004802MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.





Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Key:

-  Stationary Truck
-  Bus after turning right from Bukit Merah Central – and then trying to cut out to outer lane because of obstruction by Stationary Truck
-  My car (SLE7003C), after turning right from Bukit Merah Central behind bus. I was on the outer lane, but I slowed and then stop as the bus was cutting out to my lane (bus was signalling)
-  Taxi (City Cab, SHA 9154E), also turning right from Bukit Merah Central behind me, but did not notice all vehicles in front have stopped – thus crashing into the back of my car. His front right bumper hitting my car's back left bumper. Damages can be seen in the photos below. Accident happened at around 3.15 pm on Saturday, 16 June 2018.

Both cars as shown in the photos have been parked at the side the road so as not to block the flow of traffic.

Particular from Taxi Driver:

Name: Mr Chua Hock Seng
IC: S0236329A
HP: 93882915





WEARNES

SERVICE ESTIMATE

86450 - C00001 SL: SERVICE SALES - PC

Prof Leong Kwong Sin

1 JALAN KUALA

#12-01

Singapore 239639

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 18/06/2018

WIP No. : 11505

Veh.In/Out:

*Tel.No. : Mobile: 90897620

Reg.No. : SLE7003C

Reg.date : 29/07/2016

Mileage : 0

Chassis No: JN1BCAV37Z0480667

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Prof Leong Kwong Sin

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BOOTLID, REAR BUMPER, REAR TAILLAMP. ETC	0	2700.00	0	2,700.00	\$ 1800	
800	TO PUTTY SPRAYPAINT ON REAR BOOTLID, REAR BUMPER, ETC	0	2400.00	0	2,400.00	\$ 1600	
802	TO REMOVE & REFIT REAR BOOTLID PARTS	0	1000.00	0	1,000.00	\$ 500	
R06	REAR NUMBER PLATE & HOLDER	0	60.00	0	60.00	\$ X 11	
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	390.00	0	390.00	\$	
	BUMPER REAR Q50 2.0	1.0 EA	800.10		800.10	\$ DE- 720.09	
	BRACKET-BUMPER RR LH	1.0 EA	30.80		30.80	\$ M- 27.72	
	BUMPER REAR LH BRACK	1.0 EA	30.80		30.80	\$ M- 27.72	
	BRACKET-BUMPER	1.0 EA	30.80		30.80	\$ M- 27.72	
	BRACKET-BUMPER	1.0 EA	30.80		30.80	\$ M- 27.72	
	BUMPER REAR CTR FINI	1.0 EA	19.90		19.90	\$ X SVC	
	REINF-BUMPER RR	1.0 EA	567.40		567.40	\$? X M	

SERVICE ESTIMATE

86450 - C00001 SL: SERVICE SALES - PC

Prof Leong Kwong Sin

1 JALAN KUALA

#12-01

Singapore 239639

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date : 18/06/2018

WIP No. : 11505

Veh.In/Out:

*Tel.No. : Mobile: 90897620

Reg.No. : SLE7003C

Reg.date : 29/07/2016

Mileage : 0

Chassis No: JN1BCAV37Z0480667

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Prof Leong Kwong Sin

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	CLIP	4.0 EA	7.00			28.00 S	X
	ORNAMENT ASSY R	1.0 EA	56.80			56.80 S	X
	ORNAMENT ASSY L	1.0 EA	56.80			56.80 S	X
	LAMP COMB RR LH Q50	1.0 EA	581.70			581.70 S	X
	LAMP COMB RR,RH	1.0 EA	581.70			581.70 S	X
	LAMP COMB RR,LH	1.0 EA	290.90			290.90 S	X
	LAMP COMB RR,RH	1.0 EA	290.90			290.90 S	X
	LID TRUNK	1.0 EA	714.80			714.80 S	X
	MLDG ASSY-TRUNK	1.0 EA	114.40			114.40 S	X
	HINGE TRUNK LID RH	1.0 EA	79.00			79.00 S	X
	HINGE TRUNK LID LH	1.0 EA	79.00			79.00 S	X
	EMBLEM	1.0 EA	47.90			47.90 S	X
	I848904HB2A/EMBLEM	1.0 EA	81.10			81.10 S	X
	NOISE DEADENING PAD	1.0 EA	500.00			500.00 S	X
	BODY PANEL SEALANT X	1.0 EA	937.50			937.50 S	X

Gross Total. 12,501.10

14,201.10

Labour Total 6,550.00
Parts Total 5,951.10
Package Total 0.00

Net..... 12,501.10

GST @ 7.0% 875.08

Total..... 13,376.20

Paid..... 0.00

Please Pay.. 13,376.20

GST: S=StdRated; O=OutOfScope

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T +65 6430 4700

Co reg no. 199501400R / GST reg no. M28920628X

www.wearnesauto.com



SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD
 FIRST CAPITAL INSURANCE LTD
 37 ROBINSON ROAD
 #12-01, CITY HOUSE
 SINGAPORE
 Singapore 06877
 GST Reg. No: M79920628X
 Inv. No. : BAP 0 Page 1
 Inv. date. : 23/10/2018
 WIP No. : 11505
 Veh. In/Out: 21/06/2018 21/07/2018
 *Tel. No. :
 Reg. No. : SLE7003C
 Reg. date. : 29/07/2016
 Mileage : 0,093
 Chassis No: JN1BCAV5720489667
 Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Prof Leong Kwong Sin

Op. No	Description	Work Qty	Price	Disc%	Pkg	Amount	3
302	TO REPLACE REAR BOOTLID, REAR BUMPER, REAR TAILLAMP, ETC	0	1800.00	0		1,800.00	✓
300	TO PUTTY SPRAYPAINT ON REAR BOOTLID, REAR BUMPER, ETC	0	1600.00	0		1,600.00	✓
302	TO REMOVE & REFIT REAR BOOTLID PARTS	0	500.00	0		500.00	✓
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	590.00	0		590.00	✓
302	TO REPAIR REAR LH FENDER END P	0	900.00	0		900.00	3
300	TO PUTTY SPRAYPAINT ON REAR LH FENDER END PANEL	0	800.00	0		800.00	3
	BUMPER REAR Q50 2.0	1.0 EA	800.10	✓		720.09	3
	BRACKET-BUMPER RR LH	1.0 EA	30.80	✓		27.72	3
	BUMPER REAR LH BRACK	1.0 EA	30.80	✓		27.72	3
	BRACKET-BUMPER	1.0 EA	30.80	✓		27.72	3
	BRACKET-BUMPER	1.0 EA	30.80	✓		27.72	3

SERVICE ESTIMATE

O - F00003 SL: FIRST CAPITAL INSURANCE LTD GST Reg.No: M28920628X
 FIRST CAPITAL INSURANCE LTD Inv.No. : B&P 0 Page 2
 36 ROBINSON ROAD Inv.date: 23/10/2018
 #16-01, CITY HOUSE WIP No. : 11505
 SINGAPORE Veh.In/Out: 21/06/2018 21/07/2018
 Singapore 068877 *Tel.No. :
 Reg.No. : SLE70030
 Closed by : Paul Ong Qing Yong Reg.date: 29/07/2016
 Svc Consultant : ACC Mileage : 3,073
 Remarks : Prof Leong Kwong Sin Chassis No: JN1BCAV57Z0480667

Op.No	Description	Mech Qty	Price	Disc	Pkg	Amount	G
	LAMP CORB RR LH Q50	1.0 EA	581.70			523.53	3
	LAMP CUMB RR LH	1.0 EA	290.90			261.81	3
	LID TRUNK	1.0 EA	714.80			643.32	3
	EMBLEM	1.0 EA	47.90			43.11	3
	1848904HB2A/EMBLEM	1.0 EA	81.10			72.99	3

		Gross Total	8,365.73
Labour Total	5,990.00	Net	8,365.73
Parts Total	2,375.73	GST @ 7.0%	585.60
Package Total	0.00	Total	8,951.33
		Paid	0.00
		Please Pay	8,951.33

GST: S=StdRated; O=OutOfScope; Z=ZeroRated




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18011079/R1sd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 12-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9154E	Veh. Inspected	SLE 7003C	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18004802MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	19/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	INFINITI Q50 2.0T A	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JN1BCAV37Z0480667	Colour	BLACK	
Odometer	8093	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/06/2018	Inspection Date	21/06/2018	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 7003C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER REAR Q50 2.0 (SN)	DEFORMED	800.10	720.09
1	BRACKET-BUMPER RR LH (SN)	NECESSARY	30.80	27.72
1	BUMPER REAR LH BRACK (SN)	NECESSARY	30.80	27.72
1	BRACKET-BUMPER (SN)	NECESSARY	30.80	27.72
1	BRACKET-BUMPER (SN)	NECESSARY	30.80	27.72
1	BUMPER REAR CTR FINI (SN)	SERVICEABLE	19.90	-
1	REINF-BUMPER RR (SN)	SERVICEABLE	567.40	-
4	CLIP (SN)	SERVICEABLE	28.00	-
1	ORNAMENT ASSY R (SN)	SERVICEABLE	56.80	-
1	ORNAMENT ASSY L (SN)	SERVICEABLE	56.80	-
1	LAMP COMB RR LH Q50 (SN)	BROKEN	581.70	523.53
1	LAMP COMB RR,RH (SN)	NOT NECESSARY	581.70	-
1	LAMP COMB RR,LH (SN)	SCRATCHED	290.90	261.81
1	LAMP COMB RR,RH (SN)	NOT NECESSARY	290.90	-
1	LID TRUNK (SN)	BENT	714.80	643.32
1	MLDG ASSY-TRUNK (SN)	NOT NECESSARY	114.40	-
1	HINGE TRUNK LID RH (SN)	NOT NECESSARY	79.00	-
1	HINGE TRUNK LID LH (SN)	NOT NECESSARY	79.00	-
1	EMBLEM (SN)	NECESSARY	47.90	43.11
1	I848904HB2A/EMBLEM (SN)	NECESSARY	81.10	72.99
1	NOISE DEADENING PAD (SN)	NOT NECESSARY	500.00	-
1	REAR NUMBER PLATE & HOLDER (SN)	NOT NECESSARY	60.00	-
1	BODY PANEL SEALANT X (SN)	NOT NECESSARY	937.50	-
			6,011.10	2,375.73
LABOUR				
TO PUTTY SPRAYPAINT ON REAR LH FENDER END PANEL (ADDITIONAL).			800.00	800.00
TO REPLACE REAR BOOTLID,REAR BUMPER,REAR TAILLAMP,ETC.			2,700.00	1,800.00
TO PUTTY SPRAYPAINT ON REAR BOOTLID,REAR BUMPER,ETC.			2,400.00	1,600.00

Report Ref No. CS/FC118011079/R1sd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT REAR BOOTLID PARTS.		1,000.00	500.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		390.00	390.00
	TO REPAIR REAR LH FENDER END P (ADDITIONAL).		900.00	900.00
			8,190.00	5,990.00
	GRAND TOTAL		14,201.10	8,365.73
RECOMMENDED COST OF REPAIRS				8,365.73

Report Ref No. CS/FCI18011079/R1sd3n2

MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.