

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01, CITY HOUSE
 SINGAPORE
 Singapore 068877
 GST Reg.No: M28920628X
 Inv.No. : B&P 0 Page 1
 Inv.date : 23/10/2018
 WIP No. : 11505
 Veh.In/Out: 21/06/2018 21/07/2018
 *Tel.No. :
 Reg.No. : SLE7003C
 Reg.date : 29/07/2016
 Mileage : 8,093
 Chassis No: JN1BCAV37Z0480667
 Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Prof Leong Kwong Sin

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BOOTLID, REAR BUMPER, REAR TAILLAMP, ETC	0	1800.00	0		1,800.00	S
800	TO PUTTY SPRAYPAINT ON REAR BOOTLID, REAR BUMPER, ETC	0	1600.00	0		1,600.00	S
802	TO REMOVE & REFIT REAR BOOTLID PARTS	0	500.00	0		500.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	390.00	0		390.00	S
802	TO REPAIR REAR LH FENDER END P	0	900.00	0		900.00	S
800	TO PUTTY SPRAYPAINT ON REAR LH FENDER END PANEL	0	800.00	0		800.00	S
	BUMPER REAR Q50 2.0	1.0 EA	800.10	10		720.09	S
	BRACKET-BUMPER RR LH	1.0 EA	30.80	10		27.72	S
	BUMPER REAR LH BRACK	1.0 EA	30.80	10		27.72	S
	BRACKET-BUMPER	1.0 EA	30.80	10		27.72	S
	BRACKET-BUMPER	1.0 EA	30.80	10		27.72	S