

ASS. REC. BY:

REF:

CS/FCI18011082 / R1qds / n2

Special Instruction:

Surveyor
aws

ASSIGNMENT (Office)

From (Person):

Lurene jaw

of

FCI

Date/Time:

19/6/18 @ 9.27am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJU 9136D

Insured:

SHC 7220A

at Workshop m/s

Ethoz Group

Tel:

88 22 8339

of

30 Bukit Batok Crescent

Policy No:

Claim No:

D18003256 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/04/2018

CA / REV / REP. / REV 24 HRS

(up)

03/07/2018 @ before 11.30am

H.O.D. endorsement

Date/Time:

9.38am @ 19/6/18

Person Contacted:

Lee chen sin

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJU 9136D - X

SHC 7220A - X

04/7/18 @ 7.42pm revised to invoice by email.

09/11/19 @ 9.46am Request finalised with Mr Lee LS @ 4.50, 4 days.

Form

REF: FCL

7637D

ASSIGNMENT

From: Date: 03/01/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJU 9136D

at Workshop m/s

ETHOZ

of 30 Bukit Batok Crescent

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

ke

before 11:30am.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SJU 9136D

Yr Regn: 2010 JAN

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Odyssey 2.4a c.o 2354

Colour:

Purple

A/C: Insured / Std / NI / NA

Sp. Reading:

097434

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHM RB38 309C201751

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

23/04/18

D.O.I.

03/07/18

Survey held at

ETHOZ

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt/O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 16 JAN 2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 16/1/18

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format :

TP

Lump Sum / I.B. (\$)

4150

160

50

50

68

328



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003256MFSH

Date: 04 July 2018

Our Ref: CS/FCI18011082/R1qd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJU 9136D

Please be informed that we had conducted the inspection of the abovementioned vehicle on 03/07/2018 at the premises of M/s ETHOZ and have the following to report:-

Workshop Estimate Amount	: S\$ <u>8,580.80</u>
Revised Estimate Amount	: S\$ <u>3,508.40</u>
"Check" Items Amount	: S\$ <u>1,694.24</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the front o/s portion.



Yours faithfully

Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	25-04-2018	Our Ref No. D18003256MFSH
Accident Date	23-04-2018	Claim Type. Third Party
Insured Vehicle	SHC7220A	Third Party Vehicle. SJU9136D
Survey Location	30 BUKIT BATOK CRESCENT	
Contact Person.	LEE CHEN SIN	
Contact No.	66547250/ 88228339	Fax No. 66547542
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ETHOZ GROUP LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/239297)



PRI Documents



Close



PRI Header Details

Claim No	D18003256MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & ETHOZ GR
Workshop Name	ETHOZ GROUP LTD (Contact Person : LEE CHEN SIN)	Survey Location & Contact Details	30 BUKIT BATOK CRESCENT Mobile: 88228339 , Phone: 66547250 , Fax: 6654754; EmailId: CHENSIN.LEE@ETHOZGROUP.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7220A	TP Vehicle No	SJU9136D
PRI Recieved Date	18-06-2018 05:15:05 PM	Surveyor Appointed Date	19-06-2018 09:26:40 AM	Surveyor Accept Date	19-06-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	19-06-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Wednesday, 9 January 2019 9:46 AM
To: Lee Chen Sin
Cc: SUR
Subject: RE: FINALIZATION REPORT OF SJU-9136-D HONDA ODYSSEY (TP)(MS FIRST CAPITAL)

Hi Lee,

Finalised amount confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Lee Chen Sin [mailto:ChenSin.Lee@ethozgroup.com]
Sent: Tuesday, 8 January, 2019 6:12 PM
To: Rasul (LKKAUTO)
Cc: SUR
Subject: FINALIZATION REPORT OF SJU-9136-D HONDA ODYSSEY (TP)(MS FIRST CAPITAL)

Hi Rasul,

Attached are the finalization report, check item photo and photo after paint of above mention vehicle.

Please send acceptance once the COR is confirm.

COR : \$ 4,150.00 (Lump Sum Repair)
Repair days : 4

Kindly revert.


Thank you.

Warmest Regards,
Lee Chen Sin
Motor Claims Operations

ETHOZ
ETHOZ GROUP LTD

30 Bukit Batok Crescent Singapore 658075
DID: 6654 7520 | FAX: 6654 7542 | Mobile: 8822 8339

www.ethozgroup.com



Shiau Chan (LKKAUTO)

From: Lee Chen Sin <ChenSin.Lee@ethozgroup.com>
Sent: Friday, 30 November 2018 3:12 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: FINALISE OF VEHICLE SJU 9136D (DOA: 23/04/2018)

Dear Shiau Chan,

Vehicle yet repair.

We will advise and arrange customer come our side for repair.

Thank you.

Warmest Regards,
Lee Chen Sin

*30/11/18 @ 3.13pm check with
Lee Chen Sin, he said
the vehicle may send in
next week for repair.*

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Friday, November 30, 2018 3:11 PM
To: Lee Chen Sin <ChenSin.Lee@ethozgroup.com>
Subject: FINALISE OF VEHICLE SJU 9136D (DOA: 23/04/2018)

Dear Chen Sin,

Kindly advise the status of SJU 9136D.

If done for repair, kindly send us the final bill for finalise.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 4 July 2018 3:42 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18003256MFSH/1
Attachments: CSFC18011082R1qd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SJU 9136D.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)

Sent: Tuesday, 19 June 2018 9:40 AM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18003256MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Tuesday, 19 June 2018 9:26 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18003256MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7637D
Vehicle Details	
Vehicle No.:	SJU9136D
Vehicle to be Exported:	No
Intended De-registration Date:	18 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4L AT
Primary Colour:	Purple
Manufacturing Year:	2009
Engine No.:	K24Z21301757
Chassis No.:	JHMRB38309C201751
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$31,488.00
Original Registration Date:	04 Jan 2010
First Registration Date:	04 Jan 2010
Transfer Count:	0
Actual ARF Paid:	\$31,488.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Jan 2020
PARF Rebate Amount:	\$17,318.00
Intended COE Rebate Details	
COE Expiry Date:	03 Jan 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$17,889.00
COE Rebate Amount:	\$2,760.00
Total Rebate Amount:	\$20,078.00

The information contained herein is correct as at 18 Jun 2018

OK

(LKK AUTO) (3/7)

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 18/06/2018

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : AZMAN BIN SUPANDI

: DIRECT ASIA INSURANCE(SINGAPORE) PTE LTD

Certificate No : MT/00016921/07

Accident Date : 23/04/2018

Vehicle No : SJU-9136-D

Make & Model : HONDA ODYSSEY 2.4L AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	FRONT BONNET	712.40	Bt -
10	FRONT BONNET INSULATOR CLIP	35.00	na -
1	FRONT FENDER LH		} ASVC
1	FRONT FENDER RH		
1	HEADLAMP LH	733.90	X ✓ CRA
1	HEADLAMP RH	733.90	CRA -
1	HEADLAMP LOWER BRACKET LH	37.40	X ✓ CRA
1	HEADLAMP LOWER BRACKET RH	37.40	? ✓ CRA
1	FRONT GRILLE (OUTER)	220.50	sur -
	RESTORE		
	RESTORE		

Date : 18/06/2018

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : AZMAN BIN SUPANDI

: DIRECT ASIA INSURANCE(SINGAPORE) PTE LTD

Certificate No : MT/00016921/07

Accident Date : 23/04/2018

Vehicle No : SJU-9136-D

Make & Model : HONDA ODYSSEY 2.4L AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT GRILLE (INNER)	207.90	DE /
1	FRONT GRILLE LOGO	23.40	ne /
10	FRONT GRILLE CLIP	39.00	ne /
1	FRONT BUMPER	713.60	DE /
10	FRONT BUMPER CLIP	39.00	ne /
1	FRONT BUMPER SIDE RETAINER LH	12.00	X ⁹⁰ /
1	FRONT BUMPER SIDE RETAINER RH	12.00	ne /
1	FRONT BUMPER CHROME GARNISH	356.30	CRA /
1	FRONT BUMPER LOWER GRILLE	80.00	DE /
1	FRONT BUMPER REINFORCEMENT	233.70	? /

Date : 18/06/2018

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : AZMAN BIN SUPANDI

: DIRECT ASIA INSURANCE(SINGAPORE) PTE LTD

Certificate No : MT/00016921/07

Accident Date : 23/04/2018

Vehicle No : SJU-9136-D

Make & Model : HONDA ODYSSEY 2.4L AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	CONDENSER SIDE COVER LH	9.00	X
1	CONDENSER SIDE COVER RH	9.00	? X } nn
1	SUPPORT PANEL	584.00	? X } nn
1	CONDENSER	753.70	? X } nn
1	RADIATOR	1,865.70	? X } nn
1	RADIATOR FAN COWLING	107.50	X } nn
1	RADIATOR FAN MOTOR	308.00	X } nn
1	RADIATOR FAN BLADE	55.00	X } nn
1	AIR COND FAN COWLING	82.90	X } nn
1	AIR COND FAN BLADE	52.00	X } nn

Date : 18/06/2018

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : AZMAN BIN SUPANDI

: DIRECT ASIA INSURANCE(SINGAPORE) PTE LTD

Certificate No : MT/00016921/07

Accident Date : 23/04/2018

Vehicle No : SJU-9136-D

Make & Model : HONDA ODYSSEY 2.4L AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	AIR COND FAN MOTOR	296.80	X <i>bin</i>
	Sub Total	8351.00	
	Discount 20% On Parts	(1670.20)	
	<u>Special Nett Item</u>		
1	FRONT BUMPER PARKING SENSOR (SET)	250.00	<i>200? pw</i>
1	FRONT NUMBER PLATE	35.00	<i>MA -</i>
1	RADIATOR COOLANT	30.00	X <i>bin</i>
	Sub Total	315.00	
	<u>Labour & Misc</u>		
	LABOUR TO CARRY OUT FRONT REPAIR	700.00	<i>500</i>

Date : 18/06/2018

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : AZMAN BIN SUPANDI

: DIRECT ASIA INSURANCE(SINGAPORE) PTE LTD

Certificate No : MT/00016921/07

Accident Date : 23/04/2018

Vehicle No : SJU-9136-D

Make & Model : HONDA ODYSSEY 2.4L AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	
	TO SPRAY PAINTING ON FRONT AFFECTED AREA	700.00	400
	TO REMOVE & FIX AIRCON CONDENSER INCLUDING TOP UP AIRCON GAS	150.00	100? ✓
	Sub Total	1585.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

8,580.80

Remarks:

4 days - Lumpsum

SUB TOTAL

GST 7.0 % 600.66

TOTAL 9,181.46

Surveyor's name:

Rasul - Hp 90010068

Principal's name:

AZMAN BIN SUPANDI

Survey Date & Time:

03/07/18 @ 1130

Resurvey after repair

[Signature]
5/7/18

FINALIZATION REPORT

ETHOZ

Date : 08/01/2019
To : MS FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department FAX :

Owner : AZMAN BIN SUPANDI
Insured By : DIRECT ASIA INSURANCE(SINGAPORE) PTE LTD
Certificate No : MT/00016921/07 Accident Date : 23/04/2018
Vehicle No : SJU-9136-D Make & Model : HONDA ODYSSEY 2.4L AT

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
<u>List Item</u>			
1	FRONT BONNET	712.40	712.40
10	FRONT BONNET INSULATOR CLIP	35.00	35.00
1	FRONT FENDER LH RESTORE	0.00	0.00
1	FRONT FENDER RH RESTORE	0.00	0.00
1	HEADLAMP LH CHECK ITEM OK	733.90	733.90
1	HEADLAMP RH	733.90	733.90
1	HEADLAMP LOWER BRACKET LH CHECK ITEM OK	37.40	37.40
1	HEADLAMP LOWER BRACKET RH	37.40	37.40
1	FRONT GRILLE (OUTER)	220.50	220.50
1	FRONT GRILLE (INNER)	207.90	207.90
1	FRONT GRILLE LOGO	23.40	23.40
10	FRONT GRILLE CLIP	39.00	39.00
1	FRONT BUMPER	713.60	713.60
10	FRONT BUMPER CLIP	39.00	39.00

PAGE : 1



Date : 08/01/2019

To : MS FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department

FAX :

Owner : AZMAN BIN SUPANDI

Insured By : DIRECT ASIA INSURANCE(SINGAPORE) PTE LTD

Certificate No : MT/00016921/07 Accident Date : 23/04/2018

Vehicle No : SJU-9136-D Make & Model : HONDA ODYSSEY 2.4L AT

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	FRONT BUMPER SIDE RETAINER LH	12.00	0.00
1	FRONT BUMPER SIDE RETAINER RH	12.00	12.00
1	FRONT BUMPER CHROME GARNISH	356.30	356.30
1	FRONT BUMPER LOWER GRILLE	80.00	80.00
1	FRONT BUMPER REINFORCEMENT	233.70	233.70
1	CONDENSER SIDE COVER LH	9.00	0.00
1	CONDENSER SIDE COVER RH	9.00	0.00
1	SUPPORT PANEL	584.00	0.00
1	CONDENSER <i>CHECK ITEM</i> ✓	753.70	753.70
1	RADIATOR	1865.70	0.00
1	RADIATOR FAN COWLING	107.50	0.00
1	RADIATOR FAN MOTOR	308.00	0.00
1	RADIATOR FAN BLADE	55.00	0.00
1	AIR COND FAN COWLING	82.90	0.00
1	AIR COND FAN BLADE	52.00	0.00

PAGE : 2

Date : 08/01/2019

To : MS FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department

FAX :

Owner : AZMAN BIN SUPANDI

Insured By : DIRECT ASIA INSURANCE(SINGAPORE) PTE LTD

Certificate No : MT/00016921/07 Accident Date : 23/04/2018

Vehicle No : SJU-9136-D Make & Model : HONDA ODYSSEY 2.4L AT

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	AIR COND FAN MOTOR	296.80	0.00 <i>nm</i>
	Sub Total	8351.00	4969.10
	Discount <u>20%</u> On Parts	(0.00)	(993.82)
Special Nett Item			
1	FRONT BUMPER PARKING SENSOR (SET) <i>Check Item nm</i>	250.00	200.00
1	FRONT NUMBER PLATE	35.00	35.00
1	RADIATOR COOLANT	30.00	0.00 <i>nm</i>
	Sub Total	315.00	235.00
Labour & Misc			
	LABOUR TO CARRY OUT FRONT REPAIR	700.00	500.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	35.00
	TO SPRAY PAINTING ON FRONT	700.00	400.00

Date : 08/01/2019
 To : MS FIRST CAPITAL INSURANCE LIMITED
 Attn : Motor Claim Department

FAX :

Owner : AZMAN BIN SUPANDI
 Insured By : DIRECT ASIA INSURANCE(SINGAPORE) PTE LTD
 Certificate No : MT/00016921/07 Accident Date : 23/04/2018
 Vehicle No : SJU-9136-D Make & Model : HONDA ODYSSEY 2.4L AT

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	AFFECTED AREA		
	TO REMOVE & FIX AIRCON CONDENSER	150.00	100.00
	INCLUDING TOP UP AIRCON GAS		
	Sub Total	1585.00	1035.00

Sub Total	8,580.80	5,245.28
GST 7.0 %	600.66	367.17
Total	9,181.46	5,612.45

COR : ~~10,150.00~~ (45 REPAIR)
 4 DAYS REPAIR

Surveyor Name : RASUL - LKK
 Date & Time : 03/07/2018 11:30:00 AM
 Lee Chen Sin
 CLAIM DEPARTMENT
 DID : 66547520
 FAX :

PARTS - ~~10,150.00~~ - 20%

- ~~2,030.00~~

SIN - ~~235.00~~

LABOUR - ~~1,035.00~~

~~5,245.28~~

- 20% (45 REPAIR)

~~4,196.22~~

PAGE: 4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18011082/R1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7220A	Veh. Inspected	SJU 9136D	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18003256MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	19/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA ODYSSEY 2.4A	c.c	2354	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JHMRB38309C201751	Colour	PURPLE	
Odometer	97434	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/04/2018	Inspection Date	03/07/2018	
Survey held at	ETHOZ GROUP LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 9136D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	BENT	712.40	712.40
10	FRONT BONNET INSULATOR CLIP	NECESSARY	35.00	35.00
1	FRONT FENDER LH (NPA)	SERVICEABLE	-	-
1	FRONT FENDER RH (NPA)	SERVICEABLE	-	-
1	HEADLAMP LH	CRACKED	733.90	733.90
1	HEADLAMP RH	CRACKED	733.90	733.90
1	HEADLAMP LOWER BRACKET LH	CRACKED	37.40	37.40
1	HEADLAMP LOWER BRACKET RH	CRACKED	37.40	37.40
1	FRONT GRILLE (OUTER)	SCRATCHED	220.50	220.50
1	FRONT GRILLE (INNER)	DEFORMED	207.90	207.90
1	FRONT GRILLE LOGO	NECESSARY	23.40	23.40
10	FRONT GRILLE CLIP	NECESSARY	39.00	39.00
1	FRONT BUMPER	DEFORMED	713.60	713.60
10	FRONT BUMPER CLIP	NECESSARY	39.00	39.00
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	12.00	-
1	FRONT BUMPER SIDE RETAINER RH	NECESSARY	12.00	12.00
1	FRONT BUMPER CHROME GARNISH	CRACKED	356.30	356.30
1	FRONT BUMPER LOWER GRILLE	DEFORMED	80.00	80.00
1	FRONT BUMPER REINFORCEMENT	BENT	233.70	233.70
1	CONDENSER SIDE COVER LH	NOT NECESSARY	9.00	-
1	CONDENSER SIDE COVER RH	NOT NECESSARY	9.00	-
1	SUPPORT PANEL	NOT NECESSARY	584.00	-
1	CONDENSER	BENT	753.70	753.70
1	RADIATOR	NOT NECESSARY	1,865.70	-
1	RADIATOR FAN COWLING	NOT NECESSARY	107.50	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	308.00	-
1	RADIATOR FAN BLADE	NOT NECESSARY	55.00	-
1	AIR COND FAN COWLING	NOT NECESSARY	82.90	-
1	AIR COND FAN BLADE	NOT NECESSARY	52.00	-
1	AIR COND FAN MOTOR	NOT NECESSARY	296.80	-

Report Ref No. CS/FC118011082/R1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-1,670.20	-993.82
			6,680.80	3,975.28
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER PARKING SENSOR (SN)	NOT WORKING	250.00	200.00
1	FRONT NUMBER PLATE (SN)	BENT	35.00	35.00
1	RADIATOR COOLANT (SN)	NOT NECESSARY	30.00	-
			315.00	235.00
	LABOUR			
	LABOUR TO CARRY OUT FRONT REPAIR.		700.00	500.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		35.00	35.00
	TO SPRAY PAINTING ON FRONT AFFECTED AREA.		700.00	400.00
	TO REMOVE & FIX AIRCON CONDENSER INCLUDING TOP UP AIRCON GAS.		150.00	100.00
			1,585.00	1,035.00
	GRAND TOTAL		8,580.80	5,245.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,150.00

Report Ref No. CS/FCI18011082/R1qd3n2

MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.