

22/03/2002

SS. REP. BY:

REF:

CS/EQ118011083/Ntber

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Joel Goh

of

EQ1

Date/Time:

19062018 10.46am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

AKB 8880

Insured:

Shw 9284J

at Workshop m/s

Siang Hui

Tel:

6744 4605.

of

Blk 3006 Ubi Rd 1 #01-338

Policy No:

Claim No:

DM18H001516-JG

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi

H.O.D. Endorsement:

Date/Time:

19062018 1128am

Person Contacted:

Siang Hui

Vehicle IN / OUT

2050.

Date/Time

Action/Instruction (✓) Estimate

AKB 8880 - X

Shw 9284J - X

\$2000

10/10 -

Confirm with Siang Hui Lump Sum \$2300, 4days
cred: 2841.60 : 52%

(08/11/13) wef

ASS. REC. BY:

REF: EQI

ASSIGNMENT

From: _____ Date: 09/07/2018

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: AKB 8880

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^(up)

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: AKB 8880 Yr Regn: _____ /Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mazda c.c. _____Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 166629 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: mm6DL2SAAFW125965Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/55 R16R: 185/55 R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
YOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 14/6/2018D.O.I. 9/7/2018

Survey held at

LKK AutoDes. of Damages: ☒ Frt / ☒ Rear / ☒ O/S / N/S / U/C / Rooftop orqs front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Sathya, PLS see my remarks

RECEIVED 10 OCT 2018

10/7

Date/Time, File Pass to?

☐ : Preli. Report☒ : Final Report

Date/Time, File Return to?

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

160

160

Report Format :

ump Sum / I.B.I: (\$ 2000)

Denise Tay (LKKAUTO)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Wednesday, 10 October 2018 3:44 PM
To: Denise Tay (LKKAUTO)
Subject: RE: PRS FOR AKB8880 (OUR REF: DM18HO01516-JG)

Dear Denise

Our claim ref is DM18HO01516-JG

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify t

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Wednesday, October 10, 2018 3:33 PM
To: Joel Goh
Subject: RE: PRS FOR AKB8880 (OUR REF: SGW9284J)

Dear Joel,

Can provide me the Claim no.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAUTO)
Sent: Tuesday, 19 June 2018 10:46 AM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: FW: PRS FOR AKB8880 (OUR REF: SGW9284J)

Catherine Chong (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Tuesday, 19 June, 2018 10:46 AM
To: Admin-D (LKKAuto)
Cc: Admin A
Subject: FW: PRS FOR AKB8880 (OUR REF: SGW9284J)

Hi,

FYNA please.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh [<mailto:joel.goh@eqinsurance.com.sg>]
Sent: Tuesday, 19 June, 2018 9:04 AM
To: bonnie kwok <litigation@bonniekwok.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: PRS FOR AKB8880 (OUR REF: SGW9284J)

Without Prejudice

Dear ST

Thank you for the confirmation.

Best Regards,

Joel Goh

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: bonnie kwok [<mailto:litigation@bonniekwok.com>]
Sent: Tuesday, June 19, 2018 9:03 AM
To: Joel Goh

Cc: Admin A

Subject: Re: PRS FOR AKB8880 (OUR REF: SGW9284J)

Hi Joel,

Please be informed that our client has reported that the accident had occurred at 8 a.m.

Regards,

ST

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On 19 June 2018 at 08:47, Joel Goh <joel.goh@eqinsurance.com.sg> wrote:

Without Prejudice

Dear ST

We will arrange accordingly.

Meanwhile, please assist to provide us with the time of the accident for admin purposes.

Dear LKK

Kindly assist on this PRS.

Our insured has not reported the accident.

Workshop Details:

Siang Hui Motor Works

Blk 3006 Ubi Road 1

#01-338

Singapore 408700

Best Regards,

Joel Goh

Executive | Claims




EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: bonnie kwok [mailto:litigation@bonniekwok.com]

Sent: Monday, June 18, 2018 5:14 PM

To: Joel Goh

Subject: Re: PRS FOR AKB8880 (OUR REF: SGW9284J)

Dear Sirs,

Our client agrees to LKK Auto Consultants Pte Ltd as the Single Joint Expert (SJE).

Please let us have their report in due course.

Kindly request for the SJE to contact the repairers, M/s Siang Hui Motor Works at 6744 4605 to make the necessary arrangements.

Regards,

ST

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On 18 June 2018 at 10:59, Joel Goh <joel.goh@eqinsurance.com.sg> wrote:

OUR REF: SGW9284J

YOUR REF: SIANGHUI-AKB8880

Without Prejudice

Dear Sirs

Kindly email all PRS request to eqiprs@eqinsurance.com.sg

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155 Contact person : Joey/Joseh	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon Kho
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Ricky Teng	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd	

Tel: 63450068	
Fax: 63445328	
Contact Person: Edna Lee	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Best Regards,

Joel Goh

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please



**SINGAPORE
POLICE FORCE**



T/20180614/2132

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20180614/2132

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/06/2018 17:19		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: KOH CHIN SIANG			Address:		
ID Type / ID No.: NEW MALAYSIAN IC / 850622045555			Contact No.: Home/Office:		Mobile: 86856226
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 32	Date of Birth: 22/06/1985	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: PRODUCT EXECUTIVE			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 14/06/2018 08:00	Type of Location: Bend
Location: Along Road 1 SECOND LINK TUAS CHECKPOINT TOWARDS SINGAPORE				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
AKB8880	Car				Slightly Damaged	1
SGW9284J	Car	TOYOTA	VIOS E AUTO	Beige	Slightly Damaged	3



**SINGAPORE
POLICE FORCE**



T/20180614/2132

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20180614/2132

CONTINUATION OF REPORT

Brief Details.

ON THE ABOVE MENTION DATE TIME AND LOCATION
I WAS TRAVELLING TOWARDS TUAS CHECKPOINT GOING TOWARDS SIGNAPORE. I WAS ON THE 2ND LANE. THERE WAS A DIVIDER IN THE MIDST OF THE TWO WAY ROAD. THE DIVIDER HAD AN OPENING THAT ALLOWS THE VEHICLE ON THE 1ST LANE TO CUT INBETWEEN AND IMPROVE TRAFFIC FLOW. I WAS ON THE 2ND LANE, I MOVE FORWARD TO THE 1ST LANE, AFTER PASSING THE OPENING GAP INBETWEEN THE DIVIDER, ANOTHER VEHICLE THAT WAS ON THE 1ST LANE WHO WAS BEHIND ME, KEPT MOVING STRAIGHT WITHOUT STOPPNG AND THUS COLLIDING WHEN HE'S SUPPOSE TO MOVE INTO THE DIVIDING GAP.

IN ORDER TO NOT CAUSE JAM TO THE TRAFFIC FLOW, I WENT TO THE CHECKPOINT, UPON REACHING THERE I TOLD THE OFFICER THERE. THE OFFICER HOLD THE DRIVER'S PASSPORT AND STOP THEM AT THE SIDE OF THE ROAD. WE DISCUSS ABOUT THE SITUATION HOWEVER HE REFUSE GIVE ME HIS PARTICULARS. I DID NOT GIVE HIM MINE AS WELL.

AFTER THE ACCIDENT, HE'S SAYING HE IS NOT AT FAULT AS HE THINKS THAT THE DAMAGE WAS CAUSE BY THE VEHICLE INFRONT OF ME.



**SINGAPORE
POLICE FORCE**



T/20180614/2132

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20180614/2132

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
TP /
NG JIN SHENG

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIA /
Staff Sgt TANG SIEW PING
Contact No.: 65476430

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
14/06/2018 17:19

Classification Of Case:

祥輝汽車修理 SIANG HUI MOTOR WORKS

Blk 3006, Ubi Road 1 #01-338, Singapore 408700.

Tel: 67444605 Fax: 67440726

REG. No. 322208/00M

Date, 9/7/18

Vehicle No AKB 8880 Mazda

1pc	Front bumper ✓ CRK	833.00	\$ 963.00
1pc	Bumper side Retainer (LH) ✓ CRK	14.00	\$ 43.00
1pc	Front fender (LH) R	380.00	\$ 453.00
1pc	Headlamps ✓ CRK	644.00	\$ 734.00
1pc	side mirror ✓ TM	490.00	\$ 637.00
1pc	side mirror cover ✓ CRK		\$ 67.00 ✓

\$ 5,927.00

Less 20%

585.40

\$ 2341.60

S/Nett

1pc wheel rim R \$ 980.00

Labour charge:-

- 1) To check wheel alignment \$ ~~60.00~~ 40.00
- 2) To spray painting \$ ~~680.00~~ 500.00
- 3) To replace, repair straighten
+ replace all damaged parts \$ ~~780.00~~ 400/-

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4 days

Grand Total \$ 4841.60

Sathya Sai

Sathya333@khawto.com

- Lump Sum Repair

- Photo after paint

祥輝汽車修理 SIANG HUI MOTOR WORKS

Blk 3006, Ubi Road 1 #01-338, Singapore 408700.
Tel: 67444605 Fax: 67440726
REG. No. 322208/00M

Date, 9/7/18

Vehicle No: AKB 8880 Mazda

1pc	Front bumper ✓CRK	\$ 963.00
1pc	Bumper side Retainer (LH) ✓cut	\$ 43.00
1pc	Front fender (LH) R	\$ 483.00
1pc	Headlamp ✓scr	\$ 734.00
1pc	side mirror ✓JM	\$ 637.00
1pc	side mirror Cover ✓scr	\$ 67.00
		<u>\$ 2,927.00</u>
	less 20%	585.40
		\$ 2341.60

S / Nett

1pc	wheel rim R	\$ 980.00
-----	-------------	-----------

Labour charge :-

- 1) To check wheel alignment \$ ~~60.00~~ 40.00
- 2) To spray painting \$ ~~680.00~~ 500.00
- 3) To replace, repair straighten & realign all damaged parts \$ ~~780.00~~ (600.00)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4 days

Grand Total \$ 4841.60

Sathya Sai

Sathya Sai @ lkkauto.com

- Lump Sum Repair
- Photo after paint.


10/7/18




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CS/EQI18011083/Ntbe2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 02-11-2018		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGW 9284J	Veh. Inspected	AKB 8880	
Policy No.		Coverage (\$)	0.00	
Claim No.	DM18HO01516-JG	Excess (\$)	0.00	
Assign From	JOEL GOH	Assign Date	19/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA	c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	MM6DL2SAAFW125965	Colour	GREY	
Odometer	166629	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	TOYO	6 mm	
L/H Front Tyre	185/55 R16	TOYO	6 mm	
R/H Rear Tyre	185/55 R16	TOYO	6 mm	
L/H Rear Tyre	185/55 R16	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/06/2018	Inspection Date	09/07/2018	
Survey held at	IDAC PAYA UBI			
Repairer	SIANG HUI MOTOR WORKS			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. AKB 8880

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	CRACKED	963.00	833.00
1	BUMPER SIDE RETAINER (LH)	CUT	43.00	14.00
1	FRONT FENDER (LH)	TO REPAIR SEE LABOUR	483.00	-
1	HEADLAMP	SCRATCHED	734.00	644.00
1	SIDE MIRROR	JAMMED	637.00	490.00
1	SIDE MIRROR COVER	SCRATCHED	67.00	67.00
	LESS 20% DISCOUNT		-585.40	-409.60
			2,341.60	1,638.40
	<u>SPECIAL NETT ITEMS</u>			
1	WHEEL RIM (SN)	TO REPAIR SEE LABOUR	980.00	-
			980.00	-
	<u>LABOUR</u>			
	TO CHECK WHEEL ALIGNMENT.		60.00	40.00
	TO SPRAY PAINTING.		680.00	500.00
	TO REPLACE REPAIR STRAIGHTEN & REALIGN ALL DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER (LH) AND WHEEL RIM.		780.00	400.00
			1,520.00	940.00
	GRAND TOTAL		4,841.60	2,578.40
	RECOMMENDED COST OF LUMP SUM REPAIRS			2,000.00

Report Ref No. CS/EQ118011083/Ntbe2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.