

祥輝汽車修理 SIANG HUI MOTOR WORKS

Blk 3006, Ubi Road 1 #01-338, Singapore 408700.

Tel: 67444605 Fax: 67440726

REG. No. 322208/00M

Date, 9/7/18

Vehicle No AKB 8880 Mazda

1pc	Front bumper ✓ CRK	833.00	\$ 963.00
1pc	Bumper side Retainer (LH) ✓ ^{14.00} cut		\$ 43.00
1pc	Front fender (LH) R	380.00	\$ 483.00
1pc	Headlamp ✓ SCR	644.00	\$ 734.00
1pc	side mirror ✓ JM	490.00	\$ 637.00
1pc	side mirror cover ✓ SCR		\$ 67.00 ✓
			\$2,927.00
Less 20%			585.40
			\$ 2341.60
S/Nett			
1pc	wheel rim R		\$ 980.00

Labour charge :-

- 1) To check wheel alignment \$ ~~60.00~~ 40.00
- 2) To spray painting \$ ~~680.00~~ 500.00
- 3) To replace, repair straighten
+ re-align all damaged parts \$ ~~780.00~~ 400/-

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer *

Signature:

Date:

4 days

Grand Total \$ 4841.60

Sathya Sai

Sathya Sai @ lkkauto.com

- Lump Sum Repair

- Photo after paint