

Surveyor: Taufik

## ASSIGNMENT (Office)

From (Person): Yee Pei Li

of

EGIDate/Time: 18/6/18 @ 3:53pm

Estimated Cost:

Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 5429S

Insured:

XB 6752D

at Workshop m/s

AMA Automotive

Tel:

8778 3636

of

36 Joh Guan Rd East #01-36

Policy No:

Claim No:

DSM(V1801181)

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/06/2018

CA / REV / REP. / REV 24 HRS

'up'

Date/Time: 9:15am @ 19/6/18

Person Contacted:

Melvin

H.O.D. Endorsement:

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SLA 5429S - X</u>
	<u>XB 6752D - cc3 / EGT14012788 / 11/1/2014</u>
	<u>D.O.A: 04/07/2014</u>
<u>20/6/18</u>	<u>Dismantled</u>

Signature

Taylor

REF: EGI

# ASSIGNMENT

From:

Date: 19/6/18

Estimated Cost:

OD / (P) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLA 5429S  
at Workshop m/s: AMA Automotive  
of 36toh Guan Rd East #01-36

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>1 up</sup>

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLA 5429S Yr Regn: 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel C.C.

Colour: Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 50628 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: R41106365

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: 4 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. D.O.I. 19/6/18 0647pm

Survey held at

Des. of Damages (Prt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range - \$4,000 - \$5,000

23/6/18 Submit PRS Report

22/6/2018

RECEIVED 25 JUN 2018

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : Weekend (\$

Survey Fee:

Transportation

☐ \$ + RS ☐ \$

☐ Photos

☐ Others

TOTAL

50  
50

100

**Nivitha (LKK Auto)**

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Monday, 18 June 2018 3:53 PM  
**To:** admin-d@lkkauto.com  
**Cc:** ASSIGNMENTS@LKKAUTO.COM  
**Subject:** OI : XB6752D / TP : SLA5429S/LKK / DOA : 10/06/2018  
**Attachments:** SLA5429S - PRI NOTICE.pdf; RE: PRS Notice for SLA 5429S (20.6 KB)

Dear Catherine,

We have rejected to their PRS list, please assist to conduct this survey from **CHIA S ARUL LLC**.

ADDRESS : **AMA AUTOMOTIVE PTE LTD**  
36 TOH GUAN ROAD EAST  
#01-36  
SINGAPORE 608580

PERSON TO CONTACT : MR MELVIN @ 8778 3636

ERGO OFFICER-IN-CHARGE : STEVE LIM

*Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle. Try to obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.*

Please update the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

**Kindly acknowledge receipt of this email.**

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS3/EGI18011086/T1z4d3

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 19-06-2018



Code : EGI

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	XB 6752D	Veh. Inspected	SLA 5429S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	19/06/2018

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--	--

### 5. General Information

Accident Date	10/06/2018	Inspection Date	19/06/2018
Survey held at	AMA AUTOMOTIVE PTE. LTD. 36 TOH GUAN ROAD EAST #03-36 SINAGPORE 608580		

5a. Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
ERGO INSURANCE PTE LTD		Ref: CS3/EGI18011086/T1z4d3e2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER		Date: 28-06-2018		
FIVE SINGAPORE 038985		Code: EGI		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	XB 6752D	Veh. Inspected	SLA 5429S	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMCV1801181	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	18/06/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA VEZEL	c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	RU11106365	Colour	MAROON	
Odometer	50628 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	MICHELIN	6 mm	
L/H Front Tyre	215/60 R16	MICHELIN	6 mm	
R/H Rear Tyre	215/60 R16	MICHELIN	6 mm	
L/H Rear Tyre	215/60 R16	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND UNDERCARRIAGE PORTION.				
<b>5. General Information</b>				
Accident Date	10/06/2018	Inspect Date / Time	19/06/2018 ( 06:47 PM )	
Survey held at	AMA AUTOMOTIVE PTE. LTD. 36 TOH GUAN ROAD EAST #03-36 SINGAPORE 608580			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

Report Ref No. CS3/EGI18011086/T1z4d3e2

Inspected By



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.