



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLM 8995 R

Parts	(a) Cost / List Price Items	\$	1,288.80
	Plus/Less 25%	\$	322.20
	Total of Cost / List	\$	966.60
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost			
Labour		\$	850.00
Total		\$	1,816.60

Not Authorized

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 19/6/18 at _____

Remarks By Surveyor

- (a) The repair of this vehicle is authorized / is not authorized until further notice.
- (b) Recommended Days of Repair : 02 day(s)
- (c) Resurvey : Required / Not Required
- (d) Excess : \$ _____
- (e) Signature of surveyor : LK Date: 19/6/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLM 8995 R**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU103555391**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper	1	\$450.80		✓
2	Front bumper clip	10	\$40.00		✓
3	Front bumper side retainer RH	1	\$107.20		✓
4	Front bumper side retainer LH	1	\$107.20		✓
5	Front bumper upper grille	1	\$321.90		✓
6	Front bumper lower grille	1	\$148.60		✓
7	Front bumper tow cover LH	1	\$25.70		✓
8	RH wing mirror (cover)	1	\$87.40		✓
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Vehicle No. :	<u>SLM 8995 R</u>	Submit By :	<u>Carmen Lim</u>
Make & Model :	<u>TOYOTA PRIUS</u>	Year of Manufacture :	<u>2017</u>

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.