

INS. CO. OWNER:

COO, CTI 183 11098, 191ha3n2

LKK:
IDAC:

Surveyor:

Amc

DOI:

ASSIGNMENT:

18.6.18

Date / Time:

18.6.18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJC 272K

Name of Insured:

MULTEN SYSTEMS P/L

Insured Tel No.:

HP:

Excess See II:SS

D.O.A:

14.6.18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Judy Yew Hai

Driver Tel No.:

91000331

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final? Yes / No

SJC 1660C



INSRS:

WSP:

Tel:

Liability:

RMKS:

CPLC
1044

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time	STAGE	DATE / PIC
29/6	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
29/06/18	Call OI:	29/06/18 - VIC
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☐
	LTA / GIA:	☐
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☒
	LOD:	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐
PRELIMINARY ADVICE	Date/Time: 18/6	Sent By: Amc
FINALIZATION	Date/Time: 18/6	Confirm with: Amc
Repair Cost: P/P	SS 2,354.00 (3 days) Reduction: 51 %	Confirm by: Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 14/09/18	Confirm with: WUWUWU
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.: 27	Email ☒ Call ☐
Repair Cost: (W/SSC)	SS 2,518.78	If NO or B 28, Ass. Lia: (OLD RATE - ENDS UP)
Loss of Rental (LOR):	SS 624.00 (5 days) X \$126.40	
Loss of Use (LOU):	SS 250.00 (\$50 x 5 days)	
Loss of Income (LOI):	SS - (\$ x days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☒	[Tick only one]	
GIA/LTA Search	SS 7.49	
Medical:	SS -	
Disbursement:	SS - (e.g. Tow/ Independent)	
Legal Cost	SS -	
Total:	SS 3,403.27	Global Sum SS: 3,400.00
FINAL PAYMENT	Date/Time: 14/09/18	Confirm with: WUWUWU
Payee 1:	SS 3,400.00	Name 1: COMFORTOLARO ENGINEERING PTE LTD
Payee 2: (Strike if N.A.)	SS -	Name 2: -
Payee 3: (Strike if N.A.)	SS -	Name 3: -

Kalin

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s

of

Insured

Policy No

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

-

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SHC1660C Yr Regn: 10 Ag / 217
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

C.C

1798

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

132377

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKBJF48035 63259

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R165

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

2

mm

R/Bal.

2

mm

L/Bal.

2

mm

L/Bal.

2

mm

D.O.A.

14/6/08

D.O.I.

18/6/08

Survey held at

CDHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P \$2,354.00
 CRAB: \$2,526.53 (51%)

CT2
 P/P

Date/Time, File Pass to?



: Preli. Report



: Final Report

1)

Date/Time, File Return to?

2)

Report Format:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS. SI

) Photos

) Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$

Mei Kwan (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Wednesday, 27 June, 2018 1:17 PM
To: Mei Kwan (LKKAUTO)
Cc: Alfred Toh
Subject: RE: Direct Settlement - Accident Involving SJQ2272K (OI : CTI - SNM18D02990C02) and SHC1660C (TP : LKK REF - CC3/CTI18011098/K1ha3) on 14/06/2018
Attachments: leeSZ_SNM18D02990C01-SJQ2272K-LKKDirectSettlementAccidentLtr_CLCR95.454.pdf; MCHM18077297-SJQ2272K.pdf

Follow Up Flag: Follow up
Flag Status: Completed

Categories: HMK

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Alfred Toh

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Friday, 22 June, 2018 10:22 AM
To: Claims Dept of CTI
Cc: Sharon Han; Angie Foo; Vic (LKKAUTO); Hsiao Tong (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving SJQ2272K (OI : CTI - TBA) and SHC1660C (TP : LKK REF - CC3/CTI18011098/K1ha3) on 14/06/2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHC 1660C at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge Vic and he can be contacted at DID: 6841 2096.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.chinataiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D02990/C01/2**

Date : **27 JUNE 2018**

via Ordinary & Registered Mail

**MULTRON SYSTEMS PTE LTD
217 KALLANG BAHRU
MULTRON BUILDING
SINGAPORE 339347**

Dear Sir / Madam

**ACCIDENT INVOLVING SJQ2272K AND SHC1660C ON 14 JUNE 2018
ALONG MOULMEIN ROAD TOWARDS BALESTIER**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHC1660C**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : VIC
Ref : CC3/CTI18011098/K1HA3
Contact No : 68412096
via Email : VIC@LKKAUTO.COM

CC : Agent - (AN0056A) - DAGLEN GI PTE LTD

F01/LKKDS-2013

number of COMFORTDELGRO

Date/Time: 14.06.2018 15:47

Page : 1

ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO305175527

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)

REGN NO. SHC1660C	MILEAGE
MAKE TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4)14.0	DATE/TIME IN 06.2018 13:35
YR OF MANU. 10.08.2017	TARGET DATE
CHASSIS CODE JTDKB3FU803563259	COMPLETION DATE/TIME:

CHINA

UNT CARD NO.

JOB DESCRIPTION

cident Date: 14.06.2018
TURE: 3P 14.06.2018

NO LABOR CODE DESCRIPTION

ICKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ledgement Slip

Exit Pass

No.: SHC1660C

LKE

Vehicle No.: SHC1660C

if Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO : SHC 1660C

14/6/2018 14:21

MAKE :

MODEL : TOYOTA PRIUS

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR TRUNK LID LOGO(PRIUS) X			\$ 60.80
REAR TRUNK LID LOGO(HYBRID) X			\$ 52.40
REAR TRUNK LID LOGO(TOYOTA STAR) X			\$ 52.90
REAR BUMPER			\$ 458.60
REAR BUMPER RE-INFORCEMENT X			\$ 318.80
REAR BUMPER UNDER COVER ?			\$ 552.60
REAR BUMPER SIDE RETAINER ?			\$ 112.70
REAR BUMPER SPONGE X			\$ 143.40
REAR BUMPER UNDER SIDE COVER (RH) /			\$ 167.60
REAR BUMPER CLIPS /			\$ 22.00
RETAINER, REAR BUMPER, SIDE, RH ?			\$ 94.80
SEAL, REAR BUMPER SIDE, RH ?			\$ 148.40
TAIL LAMP ASSY (LOWER) (RH) /			\$ 548.40
REAR FENDER, RH X old Pmry			\$ 817.50
REAR FENDER SHEILD (RH) X			\$ 134.20
SUB TOTAL			\$ 3,685.10
LESS 25%			\$ 921.28
DISCOUNTED TOTAL			\$ 2,763.83
REAR TRUNK LID APPS STICKER X			\$ 40.00
REAR TRUNK LID COMFORT & TEL NO. STCIKER X			\$ 60.00
REAR BUMPER REVERSE SENSOR /			\$ 135.70
REAR BUMPER RUBBER MAT /			\$ 50.00
			\$ 285.70
LABOUR CHARGE			
Panel Beating			\$ 860.00
Spray Painting Charge-Bootlid/Bumper/Fender X			\$ 750.00
Wiring Charge			\$ 50.00
Tuff Kote			\$ 50.00
Remove/Refix Reverse Sensor			\$ 120.00
TOTAL LABOUR			\$ 1,820.00
ESTIMATE TOTAL			\$ 4,869.53

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

TOTAL LABOUR

ESTIMATE TOTAL

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO : SHC 1660C

MAKE :

MODEL : TOYOTA PRIUS

14/6/2018 14:21

Like

CHINA

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR TRUNK LID LOGO(PRIUS) X 1			\$ 60.80
REAR TRUNK LID LOGO(HYBRID) X 1			\$ 52.40
REAR TRUNK LID LOGO(TOYOTA STAR) X 1			\$ 52.90
REAR BUMPER			\$ 458.60
REAR BUMPER RE-INFORCEMENT X 1			\$ 318.80
REAR BUMPER UNDER COVER			\$ 552.80
REAR BUMPER SIDE RETAINER X 1			\$ 112.70
REAR BUMPER SPONGE X 1			\$ 143.40
REAR BUMPER UNDER SIDE COVER (RH) X 1			\$ 167.60
REAR BUMPER CLIPS			\$ 22.00
RETAINER, REAR BUMPER, SIDE, RH X 1			\$ 94.80
SEAL, REAR BUMPER SIDE, RH			\$ 148.40
TAIL LAMP ASSY (LOWER) (RH)			\$ 548.40
REAR FENDER, RH X 1			\$ 817.50
REAR FENDER SHEILD (RH) X 1			\$ 134.20
REAR Bumper Tow Hook Cover - missing \$14.70			
SUB TOTAL			\$ 3,685.10
LESS 25%			\$ 921.28
DISCOUNTED TOTAL			\$ 2,763.83
REAR TRUNK LID APPS STICKER X 1			\$ 40.00
REAR TRUNK LID COMFORT & TEL NO. STICKER X 1			\$ 60.00
REAR BUMPER REVERSE SENSOR			\$ 135.70
REAR BUMPER RUBBER MAT			\$ 50.00
			\$ 285.70
LABOUR CHARGE			
Panel Beating			\$ 400
Spray Painting Charge-Bootlid/Bumper/Fender			\$ 860.00
Wiring Charge			\$ 750.00
Tuff Kote			\$ 50.00
Remove/Refix Reverse Sensor			\$ 50.00
			\$ 120.00
TOTAL LABOUR			\$ 1,820.00
ESTIMATE TOTAL			\$ 4,869.53
			4,880.53

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalu 11/11/14

18/6/18 1025hrs.

3 hrs

PIP

Before Part pth

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

VEHICLE NO.: SHC1660C
MODEL : TOYOTA PRIUS HYBRID
JOB NO : 305175527

TYPE OF CLAIM : TP-SJQ2272K
SURVEY BY : LKK/Kalvin Ong
DATE : 18/6/18

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

[illegible]

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 21.06.2018
Time: 12:01:06
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305175527
REGN NO : SHC1660C
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 10.08.2017
DATE/TIME IN : 14.06.2018 13:35
ACCIDENT DATE : 14.06.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2282-G	PRIG4 COVER REAR BUMPER	1 L	458.60	25.00	343.95
0002 04-01-0302-2965-G	PRIG4 FILLER-REAR BUMPER	1 L	148.40	25.00	111.30
0003 04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C	1 L	552.30	25.00	414.22
0004 09-01-0302-2005-A	PRIG4 REVERSE SENSOR ASSY	1 N	135.70	2.50-	135.70
0005 04-01-0302-0795-G	PRIG4 LENS AND BODY REAR	1 L	548.40	25.00	411.30
0006 04-01-0302-2267-G	PRIVC BUMPER PIECE	10 L	22.00	25.00	16.50
0007 04-01-0302-2286-G	PRIG4 COVER REAR BUMPER-T	1 L	14.70	25.00	11.02

SUB-TOTAL : 1,443.99

JOB NATURE

0000 L	REAR BUMPER MAT	50.00
0001 L	PANEL BEATING	400.00
0002 23-502	SPRAYPAINT ON AFFECTED AREA	400.00
0003 17-01	CHECK ALL LIGHTING	30.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 21.06.2018

Time: 12:01:06

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305175527
REGN NO : SHC1660C
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(C
DATE OF REGN : 10.08.2017
DATE/TIME IN : 14.06.2018 13:35
ACCIDENT DATE : 14.06.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0004 20-22 REMOVE/REFIX REVERSE SENSOR

30.00

SUB-TOTAL : 910.00

TOTAL : 2,353.99

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

Our Job Ref No 305175527
Date 21/06/18

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr KALVIN ANG
Vehicle Reg No. SHC1660C CTPL

Fax :

14.06.18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- SJQ2272K
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$1,444.00
 - (b) Labour Charges \$910.00
 - Total for Part-By-Part Repair Cost** \$2,354.00
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156

Signature : 
Name : Kalvin
Date : 22/6/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Friday, 14 September, 2018 10:11 AM
To: William Tan Thoo Seng
Cc: Catherine Koh Mui Gek; Admin A; Vic (LKKAUTO)
Subject: Your Ref: T0618/SHC1660C/WT(st)_ACCIDENT INVOLVING VEHICLES SJQ 2272K AND SHC 1660C ON 14/06/2018 - LKK REF CC3/CTI18011098/K1ha3
Attachments: DV.pdf

Your Ref: T0618/SHC1660C/WT(st) Without Prejudice

Dear William,

ACCIDENT INVOLVING VEHICLES SJQ 2272K AND SHC 1660C ON 14/06/2018

We refer to the above matter and we confirmed in receipt of the LOD.

Purely for an amicable settlement on a without prejudice basis and without admission of liability to our Insured's part, we have our principal's mandate and we propose a global sum of **\$3,400.00** (all in) to settle your client's claim.

If agreeable, kindly chop and sign the attached DV and forward the original copy to us for payment processing.

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: yicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contains confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18011098/K1ha3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 28-09-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJQ 2272K	Veh. Inspected	SHC 1660C
Policy No.	DMPCSN3028001801	Coverage (\$)	0.00
Claim No.	SNM18D02990/C02/2	Excess (\$)	0.00
Assign From		Assign Date	18/06/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU803563259	Colour	BLUE
Odometer	132377	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	7 mm
L/H Front Tyre	195/65 R15	WEST LAKE	7 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	7 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	14/06/2018	Inspection Date	18/06/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1660C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TRUNK LID LOGO (PRIUS)	NOT NECESSARY	60.80	-
1	REAR TRUNK LID LOGO (HYBRID)	NOT NECESSARY	52.40	-
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NOT NECESSARY	52.90	-
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	318.80	-
1	REAR BUMPER UNDER COVER	CRACKED	552.60	552.30
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	112.70	-
1	REAR BUMPER SPONGE	NOT NECESSARY	143.40	-
1	REAR BUMPER UNDER SIDE COVER (RH)	SERVICEABLE	167.60	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	RETAINER ,REAR BUMPER ,SIDE ,RH	SERVICEABLE	94.80	-
1	SEAL ,REAR BUMPER SIDE ,RH	CRACKED	148.40	148.40
1	TAIL LAMP ASSY (LOWER) (RH)	CRACKED	548.40	548.40
1	REAR FENDER ,RH (DENTED)	OLD DAMAGED	817.50	-
1	REAR FENDER SHIELD (RH)	SERVICEABLE	134.20	-
1	REAR BUMPER TOW HOOK COVER	MISSING	14.70	14.70
	LESS 25% DISCOUNT		-924.95	-436.10
			2,774.85	1,308.30
<u>SPECIAL NETT ITEMS</u>				
1	REAR TRUNK LID APPS STICKER (SN)	NOT NECESSARY	40.00	-
1	REAR TRUNK LID COMFORT & TEL NO. STICKER (SN)	NOT NECESSARY	60.00	-
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			285.70	185.70
<u>LABOUR</u>				
	PANEL BEATING .		850.00	400.00
	SPRAY PAINTING CHARGE-BOOTLID /BUMPER/FENDER.		750.00	400.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.	NOT NECESSARY	50.00	-

Report Ref No. CC3/CTI18011098/K1ha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX REVERSE SENSOR .		120.00	30.00
			1,820.00	860.00
	GRAND TOTAL		4,880.55	2,354.00
RECOMMENDED COST OF REPAIRS				2,354.00

Report Ref No. CC3/CTI18011098/K1ha3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.