



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 3999T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR DOOR COMFORT LIMO CAB LOGO (CONSISTENT) (SN)	SERVICEABLE	60.00	-
1	REAR BUMPER (CONSISTENT) (SN)(NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR RH FENDER (CONSISTENT) (SN) (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR RH DOOR (CONSISTENT) (SN) (NPA)	TO REPAIR SEE LABOUR	-	-
			60.00	-
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER,REAR RH FENDER AND REAR RH DOOR.		350.00	200.00
	SPRAY PAINTING CHARGE.		750.00	600.00
	TUFF KOTE.	NOT NECESSARY	50.00	-
			1,150.00	800.00
	GRAND TOTAL		1,210.00	800.00
	RECOMMENDED COST OF REPAIRS			800.00

Report Ref No. CC4/ASM18011102/K1pa3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.