

REPAIR ESTIMATE\*

CCPL

VEHICLE NO : SHB 3999T

DATE 18/6/2018 8:35

MAKE :

Like

AXA

MODEL : MERCEDES BENZ

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Door Comfort Limo Cab Logo <input checked="" type="checkbox"/> X SVC			\$ 60.00	Nett
	Rear Bumper x repair				
	Rear RH Fender x repair				
	Rear RH Door x repair				
	<b>Labour Charge</b>				
	Panel Beating			\$ 350.00	
	Spray Painting Charge			\$ 750.00	600
	Tuff Kote			\$ 50.00	x
	<b>TOTAL LABOUR</b>			<b>\$ 1,150.00</b>	
	<b>ESTIMATE TOTAL</b>			<b>\$ 1,210.00</b>	
<p>Kalkulasi</p> <p>18/6/18 1505hrs.</p> <p>2 Days</p> <p>4/3</p> <p>After Repair photo</p>					
<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: auto;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from insurance company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p> </div>					
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>					