

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJQ3430P

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department \ THE MOTOR

WS Ref: TP-AIG

Claim Type: Third Party

Accident Date: 14/06/2018

TP Veh Reg No: SLX2491J

Estimate No: ES1890665/WS

Date: 18 Jun 2018

Policy No: D17MTPV01016042

Veh Reg No: SJQ3430P

Make/Model: MAZDA MAZDA3 1.6L

Chassis No: JM6BL10Z1A0100918

Engine No: Z6791503

Reg. Date: 05/05/2009

Not Notified

1/1/2018

Missing After Paint

4 days

Estimate Repair Cost to Vehicle No :SJQ3430P

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	1,049.80	1 PCS	1,049.80	✓
2 REAR BUMPER REINFORCEMENT	529.00	1 PC	529.00	✓
3 REAR BUMPER LH REFLECTOR	59.00	1 PC	59.00	✓
4 REAR BUMPER CLIPS	5.60	6 PC	33.60	✓
5 REAR NUMBER PLATE LAMP	155.00	1 PC	155.00	✓
6 REAR BOOT	1,161.60	1 PC	1,161.60	✓
7 REAR BOOT EMBLEM '3'	38.80	1 PC	38.80	✓
8 REAR BOOT LOGO	32.40	1 PC	32.40	✓
9 REAR BOOT INNER LOCK	177.20	1 PC	177.20	✓
			3,236.40	
		Less 20%	647.28	2,589.12
Special Net				
10 REAR NUMBER PLATE	35.00	1 PC	35.00	✓
11 REVERSE SENSOR	200.00	1 PC	200.00	✓
			235.00	235.00
Labour				
12 REMOVE AND REFIX REAR BUMPER ASSY, BOOT, TAIL LAMP. TO KNOCK AND REPAIR REAR PANEL AND REALIGN THE SAME	600.00	1 LA	600.00	500
13 PUTTY AND RESPRAY ON REAR BUMPER REINFORCEMENT, BOOT, REAR PANEL AND REAR AFFECTED AREA	700.00	1 LA	700.00	600
14 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,330.00	1,330.00

Total S\$ 4,154.12

Add GST @ 7% 290.79

Total Amount Payable S\$ 4,444.91

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE