

INSURANCE

INS CASE OWNER:

Yuntwin

CC 4/AXA1801

1104, Awhb^{sr}

LKK:

IDAC:

Surveyor:

Active

DOI:

ASSIGNMENT

18/6/18

Date / Time:

18/6/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKK 2284H

Claim No.:

880000015005

Name of insured:

PLAN KENG YIN ANNETTE MARIE

Policy No.:

01446659

Insured Tel No.:

HP:

14/6/18

Make / Model:

VOLKSWAGEN

Excess Sec II : \$5

D.O.A.:

Place of Accident:

WORTH BUONA VISTA RD ENTER

Is driver the owner?

(YES / NO)

Nature of Accident:

SWP K6 INTO RYE

If NO, Driver Name / Age:

Fong Yoon Sheng

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SLM 645



INSRS:
WSP:
Tel:
Liability:
RMKS:

premium



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

18/6/18
Active

SLM 645-4

SKK 2284H-4

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

25/6/18
Vion

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others: NRIC

PRELIMINARY ADVICE

Date/Time:

18/6/18

Sent By:

h

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Master

Email

Call

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28. Ass. Lia :

Repair Cost:

\$5 32803.10

Loss of Rental (LOR):

\$5

;

(

days)

Loss of Use (LOU):

\$5 300.00

;

100

x

23

days)

Loss of Income (LOI):

\$5

;

(

\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

\$5

;

00

Medical:

\$5

;

1322.50

Disbursement:

\$5

;

-

(e.g. Tow/ Independent)

Legal Cost

\$5

;

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

\$5

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

;

36427.60

Name 1:

Premium Automobiles Pte cto

Payee 2: (Strike if N.A.)

\$5

;

-

Name 2:

Payee 3: (Strike if N.A.)

\$5

;

-

Name 3:

COPY SENT

REF:

ASS. REC BY Adrian Ling**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 2451C

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 wks days Res.: Yes or NoLum Sum: 2-B-2 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLM69S Yr Regn: 2017, MarchType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi S4 c.c. 2995Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 25201 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZF4HA095266Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/35R19R: 245/35R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 18/06/18Survey held at PremisesDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPAXA.27/9/18 Confirm 2-B-2 \$30657.10 with 14 working day(Tel: \$20957.90
(41.1)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18011104/Awb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 19-06-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKK 2289H	Veh. Inspected	SLM 69S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	19/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	14/06/2018	Inspection Date	18/06/2018
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0686/2018/PH
Date	:	14-Jun-18

Vehicle not IN workshop. Kindly arrange for survey.

Your insured vehicle is : SKK 2289 H

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name	:	Mr. Kester Andrew Lim Tan
Address	:	10 Lakeshore View Singapore 098152
Telephone	:	HP +65 91822086
Type of Claim	:	Third Party Claims
Policy No.	:	2100503640-01
Vehicle No	:	SLM 69 S
Model Code	:	Audi S4 3.0 TFSI QU
Model / Year	:	Mar-17
Engine No	:	CWG 003119
Chassis No	:	WAUZZZF4HA095266
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	14-Jun-18
Place of Accident	:	South Buona Vista Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLM 69 S.

S/n	Nature of Jobs		Estimated Charges		
1	To carry out first measurement on car-o-liner	S/N	\$ 800.00	?	X
2	To remove and renew rear parking aid and rear lid kick sensor.	S/N	\$ 360.00	✓	✓
3	To dislodge and reinstall rear wire harness, audio equipment, control unit, relay and fuse trays, end	S/N	\$ 1,800.00	✓	✓
4	To remove and reinstall rear seats, back rest, carpets, ABCD pillar trims, disengage airbag system.	S/N	\$ 1,800.00	✓	✓
5	To remove and inspect center and rear exhaust silencers. Renew if necessary.	S/N	\$ 480.00	X	
SUB-TOTAL LABOUR CHARGES		:	\$ 5,240.00		

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLM 69 S.

S/n	Nature of Jobs	Estimated Charges
4	To remove and install rear suspension assy including rear axle for car-o-liner repairs. Inspect for damages and renew if necessary.	S/N \$ 3,200.00 28
5	To remove and reinstall fuel tank assy.	S/N \$ 600.00 28
6	To set up and place vehicle on car-o-liner.	S/N \$ 2,400.00 28
7	To dismantle rear bumper and rear lid. Cut out and weld rear end panels, spare wheel housing and cross members. Repair and align whole rear substructure	\$ 7,200.00 3600 ✓
8	To carry out stone chip primer work on rear panelling and spare wheel housing.	S/N \$ 800.00 ? 400.00
SUB-TOTAL LABOUR CHARGES		: \$ 14,200.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLM 69 S.

S/n	Nature of Jobs	Estimated Charges
9	To carry out stone chip primer work on rear panelling and spare wheel housing. <i>Repeated</i>	S/N \$ 800.00 <i>X</i>
10	To spray paint on rear bumper, rear lid, spare wheel housing, boot floor and end panelling. To carry out joint sealer works and cavity preservation.	S \$ 3,700.00 <i>2500.00</i>
11	To spray and install rear lid spoiler.	S/N \$ 780.00 <i>✓</i>
12	To carry out wheel alignment.	S/N \$ 240.00 <i>✓</i>
13	To rewrap sticker on affected area.	S/N TBC <i>1500.00</i>
14	To carry out diagnostic check.	S/N \$ 384.00 <i>✓</i>
TOTAL LABOUR CHARGES		: \$ 25,344.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLM 69 S.

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
1	REAR BUMPER <i>Disbld</i>	\$	1,619.00 ✓	2462.00
2	FIXING PARTS FOR BUMPER <i>Neu</i>	\$	63.00 +	
3	SPOILER <i>Disbld</i>	\$	710.00 ✓	710
4	SECURING STRIP <i>Disbld</i>	\$	191.00 ✓	191
5	TRIM <i>Disbld</i>	\$	250.00 ✓	250
6	TRIM ALUMINIUM <i>missing</i>	\$	920.00 ✓	919.50
7	TRIM - LH / RH <i>Neu</i>	2 \$	70.00 ✓	68.20
8	REAR LIGHT REFLECTOR - LH/RH <i>Neu</i>	2 \$	70.00x	
9	SENSOR <i>3 pieces disbld</i>	4 \$	842.00 631.50	631.50
10	WIRING SET FOR BUMPER <i>Not Neu</i>	\$	598.00 x	
11	CONTROL UNIT FOR OPENING BOOT LID <i>Neu</i>	\$	372.00 +	
12	SENSOR LINE FOR TAILGATE OPENING <i>Not Neu</i>	\$	184.00 x	
13	REAR LID <i>Disbld</i>	\$	2,362.00 ✓	2362.00
14	ATTACHMENT PARTS FOR REAR LID <i>Neu</i>	\$	125.00 x	
15	LID HINGE - LH/RH <i>Not Neu</i>	2 \$	400.00 x	
16	GUIDE PIECE LID HINGE - LH/RH REAR <i>Neu</i>	2 \$	50.00x	
17	LID LOCK <i>Disbld</i>	\$	202.00 ✓	202.00
18	PUSH BUTTON FOR LID LOCK ACTUATOR <i>Not Neu</i>	\$	1,181.00 x	
19	LOCK STRIKER <i>Best</i>	\$	29.00 ✓	28.10
20	STOP BUFFER <i>Neu</i>	\$	28.00 ✓	28.00
SUB - SPARE PARTS CHARGES		:	\$ 10,266.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLM 69 S.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
11	GASKET FOR FLAP <i>lit</i>	\$ 176.00	✓ 175.50
12	SPOILER <i>new</i>	\$ 1,307.00	✓ 1307
13	PACKING ADHESIVE <i>new</i>	\$ 15.00	✓ 14.50
14	AUDI EMBLEM <i>new</i>	\$ 108.00	✓ 107.50
15	S4' EMBLEM <i>new</i>	\$ 108.00	✓ 107.50
16	REAR LID TRIM PANEL <i>Del'd</i>	\$ 290.00	✓ 289.50
17	LED TAIL LIGHT -LH/RH <i>Del'd</i> <i>lit</i>	2 \$ 1,830.00	✓ 515.00
18	TRIM FOR TAIL LIGHT - LH/RH <i>lit</i>	2 \$ 54.00	✓ 50.20
19	LED TAIL LIGHT -LH/RH <i>lit</i>	2 \$ 1,632.00	✓ 1631.00
20	TRIM FOR TAIL LIGHT - LH/RH <i>lit</i>	2 \$ 54.00	✓ 50.20
21	REAR CROSS PANEL <i>Dented</i>	\$ 230.00	✓ 229.50
22	REINFORCEMENT CROSS PANEL <i>Dishbed</i>	\$ 445.00	✓ 445.00
23	REINFORCEMENT FOR SIDE PANEL - LH REAR <i>Bent</i>	\$ 180.00	? 179.50
24	REINFORCEMENT FOR SIDE PANEL - RH REAR <i>Bent</i>	\$ 180.00	? 179.50
25	SUPPORT - LH/RH <i>Dishbed</i>	2 \$ 172.00	? 170.40
26	TRIM FOR REAR CROSS PANEL SOUL <i>Del'd</i>	\$ 146.00	✓ 146.00
27	INSERT PART <i>Repair</i>	\$ 237.00	✗
28	LUGGAGE COMPARTMENT FLOOR <i>new</i>	\$ 621.00	✗
29	LUGGAGE COMPARTMENT TRIM - LH/RH <i>new</i>	2 \$ 1,380.00	✗
30	STOWAGE COMPARTMENT <i>Del'd</i>	\$ 80.00	✓ 79.30
SUB - SPARE PARTS CHARGES		\$ 9,245.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLM 69 S.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
31	NUT FOR SPARE WHEEL MOUNTING <i>Not Nec</i>	\$ 31.00	X
32	STOWAGE COMPARTMENT <i>Not Nec</i>	\$ 45.00	X
33	COVER FOR TOOL BOX <i>Not Nec.</i>	\$ 40.00	X
34	SPARE WHEEL WELL <i>Repair</i>	\$ 1,938.00	X
35	MOUNTING FOR SPARE WHEEL <i>Not Nec</i>	\$ 117.00	X
36	CLAMPING STRIP FOR BATTERY <i>Not Nec</i>	\$ 11.00	X
37	REAR SILENCER WITH EXHAUST FLAP - LH <i>Not Nec</i>	\$ 771.00	X
38	REAR SILENCER WITH EXHAUST FLAP - RH <i>Not Nec</i>	\$ 789.00	X
39	DUAL CLIP <i>Not Nec</i>	\$ 43.00	X
40	BRACKET FOR EXHAUST SILENCER <i>Not Nec</i>	2 \$ 73.00	X
41	CENTRE SILENCER <i>Not Nec</i>	\$ 801.00	X
42	HEAT SHIELD FOR REAR SILENCER - LH/RH <i>2 supplied</i>	2 \$ 266.00	? 132.50
43	ARCYLIC SEALER <i>Not</i>	S/N \$ 360.00	✓ 180.00
44	CAVITY WAX <i>Not</i>	S/N \$ 280.00	✓ 140.00
45	STONE CHIP <i>Not</i>	S/N \$ 360.00	✓ 180.00
46	METAL FILLER POWDER <i>Not</i>	S/N \$ 280.00	✓ 280.00
47	REAR NUMBER PLATE <i>Not</i>	S/N \$ 25.00	✓ 25.00
48	SUNDRIES <i>Not</i>	\$ 500.00	? 47.50
TOTAL - SPARE PARTS CHARGES		:	\$ 26,241.00
TOTAL LABOUR CHARGES		:	\$ 25,344.00
GRAND TOTAL		:	\$ 51,585.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

53 933

56 406.70

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 18/06/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 10 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0686/2018/PH
Date : 14-Jun-18

Vehicle not IN workshop. Kindly arrange for survey.

Your insured vehicle is : SKK 2289 H

Hi Adrian

14 days exclude 2 Sundays

Additional jobs - jb - 16 Aug 18

(Pls Add 1 day for wrap work - by owner)

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Kester Andrew Lim Tan
Address : 10 Lakeshore View
Singapore 098152
Telephone : HP +65 91822086
Type of Claim : Third Party Claims
Policy No. : 2100503640-01
Vehicle No : **SLM 69 S**
Model Code : Audi S4 3.0 TFSI QU
Model / Year : Mar-17
Engine No : CWG 003119
Chassis No : WAUZZZF4HA095266
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Jun-18
Place of Accident : South Buona Vista Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLM 69 S.

S/n	Nature of Jobs	Estimated Charges	
1	To carry out first measurement on car-o-liner	S/N \$	800.00
2	To remove and renew rear parking aid and rear lid kick sensor.	S/N \$	360.00
3	To dislodge and reinstall rear wire harness, audio equipment, control unit, relay and fuse trays, end travelling across wheel housing and rear lid harness	S/N \$	1,800.00
4	To remove and reinstall rear seats, back rest, carpets, ABCD pillar trims, disengage airbag system.	S/N \$	1,800.00
5	To remove and inspect center and rear exhaust silencers. Renew if necessary.	S/N \$	480.00
SUB-TOTAL LABOUR CHARGES		: \$	5,240.00
			\$ 3,960.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLM 69 S.

S/n	Nature of Jobs	Estimated Charges	
		c/f	\$
			3,960.00
4	To remove and install rear suspension assy including rear axle for car-o-liner repairs. Inspect for damages and renew if necessary.	S/N \$	3,200.00
5	To remove and reinstall fuel tank assy.	S/N \$	600.00
6	To set up and place vehicle on car-o-liner.	S/N \$	2,400.00
7	To dismantle rear bumper and rear lid. Cut out and weld rear end panels, spare wheel housing and cross members. Repair and align whole rear substructure to position. Renew rear bumper and rear lid. Reinstall all	\$	7,200.00
			\$ 3,600.00
8	To carry out stone chip primer work on rear panelling and spare wheel housing. <i>(Partial)</i>	S/N \$	800.00
			\$ 400.00
SUB-TOTAL LABOUR CHARGES		:	\$ 14,200.00
			\$ 7,960.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLM 69 S.

S/n	Nature of Jobs	Estimated Charges	
	<i>c/f</i>	\$	7,960.00
9	To carry out stone chip primer work on rear panelling and spare wheel housing.	S/N \$ 800.00	<i>nil</i>
10	To spray paint on rear bumper, rear lid, spare wheel housing, boot floor and end panelling. To carry out joint sealer works and cavity preservation.	\$ 3,700.00	\$ 2,500.00
11	To spray and install rear lid spoiler.	S/N \$ 780.00	\$ 780.00
12	To carry out wheel alignment.	S/N \$ 240.00	\$ 240.00
13	To rewrap sticker on affected area. <i>(By owner)</i>	S/N \$ 1,500.00	\$ 1,500.00
14	Added labour charges	\$ 1,500.00	\$ 1,400.00
15	To carry out diagnostic check.	S/N \$ 384.00	\$ 384.00
TOTAL LABOUR CHARGES		\$ 28,344.00	\$ 14,764.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLM 69 S.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 1,619.00	\$ 2,467.00
2	FIXING PARTS FOR BUMPER	\$ 63.00	
3	SPOILER	\$ 710.00	\$ 710.00
4	SECURING STRIP	\$ 191.00	\$ 191.00
5	TRIM	\$ 250.00	\$ 250.00
6	TRIM ALUMINIUM	\$ 920.00	\$ 919.50
7	TRIM - LH / RH	2 \$ 70.00	\$ 68.20
8	REAR LIGHT REFLECTOR - LH/RH	2 \$ 70.00	
9	SENSOR	4 \$ 842.00	\$ 631.50
10	WIRING SET FOR BUMPER	\$ 598.00	
11	CONTROL UNIT FOR OPENING BOOT LID	\$ 372.00	
12	SENSOR LINE FOR TAILGATE OPENING	\$ 184.00	
13	REAR LID	\$ 2,362.00	\$ 2,362.00
14	ATTACHMENT PARTS FOR REAR LID	\$ 125.00	
15	LID HINGE - LH/RH	2 \$ 400.00	
16	GUIDE PIECE LID HINGE - LH/RH REAR	2 \$ 50.00	
17	LID LOCK	\$ 202.00	\$ 202.00
18	PUSH BUTTON FOR LID LOCK ACTUATOR	\$ 1,181.00	
19	LOCK STRIKER	\$ 29.00	\$ 28.10
20	STOP BUFFER	\$ 28.00	\$ 28.00
SUB - SPARE PARTS CHARGES		\$ 10,266.00	\$ 7,857.30

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLM 69 S.

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
		c/f		\$ 7,857.30
11	GASKET FOR FLAP	\$	176.00	\$ 175.50
12	SPOILER	\$	1,307.00	\$ 1,307.00
13	PACKING ADHESIVE	\$	15.00	\$ 14.50
14	AUDI EMBLEM	\$	108.00	\$ 107.50
15	S4' EMBLEM	\$	108.00	\$ 107.50
16	REAR LID TRIM PANEL	\$	290.00	\$ 289.50
17	LED TAIL LIGHT -LH/RH	2 \$	1,830.00	\$ 915.00
18	TRIM FOR TAIL LIGHT - LH/RH	2 \$	54.00	\$ 50.20
19	LED TAIL LIGHT -LH/RH	2 \$	1,632.00	\$ 1,631.00
20	TRIM FOR TAIL LIGHT - LH/RH	2 \$	54.00	\$ 50.20
21	REAR CROSS PANEL	\$	230.00	\$ 229.50
22	REINFORCEMENT CROSS PANEL	\$	445.00	\$ 445.00
23	REINFORCEMENT FOR SIDE PANEL - LH REAR	\$	180.00	\$ 179.50
24	REINFORCEMENT FOR SIDE PANEL - RH REAR	\$	180.00	\$ 179.50
25	SUPPORT - LH/RH	2 \$	172.00	\$ 170.40
26	TRIM FOR REAR CROSS PANEL SOUL	\$	146.00	\$ 146.00
27	INSERT PART	\$	237.00	
28	LUGGAGE COMPARTMENT FLOOR	\$	621.00	
29	LUGGAGE COMPARTMENT TRIM - LH/RH	2 \$	1,380.00	
30	STOWAGE COMPARTMENT	\$	80.00	\$ 79.30
	SUB - SPARE PARTS CHARGES	:	\$ 9,245.00	\$ 13,934.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLM 69 S.

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
		<i>c/f</i>		\$ 13,934.40
31	NUT FOR SPARE WHEEL MOUNTING	\$	31.00	
32	STOWAGE COMPARTMENT	\$	45.00	
33	COVER FOR TOOL BOX	\$	40.00	
34	SPARE WHEEL WELL	\$	1,938.00	
35	MOUNTING FOR SPARE WHEEL	\$	117.00	
36	CLAMPING STRIP FOR BATTERY	\$	11.00	
37	REAR SILENCER WITH EXHAUST FLAP - LH	\$	771.00	
38	REAR SILENCER WITH EXHAUST FLAP - RH	\$	789.00	
39	DUAL CLIP	\$	43.00	
40	BRACKET FOR EXHAUST SILENCER	2 \$	73.00	
41	CENTRE SILENCER	\$	801.00	
42	HEAT SHIELD FOR REAR SILENCER - LH/RH	2 \$	266.00	\$ 132.50
43	ARCYLIC SEALER	S/N \$	360.00	\$ 180.00
44	CAVITY WAX	S/N \$	280.00	\$ 140.00
45	STONE CHIP	S/N \$	360.00	\$ 180.00
46	METAL FILLER POWDER	S/N \$	280.00	\$ 280.00
47	REAR NUMBER PLATE	S/N \$	25.00	\$ 25.00
48	Added parts - see attached	\$	974.20	\$ 973.70
50	SUNDRIES	\$	500.00	\$ 47.50
TOTAL - SPARE PARTS CHARGES		:	\$ 27,215.20	\$ 15,893.10
TOTAL LABOUR CHARGES		:	\$ 25,344.00	\$ 14,764.00
GRAND TOTAL		:	\$ 52,559.20	\$ 30,657.10

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AXA Insurance Singapore Pte Ltd 8 Shenton Way #27-01 AXA Tower Singapore 068811 Attn: Motor Claims Dept Tel: 6880 4602 - Fax 6880 4838		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0686/2018/PH 28-Jul-18 CHANG 1 SLM 69 S Audi S4 3.0 TFSI QU
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	To repair lhs rear fender.	\$ 600.00	\$ 600.00 ✓
2	To respray lhs rear fender.	\$ 900.00	\$ 800.00 ✓
		\$ 1,500.00	\$ 1,400.00
<u>Parts</u>			
1	REAR REINFORCEMENT BEAM Bent	\$ 786.00	\$ 785.50 ✓
2	Rear panel connection plate LHS/RHS Bent	\$ 188.20	\$ 188.20 ✓
	Materials	\$ 974.20	\$ 973.70
	Labour		\$ 1,400.00
GRAND TOTAL		:	\$ 2,474.00 \$ 2,373.70

Adrian Ly

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

M O T O R E N
CO REG: 201538300K

Motoren Werkz Pte Ltd
25 Kaki Bukit Road 4, #01-46 S(417800) Tel: 6385 8330

MTR
MOTOREN
CO REG: 201538300K

Item Description	Price
TO RE-WRAP WHOLE VEHICLE WITH CHROME VINYL STICKER	\$2,500.00
TOTAL	\$2,500.00

Motoren Werkz Pte Ltd
25 Kaki Bukit Road 4, #01-46 S(417800) Tel: 6385 8330



Service Request Details

Claim

S8M00KUA

Reference

None

Loss Date

June 14, 2018

Request Date

June 14, 2018

Due Date

June 22, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

18062018 @ 223pm
Mastera veh in
Tony
Adrian

Actions

Next Step

Agree to perform service

Decline WorkAccept Work

Vehicle Information

Incident Vehicle Registration #

SLM69S

Make

TPVD AUDI

Model

S4 SEDAN 3.0 TFSI QU

Service Address

, , ,

Primary Contact/Insured

PAU KENG YIN ANNETTE MARIE

BLK 991, BUKIT TIMAH ROAD, #01-03, 589630, Singapore

CONTACT@INSUREPAC.COM.SG

Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

Additional Instructions

INSD GIA NOT REPORTED

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Re:RE: Seeking for Mandate approval S8M00KUA

Type

🔗 Question

Message

MANDATE APPROVED

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKK 2289H (Insd veh)	Model:	AUDI S4
	SLM 69S (TP veh)		
Date of Accident:	14/06/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	60,355.17
Final Repair Cost	:	\$	32,803.10
Loss of Use	:	\$	2,300.00
Rental (if any)	:	\$	
LTA / GIA Search Fee	:	\$	2.00

Medical Fee	:	\$	1,322.50
-------------	---	----	----------

	:	\$	
Final Settlement Sum	:	\$	36,427.60

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____(%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____100_____(%)	Assessed Liability (*): _____(%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown			
1)	PREMIUM AUTOMOBILES PTE LTD	:	\$ 36,427.60

NUR SHAQILAH BTE ABDOL
WAHAB

10/05/2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18011104/Awb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA LOH		Date : 10-05-2019 Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKK 2289H	Veh. Inspected	SLM 69S
Policy No.	GA246459	Coverage (\$)	0.00
Claim No.	S8M00KUA	Excess (\$)	0.00
Assign From	CYNTHIA LOH	Assign Date	18/06/2018
2. Vehicle Particulars & Condition			
Make & Model	AUDI S4	c.c	2995
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WAUZZZF47HA095266	Colour	GREY
Odometer	25201	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/35R19	HANKOOK	6 mm
L/H Front Tyre	245/35R19	HANKOOK	6 mm
R/H Rear Tyre	245/35R19	HANKOOK	6 mm
L/H Rear Tyre	245/35R19	HANKOOK	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/06/2018	Inspection Date	18/06/2018
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 69S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (SN) (CONSISTENT)	DISTORTED	2,467.00	2,467.00
1	FIXING PARTS FOR BUMPER (SN) (CONSISTENT)	NOT NECESSARY	63.00	-
1	SPOILER (SN) (CONSISTENT)	DISTORTED	710.00	710.00
1	SECURING STRIP (SN) (CONSISTENT)	DAMAGED	191.00	191.00
1	TRIM (SN) (CONSISTENT)	DISTORTED	250.00	250.00
1	TRIM ALUMINIUM (SN) (CONSISTENT)	MISSING	920.00	919.50
2	TRIM - LH/RH (SN) (CONSISTENT)	NECESSARY	70.00	68.20
2	REAR LIGHT REFLECTOR - LH/RH (SN) (CONSISTENT)	NOT NECESSARY	70.00	-
4	SENSOR (SN) (CONSISTENT)	DAMAGED 3PCS ONLY	842.00	631.50
1	WIRING SET FOR BUMPER (SN) (CONSISTENT)	NOT NECESSARY	598.00	-
1	CONTROL UNIT FOR OPENING BOOT LID (SN) (CONSISTENT)	NOT NECESSARY	372.00	-
1	SENSOR LINE FOR TAILGATE OPENING (SN) (CONSISTENT)	NOT NECESSARY	184.00	-
1	REAR LID (SN) (CONSISTENT)	DENTED	2,362.00	2,362.00
1	ATTACHMENT PARTS FOR REAR LID (SN) (CONSISTENT)	NOT NECESSARY	125.00	-
2	LID HINGE - LH/RH (SN) (CONSISTENT)	NOT NECESSARY	400.00	-
2	GUIDE PIECE LID HINGE - LH/RH REAR (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	LID LOCK (SN) (CONSISTENT)	DAMAGED	202.00	202.00
1	PUSH BUTTON FOR LID LOCK ACTUATOR (SN) (CONSISTENT)	NOT NECESSARY	1,181.00	-
1	LOCK STRIKER (SN) (CONSISTENT)	BENT	29.00	28.10
1	STOP BUFFER (SN) (CONSISTENT)	NECESSARY	28.00	28.00
1	GASKET FOR FLAP (SN) (CONSISTENT)	CUT	176.00	175.50
1	SPOILER (SN) (CONSISTENT)	NECESSARY	1,307.00	1,307.00
1	PACKING ADHESIVE (SN) (CONSISTENT)	NECESSARY	15.00	14.50
1	AUDI EMBLEM (SN) (CONSISTENT)	NECESSARY	108.00	107.50
1	S4' EMBLEM (SN) (CONSISTENT)	NECESSARY	108.00	107.50
1	REAR LID TRIM PANEL (SN) (CONSISTENT)	DEFORMED	290.00	289.50
2	LED TAIL LIGHT - LH/RH (SN) (CONSISTENT)	N/S CUT	1,830.00	915.00

Report Ref No. CC4/ASM18011104/Awb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	TRIM FOR TAIL LIGHT - LH/RH (SN) (CONSISTENT)	CUT	54.00	50.20
2	LED TAIL LIGHT - LH/RH (SN) (CONSISTENT)	CUT	1,632.00	1,631.00
2	TRIM FOR TAIL LIGHT - LH/RH (SN) (CONSISTENT)	CUT	54.00	50.20
1	REAR CROSS PANEL (SN) (CONSISTENT)	DENTED	230.00	229.50
1	REINFORCEMENT CROSS PANEL (SN) (CONSISTENT)	DISTORTED	445.00	445.00
1	REINFORCEMENT FOR SIDE PANEL - LH REAR (SN) (CONSISTENT)	BENT	180.00	179.50
1	REINFORCEMENT FOR SIDE PANEL - RH REAR (SN) (CONSISTENT)	BENT	180.00	179.50
2	SUPPORT - LH/RH (SN) (CONSISTENT)	DISTORTED	172.00	170.40
1	TRIM FOR REAR CROSS PANEL SOUL (SN) (CONSISTENT)	DEFORMED	146.00	146.00
1	INSERT PART (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	237.00	-
1	LUGGAGE COMPARTMENT FLOOR (SN) (CONSISTENT)	NOT NECESSARY	621.00	-
2	LUGGAGE COMPARTMENT TRIM - LH/RH (SN) (CONSISTENT)	NOT NECESSARY	1,380.00	-
1	STOWAGE COMPARTMENT (SN) (CONSISTENT)	DEFORMED	80.00	79.30
1	NUT FOR SPARE WHEEL MOUNTING (SN) (CONSISTENT)	NOT NECESSARY	31.00	-
1	STOWAGE COMPARTMENT (SN) (CONSISTENT)	NOT NECESSARY	45.00	-
1	COVER FOR TOOL BOX (SN) (CONSISTENT)	NOT NECESSARY	40.00	-
1	SPARE WHEEL WELL (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	1,938.00	-
1	MOUNTING FOR SPARE WHEEL (SN) (CONSISTENT)	NOT NECESSARY	117.00	-
1	CLAMPING STRIP FOR BATTERY (SN) (CONSISTENT)	NOT NECESSARY	11.00	-
1	REAR SILENCER WITH EXHAUST FLAP - LH (SN) (CONSISTENT)	NOT NECESSARY	771.00	-
1	REAR SILENCER WITH EXHAUST FLAP - RH (SN) (CONSISTENT)	NOT NECESSARY	789.00	-
1	DUAL CLIP (SN) (CONSISTENT)	NOT NECESSARY	43.00	-
2	BRACKET FOR EXHAUST SILENCER (SN) (CONSISTENT)	NOT NECESSARY	73.00	-
1	CENTRE SILENCER (SN) (CONSISTENT)	NOT NECESSARY	801.00	-
2	HEAT SHIELD FOR REAR SILENCER - LH/RH (SN) (CONSISTENT)	CRUMPLED	266.00	132.50
1	ARCYLIC SEALER (SN) (CONSISTENT)	NECESSARY	360.00	180.00
1	CAVITY WAX (SN) (CONSISTENT)	NECESSARY	280.00	140.00

Report Ref No. CC4/ASM18011104/Awb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STONE CHIP (SN) (CONSISTENT)	NECESSARY	360.00	180.00
1	METAL FILLER POWDER (SN) (CONSISTENT)	NECESSARY	280.00	280.00
1	REAR NUMBER PLATE (SN) (CONSISTENT)	BENT	25.00	25.00
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	500.00	47.50
1	REAR REINFORCEMENT BEAM (SN) (CONSISTENT) (ADDITIONAL)	BENT	785.50	785.50
1	REAR PANEL CONNECTION PLATE LHS/RHS (SN) (CONSISTENT) (ADDITIONAL)	BENT	188.20	188.20
			28,062.70	15,893.10
	LABOUR			
	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER.	NOT NECESSARY	800.00	-
	TO REMOVE AND RENEW REAR PARKING AID AND REAR LID KICK SENSOR.		360.00	360.00
	TO DISLODGE AND REINSTALL REAR WIRE HARNESS, AUDIO EQUIPMENT, CONTROL UNIT, RELAY AND FUSE TRAYS, END.		1,800.00	1,800.00
	TO REMOVE AND REINSTALL REAR SEATS, BACK REST, CARPETS, ABCD PILLAR TRIMS, DISENGAGE AIRBAG SYSTEM.		1,800.00	1,800.00
	TO REMOVE AND INSPECT CENTER AND REAR EXHAUST SILENCERS. RENEW IF NECESSARY.	NOT NECESSARY	480.00	-
	TO REMOVE AND INSTALL REAR SUSPENSION ASSY INCLUDING REAR AXLE FOR CAR-O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	NOT NECESSARY	3,200.00	-
	TO REMOVE AND REINSTALL FUEL TANK ASSY.	NOT NECESSARY	600.00	-
	TO SET UP AND PLACE VEHICLE ON CAR-O-LINER.	NOT NECESSARY	2,400.00	-
	TO DISMANTLE REAR BUMPER AND REAR LID. CUT OUT AND WELD REAR END PANELS, SPARE WHEEL HOUSING AND CROSS MEMBERS. REPAIR AND REALIGN WHOLE REAR SUBSTRUCTURE. INCLUSIVE OF THE REPAIR OF INSERT PART AND SPARE WHEEL WELL.		7,200.00	3,600.00
	TO CARRY OUT STONE CHIP PRIMER WORK ON REAR PANELLING AND SPARE WHEEL HOUSING.		800.00	400.00
	TO CARRY OUT STONE CHIP PRIMER WORK ON REAR PANELLING AND SPARE WHEEL HOUSING.	REPEATED	800.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINT ON REAR BUMPER, REAR LID, SPARE WHEEL HOUSING, BOOT FLOOR AND END PANELLING. TO CARRY OUT JOINT SEALER WORKS AND CAVITY PRESERVATION.		3,700.00	2,500.00
	TO SPRAY AND INSTALL REAR LID SPOILER.		780.00	780.00
	TO CARRY OUT WHEEL ALIGNMENT.		240.00	240.00
	TO REWRAP STICKER ON AFFECTED AREA.		1,500.00	1,500.00
	TO CARRY OUT DIAGNOSTIC CHECK.		384.00	384.00
	TO REPAIR LHS REAR FENDER. (ADDITIONAL)		600.00	600.00
	TO RESPRAY LHS REAR FENDER. (ADDITIONAL)		900.00	800.00
			28,344.00	14,764.00
GRAND TOTAL			56,406.70	30,657.10
RECOMMENDED COST OF REPAIRS				30,657.10

Report Ref No. CC4/ASM18011104/Awb3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.