

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0686/2018/PH
Date : 14-Jun-18

Vehicle not IN workshop. Kindly arrange for survey.

Your insured vehicle is : SKK 2289 H

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Kester Andrew Lim Tan
Address : 10 Lakeshore View
Singapore 098152
Telephone : HP +65 91822086
Type of Claim : Third Party Claims
Policy No. : 2100503640-01
Vehicle No : **SLM 69 S**
Model Code : Audi S4 3.0 TFSI QU
Model / Year : Mar-17
Engine No : CWG 003119
Chassis No : WAUZZZF4HA095266
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Jun-18
Place of Accident : South Buona Vista Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLM 69 S.

S/n	Nature of Jobs	Estimated Charges
1	To carry out first measurement on car-o-liner	S/N \$ 800.00 ?
2	To remove and renew rear parking aid and rear lid kick sensor.	S/N \$ 360.00 ✓
3	To dislodge and reinstall rear wire harness, audio equipment, control unit, relay and fuse trays, end	S/N \$ 1,800.00 ✓
4	To remove and reinstall rear seats, back rest, carpets, ABCD pillar trims, disengage airbag system.	S/N \$ 1,800.00 ✓
5	To remove and inspect center and rear exhaust silencers. Renew if necessary.	S/N \$ 480.00 ?
SUB-TOTAL LABOUR CHARGES		: \$ 5,240.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLM 69 S.

S/n	Nature of Jobs	Estimated Charges
4	To remove and install rear suspension assy including rear axle for car-o-liner repairs. Inspect for damages and renew if necessary.	S/N \$ 3,200.00 ?
5	To remove and reinstall fuel tank assy.	S/N \$ 600.00 ?
6	To set up and place vehicle on car-o-liner.	S/N \$ 2,400.00 ?
7	To dismantle rear bumper and rear lid. Cut out and weld rear end panels, spare wheel housing and cross members. Repair and align whole rear substructure	\$ 7,200.00 3600.
8	To carry out stone chip primer work on rear panelling and spare wheel housing.	S/N \$ 800.00 ?
SUB-TOTAL LABOUR CHARGES		: \$ 14,200.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLM 69 S.

S/n	Nature of Jobs	Estimated Charges
9	To carry out stone chip primer work on rear panelling and spare wheel housing. <i>Repeated</i>	S/N \$ 800.00 *
10	To spray paint on rear bumper, rear lid, spare wheel housing, boot floor and end panelling. To carry out joint sealer works and cavity preservation.	\$ 3,700.00 2500.
11	To spray and install rear lid spoiler.	S/N \$ 780.00 ✓
12	To carry out wheel alignment.	S/N \$ 240.00 ✓
13	To rewrap sticker on affected area.	S/N TBC ✓
14	To carry out diagnostic check.	S/N \$ 384.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 25,344.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLM 69 S.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Dishled</i>	\$ 1,619.00	✓
2	FIXING PARTS FOR BUMPER <i>Neu</i>	\$ 63.00	+
3	SPOILER <i>Dishled</i>	\$ 710.00	✓
4	SECURING STRIP <i>Dishled</i>	\$ 191.00	✓
5	TRIM <i>Dishled</i>	\$ 250.00	✓
6	TRIM ALUMINIUM <i>missing</i>	\$ 920.00	✓
7	TRIM - LH / RH <i>Neu</i>	2 \$ 70.00	✓
8	REAR LIGHT REFLECTOR - LH/RH <i>Neu</i>	2 \$ 70.00	X
9	SENSOR <i>3 pieces dished</i>	4 \$ 842.00 631.50	
10	WIRING SET FOR BUMPER ?	\$ 598.00	?
11	CONTROL UNIT FOR OPENING BOOT LID <i>Neu</i>	\$ 372.00	+
12	SENSOR LINE FOR TAILGATE OPENING ?	\$ 184.00	?
13	REAR LID <i>Dented</i>	\$ 2,362.00	✓
14	ATTACHMENT PARTS FOR REAR LID <i>an</i>	\$ 125.00	✓
15	LID HINGE - LH/RH ?	2 \$ 400.00	?
16	GUIDE PIECE LID HINGE - LH/RH REAR <i>Neu</i>	2 \$ 50.00	+
17	LID LOCK <i>Dishled</i>	\$ 202.00	✓
18	PUSH BUTTON FOR LID LOCK ACTUATOR <i>Neu</i>	\$ 1,181.00	+
19	LOCK STRIKER <i>Best</i>	\$ 29.00	✓
20	STOP BUFFER <i>Neu</i>	\$ 28.00	✓
SUB - SPARE PARTS CHARGES		\$ 10,266.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLM 69 S.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
11	GASKET FOR FLAP <i>lit</i>	\$ 176.00	✓
12	SPOILER <i>new</i>	\$ 1,307.00	✓
13	PACKING ADHESIVE <i>new</i>	\$ 15.00	✓
14	AUDI EMBLEM <i>new</i>	\$ 108.00	✓
15	S4' EMBLEM <i>new</i>	\$ 108.00	✓
16	REAR LID TRIM PANEL <i>Del'd</i>	\$ 290.00	✓
17	LED TAIL LIGHT -LH/RH <i>del'd LH ut</i>	2 \$ 1,830.00	✓ <i>515</i>
18	TRIM FOR TAIL LIGHT - LH/RH <i>lit</i>	2 \$ 54.00	✓
19	LED TAIL LIGHT -LH/RH <i>lit</i>	2 \$ 1,632.00	✓
20	TRIM FOR TAIL LIGHT - LH/RH <i>lit</i>	2 \$ 54.00	✓
21	REAR CROSS PANEL <i>Dented</i>	\$ 230.00	✓
22	REINFORCEMENT CROSS PANEL <i>Dish'd</i>	\$ 445.00	✓
23	REINFORCEMENT FOR SIDE PANEL - LH REAR	\$ 180.00	?
24	REINFORCEMENT FOR SIDE PANEL - RH REAR	\$ 180.00	?
25	SUPPORT - LH/RH	2 \$ 172.00	?
26	TRIM FOR REAR CROSS PANEL SOUL <i>Del'd</i>	\$ 146.00	✓
27	INSERT PART	\$ 237.00	?
28	LUGGAGE COMPARTMENT FLOOR <i>new</i>	\$ 621.00	✗
29	LUGGAGE COMPARTMENT TRIM - LH/RH <i>new</i>	2 \$ 1,380.00	✗
30	STOWAGE COMPARTMENT <i>Del'd</i>	\$ 80.00	✓
SUB - SPARE PARTS CHARGES		\$ 9,245.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLM 69 S.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
31	NUT FOR SPARE WHEEL MOUNTING ?	\$ 31.00	?
32	STOWAGE COMPARTMENT ?	\$ 45.00	?
33	COVER FOR TOOL BOX ?	\$ 40.00	?
34	SPARE WHEEL WELL <i>Repair</i>	\$ 1,938.00	X
35	MOUNTING FOR SPARE WHEEL ?	\$ 117.00	?
36	CLAMPING STRIP FOR BATTERY ?	\$ 11.00	?
37	REAR SILENCER WITH EXHAUST FLAP - LH ?	\$ 771.00	?
38	REAR SILENCER WITH EXHAUST FLAP - RH ?	\$ 789.00	?
39	DUAL CLIP <i>me</i>	\$ 43.00	✓
40	BRACKET FOR EXHAUST SILENCER ?	2 \$ 73.00	?
41	CENTRE SILENCER ?	\$ 801.00	?
42	HEAT SHIELD FOR REAR SILENCER - LH/RH ?	2 \$ 266.00	?
43	ARCYLIC SEALER <i>me</i>	S/N \$ 360.00	✓
44	CAVITY WAX <i>me</i>	S/N \$ 280.00	✓
45	STONE CHIP <i>me</i>	S/N \$ 360.00	✓
46	METAL FILLER POWDER <i>me</i>	S/N \$ 280.00	✓
47	REAR NUMBER PLATE <i>Best</i>	S/N \$ 25.00	✓
48	SUNDRIES	\$ 500.00	?
TOTAL - SPARE PARTS CHARGES		: \$ 26,241.00	
TOTAL LABOUR CHARGES		: \$ 25,344.00	
GRAND TOTAL		: \$ 51,585.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 18/06/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 10 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant