

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SKJ9694E

TP/AXA

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

Estimate No: ES1890681/YISHUN

Date: 18 Jun 2018

Policy No: 18-MY008399-R04

Veh Reg No: SKJ9694E

Make/Model: VOLKSWAGEN GOLF
A7 1.4 TSI AT BMT
5G13GZ

WS Ref: TP/AXA/YS

Claim Type: Third Party

Accident Date: 18/06/2018

TP Veh Reg No: GBD115H

Chassis No: WVWZZZAUZDW026805

Engine No: CMB107152

Reg. Date: 28/01/2013

Estimate Repair Cost to Vehicle No :SKJ9694E

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	1,012.00	1 PC	Bu 1,012.00	✓
2 REAR BUMPER REINFORCEMENT	484.00	1 PC	484.00	?
3 REAR BUMPER TOW COVER	33.00	1 PC	mi 33.00	✓
4 REAR BUMPER LOWER SKIRT	320.00	1 PC	Di 320.00	✓
5 REAR BUMPER RH SIDE RETAINER	44.00	1 PC	Di 44.00	✓
6 REAR BUMPER RH REFLECTOR	55.00	1 PC	cm 55.00	✓
7 REAR TAILGATE	1,450.00	1 PC	Bu 1,450.00	✓
8 TAILGATE EMBLEM (GOLF)	88.00	1 PC	mi 88.00	✓
9 TAILGATE EMBLEM (TSI)	75.00	1 PC	mi 75.00	✓
10 TAILGATE LOGO	390.00	1 PC	Di 390.00	✓
11 TAILGATE INNER LOCK	330.00	1 PC	Di 330.00	✓
12 TAILGATE INNER RUBBER	340.00	1 PC	Di 340.00	508.00
13 TAILGATE INNER TRIM BOARD	235.00	1 PC	235.00	?
14 TAILGATE REFLECTORS	220.00	2 PCS	440.00	4
15 TAILLAMPS	248.00	2 PCS	496.00	4
16 REAR PANEL	730.00	1 PC	730.00	?
17 REAR PANEL INNER TOP GARNISH	178.00	1 PC	Di 178.00	✓
18 REAR SPARE TYRE TOP BOARD	380.00	1 PC	380.00	?
19 REAR EXHAUST PIPE	750.00	1 PC	R 750.00	?
20 REAR EXHAUST TOP HEAT SHIELD	145.00	1 PC	Bu 145.00	✓
21 REAR WIPER ARM COVER	10.00	1 PC	cm 10.00	✓
			7,985.00	
Less 10%			798.50	7,186.50
Special Net				
22 REAR WINDSCREEN GLASS GUM	40.00	1 ROLL	mi 40.00	✓
23 REAR NUMBER PLATE	35.00	1 PC	Bu 35.00	✓
			75.00	75.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

Estimate No: ES1890681/YISHUN

Date: 18 Jun 2018

Policy No: 18-MY008399-R04

Veh Reg No: SKJ9694E

Make/Model: VOLKSWAGEN GOLF
A7 1.4 TSI AT BMT
5G13GZ

Chassis No: WVWZZZAUZDW026805

Engine No: CMB107152

Reg. Date: 28/01/2013

WS Ref: TP/AXA/YS

Claim Type: Third Party

Accident Date: 18/06/2018

TP Veh Reg No: GBD115H

Estimate Repair Cost to Vehicle No :SKJ9694E

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
24 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	800
25 PANEL BEATING	1,100.00	1 LA	1,100.00	800
26 PUTTY & RESPRAY PAINT	1,000.00	1 LA	1,000.00	800
27 REMOVE & REFIX EXHAUST PIPE	60.00	1 LA	60.00	600
28 RUSTPROOFING	90.00	1 LA	90.00	600
29 REMOVE & REFIX GARNISH,ETC TO FACILITATE ON REPAIR	120.00	1 LA	120.00	600
			2,490.00	2,490.00
			Total	S\$ 9,751.50
			Add GST @ 7%	682.61
			Total Amount Payable	<u>S\$ 10,434.11</u>

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE