

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 10 Jul 2018

**Preliminary Advice**

Insured Vehicle No : SLG1949C

TP Vehicle No : SJB9968U

Accident Date : 17/06/2018

Make : DAIHATSU TERIOS

Assignment Date : 19/06/2018

Date of Inspection : 09/07/2018

Est. Duration of Repair : 6.00

Inspection At : ALAN'S UNITED AUTO PTE LTD (HQ)

BLK 7 SIN MING INDUSTRIAL ESTATE, #01-76

SINGAPORE 575642

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 5,005.75 |
| Revised Amount              | :S\$ | 3,391.95 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 3,391.95 |

|                 |      |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.