

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE PTE LTD		Ref:	CC4/ASM18011118/Vga3q2	
	8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date:	01/02/2021	
	ATTN:CYNTHIA		Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SFU 1773P	Veh. Inspected	SG 1031S	
	Policy No.	CN824270	Coverage (\$)	0.00	
	Claim No.	S8M00JXA	Excess (\$)	0.00	
	Assign From		Assign Date	12/06/2018	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ	c.c	6374	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	WEB62808323130285	Colour	MULTI COLOUR	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	275/70 R22.5	BRIDGESTONE	6 mm	
	L/H Front Tyre	275/70 R22.5	BRIDGESTONE	6 mm	
	R/H Rear Tyre	275/70 R22.5	BRIDGESTONE	6 mm	
	L/H Rear Tyre	275/70 R22.5	BRIDGESTONE	6 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.  DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	18/08/2018	Inspection Date	12/06/2018	
	Survey held at	SMRT AUTOMOTIVE SERVICES	S PTE LTD		
	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705				
5a.	a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				