

ASS. REC. BY:

REF:

CS/FCI18011123/K1rd3n2

Special Instruction:

Surveyor:

K9/vip

ASSIGNMENT (Office)

CWS

From (Person):

Eileen Lee

of

FCI

Date/Time: 19/6/18 @ 4:27pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 1394R

Insured:

SHA 6928J

at Workshop m/s:

Premier Automotive

Tel:

6544 6671

of

23 Changi South Ave 2 # 03-02

Policy No:

Claim No:

D18004796MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 18/06/2018

CA / REV / REP. / REV 24 HRS

up

20/06/2018

H.O.D. Endorsement:

Date/Time:

4:38pm @ 19/06/18

Person Contacted:

Gary

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHD 1394R - NA / INC1400 2979 / m2	DOA: 15/02/2014
	SHA 6928J - CS/FCI16015751 / Agh3n2	DOA: 16/08/2016
21/6/18	Sent preli thru email.	

ASSIGNMENT

From: 20/06/2018 Date: 20/06/2018 Veh No: SHD 1394R Yr Regn: 14 Jun 2017

Estimated Cost: TP RES / OD RES / EVA / INV / MV Type: M.Car / M.Cycle / Bus / Van / Lorry / T.O. / Prime Mover /

OD TP RES / TP RES / OD RES / EVA / INV / MV Truck / Trailer or Hyundai 230 C.C. 1582

To Inspect Vehicle No: SHD 1394R Make: Hyundai 230 A/C: Insured / Std / NI / NA

at Workshop n/s: Premier Automotive Colour: Silver T/Radio: Insured / Std / NI / NA

of 23 Changi South Ave 2 # 03-02 Sp Reading: 18 433 Eng/No: TMAD2814VHJ128021

Insured: 18 433 C/No: TMAD2814VHJ128021 Gen. Cond: Good / Fair / Poor / Burnt

Policy No: 18 433 Steering: Inorder / Jammed / Leaked / Burnt or

Claims No: 18 433 Brake: Inorder / Jammed / Leaked / Burnt or

Sum Insured: 18 433 Mod: Nil / S/Rim / STD / A/Rim or

(Client's Record) 18 433 Tyre Size: F: 195/65 R15

Make of Veh: 18 433 R: 195/65 R15

(Policy Condition) 18 433 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

Remark: The veh had commenced its repair at the time of inspection. 18 433 TOYO / YOKO or 18 433

Bal. or Market Value: 18 433 Front 18 433 Rear 18 433

IDAC Accident Rpt: 18 433 R/Bal. 18 433 mm 18 433 mm


GIA / PR Seen: 18 433 L/Bal. 18 433 mm 18 433 mm

Est. Repairs: 18 433 D.O.A. 18 433 D.O.I. 18 433

Lum Sum: 18 433 Survey held at 18 433

CA / REV / REP. / 24 HRS 18 433 Des. of Damages: 18 433

Date: 18 433 Person Contacted: 18 433 The U/C / Chassis frame / Body Structure affected due to collision.



RECEIVED 25 JUN 2018

Date/Time File Pass to? 22/6/18 Action / Instruction Check R/P \$280 / 24hrs.

1) typist ☐ : Preli. Report ☒ : Final Report

Date/Time File Return to? 22/6/18 Days Of Repair: 2

Report Format: TP Resurvey No. of Trip: 1

Lump Sum / I.B.E. (\$) 280 Add Fee: ☐ Site Insp. (\$) ☐ Interview (\$) ☐ Tech. Insp. (\$) ☐ Weekend (\$)

Survey Fee: 130 Transportation: 50 50 18

TOTAL 248



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18011123/K1rd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 19-06-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 6928J	Veh. Inspected	SHD 1394R
Policy No.		Coverage (\$)	0.00
Claim No.	D18004796MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	19/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/06/2018	Inspection Date
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004796MFSH

Our Ref: CS/FCI18011123/K1rd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 1394R .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20.06.2018 at the premises of M/s PREMIER AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,211.64</u> .
Revised Estimate Amount	: S\$ <u>280.00</u> .
"Check" Items Amount	: S\$ <u> </u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at rear portion.



Yours faithfully
KALVIN
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	18-06-2018	Our Ref No.	D18004796MFSH
Accident Date	18-06-2018	Claim Type.	Third Party
Insured Vehicle	SHA6928J	Third Party Vehicle.	SHD1394R
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02		
Contact Person.	GARY SHI		
Contact No.	62148880/ 65446671	Fax No.	62141511
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	EILEEN LEE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241527)



PRI Documents



Close



PRI Header Details

Claim No	D18004796MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PREMIER LTD
Workshop Name	PREMIER AUTOMOTIVE SERVICES PTE LTD (Contact Person : GARY SHI)	Survey Location & Contact Details	23 CHANGI SOUTH AVENUE 2 #03-02 Mobile: 65446671 , Phone: 62148880 , Fax: 62141511 EmailId: GARY.SHI@PREMIERTAXI.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA6928J	TP Vehicle No	SHD1394R
PRI Recieved Date	18-06-2018 09:50:26 PM	Surveyor Appointed Date	19-06-2018 04:26:20 PM	Surveyor Accept Date	19-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	19-06-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
 Owner ID Type: Company
 Owner Name: PREMIER TAXIS PTE. LTD.
 Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: SHD1394R
 Previous Vehicle No.: -
 Effective Date of Ownership: 14 Jun 2017
 Original Regn Date: 14 Jun 2017
 Registration Date: 14 Jun 2017
 Year of Manufacture: 2016
 Vehicle Type: Public Transport Taxi (Motor Car)
 Vehicle Scheme: Taxi (Company)
 Vehicle Attachment 1: Air-Con (Taxi)
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: HYUNDAI
 Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
 Primary Colour: Silver
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: TMAD281UVHJ128021
 Engine No.: D4FBGZ122121
 Engine Capacity/Power Rating: 1582 cc / -
 Maximum Power Output: 100.0 kW (134 bhp)
 Propellant: Diesel
 Max Unladen Weight: 1496 kg
 Maximum Laden Weight: 1940 kg
 Open Market Value: S20,845.00
 PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 13 Jun 2025
 Minimum PARF Benefit: S8,041.00
 No. of Transfers: 0
 IU Label No.: 1050700278
 COE No.: 2017061401003835R
 COE Expiry Date: 13 Jun 2025
 COE Category: A - Car up to 1600cc & 97kW (130bhp)
 COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)
 Quota Premium (QP) / Prevailing Quota Premium: - / \$50,625.00
 PQP Paid: S40,500.00
 QP (Regn Cat): -
 OPC Cash Rebate Eligibility: No

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

18-Jun-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1394 R

1 pc	Rear bumper <i>X repri</i>	\$	811.11
1 pc	Rear bumper sponge <i>X sue</i>	\$	79.20
1 pc	Rear bumper reinforcement <i>X sue</i>	\$	815.64
1 pc	Rear bumper reinforcement centre <i>X sue</i>	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20 <i>X sue</i>	\$	104.40
2 pcs	Rear bumper n/s & o/s reflector @ \$107.50 <i>X sue</i>	\$	215.00
		\$	2,104.55
	Less 20%	\$	420.91
		\$	1,683.64

S/NETT

1 set	Rear bumper clips <i>X sue</i>	\$	48.00
1 set	Reverse sensor <i>X sue</i>	\$	280.00
	Sundry	\$	50.00 <i>X sue</i>
	To dismantle and replace reverse sensor and test system	\$	80.00 <i>X sue</i>
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, etc.	\$	450.00 100
	To putty and spray painting on the rear bumper & end panel <i>X sue</i>	\$	500.00 180
	To apply rustproofing on the repaired and replaced panels	\$	120.00 50
	Total	\$	3,211.64

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

- To resurvey before and after painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalar 11/06/18
20/6/18 1000h
2 R/s
PIP
After Repair photo



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18011123/K1rd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 6928J	Veh. Inspected	SHD 1394R	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18004796MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	19/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I30	c.c	1582	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	TMAD281UVHJ128021	Colour	SILVER	
Odometer	18433	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	HANKOOK	7 mm	
L/H Front Tyre	195/65 R15	HANKOOK	7 mm	
R/H Rear Tyre	195/65 R15	HANKOOK	7 mm	
L/H Rear Tyre	195/65 R15	HANKOOK	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/06/2018	Inspection Date	20/06/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1394R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	811.11	-
1	REAR BUMPER SPONGE	SERVICEABLE	79.20	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	815.64	-
1	REAR BUMPER REINFORCEMENT CENTRE	SERVICEABLE	79.20	-
2	REAR BUMPER N/S & O/S SIDE BRACKET @\$52.20	SERVICEABLE	104.40	-
2	REAR BUMPER N/S & O/S REFLECTOR @\$107.50	SERVICEABLE	215.00	-
	LESS 20% DISCOUNT		-420.91	-
			1,683.64	-
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	SET REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			378.00	-
	LABOUR			
	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM.	NOT NECESSARY	80.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING TO KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE OF THE END PANEL,ETC.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		450.00	100.00
	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER & END PANEL.		500.00	180.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
	-		-	-
	-		-	-
	-		-	-
			1,150.00	280.00
	GRAND TOTAL		3,211.64	280.00
	RECOMMENDED COST OF REPAIRS			280.00

Report Ref No. CS/FCI18011123/K1rd3n2



Report Ref No. CS/FCI18011123/K1rd3n2

A stylized handwritten signature in black ink, appearing to be 'W' or 'A'.

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

A stylized handwritten signature in black ink, appearing to be 'A.L.P.' or similar.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.