



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

5 Benoi Place Singapore 629926

Tel: 6861 0908 Fax: 6515 2948

Date: 18.06.2018

EQ Insurance Company Ltd
5 Maxwell Road #17-00
Tower Block MND Complex
Singapore 069110

Attn: Motor Claim Dept

ESTIMATE COST OF REPAIR TO VEHICLE SJA7444J TOYOTA ALPHARD 2015

To Supply

1) 1pc	rear bumper	\$	1,774.60 <i>Ry</i>
2) 1set	rear bumper clip	\$	30.00 <i>X</i>
Sub total parts		\$	1,804.60
Less: 25% discount		\$	(451.15)
		\$	1,353.45

L/charges

1)	To remove & refit reverse sensors and check wiring.	\$	50.00 ³⁰
2)	To remove & replace rear bumper, knock & welding right rear fender & align rear bumper	\$	300.00 ²⁵⁰
3)	To putty, respray painting rear bumper, right rear fender & polish	\$	600.00 ⁴⁰⁰

Sub total L/charges	\$	950.00
Estimated Total	\$	2,303.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
"WP"

26/6/18 R 1145

2 days

sun@lkkauto.com

Resurvey after repair