

Sunday

CC 4 / 111180

11154

R1 #3

Surveyor

RAGUL

DOI:

ASSIGNMENT

20-6-18

Date / Time:

19.6.18

Registered in Merimen:

19.6.18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHD 4523 R

Name of Insured:

CTPL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

6/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

GUTH KENG BOON

Driver Tel No.:

01243592

(V/L- YES / NO)

Claim No.:

Policy No.:

M100001

Make / Model:

H-140

Place of Accident:

MARGARET DRIVE > TANGHUN RD

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

PA 10 B



INSRS:

WSP:

Tel:

Liability:

RMKS:

JCN Antelution



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

DATE / PIC

STAGE

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

5/7/2018 K10 T11 upload video footage

9/7/2018 TP video footage upload by T11, seek Mr Yeo opinion.

11/8/2018 seek market from T11, 50%/50% or 100% against

2/8/2018 T11 approve 50/50

pending Handler LOR

16/7/2019 priya call in and mention that, they have released the matter again, and they want reject TP claim

8/8 - Rejectant email send TP.

8/8 - PRP pass me to close.

Enlist Case

Cecilia

PRELIMINARY ADVICE Date/Time:

Sent By:

03-02-20

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
4/3/2020

REF:

III

ASSIGNMENT

From

Date:

20/06/18

Veh No.

PA10B

Yr Regn:

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TR / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

PA10B

Make

TOYOTA HILUX

C.C

at Workshop m/s

Ace Autolution

Colour

Green

A/C: Insured / Std / NI / NA

of 13 Kakki Bulkit Rd 4 #03-29 Bartley

Sp. Reading

168305

T/Radio: Insured / Std / NI / NA

Insured: Biz Centre

Eng/No:

Policy No.

C/No.

KOH 2230W4438

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Mod: All / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:


F:

195/15C

R:

1 -

Remark: The veh had commenced its repair at the time of inspection.



B3 DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

5

days

Res:

Yes or No

D.O.A.

06/06/18

D.O.I.

20/06/18

Lum Sum:

70

%

3 Val:

Yes or No

Survey held at:

ACE Autolution

CA / REV / REP. / 24 HRS 'up'

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No GIA

UB 438501 - (Red 438501-12/487.)

Date/Time: File Pass to?

☐

Prel. Report

Days Of Repair:

1)

☐

Final Report

Resurvey No. of Trip:

Date/Time: File Return to?

Survey Fee:

2)

Transportation:

Report Format:

Add Fee:

☐

Site Insp. (\$

1.2 + RS 9

☐

Interview (\$

1. Photo

☐

Tech. Insp. (\$

1. Other

☐

Workshop (\$

Lump Sum / I.B.I. (\$

TOTAL



JCN Autolution Pte Ltd

COMPANY REG. NO.: 201813325W

No.1 Kaki Bukit Ave 6, Blk D #01-85, AutoBay @ Kaki Bukit,
Singapore 417883.

+65 6881 1772 sales@jcngroup.com

ESTIMATE

JK59 TRANSPORT PTE LTD JK59 TRANSPORT
55 HUIJ AVE #04-04 PARC PALAIS Singapore
596752

Contact: 97229759

Code: C100007

Date in: 20/06/2018

Vehicle Num.: PA10B

Model: TOYOTA HIACE.C.GL 3.0A

Chassis/Eng#: KDH2230004438/1KD1842908

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
AIR ISONATOR BOX <i>at</i>	1	294.00	294.00
AIR ISONATOR BOX AIR DUCT <i>x sec</i>	1	145.00	145.00 ✓
FRONT BUMPER LOWER GRILLE GARNISH R.H. <i>x sec</i>	1	103.10	103.10 ✓
FRONT BUMPER SIDE HOLDER. <i>all</i>	1	126.10	126.10
FRONT BUMPER. <i>de</i>	1	594.10	594.10
FRONT DOOR R.H. <i>bl</i>	1	1680.45	1,680.45
FRONT DOOR R.H CHECKER <i>R+</i>	1	120.45	120.45 ✓
FRONT DOOR R.H STEP PANEL GARNISH. <i>at</i>	1	258.90	258.90
FRONT DOOR R.H WEATHER STRIPS <i>all</i>	1	399.15	399.15
FRONT DOOR R.H WITH HINGE UPPER & LOWER. <i>R+</i>	1	74.10	74.10 ✓
FRONT FENDER RH <i>R+</i>	1	158.10	158.10 ✓
FRONT HEADLAMP RH <i>all</i>	1	689.45	689.45
Subtotal before discount		4042.15	4,642.90
Percentage discount 25%		25%	1,160.73
Sub-total 1		3031.61	3,482.18
FRONT BUMPER CLIPS <i>all</i>	1	30.00	30.00
FRONT BUMPER PARKING SENSOR. <i>all</i>	1	350.00	200 350.00 ✓



JCN Autolution Pte Ltd

COMPANY REG. NO.: 201813329W

9 No.1 Kaki Bukit Ave 6, Blk D #01-85, AutoBay @ Kaki Bukit,
Singapore 417883.

+65 6881 1772 sales@jcngroup.com

FRONT DOOR R.H INNER TRIMMBOARD CLIPS	1	30.00	30.00
FRONT FENDER OUTDOOR CAMERA SET	1	500.00	500.00
FRONT HEADLAMP R.H SIGNAL BULB RH	1	25.00	25.00
FRONT HEADLAMP SIGNAL BULB R.H	1	25.00	25.00
Subtotal before discount		255	980.00
Percentage discount 0%			0.00
Sub-total 2			980.00
Parts-total			4,442.18

LABOUR

Description	Price
TO REMOVE, REINSTALL AIR-CON PARTS, VACUUMS, REFILL AIR-CON GAS (TO FR)	180.00 x
TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETING HEADLAMP FOCUSING (TO FR)	120.00 30
TO REMOVE, REFIX/RENEW PARKING CAMERA	300.00
TO DIAGNOSE, REPLACE AND/OR REPAIR TO RECTIFY FRONT PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	90.00
TO REMOVE, REINSTALL FRONT DOOR WINDOW GLASS (FR)	150.00 200
TO TRANSFER FRONT DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE	100.00 60
TO RESPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR POSITION, AND WHERE CONSISTENT TO THE ACCIDENT	1,000.00 600
TO REPAIR LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND WHERE CONSISTENT TO THE ACCIDENT	800.00 600
Labour Total	2,740.00
Parts & Labour Total	7,182.18

page 2

LKK Auto Consultants would notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during the survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

P - 3031.61

SLN - 255.00

L - 1290.00

Suppl - 260.00

T - 4836.61

20%

3869.28

42-3,850

erike@jcngroup.com

5 days



JCN
AUTOLUTION

JCN Autolution Pte Ltd

COMPANY REG. NO.: 201813305W

📍 No.1 Kaki Bukit Ave 6, Blk D #01-85, AutoBay @ Kaki Bukit,
Singapore 417883.

☎ +65 6881 1772 ✉ sales@jcngroup.com

JK59 TRANSPORT PTE LTD
55 HUM AVE #04-04 PARC PALAIS
S 598752
CONTACT: 97229759

Supplementary List

Code: C100012
Date: 9/11/2018
Vehicle No. PA 10B
Model TOYOTA HIACE 3.0A
CHASSIS/ENG# KDH2230004438
1KD1842908

PARTS

S/N Particular	Quantity	Unit Price	Amount
1 FRONT FENDER SIDE CAMERA(SN)	1	\$ 450.00	\$ 450.00
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
SUBTOTAL BEFORE DISCOUNT			\$ 450.00
PERCENTAGE DISCOUNT			
PARTS TOTAL			\$ 450.00

450.00
250

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 19 June 2018 10:37 AM
To: Cheeteck Chan; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Sundari Nagarajan - III
Subject: RE: Arranging Pre-Repair Inspection For Vehicle no.PA10B
Attachments: India-PRI PA10B 06062018.docx

11:01am @ 19/06/2018
penon @ chan
vehicle not in
amerey on 20/06/2018

Dear Sir / Mdm,

Please conduct a survey on TP vehicle PA10B and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Cheeteck Chan [mailto:onehub77@gmail.com]
Sent: 19 June, 2018 10:07 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: Arranging Pre-Repair Inspection For Vehicle no.PA10B

Morning Wee

Please kindly assign LKK to conduct the inspection on the said vehicle at Bartley BizHub tomorrow 20-jun-2018. Pls pass my contact 96775772.

Regards
Chan

On Tue, Jun 12, 2018 at 4:21 PM, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Cheeteck Chan [mailto:onehub77@gmail.com]

Sent: 12 June, 2018 2:45 PM

To: Motor Claim - III <motorclaim@iii.com.sg>; lathitha@iii.com.sg

Subject: Arranging Pre-Repair Inspection For Vehicle no.PA10B

Dear Sir/Madam,

Please kindly inform us when will you be arranging your surveyor to conduct survey said vehicle at No.17 Lor Kilat #01-10 Singapore 598139.

Regards

Chan

M: 96775772

E: onehub77@gmail.com

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing,

handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

--

Best Regards,

Erik Chan JCN Autolution Pte Ltd

8 Kaki Bukit Ave 4.

Premier@Kaki Bukit,

#07-23, Singapore 415 875

HP: (65) 8866 6577 F: 6881 1772. E: erik@jcngroup.com

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Print Received Message

This mail is associated with :

***PA10B (MCT18060207)
[SHD4523R]**

TP

JK59 TRANSPORT PTE. LTD.
Jun 6 2018 12:00AM

Jcn Autolotion Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 16/07/2019 17:53 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - PA10B - Claim Handler: Sundari Nagarajan

Approved:0.00:We deny TP claim. TP making a illegal turn in the middle of the road

Print Received Message

This mail is associated with :

***PA10B (MCT18060207)
[SHD4523R]**

TP

JK59 TRANSPORT PTE. LTD.
Jun 6 2018 12:00AM

Jcn Autolotion Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 30/08/2018 14:17 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - PA10B - Claim Handler: Sundari Nagarajan

Approved:0.00.

Print Received Message

This mail is associated with :

***PA10B (MCT18060207)**
[SHD4523R]

TP
JK59 TRANSPORT PTE. LTD.
Jun 6 2018 12:00AM

Jcn Autolution Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 16/07/2019 17:53 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - PA10B - Claim Handler: Sundari Nagarajan

Approved:0.00:We deny TP claim. TP making a illegal turn in the middle of the road

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Thursday, 8 August 2019 4:43 PM
To: enquiry@jcngroup.com
Subject: RE: MCT18060207/01/sn; Your Ref: SHD 4523R Our Ref: PA 10B ACCIDENT INVOLVING PA 10B & SHD 4523R ALONG MARGARET DRIVE TO TANGLIN ROAD ON 06/06/2018 AT ABOUT 1845 HOURS
Attachments: OI SHD 4523R .MP4

Your Ref: PA 10B
Our Ref: CC4/III18011154/R1ga3

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING PA 10B & SHD 4523R ON 06/06/2018

We refer to the above matter.

Attached is a copy of Our Insured Video Footage for your easy reference. We have reviewed the matter and we are of the view that our driver is not liable for the accident. Your client is making a illegal turn in the middle of the road that leads to the collision.

In view of the above, we have our principal instruction to deny liability and unable to look into your client's matter.

Thank you.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: enquiry@jcngroup.com [mailto:enquiry@jcngroup.com]

Sent: Thursday, 27 June 2019 4:39 PM

To: Sundari Nagarajan - III <sundari@iii.com.sg>

Cc: CS A Team <cs-a@lkkauto.com>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: Re: MCT18060207/01/sn; Your Ref: SHD 4523R Our Ref: PA 10B ACCIDENT INVOLVING PA 10B & SHD 4523R ALONG MARGARET DRIVE TO TANGLIN ROAD ON 06/06/2018 AT ABOUT 1845 HOURS

Importance: High

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jun 2018 Edit Reg		19 Jun 2018 00:00 Edit Adj Rpt	S\$3,850.00 Edit Estimates	S\$3,850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -								
Main Claimant:	JK59 TRANSPORT PTE. LTD., Co. Reg. No.: 200909207D								
Vehicle Reg. No.:	PA10B	Date of Loss:	06/06/2018 00:00 - :59 [116 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18060207	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHD4523R	Policy No. (Claimant):	5066655655-03						
		Excess:							
Repairer:	Jcn Autolution Pte Ltd (HQ) 8 Kaki Bukit Ave 4 #07-23, Premier@ Kaki Bukit, 415875 Kaki Bukit - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 28/06/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (04/03/2020): Alert - Adj Mandate Approved (S\$0.00) - PA10B - Claim Handler: Sundari Nagarajan III_SG (16/07/2019): Alert - Adj Mandate Approved (S\$0.00) - PA10B - Claim Handler: Sundari Nagarajan III_SG (30/08/2018): Alert - Adj Mandate Approved (S\$0.00) - PA10B - Claim Handler: Sundari Nagarajan III_SG (09/07/2018): Alert - Adj Mandate Approved (S\$0.00) - PA10B - Claim Handler: Sundari Nagarajan 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PA10B (MCT18060207)
[SHD4523R]
TP
JK59 TRANSPORT PTE. LTD.
Jun 6 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Jcn Autolution Pte Ltd

Upload Documents Upload Photos Compose New Letter			View <input type="button" value="View in Browser"/>	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	09/07/18 11:49	Video - Accident	Load MP4	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/06/18 20:49	NOTIFICATION FROM WORKSHOP	Load PDF	
2	19/06/18 20:49	ACKNOWLEDGEMENT EMAIL TO III DD 19.06.2018	Load PDF	
3	04/07/18 13:19	TP GIA REPORT	Load PDF	
4	03/03/20 15:03	REJECTION EMAIL TO TP	Load PDF	
5	03/03/20 15:05	LKK RESURVEY PHOTO	Load PDF	
6	03/03/20 15:05	LKK SURVEY PHOTO	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	20/06/18 08:49	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18011154/R1GA3Q2

Date: 05/03/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MC0M0015
 Claimant PA10B Insured Vehicle No : SHD4523R
 Vehicle No : PA10B
 Date of Loss: 06/06/2018 Nature of Claim: TP Claim No: MCT18060207

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PA10B
 Make & Model: TOYOTA HIACE, 3.0 COMMUTER GL (A) Engine No: 1KD1842908
 Reg. Date: 11/09/2008 (Man. Year: 2008) Chassis No: KDH2230004438
 Colour: Grey Odometer: 168305 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,892.17	3,536.61	1,355.56	27.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	1,290.00	1,450.00	52.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,632.17	4,826.61	2,805.56	36.76
Approved Total (Overridden) (S\$)		3,850.00		
Nett Amount (S\$)	7,632.17	3,850.00	3,782.17	49.56
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 19/06/2018
 Date Inspected: 20/06/2018 Inspected At: 13 KAKI BUKIT ROAD 4 #03-29
 BARTLEY BIZ CENTRE
 SINGAPORE 417807
 Repairer: Jcn Autolotion Pte Ltd (HQ)
 Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 04 Mar 2020)	
Parts:	N/A	TOYOTA HIACE 3.0 COMMUTER GL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PA10B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AIR ISONATOR BOX	Cut	294.00 FL	*294.00 FL
2	1		*AIR ISONATOR BOX AIR DUCT	Serviceable	145.00 FL	*- FL
3	1		*FRONT BUMPER LOWER GRILLE GARNISH RH	Serviceable	103.10 FL	*- FL
4	1		*FRONT BUMPER SIDE HOLDER	Necessary	126.10 FL	*126.10 FL
5	1		*FRONT BUMPER	Deformed	594.10 FL	*594.10 FL
6	1		*FRONT DOOR RH	Bent	1,680.45 FL	*1,680.45 FL
7	1		*FRONT DOOR RH CHECKER	Repair	120.45 FL	*- FL
8	1		*FRONT DOOR R.H STEP PANEL GARNISH	Cut	258.90 FL	*258.90 FL
9	1		*FRONT DOOR R.H WEATHERSTRIPS	Necessary	399.15 FL	*399.15 FL
10	1		*FRONT DOOR R.H WIHT HINGE UPPER & LOWER	Repair	74.10 FL	*- FL
11	1		*FRONT FENDER RH	Repair	158.10 FL	*- FL
12	1		*FRONT HEADLAMP RH	Cracked	689.45 FL	*689.45 FL
13	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
14	1		*FRONT BUMPER PARKING SENSOR	Not Working	350.00 FS	*200.00 FS
15	1		*FRONT DOOR R.H INNER TRIMBOARD CLIPS	Not Necessary	30.00 FS	*- FS
16	1		*SET FRONT FENDER OUTDOOR CAMERA	Not Necessary	500.00 FS	*- FS
17	1		*FRONT HEADLAMP R.H SIGNAL BULB RH	Cracked	25.00 FS	*25.00 FS
18	1		*FRONT HEADLAMP SIGNAL BULB R.H	Not Necessary	25.00 FS	*- FS
19	1		*FRONT FENDER SIDE CAMERA	Necessary	450.00 FS	*250.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	6,052.90	4,547.15
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,160.73	1,010.54
Total Parts (\$\$)	4,892.17	3,536.61

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REINSTALL AIR-CON PARTS ,VACUUMS ,REFILL AIR-CON GAS (TO FR)	New	180.00	0.00
2	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING (TO FR)	New	120.00	30.00
3	TO REMOVE ,REFIX /RENEW PARKING CAMERA	New	300.00	0.00
4	TO DIAGNOSSE ,REPLACE AND/OR REPAIR TO RECTIFY FRONT PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	90.00	0.00
5	TO REMOVE,REINSTALL FRONT DOOR WINDOW GLASS (FR)	New	150.00	0.00
6	TO TRANSFER FRONT DOOR GLASS REGULATOR GEAR,MOTOR ,RAILING ,CHANNEL ,TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	100.00	60.00
7	TO RESPRAY PAINTING ON THE CHANGE BODYPARTS ,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
8	TO PROVIDE LABOUR ,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS ,REPAIR RE-ALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	800.00	600.00
Gross Labour Cost (S\$)			2,740.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >