

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK, MND COMPLEX
SINGAPORE 069110

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 13/06/2018
TP Veh Reg No: YM9273E

Estimate No: EST1800178

Date: 18 Jun 2018

Veh Reg No: SLD6046R

Make/Model: HONDA ACCORD 2.0A

Chasis No: CL73203118

Reg. Date: 10/01/2007

Your Ref No: YM9273E

Xiao Tong

Estimate Repair Cost to Vehicle No :SLD6046R

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID <i>Distorted</i>	850.00	✓
2	1 PC BOOT LID LOGO	46.30	✓
3	1 PC BOOTLID "ACCORD" EMBLEM <i>3pc</i>	30.00	✓
4	1 PC BOOT LID LAMP LH <i>could</i>	265.00	✓
5	1 PC BOOT LID LAMP RH <i>nt</i>	265.00	✓
6	2 PCS BOOT LID HINGE <i>but</i>	160.00	✓
7	2 PCS BOOT LID HINGE COVER <i>del d L11</i>	130.00	65
8	2 PCS BOOTLID SPRING <i>new</i>	110.00+	
9	1 PC BOOT LID RUBBER <i>nt</i>	165.00	✓
10	1 PC BOOT LID LOCK <i>nt</i>	269.00	✓
11	1 PC REAR BOOT LID LOCK CABLE <i>2nd</i>	110.00	✓
12	1 PC BOOTLID LOCK CHECKER <i>new</i>	37.50	+
13	1 PC BOOTLID AUTO LOCK <i>new</i>	295.10	+
14	1 PC BOOTLID TRIM <i>del d</i>	265.00	✓
15	2 PCS BOOTLID SMALL STOPPER <i>3pc</i>	37.00	+
16	2 PCS BOOTLID BIG STOPPER	37.00	+
17	2 PCS REAR NUMBER PLATE LAMP <i>new</i>	225.20	+
18	1 PC REAR NUMBER PLATE LAMP GARNISH <i>could</i>	185.60	✓
19	1 PC REAR FENDER LH <i>Distorted</i>	1,030.80	✓
20	1 PC REAR FENDER COWLING LH <i>new</i>	140.00	+
21	1 PC REAR FENDER AIR VENTILATOR <i>could</i>	67.90	✓
22	1 PC REAR LH ROOF MOULDING <i>new</i>	223.10	+
23	1 PC REAR FENDER TRIM LH <i>crushed</i>	235.00	✓
24	1 PC REAR FENDER TRIM RH <i>new</i>	235.00	+
25	1 PC FUEL TANK LID <i>new</i>	68.00	+
26	1 PC FUEL NECK PIPE <i>new</i>	215.00	+
27	1 PC REAR DOOR LH <i>Regis</i>	1,120.00	+
28	1 PC REAR DOOR RUBBER LH <i>3pc</i>	125.00	+
29	1 PC REAR DOOR LOCK RH <i>new</i>	265.00	+

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S: EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK, MND COMPLEX
SINGAPORE 069110

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 13/06/2018
TP Veh Reg No: YM9273E

Estimate No: EST1800178
Date: 18 Jun 2018

Veh Reg No: SLD6046R
Make/Model: HONDA ACCORD 2.0A
Chasis No: CL73203118
Reg. Date: 10/01/2007
Your Ref No: YM9273E

Estimate Repair Cost to Vehicle No :SLD6046R

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
30	1 PC REAR PANEL <i>Distorted</i>	400.60 ✓	
31	1 PC REAR PANEL TRIM <i>Replaced</i>	202.60 ✓	
32	1 PC TAIL LAMP LH <i>smashed</i>	280.00 ✓	
33	1 PC TAIL LAMP - RH <i>at</i>	280.00 ✓	
34	1 PC TAIL LAMP PANEL LH <i>Replaced</i>	160.00 ✓	
35	1 PC REAR BUMPER <i>Distorted</i>	1,120.00 ✓	
36	1 PC REAR BUMPER REINFORCEMENT <i>new</i>	230.00 +	
37	2 PCS REAR BUMPER BRACKET <i>new</i>	70.00 +	
38	2 PCS REAR BUMPER SIDE RETAINER <i>new</i>	76.00 ✓	
39	2 PCS REAR BUMPER REFLECTOR <i>LH cancelled</i>	130.00 63	
40	2 PCS REAR BUMPER SCREW COVER <i>new</i>	36.00 +	
41	1 PC SPARE TYRE PANEL <i>Replaced</i>	1,514.00 +	
42	1 PC SPARE TYRE COVER <i>Replaced</i>	325.00 ✓	
43	1 PC SPARE TYRE PANEL SPONGE <i>new</i>	85.00 +	
44	1 PC REAR WINDSCREEN GLASS <i>shattered</i>	1,363.10 ✓	
45	1 PC REAR WINDSCREEN GLASS BOTTOM PANEL <i>Replaced</i>	665.10 +	
46	1 PC REAR WINDSCREEN GLASS PANEL TRIM <i>at</i>	588.20 ✓	
47	1 PC EXHAUST PIPE <i>Replaced</i>	1,208.00 +	
48	5 PCS EXHAUST PIPE MOULDING <i>new</i>	82.50 +	
49	1 PC REAR SHOCK ABSORBER LH	387.50 +	
50	1 PC REAR SHOCK ABSORBER MOUNTING LH	48.60 +	
51	1 PC REAR KNUCKLE ARM LH	359.40 +	
52	1 PC REAR KNUCKLE ARM CENTRE STAY BAR	109.00 +	
53	1 PC REAR KNUCKLE ARM TOP STAY BAR	115.50 +	
54	1 PC REAR KNUCKLE ARM RH STAY BAR	115.50 +	
55	1 PC REAR KNUCKLE ARM LH STAY BAR	115.50 +	
56	1 PC REAR WHEEL HUB LH	368.80 +	
		17,643.40	
		Less 20%	3,528.68
			14,114.72

Special Net

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK, MND COMPLEX
SINGAPORE 069110

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 13/06/2018
TP Veh Reg No: YM9273E

Estimate No: EST1800178

Date: 18 Jun 2018

Veh Reg No: SLD6046R
Make/Model: HONDA ACCORD 2.0A
Chasis No: CL73203118
Reg. Date: 10/01/2007
Your Ref No: YM9273E

Estimate Repair Cost to Vehicle No :SLD6046R

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
57	1 SET REVERSE CAMERA <i>Byd</i>	650.00 380	
58	1 SET BOOT LID TRIM CLIPS <i>re</i>	40.00 30	
59	1 PC REAR NUMBER PLATE <i>Best</i>	50.00 30	
60	1 PC REAR NUMBER PLATE BASE <i>Best</i>	50.00 30	
61	1 PC REAR IN CAR CAMERA <i>Byd</i>	650.00 420	
62	1 SET REAR FENDER COWLING CLIPS LH <i>re</i>	40.00 +	
63	1 SET REAR FENDER TRIM CLIPS LH <i>re</i>	40.00 30	
64	1 SET REAR FENDER TRIM CLIPS RH <i>re</i>	40.00 +	
65	1 SET REAR PANEL TRIM CLIPS <i>re</i>	40.00 10	
66	1 PC REAR BUMPER SPOILER <i>Dischld</i>	1,000.00 420	
67	1 PC REAR BUMPER LOWER SPOILER STICKER <i>re</i>	280.00 180	
68	1 SET REAR BUMPER LOWER SPOILER GARNISH CLIPS <i>re</i>	40.00 30	
69	1 SET REAR BUMPER CLIPS <i>re</i>	60.00 30	
70	1 PC REAR WINDSCREEN SEAL <i>3re</i>	60.00 30	
71	1 PC REAR WINDSCREEN SEALANT	60.00 30	
72	2 PCS REAR RADIO SPEAKER <i>2re</i>	700.00 +	
73	1 PC REAR SPORTS RIM LH <i>2130</i>	800.00 +	
		4,600.00	4,600.00
	Labour		
74	1 TOWING	80.00 60	
75	1 TO CHECK WIRING	80.00 30	
76	1 TO REMOVE AND REFIT IN CAR CAMERA	200.00 60	
77	1 TO REMOVE AND REFIT REVERSE CAMERA	200.00 60	
78	1 TO REMOVE AND REFIT FUEL TANK	180.00 80	
79	1 TO REMOVE AND REFIT REAR WINDSCREEN GLASS	120.00 ✓	
80	1 TO REMOVE AND REFIT SEAT CUSHION	250.00 120	
81	1 TO REMOVE AND REFIT RADIO SPEAKER	150.00 80	
82	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	180.00 80	
83	1 TO REMOVE AND REFIT UNDERCARRIAGE	450.00 x	
84	1 TO CHECK WHEEL ALIGNMENT	150.00 x	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autohub@Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S: EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK, MND COMPLEX
SINGAPORE 069110

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 13/06/2018
TP Veh Reg No: YM9273E

Estimate No: EST1800178
Date: 18 Jun 2018

Veh Reg No: SLD6046R
Make/Model: HONDA ACCORD 2.0A
Chasis No: CL73203118
Reg. Date: 10/01/2007
Your Ref No: YM9273E

Estimate Repair Cost to Vehicle No :SLD6046R

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
85	1 TO SPRAY UNDERSEAL	200.00 3890	100
86	1 (REAR) TO SPRAY PAINTING	2200.00	1500
87	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	3,000.00	1600
		7,440.00	7,440.00
	Total		S\$ 26,154.72
	Add GST @ 7%		1,830.83
	Total Amount Payable		<u>S\$ 27,985.55</u>

TOTAL: SINGAPORE DOLLAR TWENTY SEVEN THOUSAND NINE HUNDRED EIGHTY FIVE AND CENTS FIFTY FIVE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on an "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total 1312.08
4/5 10.5K
Adrian Lij
4/5 18/06/18.
14 Day
10.5K 1423.