

Surveyor
Menimen

ASSIGNMENT (Office)

From (Person)

Chong Boon Sen

of

CTI

Date/Time

19/6/2018 @ 6:10pm

Estimated Cost

Bill to

①

TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SLL 552 T

Insured

at Workshop n/s

Sng Ah Tee Motor

Tel

6268 6183

of

Blk 3, Pioneer Rd North # 01-18

Policy No

DMPCSN1711821801

Claim No

SNM18 D 02969C01

Sum Insured

Excess

\$ 1,000.00

Make of Veh

(Client's Record)

D.O.A

09/06/2018

CA / REV

/

REP

/

REV 24 HRS

22/06/2018 @ after 10am

Date/Time

20/06/2018

Person Contacted

joyce

H.O.D. Endorsement

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLL 552 T - CC3/CTI18010700/K/ea3 DOA 9/6/2018
25/6	Report via menimen.
27/6/18 @ 12.05pm	Susan Teo informed C/A via menimen.
27/6/18 @ 2.22pm	Informed Joyce C/A & ex=\$1000 by email.
14/11/18 @ 10.10am	confirmed with Sharon Annal Rg 3434.16, 4 days. (Red @ 2672, 44%)

REF: CTI

ASSIGNMENT

From

Date: 22/06/18

Veh No: SLL552T Yr Regn: 2017 Feb.

Estimated Cost:

Type: Motor / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

① TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

SLL 552T

Make:

Mando Benz GLAR0

C.G.

1595

at Workshop n/s

Sng Ah Tee

Colour:

Grey

A/C:

Insured / Std / NI / NA

at 81K 3, Pioneer Rd North #01-18

Sp Reading:

38555

T/Radio: Insured / Std / NI / NA

Insured

Eng/Nr:

WDC 15694225289480

Policy No.

C/No

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured

Excess: \$1,000.00

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

after 10am

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Mod: Nil / S/Rim / STD A/Rim or

(Policy Condition)


Tyre Size:

F:

235/50R18

R:

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Continental

Bal. or Market Value:

\$123K

Front

Rear

IDAC Accident Report:

Consistent? : Yes or No

R/Bal.

6

mm

R/Bal.

6

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6

mm

L/Bal.

6

mm

Est. Repair:

4

days

Res: Yes or No

D.O.A.

D.O.A.

22/6/180/145

Lump Sum:

%

3 Val: Yes or No

Survey held at

Sng Ah Tee

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

RECEIVED 14 NOV 2018

Date/Time: File Pass to?



: Prel. Report

Days Of Repair:

4

Date/Time: File Return to?



: Final Report

Resurvey No. of Trip:

1

Survey Fee:

20

Transportation:

1 x 2 x 20 = 40

1 x 100 = 100

1 x 100 = 100

1

TOTAL

220

Add Fee:



Site Insp: \$



Interview: \$



Tech Insp: \$



Weekend: \$

Report Format:

MER-00

Lump Sum / I.B.I: \$

3434.16

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins. Auth'd	Status
Main	19 Jun 2018 Sendback Est	19 Jun 2018 15:54 S\$5,903.16	19 Jun 2018 18:10 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	FUN WUN FAI ANDREW, ID: S1802006H, Tel: +6598233633		
Vehicle Reg. No.:	SLL552T	Date of Loss:	09/06/2018 22:00 - :59 [15 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D02969C01	Policy/Cover Note No.:	DMPCSN1711821801 (Comprehensive) Coverage: 13/02/2018 - 12/02/2019
		Excess:	S\$1,000.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/06/2018]		
Driver/Custodian:	CHOOI SYAD SENG (49 / Male), NRIC: S2593414H, Tel: +6594528670		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Shiau Chan (LKKAuto)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Wednesday, 14 November 2018 10:10 AM
To: Shiau Chan (LKKAuto); Taufikh (LKKAuto); SUR
Subject: RE: SLL552T - FINALISE & BEFORE PAINT

Hi Shiau Chan

we confirm. Pls offer in merimen.
thanks.

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Tuesday, November 13, 2018 5:27 PM
To: Sharon Sng <sharon@sngahtee.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: SLL552T - FINALISE & BEFORE PAINT

Dear Sharon,

WITHOUT PREJUDICE

Offer final fig \$3,434.16 before excess \$1,000.00 & GST and 4 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Wednesday, 17 October 2018 6:25 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: SLL552T - FINALISE & BEFORE PAINT

View Sent Message

This mail is associated with :

SLL552T (SNM18D02969C01)

OD

Jun 9 2018 10:00PM

[FUN WUN FAI ANDREW]

Sng Ah Tee Motor & Panel Service Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 09/11/2018 13:45 PM.

To CHINA_TAIPING

CC sur@lkkauto.com

Subject VEHICLE SLL 552T (YOUR REF: SNM18D02969C01)

Dear Boon Sen,

We have received supplementary of \$203.00 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident, within authorise limit and is economical to repair.

Thanks & Regards,

Shiau Chan (Ms)

LKK Auto Consultants Pte Ltd

Tel: 6256 3561

DOCUMENTS SUMMARY

There are no documents.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 27 June 2018 3:22 PM
To: admin@sngahtee.com
Cc: SUR
Subject: VEHICLE SLL 552T (DOA: 09/06/2018)

Dear Joyce,

As instructed by our client China Taiping Insurance, please proceed to repair the insured vehicle **SLL 552T (excess \$1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	19 Jun 2018 15:47	Cim Veh Model Changed	(204229) MERCEDES-BENZ GLA180 1.6 (A).	[R] Samantha Tan Yong Sing
2	19 Jun 2018 15:47	Cim Created	Reg No: SLL552T, Policy No: DMPCSN1711821801, Acct Date: 2018/06/09, Claim Type: OD, Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ), Workshop: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer). Created from SAS:MSAT18076698	[R] Samantha Tan Yong Sing
3	19 Jun 2018 15:54	Cim Submitted	5903.16.	[R] Samantha Tan Yong Sing
4	19 Jun 2018 18:10	Cim Registration Modified	Excess: -> 1000.00.	[I] Chong Boon Sen
5	19 Jun 2018 18:10	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):SURVEY REVERT	[I] Chong Boon Sen
6	19 Jun 2018 18:10	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/28	[I] Chong Boon Sen
7	19 Jun 2018 18:10	Adj Mandate Set	Approved:0.00.	[I] Chong Boon Sen
8	19 Jun 2018 18:32	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	20 Jun 2018 12:21	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
10	25 Jun 2018 14:19	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
11	25 Jun 2018 14:31	Adj Mandate Request	Cur.Req:5720.16:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
12	25 Jun 2018 14:34	Adj Mandate Request Cancelled		[A] DENISE TAY KWEE CHENG
13	25 Jun 2018 14:34	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/06/28	[A] DENISE TAY KWEE CHENG
14	25 Jun 2018 14:34	Adj Mandate Request	Cur.Req:5720.16:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
15	27 Jun 2018 12:05	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/28	[I] Susan Teo
16	27 Jun 2018 12:05	Adj Mandate Set	Approved:5720.16.	[I] Susan Teo

Date From



Date To



Audit Type

None

Go

ACTIVITY

[20/06/2018 09:26] Nivitha Govindasamy:

Repairer called and rearrange back on 22/06/2018.

[20/06/2018 09:24] Nivitha Govindasamy:

Vehicle not in workshop, repairer arrange on 21/06/2018.

Merimen Billing for this case - Transaction History

Bill Ref No.	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1836100	19/06/2018 15:47	Motor	Sng Ah Tee Motor & Panel Service Pte Ltd (HQ)	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	SLL552T		xx.xx
1840750	25/06/2018 14:19	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLL552T		10.70

LKK Auto Consultants Pte Ltd (Co.Reg.No:189607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 25 Jun 2018

Preliminary Advice

Vehicle No	: SLL552T	Accident Date	: 09/06/2018
Make	: MERCEDES-BENZ GLA180	Policy No.	: DMPCSN1711821801
Assignment Date	: 19/06/2018	Excess	: S\$1,000.00
Date of Inspection	: 25/06/2018	Est. Duration of Repair	: 5.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,903.16
Revised Amount	:S\$	3,307.16
Check Items (Estimated)	:S\$	2,413.00
Total	:S\$	5,720.16

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	123,000.00
COE / PARF Rebate	:S\$	63,762.00
Salvage Value	:S\$	
Margin for Repair	:S\$	59,238.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2006H

Vehicle Details

Vehicle No.: SLL552T
Vehicle to be Exported: No
Intended De-registration Date: 30 Jun 2018
Vehicle Make: MERCEDES BENZ
Vehicle Model: GLA180 (R18 B1)
Primary Colour: Grey
Manufacturing Year: 2016
Engine No.: 27091031056490
Chassis No.: WDC1569422J289480
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$28,886.00
Original Registration Date: 13 Feb 2017
First Registration Date: 13 Feb 2017
Transfer Count: 0
Actual ARF Paid: \$27,441.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 12 Feb 2027
PARF Rebate Amount: \$20,580.00

Intended COE Rebate Details

COE Expiry Date: 12 Feb 2027
COE Category: A - Car up to 1600cc & 97kW (130php)
COE Period(Years): 10
QP Paid: \$50,101.00
COE Rebate Amount: \$43,182.00
Total Rebate Amount: \$63,762.00

The information contained herein is correct as at 13 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/06/2018 14:29
Date Of Accident	09/06/2018 22:00
Exact Location Of Accident	THOMSON RD OUTSIDE SHELL PETROL STATION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL552T
Insured/Policyholder	
Name Of Registered Owner	FUN WUN FAI ANDREW
NRIC No	S1802006H
Email Address	AFUN1500@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98233633
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	GLA180-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1711821801
Cover Note Number	

Driver

Name of Driver	CHOOI SYAD SENG
NRIC No	S2593414H
Date Of Birth	01/02/1969
Occupation	INDOOR
Date Of Driving Pass	29/07/1992
Driving Experience	25 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94528670
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 21 OXFORD RD #06-02
Postcode	218817
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 09/06/2018 AT AROUND 2200HRS. I WAS TRAVELLING ALONG THOMSON RD TOWARDS THE PETROL STATION SHELL. I WAS ON THE MIDDLE LANE AS I SAW VEHICLE B WAS STATIONARY AT THAT TIME TO PICK UP CUSTOMER. I SLOWLY MAKE MY WAY TO LEFT TO OVERTAKE HIM AND ALLOW MY VEHICLE TO PROCEED TO TURN INTO IT, I FEEL IMPACT FROM MY LEFT THEN I STOP AND WENT DOWN TO SEE AND NOTICES VEHICLE HAD COLLIDED ONTO MY LEFT SIDE PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB4424D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	TAN KIM CHOON
NRIC/Passport Number	S1354507C
Contact Number	94592223
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 09/06/2018 @ around 22:00 hrs, I was travelling along Thompson RD toward the petrol station Shell. I was on the middle lane as I saw Vehicle B was stationary at that time to pick up customer. I slowly make my way to left to overtake him and allow my vehicle to proceed to turn into the Shell petrol station. But suddenly I almost going to turn into it, I feel impact from my left then I stop & went down to see and notices Vehicle B had Collided onto my left side portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

☐ Claim own policy
☐ Claim third party
☐ Claim OD / TP at other works hop
☐ For record purpose
Policy No. DMPCAN711821301
Insurer CHINA Veh. No. SL5527

**SNG AH TEE MOTOR &
PANEL SERVICE PTE LTD
3 PIONEER ROAD NORTH
#01-18
SINGAPORE 628457**

Claim Reference:
Assessment Number: DS000493
Version: SNGAHTTE/4

Full Report - V1
Registration: SLL552T
Printed: 19/06/2018 15:37

Summary Information

Claim

Location: Singapore (SG)
Printed by: SNG AH TEE
Authorisation Status: Interim
Work Provider: China Taiping Insurance (S) Pte

Currency: SGD
Date of Incident: 09/06/2018
Able to Authorise Repairs: TBA
Repairs Authorised: TBA

Claim Reference:
Policy Number: DMCPN1711821801
Other Reference:
Third Party:
Insured Amount:
Under Warranty:
Warranty Expired:

Estimated Repair Time:
Quote Due Date:
Actual Repair Days:
Parts Ordered Date:
Hire Car Start:
Hire Car End:
Vehicle Collected:

*Tan Jiah 97495746
22/6/18 11:40*
Ex \$1000
Not Authorise
4-5 days
Resurvey before print
sur @ lkkauto.com

Vehicle Details

Vehicle

Manufacturer: MERCEDES
Model: GLA Class
Sub Model: 180
Model Sheet Number: 3GA 43
Registration: SLL552T
Registration Month:
Registration Year:
VIN Number: WDC1569422J289480
Odometer: Not Known
Colour:
Engine Number:
Fuel Level: %

Model Specs

FR J217874/ L040733
MODEL 2017
KEYLESS GO
MIRROR PACKAGE
ELECT FOLDING MIRROR
BI-XENON HEADLAMPS
LIGHT-/VIEW PACKAGE
DIPPING AUTOM MIRROR
URBAN PACK
SILL MLDG ILLUMINAT
DRIVER SEAT MEMORY
ELECT LUMBAR ADJUST
SEAT COMFORT PACKAGE
REARVIEW CAMERA
STORAGE PACKAGE
TYRE PRESSURE SENSOR
CRUISE CONTROL
7 SPEED AUTOMATIC
DYNAMIC SEL SWITCH
COMPRESSOR VARIABLE
ELECTRIC HORN
A/C THERMATIC
RAIN-/DR/LIGHT SENS
COLLISION WARNER
AUDIO SYSTEM 20 CD
ILLUMINAT AMBIENTE
HEADLAMP WASHER UNIT
CLOTH/IMI LEATH PAD
MULTI FUNCT S-WHEEL
LEATHER STRG WHEEL
PASS SEAT MEMORY
RAISED SUSPENSION
DECORATION ANTHRACIT
EMISSION STD EURO 6
ECO START/STOP
EASY-PACK
STRG COLUMN SHIFT
TYRES 215/55 HR 18
WHEELS 7J X 18 ALLOY
CLEAR COAT HARD

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Complementary item(s) must be resurveyed and subject to final approval from Insurance Company

Vehicle Condition

Vehicle Status

Pre-Accident Condition: *Noted by Repairer*
Steering: *OK*

Severity of Impact:
Vehicle Status on Inspection:

Brakes Pedal Travel:
Place of Inspection:
Pre-Accident Damage:

Date of Inspection: 14/06/2018

Tyres Condition:
Tread Depth LHF:


Tread Depth RHF:

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD


Claim Reference:
Assessment Number: DS000493
Version: SNGAHTTE/4

Full Report - V1
Registration: SLL552T
Printed: 19/06/2018 15:37

Tread Depth LHR:
Damage Areas:



Tread Depth RHR:
Direction of Impact:



Addresses

Cost Summary

Total Labour	\$894.60
Total Paint/Material	\$152.56
Total Parts	\$4,816.00
Total of Additional Costs	\$40.00
Excess:	TBA
Grand Total Exc GST:	\$5,903.16
7 % GST:	\$413.22
Grand Total Inc GST:	\$6,316.38

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$0.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY	3.0	12.60
54-7989 01	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	8.40
72-1450 01	RENEW L/F DOOR AND CONVERT PARTS INCLUDES: DOOR TRIM REMOVE AND REFIT AND ALL ATTACHED PARTS ASSEMBLE	31.0	130.20
72-6665 01)	RENEW L/F DOOR TRIM (REMOVED)	5.0	21.00
72-5886 01	RENEW LEFT FRONT DOOR BASIS SUPPORT (DOOR MODULE REMOVED)	5.0	21.00
72-4570 01	R + R LEFT FRONT DOOR LOCK STRIKER	3.0	12.60
72-1590 01	RENEW L/R DOOR AND CONVERT PARTS INCLUDES: DOOR TRIM REMOVE AND REFIT AND ALL ATTACHED PARTS ASSEMBLE	31.0	130.20
72-2697 01	RENEW L/R UPPER DOOR HINGE	3.0	12.60
72-5887 01	RENEW LEFT REAR DOOR BASIS SUPPORT (DOOR MODULE REMOVED)	4.0	16.80
88-5205 01	R + R LEFT SILL TRIM	5.0	21.00
88-6976 01	R + R LEFT REAR LOWER WING CLOSING PANEL	3.0	12.60
68-1093 01	R + R LEFT B-PILLAR LOWER TRIM	5.0	21.00
68-1240 01)	R + R LEFT REAR SIDE TRIM	4.0	16.80
68-5570 01	R + R PARCEL SHELF	1.0	4.20
91-5404 01)	R + R LEFT REAR SEAT BACK REST	3.0	12.60

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:
Assessment Number: DS000493
Version: SNGAHTTE/4

Full Report - V1
Registration: SLL552T
Printed: 19/06/2018 15:37

91-5053 01	R + R REAR SEAT CUSHION	3.0	12.60
2083	REPAIR L/F DOOR FRAME	15.0*	63.00
LABOUR COST			
Total Work Units		126.0	
Sub Total		12.6HRS	\$529.20
Paint Labour		8.7HRS	365.40
Total Labour		21.3HRS	\$894.60

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$42.00/HR	
Guide Number	Description	WU	Cost Price (\$)
98-4015 01	LEFT FRONT DOOR PAINTING STAGE I-M	14.0	
98-4115 01	L/R DOOR PAINTING STAGE I-M	13.0	
98-5557 01	L/F DOOR FRAME PAINTING STAGE III	11.0	
98-5057 01	L/SILL PANEL PAINTING STAGE III	11.0	
98-5517 01	L/OUTER A-PILLAR PAINTING STAGE III	7.0	
98-1710 ZAX	L/F DOOR HANDLE CVR PAINTING	1.0	
98-1710 ZAX	L/F DOOR OUT HANDLE PAINTING	1.0	
98-1881 01	L/DOOR MIRROR HSG PAINTING	3.0	
98-1710 ZAX	L/R DOOR HANDLE TRIMPAINTING	1.0	
98-1710 ZAX	L/R DOOR OUT HANDLE PAINTING	1.0	
98-7046 01	L/R WING PAINTING STAGE II	10.0	
98-1340 01	WITH ROOF SIDE PANELLING LESS DOOR SHUT PREPARATION WORK FOR TWO COAT PAINTING OF FITTED BODY PARTS	14.0	
LABOUR COST - PAINT		0.0	
TIME(PAINT)		0.0	
Total Work Units (10WU/HR)		87.0	
Total Paintwork Labour		8.7HRS	\$365.40
MATERIAL COST - PAINT			Cost Price
Total Excluding Pearlescent Uplift			\$152.56
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$152.56

PARTS

					Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1479	1	L/F DOOR MODULE <i>regulator</i>	176 720 6500		0%	350.00* <i>x nm</i>
1481	1	LEFT FRONT DOOR	156 720 0105		0%	850.00* <i>880</i>
1509	1	L/F DOOR SEAL	204 727 1187		0%	145.00* <i>neu</i>
1551	1	L/F WINDOW MOTOR	246 906 5100		0%	285.00* <i>?</i>
1577	1	L/F DOOR LOCK	166 720 0335		0%	165.00* <i>?</i> <i>x ni</i>
1655	1	L/F DOOR TRIM REAR	156 722 0328		0%	65.00* <i>?</i>
1661	1	L/F OUT WINDOW SEAL	156 725 0182 28		0%	98.00* <i>?</i> <i>x nm</i>
1707	1	L/F LWR DOOR SPEAKER	246 820 0100		0%	88.00* <i>X</i> <i>nm</i>
1713	1	L/F DOOR TRIM	156 720 2500		0%	550.00* <i>?</i> <i>x nm</i>
			9D88			
1781	1	L/R DOOR	156 730 0105		0%	980.00* <i>1000</i> <i>bt</i>
1791	1	L/R UPPER DOOR HINGE	176 730 0537		0%	55.00* <i>?</i>
1793	1	L/R DOOR MODULE	176 730 3800		0%	350.00* <i>?</i> <i>x ni</i>
1795	1	L/R LOWER DOOR HINGE	176 730 0337		0%	55.00* <i>?</i>
1809	1	L/R DOOR SEAL	204 727 1187		0%	145.00* <i>neu</i>
1851	1	L/R WINDOW MOTOR	246 906 3100		0%	300.00* <i>?</i> <i>x</i>
1919	1	L/R CHANNEL SEAL	156 735 0465		0%	35.00* <i>?</i> <i>wh</i>

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:
Assessment Number: DS000493
Version: SNGAHTTE/4

Full Report - V1
Registration: SLL552T
Printed: 19/06/2018 15:37

1947	1	L/R DOOR TRIM FRONT	156 732 0329	0%	X	75.00*	} n
1961	1	L/R DOOR WINDOW SEAL	156 735 0182	0%	?	105.00*	
1000	1	FRT DOOR TRIMBOARD	RIVET X8	0%	X	20.00*	
f: OEM Parts			Sub Total			\$4,716.00	
g: Original			Sundry Parts	(Fixed)		\$100.00	
h: Secondhand			Total Parts			\$4,816.00	
p: Parallel							
x: Exchange							

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FENDER GLASS SEALANT	0%	\$40.00
	Total Extras	\$40.00

Final Calculation

Total Parts	\$4,816.00
Labour	
Total Panel/Mechanical	\$529.20
Total Paintwork	\$365.40
Total Labour	\$894.60
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$40.00
Total of Additional Costs	\$40.00
Total Paint/Material Costs	\$152.56
Grand Total Excludes GST	\$5,903.16
GST @ 7 %	\$413.22
Grand Total Includes GST	\$6,316.38

Assessment Notes

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference: SNM18D02949C01
Assessment Number: DS000493
Version: LKKAUTOC/2
Date Calculated: 25/06/2018 07:07

Full Report - V1
Registration: SLL552T
Printed: 25/06/2018 14:24

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	09/06/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM18D02949C01	Estimated Repair Time:	
Policy Number:	DMCPSN1711821801	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	GLA Class
Sub Model:	180
Model Sheet Number:	3GA 43
Registration:	SLL552T
Registration Month:	
Registration Year:	
VIN Number:	WDC1569422J289480
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FR J217874/ L040733	ELECTRIC HORN
MODEL 2017	A/C THERMATIC
KEYLESS GO	RAIN-/DR/LIGHT SENS
MIRROR PACKAGE	COLLISION WARNER
ELECT FOLDING MIRROR	AUDIO SYSTEM 20 CD
BI-XENON HEADLAMPS	ILLUMINAT AMBIENTE
LIGHT-/VIEW PACKAGE	HEADLAMP WASHER UNIT
DIPPING AUTOM MIRROR	CLOTH/IMI LEATH PAD
URBAN PACK	MULTI FUNCT S-WHEEL
SILL MLDG ILLUMINAT	LEATHER STRG WHEEL
DRIVER SEAT MEMORY	PASS SEAT MEMORY
ELECT LUMBAR ADJUST	RAISED SUSPENSION
SEAT COMFORT PACKAGE	DECORATION ANTHRACIT
REARVIEW CAMERA	EMISSION STD EURO 6
STORAGE PACKAGE	ECO START/STOP
TYRE PRESSURE SENSOR	EASY-PACK
CRUISE CONTROL	STRG COLUMN SHIFT
7 SPEED AUTOMATIC	TYRES 215/55 HR 18
DYNAMIC SEL SWITCH	WHEELS 7J X 18 ALLOY
COMPRESSOR VARIABLE	CLEAR COAT HARD

Vehicle Condition


Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	14/06/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:


51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore
Claim Reference: SNM18D02949C01
Assessment Number: DS000493
Version: LKKAUTOC/2
Date Calculated: 25/06/2018 07:07

Full Report - V1
Registration: SLL552T
Printed: 25/06/2018 14:24

Tread Depth LHR:
 Damage Areas:



Tread Depth RHR:
 Direction of Impact:



Addresses

Cost Summary

Total Labour	\$894.60
Total Paint/Material	\$152.56
Total Parts	\$4,633.00
Total of Additional Costs	\$40.00
Repair Cost Exc GST:	\$5,720.16
Overall Discount (0.0%):	- \$0.00
Excess:	-\$1,000.00
After Deduction -	
Grand Total Exc GST:	\$4,720.16
7 % GST:	\$330.41
Grand Total Inc GST:	\$5,050.57

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
 Price/Dent = \$0.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY	3.0	12.60
54-7989 01	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	8.40
72-1450 01	RENEW L/F DOOR AND CONVERT PARTS INCLUDES: DOOR TRIM REMOVE AND REFIT AND ALL ATTACHED PARTS ASSEMBLE	31.0	130.20
72-6665 01)	RENEW L/F DOOR TRIM (REMOVED)	5.0	21.00
72-5886 01	RENEW LEFT FRONT DOOR BASIS SUPPORT (DOOR MODULE REMOVED)	5.0	21.00
72-4570 01	R + R LEFT FRONT DOOR LOCK STRIKER	3.0	12.60
72-1590 01	RENEW L/R DOOR AND CONVERT PARTS INCLUDES: DOOR TRIM REMOVE AND REFIT AND ALL ATTACHED PARTS ASSEMBLE	31.0	130.20
72-2697 01	RENEW L/R UPPER DOOR HINGE	3.0	12.60
72-5887 01	RENEW LEFT REAR DOOR BASIS SUPPORT (DOOR MODULE REMOVED)	4.0	16.80
88-5205 01	R + R LEFT SILL TRIM	5.0	21.00
88-6976 01	R + R LEFT REAR LOWER WING CLOSING PANEL	3.0	12.60
68-1093 01	R + R LEFT B-PILLAR LOWER TRIM	5.0	21.00

68-1240 01)	R + R LEFT REAR SIDE TRIM	4.0	16.80
68-5570 01	R + R PARCEL SHELF	1.0	4.20
91-5404 01)	R + R LEFT REAR SEAT BACK REST	3.0	12.60
91-5053 01	R + R REAR SEAT CUSHION	3.0	12.60
2083	REPAIR L/F DOOR FRAME	15.0*	63.00

LABOUR COST

Total Work Units	126.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	12.6HRS	\$529.20
Paint Labour	8.7HRS	\$365.40
Total Labour	21.3HRS	\$894.60

PAINT WORK	Time Basis 10 WU = 1 HR. Price = \$42.00/HR
Guide Number Description	WU Cost Price (\$)

98-4015 01	LEFT FRONT DOOR PAINTING STAGE I-M	14.0	
98-4115 01	L/R DOOR PAINTING STAGE I-M	13.0	
98-5557 01	L/F DOOR FRAME PAINTING STAGE III	11.0	
98-5057 01	L/SILL PANEL PAINTING STAGE III	11.0	
98-5517 01	L/OUTER A-PILLAR PAINTING STAGE III	7.0	
98-1710 ZAX	L/F DOOR HANDLE CVR PAINTING	1.0	
98-1710 ZAX	L/F DOOR OUT HANDLE PAINTING	1.0	
98-1881 01	L/DOOR MIRROR HSG PAINTING	3.0	
98-1710 ZAX	L/R DOOR HANDLE TRIMPAINTING	1.0	
98-1710 ZAX	L/R DOOR OUT HANDLE PAINTING	1.0	
98-7046 01	L/R WING PAINTING STAGE II	10.0	
	WITH ROOF SIDE PANELLING LESS DOOR SHUT		
98-1340 01	PREPARATION WORK FOR TWO COAT PAINTING OF FITTED BODY PARTS	14.0	

LABOUR COST - PAINT

TIME(PAINT)	0.0	
Total Work Units (10WU/HR)	87.0	
Total Paintwork Labour	8.7HRS	\$365.40

MATERIAL COST - PAINT

Total Excluding Pearlescent Uplift		\$152.56
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$152.56

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1479	1	L/F DOOR MODULE	176 720 6500		0%	350.00*
1481	1	LEFT FRONT DOOR	156 720 0105		0%	850.00*
1509	1	L/F DOOR SEAL	204 727 1187		0%	145.00*
1551	1	L/F WINDOW MOTOR	246 906 5100		0%	285.00*
1577	1	L/F DOOR LOCK	166 720 0335		0%	165.00*
1655	1	L/F DOOR TRIM REAR	156 722 0328		0%	65.00*
1661	1	L/F OUT WINDOW SEAL	156 725 0182 28		0%	98.00*
1713	1	L/F DOOR TRIM	156 720 2500 9D88		0%	550.00*
1781	1	L/R DOOR	156 730 0105		0%	980.00*
1791	1	L/R UPPER DOOR HINGE	176 730 0537		0%	55.00*

Price Valid: 01/06/2015

1793	1	L/R DOOR MODULE	176 730 3800	0%	350.00*
1795	1	L/R LOWER DOOR HINGE	176 730 0337	0%	55.00*
1809	1	L/R DOOR SEAL	204 727 1187	0%	145.00*
1851	1	L/R WINDOW MOTOR	246 906 3100	0%	300.00*
1919	1	L/R CHANNEL SEAL	156 735 0465	0%	35.00*
1961	1	L/R DOOR WINDOW SEAL	156 735 0182	0%	105.00*
f: OEM Parts			Sub Total		\$4,533.00
g: Original			Sundry Parts	(Fixed)	\$100.00
h: Secondhand			Total Parts		\$4,633.00
p: Parallel					
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FENDER GLASS SEALANT	0%	\$40.00
	Total Extras	\$40.00

Final Calculation

Total Parts		\$4,633.00
Labour		
Total Panel/Mechanical	\$529.20	
Total Paintwork	\$365.40	
Total Labour		\$894.60
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$40.00	
Total of Additional Costs		\$40.00
Total Paint/Material Costs		\$152.56
Repair Costs Excludes GST		\$5,720.16
Deductions		
Deduction for Excess (Fixed)	-\$1,000.00	
Total Deductions		-\$1,000.00
Grand Total Excludes GST (After Deduction)		\$4,720.16
GST @ 7 %		\$330.41
Grand Total Includes GST (After Deduction)		\$5,050.57

Assessment Notes

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg;darren@sngahtee.com;janice@sngahtee.com

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPCSN1711821801	Date of Loss:	09/06/2018
Vehicle Reg. No.:	SLL552T	Driveable?	
Driver Age/Info:	49 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	FUN WUN FAI ANDREW	Contact No:	+6598233633
Driver:	CHOOI SYAD SENG		
Make/Model:	MERCEDES-BENZ GLA180, 1.6 (A)	Vehicle Reg. Date:	13/02/2017
Vehicle Colour:	GREY	Chassis No:	WDC1569422J289480
Engine No:	27091031056490		
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	ON 09/06/2018 AT AROUND 2200HRS, I WAS TRAVELLING ALONG THOMSON RD TOWARDS THE PETROL STATION SHELL. I WAS ON THE MIDDLE LANE AS I SAW VEHICLE B WAS STATIONARY AT THAT TIME TO PICK UP CUSTOMER. I SLOWLY MAKE MY WAY TO LEFT TO OVERTAKE HIM AND ALLOW MY VEHICLE TO PROCEED TO TURN INTO IT, I FEEL IMPACT FROM MY LEFT THEN I STOP AND WENT DOWN TO SEE AND NOTICES VEHICLE HAD COLLIDED ONTO MY LEFT SIDE PORTION.		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS	Amount
Parts	4,856.00
Miscellaneous Items	0.00
Labour	1,047.16
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,903.16
+ GST 7.00% (S\$)	413.22
Nett Amount (S\$)	6,316.38

This claim is handled by: **SAMANTHA TAN YONG SING**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Jun 2018)

Parts: M1-SUV MERCEDES-BENZ GLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/SLL552T/19/06/2018 15:54

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FRT DOOR TRIMBOARD	0.00	0.00	*20.00 F X/m
2	1	NA	*L/F DOOR LOCK	0.00	0.00	*165.00 F X/m
3	1	NA	*L/F DOOR MODULE	0.00	0.00	*350.00 F X/m
4	1	NA	*L/F DOOR SEAL	0.00	0.00	*145.00 F X/m
5	1	NA	*L/F DOOR TRIM	0.00	0.00	*550.00 F X/m
6	1	NA	*L/F DOOR TRIM REAR	0.00	0.00	*65.00 F X/m
7	1	NA	*L/F LWR DOOR SPEAKER	0.00	0.00	*88.00 F X/m
8	1	NA	*L/F OUT WINDOW SEAL	0.00	0.00	*98.00 F X/m
9	1	NA	*L/F WINDOW MOTOR	0.00	0.00	*285.00 F X/m
10	1	NA	*L/R CHANNEL SEAL	0.00	0.00	*35.00 F X/m
11	1	NA	*L/R DOOR	0.00	0.00	*980.00 F X/m
12	1	NA	*L/R DOOR MODULE	0.00	0.00	*350.00 F X/m
13	1	NA	*L/R DOOR SEAL	0.00	0.00	*145.00 F X/m
14	1	NA	*L/R DOOR TRIM FRONT	0.00	0.00	*75.00 F X/m
15	1	NA	*L/R DOOR WINDOW SEAL	0.00	0.00	*105.00 F X/m
16	1	NA	*L/R LOWER DOOR HINGE	0.00	0.00	*55.00 F X/m
17	1	NA	*L/R UPPER DOOR HINGE	0.00	0.00	*55.00 F X/m
18	1	NA	*L/R WINDOW MOTOR	0.00	0.00	*300.00 F X/m
19	1	NA	*LEFT FRONT DOOR	0.00	0.00	*850.00 F X/m
20	1	NA	*SPECIALIST FENDER GLASS SEALANT	0.00	0.00	*40.00 F X/m
21	1	NA	*SUNDRY PARTS	0.00	0.00	*100.00 F X/m

F=Franchise part.

Total Parts (S\$)

4,856.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SLL552T/19/06/2018 15:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Total Paint Labour	New	365.40
2	Total Paint Materials	New	152.56
3	Total Panel/Mechanical Labour	New	403.70 529.20
Gross Labour Cost (S\$)			1,047.16

Sng Ah Tee Motor & Panel Service Pte Ltd/SL552T/19/06/2018 15:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)Blk 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

(SUPPLEMENTARY)**INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPCSN1711821801	Date of Loss:	09/06/2018
Vehicle Reg. No.:	SLL552T	Driveable?	
Driver Age/Info:	49 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	FUN WUN FAI ANDREW	Contact No:	+6598233633
Driver:	CHOOI SYAD SENG		
Make/Model:	MERCEDES-BENZ GLA180, 1.6 (A)	Vehicle Reg. Date:	13/02/2017
Vehicle Colour:	GREY	Chassis No:	WDC1569422J289480
Engine No:	27091031056490		
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	ON 09/06/2018 AT AROUND 2200HRS, I WAS TRAVELLING ALONG THOMSON RD TOWARDS THE PETROL STATION SHELL. I WAS ON THE MIDDLE LANE AS I SAW VEHICLE B WAS STATIONARY AT THAT TIME TO PICK UP CUSTOMER. I SLOWLY MAKE MY WAY TO LEFT TO OVERTAKE HIM AND ALLOW MY VEHICLE TO PROCEED TO TURN INTO IT, I FEEL IMPACT FROM MY LEFT THEN I STOP AND WENT DOWN TO SEE AND NOTICES VEHICLE HAD COLLIDED ONTO MY LEFT SIDE PORTION.		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS	Amount
Parts	203.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	203.00
+ GST 7.00% (\$\$)	14.21
Nett Amount (\$\$)	217.21
+ Previous Estimates (\$\$)	6,316.38
Claim Total (\$\$)	6,533.59

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 17 Oct 2018)**Parts:** M1-SUV MERCEDES-BENZ GLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Sng Ah Tee Motor & Panel Service Pte Ltd/SLL552T/17/10/2018 15:52**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*L/R PROTECTION FOIL	0.00	0.00	20.00 F
2	1		*RIVET(FRT&RR LH)X15	0.00	0.00	33.00 F
3	1		*SPECIALIST DIAGNOSE & CLEAR CODE	0	0.00	150.00 FS

F=Franchise part. S=SpclNett.

Total Parts (S\$) **203.00**

Sng Ah Tee Motor & Panel Service Pte Ltd/SLL552T/17/10/2018 15:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Sng Ah Tee Motor & Panel Service Pte Ltd/SLL552T/17/10/2018 15:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**SNG AH TEE MOTOR &
PANEL SERVICE PTE LTD
3 PIONEER ROAD NORTH
#01-18
SINGAPORE 628457**

Claim Reference:
Assessment Number: DS000493
Version: SNGAHTEE/5
Date Calculated: 17/10/2018 09:08

Full Report - V1
Registration: SLL552T
Printed: 17/10/2018 18:10

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SNG AH TEE	Date of Incident:	09/06/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMCPSN1711821801	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	GLA Class
Sub Model:	180
Model Sheet Number:	3GA 43
Registration:	SLL552T
Registration Month:	
Registration Year:	
VIN Number:	WDC1569422J289480
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FR J217874/ L040733	ELECTRIC HORN
MODEL 2017	A/C THERMATIC
KEYLESS GO	RAIN-/DR/LIGHT SENS
MIRROR PACKAGE	COLLISION WARNER
ELECT FOLDING MIRROR	AUDIO SYSTEM 20 CD
BI-XENON HEADLAMPS	ILLUMINAT AMBIENTE
LIGHT-/VIEW PACKAGE	HEADLAMP WASHER UNIT
DIPPING AUTOM MIRROR	CLOTH/IMI LEATH PAD
URBAN PACK	MULTI FUNCT S-WHEEL
SILL MLDG ILLUMINAT	LEATHER STRG WHEEL
DRIVER SEAT MEMORY	PASS SEAT MEMORY
ELECT LUMBAR ADJUST	RAISED SUSPENSION
SEAT COMFORT PACKAGE	DECORATION ANTHRACIT
REARVIEW CAMERA	EMISSION STD EURO 6
STORAGE PACKAGE	ECO START/STOP
TYRE PRESSURE SENSOR	EASY-PACK
CRUISE CONTROL	STRG COLUMN SHIFT
7 SPEED AUTOMATIC	TYRES 215/55 HR 18
DYNAMIC SEL SWITCH	WHEELS 7J X 18 ALLOY
COMPRESSOR VARIABLE	CLEAR COAT HARD

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on
	Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	14/06/2018
Pre-Accident Damage:	

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000493

Version: SNGAHTEE/5

Date Calculated: 17/10/2018 09:08

Full Report - V1

Registration: SLL552T

Printed: 17/10/2018 18:10

Tyres Condition:

Tread Depth LHF:



Tread Depth LHR:

Damage Areas:

Tread Depth RHF:

Tread Depth RHR:

Direction of Impact:



Addresses

Cost Summary

Total Labour	\$789.60
Total Paint/Material	\$150.94
Total Parts	\$2,323.00
Total of Additional Costs	\$190.00
Excess:	TBA
Grand Total Exc GST:	\$3,453.54
7 % GST:	\$241.75
Grand Total Inc GST:	\$3,695.29

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$0.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
54-7989 01	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	8.40
72-1450 01	RENEW L/F DOOR AND CONVERT PARTS INCLUDES: DOOR TRIM REMOVE AND REFIT AND ALL ATTACHED PARTS ASSEMBLE	31.0	130.20
88-3424 01	R + R L/OUTER MIRROR HOUSING	3.0	12.60
72-4570 01	R + R LEFT FRONT DOOR LOCK STRIKER	3.0	12.60
72-7933 01	R + R LEFT FRONT DOOR EDGE PROTECTION	3.0	12.60
72-1590 01	RENEW L/R DOOR AND CONVERT PARTS INCLUDES: DOOR TRIM REMOVE AND REFIT AND ALL ATTACHED PARTS ASSEMBLE	31.0	130.20
72-7935 01	R + R LEFT REAR DOOR EDGE PROTECTION	2.0	8.40
88-5205 01	R + R LEFT SILL TRIM	5.0	21.00
88-6976 01	R + R LEFT REAR LOWER WING CLOSING PANEL	3.0	12.60
68-1093 01	R + R LEFT B-PILLAR LOWER TRIM	5.0	21.00
68-1240 01)	R + R LEFT REAR SIDE TRIM	4.0	16.80
68-5570 01	R + R PARCEL SHELF	1.0	4.20
91-5404 01)	R + R LEFT REAR SEAT BACK REST	3.0	12.60
91-5053 01	R + R REAR SEAT CUSHION	3.0	12.60
2083	REPAIR L/F DOOR FRAME	5.0*	21.00

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000493

Version: SNGAHTEE/5

Date Calculated: 17/10/2018 09:08

Full Report - V1

Registration: SLL552T

Printed: 17/10/2018 18:10

LABOUR COST

Total Work Units	104.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	10.4HRS	\$436.80
Paint Labour	8.4HRS	\$352.80
Total Labour	18.8HRS	\$789.60

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

Guide Number	Description	WU	Cost Price (\$)
98-4015 01	LEFT FRONT DOOR PAINTING STAGE I-M	14.0	
98-4115 01	L/R DOOR PAINTING STAGE I-M	13.0	
98-5557 01	L/F DOOR FRAME PAINTING STAGE III	11.0	
98-5057 01	L/SILL PANEL PAINTING STAGE III	11.0	
98-5517 01	L/OUTER A-PILLAR PAINTING STAGE III	7.0	
98-1710 ZAX	L/F DOOR HANDLE CVR PAINTING	1.0	
98-1710 ZAX	L/F DOOR OUT HANDLE PAINTING	1.0	
98-1710 ZAX	L/R DOOR HANDLE TRIMPAINTING	1.0	
98-1710 ZAX	L/R DOOR OUT HANDLE PAINTING	1.0	
98-7046 01	L/R WING PAINTING STAGE II	10.0	
98-1340 01	WITH ROOF SIDE PANELLING LESS DOOR SHUT PREPARATION WORK FOR TWO COAT PAINTING OF FITTED BODY PARTS	14.0	

LABOUR COST - PAINT

TIME(PAINT)	0.0	
Total Work Units (10WU/HR)	84.0	
Total Paintwork Labour	8.4HRS	\$352.80

MATERIAL COST - PAINT

Total Excluding Pearlescent Uplift	\$150.94
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$150.94

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1481	1	LEFT FRONT DOOR	156 720 0105		0%	880.00*
1509	1	L/F DOOR SEAL	204 727 1187		0%	145.00*
1781	1	L/R DOOR	156 730 0105		0%	1,000.00*
1809	1	L/R DOOR SEAL	204 727 1187		0%	145.00*
3487	1	L/R PROTECTION FOIL	156 732 0111		0%	20.00*
1000	1	RIVET(FRT&RR LH)X15	DOOR TRIM PANEL		0%	33.00*
f: OEM Parts			Sub Total			\$2,223.00
g: Original			Sundry Parts	(Fixed)		\$100.00
h: Secondhand			Total Parts			\$2,323.00
p: Parallel						
x: Exchange						

Price Valid: 01/06/2015

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FENDER GLASS	SPECIALIST	0%
SEALANT		\$40.00
DIAGNOSE&CLEAR	SPECIALIST	
CODE		\$150.00

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD**Claim Reference:****Full Report - V1****Assessment Number: DS000493****Registration: SLL552T****Version: SNGAHTEE/5****Printed: 17/10/2018 18:10****Date Calculated: 17/10/2018 09:08****Total Extras \$190.00****Final Calculation****Total Parts \$2,323.00****Labour**

Total Panel/Mechanical \$436.80

Total Paintwork \$352.80

Total Labour \$789.60**Additional Costs**

Corr Prot Materials External \$0.00

Corr Prot Materials Internal \$0.00

Cost of Specialist \$190.00

Total of Additional Costs \$190.00**Total Paint/Material Costs \$150.94****Grand Total Excludes GST \$3,453.54**


GST @ 7 % \$241.75

Grand Total Includes GST \$3,695.29**Assessment Notes**



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



D182418

REPRINT

TAX INVOICE

SNG AH TEE MOTOR & PANEL SERVICE P L
BLK 3 PIONEER ROAD NORTH
#01-18
SINGAPORE 628457
REMARK : SLL552T BY 92309747

DELIVER TO :

INV NO : I182418
DATE : 09/07/2018
A/C NO : 307680
TERM : 30
PAGE : 1 OF 1
ISSUE : TKS

Printed on 10/07/2018 16:28:48

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	000 991 5932MB	RIVET	SS2A30	22	PC	1.50	33.00
2	156 720 0105MB	FRT DOOR LH	DC	1	PC	880.00	880.00
3	156 730 0105MB	RR DOOR LH	DC	1	PC	1,000.0	1,000.00
4	156 732 0111MB	REAR DOOR GUARD PLATE LH	DC	1	PCS	20.00	20.00
5	204 727 1187MB	DOOR RUBBER LH&RH	SS3E11	2	PCS	145.00	290.00

RECEIVED BY

PICKED BY: 6803

SUB-TOTAL : S\$ 2,223.00
ADD 7% GST : S\$ 155.61
TOTAL : S\$ 2,378.61

Goods sold are not returnable except Repairs/Service at authorized workshop.

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference: SNM18D02949C01
Assessment Number: DS000493
Version: LKKAUTOC/2
Date Calculated: 18/10/2018 08:31

Full Report - V1
Registration: SLL552T
Printed: 18/10/2018 15:32

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	09/06/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM18D02949C01	Estimated Repair Time:	
Policy Number:	DMCPSN1711821801	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	GLA Class
Sub Model:	180
Model Sheet Number:	3GA 43
Registration:	SLL552T
Registration Month:	
Registration Year:	
VIN Number:	WDC1569422J289480
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs


FR J217874/ L040733	ELECTRIC HORN
MODEL 2017	A/C THERMATIC
KEYLESS GO	RAIN-/DR/LIGHT SENS
MIRROR PACKAGE	COLLISION WARNER
ELECT FOLDING MIRROR	AUDIO SYSTEM 20 CD
BI-XENON HEADLAMPS	ILLUMINAT AMBIENTE
LIGHT-/VIEW PACKAGE	HEADLAMP WASHER UNIT
DIPPING AUTOM MIRROR	CLOTH/IMI LEATH PAD
URBAN PACK	MULTI FUNCT S-WHEEL
SILL MLDG ILLUMINAT	LEATHER STRG WHEEL
DRIVER SEAT MEMORY	PASS SEAT MEMORY
ELECT LUMBAR ADJUST	RAISED SUSPENSION
SEAT COMFORT PACKAGE	DECORATION ANTHRACIT
REARVIEW CAMERA	EMISSION STD EURO 6
STORAGE PACKAGE	ECO START/STOP
TYRE PRESSURE SENSOR	EASY-PACK
CRUISE CONTROL	STRG COLUMN SHIFT
7 SPEED AUTOMATIC	TYRES 215/55 HR 18
DYNAMIC SEL SWITCH	WHEELS 7J X 18 ALLOY
COMPRESSOR VARIABLE	CLEAR COAT HARD

Vehicle Condition


Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	14/06/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:

Tread Depth LHR:
Damage Areas:



Tread Depth RHR:
Direction of Impact:



Addresses

Cost Summary

Total Labour	\$768.60
Total Paint/Material	\$152.56
Total Parts	\$2,323.00
Total of Additional Costs	\$190.00
Repair Cost Exc GST:	\$3,434.16
Overall Discount (0.0%):	- \$0.00
Excess:	-\$1,000.00
After Deduction -	
Grand Total Exc GST:	\$2,434.16
7 % GST:	\$170.39
Grand Total Inc GST:	\$2,604.55

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$0.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
54-7989 01	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	8.40
72-1450 01	RENEW L/F DOOR AND CONVERT PARTS INCLUDES: DOOR TRIM REMOVE AND REFIT AND ALL ATTACHED PARTS ASSEMBLE	31.0	130.20
72-4570 01	R + R LEFT FRONT DOOR LOCK STRIKER	3.0	12.60
72-1590 01	RENEW L/R DOOR AND CONVERT PARTS INCLUDES: DOOR TRIM REMOVE AND REFIT AND ALL ATTACHED PARTS ASSEMBLE	31.0	130.20
88-5205 01	R + R LEFT SILL TRIM	5.0	21.00
88-6976 01	R + R LEFT REAR LOWER WING CLOSING PANEL	3.0	12.60
68-1093 01	R + R LEFT B-PILLAR LOWER TRIM	5.0	21.00
68-1240 01)	R + R LEFT REAR SIDE TRIM	4.0	16.80
68-5570 01	R + R PARCEL SHELF	1.0	4.20
91-5404 01)	R + R LEFT REAR SEAT BACK REST	3.0	12.60
91-5053 01	R + R REAR SEAT CUSHION	3.0	12.60
2083	REPAIR L/F DOOR FRAME	5.0*	21.00
LABOUR COST			
Total Work Units		96.0	
Corrosion Protection External Labour		0.0HRS	0.00
Corrosion Protection Internal Labour		0.0HRS	0.00
Sub Total		9.6HRS	\$403.20
Paint Labour		8.7HRS	\$365.40

Total Labour **18.3HRS** **\$768.60**

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$42.00/HR	
Guide Number	Description	WU	Cost Price (\$)
98-4015 01	LEFT FRONT DOOR PAINTING STAGE I-M	14.0	
98-4115 01	L/R DOOR PAINTING STAGE I-M	13.0	
98-5557 01	L/F DOOR FRAME PAINTING STAGE III	11.0	
98-5057 01	L/SILL PANEL PAINTING STAGE III	11.0	
98-5517 01	L/OUTER A-PILLAR PAINTING STAGE III	7.0	
98-1710 ZAX	L/F DOOR HANDLE CVR PAINTING	1.0	
98-1710 ZAX	L/F DOOR OUT HANDLE PAINTING	1.0	
98-1881 01	L/DOOR MIRROR HSG PAINTING	3.0	
98-1710 ZAX	L/R DOOR HANDLE TRIMPAINTING	1.0	
98-1710 ZAX	L/R DOOR OUT HANDLE PAINTING	1.0	
98-7046 01	L/R WING PAINTING STAGE II	10.0	
98-1340 01	WITH ROOF SIDE PANELLING LESS DOOR SHUT PREPARATION WORK FOR TWO COAT PAINTING OF FITTED BODY PARTS	14.0	
LABOUR COST - PAINT			
TIME(PAINT)		0.0	
Total Work Units (10WU/HR)		87.0	
Total Paintwork Labour		8.7HRS	\$365.40
MATERIAL COST - PAINT			Cost Price
Total Excluding Pearlescent Uplift			\$152.56
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$152.56

PARTS

					Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1481	1	LEFT FRONT DOOR	156 720 0105		0%	880.00*
1509	1	L/F DOOR SEAL	204 727 1187		0%	145.00*
1781	1	L/R DOOR	156 730 0105		0%	1,000.00*
1809	1	L/R DOOR SEAL	204 727 1187		0%	145.00*
3487	1	L/R PROTECTION FOIL	156 732 0111		0%	20.00*
1000	1	RIVET(FRT&RR LH) X15	Renew		0%	33.00*
f: OEM Parts			Sub Total			\$2,223.00
g: Original			Sundry Parts	(Fixed)		\$100.00
h: Secondhand			Total Parts			\$2,323.00

p: Parallel
x: Exchange

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FENDER GLASS	SPECIALIST	0%
SEALANT		\$40.00
DIAGNOSE&CLEAR	SPECIALIST	
CODE		\$150.00
Total Extras		\$190.00

Final Calculation

Total Parts **\$2,323.00**

Labour		
Total Panel/Mechanical	\$403.20	
Total Paintwork	\$365.40	
Total Labour		\$768.60
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$190.00	
Total of Additional Costs		\$190.00
Total Paint/Material Costs		\$152.56
Repair Costs Excludes GST		\$3,434.16
Deductions		
Deduction for Excess (Fixed)	-\$1,000.00	
Total Deductions		-\$1,000.00
Grand Total Excludes GST (After Deduction)		\$2,434.16
GST @ 7 %		\$170.39
Grand Total Includes GST (After Deduction)		\$2,604.55

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jun 2018 Sendback Est	19 Jun 2018 15:54 S\$5,903.16	19 Jun 2018 18:10 Edit Adj Rpt	S\$3,434.16 Edit Estimates	S\$3,434.16 View Rpt		Pending for Survey Report Cancel Case
Supp #1	17 Oct 2018 15:51	17 Oct 2018 15:52 S\$203.00	17 Oct 2018 15:52			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	FUN WUN FAI ANDREW, ID: S1802006H, Tel: +6598233633		
Vehicle Reg. No.:	SLL552T	Date of Loss:	09/06/2018 22:00 - :59 [15 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D02969C01	Policy/Cover Note No.:	DMPCSN1711821801 (Comprehensive) Coverage: 13/02/2018 - 12/02/2019
		Excess:	S\$1,000.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 28/06/2018]		
Driver/Custodian:	CHOOI SYAD SENG (49 / Male), NRIC: S2593414H, Tel: +6594528670		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- CHINA_TAIPING (27/06/2018): Alert - Adj Mandate Approved (S\$5720.16) - SLL552T - Claim Handler: Chong Boon S...

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLL552T (SNM18D02969C01)

OD

Jun 9 2018 10:00PM













[FUN WUN FAI ANDREW]

Sng Ah Tee Motor & Panel Service Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)					Thumbnail	Print	
1	13/06/18 16:14	Accident Statement					Load HTM		
2	19/06/18 15:54	Repairer Estimates					Load HTM		
3	17/10/18 15:52	Repairer Estimates Suppl. #1					Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	25/06/18 14:34	Adjuster Immediate Advice					Load HTM		
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)					Thumbnail	Print	
1	13/06/18 15:16	Accident Photo <small>[Linked Accident Report Documents]</small>					Load JPG	<input checked="" type="checkbox"/>	
2	13/06/18 15:16	Accident Photo <small>[Linked Accident Report Documents]</small>					Load JPG	<input checked="" type="checkbox"/>	
3	13/06/18 15:16	Accident Photo <small>[Linked Accident Report Documents]</small>					Load JPG	<input checked="" type="checkbox"/>	
4	13/06/18 15:16	Accident Photo <small>[Linked Accident Report Documents]</small>					Load JPG	<input checked="" type="checkbox"/>	
5	13/06/18 15:16	Accident Photo <small>[Linked Accident Report Documents]</small>					Load JPG	<input checked="" type="checkbox"/>	
6	13/06/18 15:16	Accident Photo <small>[Linked Accident Report Documents]</small>					Load JPG	<input checked="" type="checkbox"/>	
7	13/06/18 15:16	Accident Photo <small>[Linked Accident Report Documents]</small>					Load JPG	<input checked="" type="checkbox"/>	
8	13/06/18 15:16	Accident Photo <small>[Linked Accident Report Documents]</small>					Load JPG	<input checked="" type="checkbox"/>	
9	13/06/18 15:16	Accident Photo <small>[Linked Accident Report Documents]</small>					Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	25/06/18 14:38	General View					Load JPG	<input checked="" type="checkbox"/>	
2	25/06/18 14:38	General View					Load JPG	<input checked="" type="checkbox"/>	
3	25/06/18 14:38	General View					Load JPG	<input checked="" type="checkbox"/>	
4	25/06/18 14:38	General View					Load JPG	<input checked="" type="checkbox"/>	
5	25/06/18 14:38	General View					Load JPG	<input checked="" type="checkbox"/>	
6	25/06/18 14:38	General View					Load JPG	<input checked="" type="checkbox"/>	
7	25/06/18 14:38	General View					Load JPG	<input checked="" type="checkbox"/>	
8	25/06/18 14:38	General View					Load JPG	<input checked="" type="checkbox"/>	
9	25/06/18 14:38	General View					Load JPG	<input checked="" type="checkbox"/>	
10	25/06/18 14:38	General View					Load JPG	<input checked="" type="checkbox"/>	
11	25/06/18 14:38	General View					Load JPG	<input checked="" type="checkbox"/>	
12	25/06/18 14:38	General View					Load JPG	<input checked="" type="checkbox"/>	
13	25/06/18 14:38	General View					Load JPG	<input checked="" type="checkbox"/>	
14	25/06/18 14:38	General View					Load JPG	<input checked="" type="checkbox"/>	
15	25/06/18 14:38	General View					Load JPG	<input checked="" type="checkbox"/>	
16	25/06/18 14:38	General View					Load JPG	<input checked="" type="checkbox"/>	
17	25/06/18 14:38	General View					Load JPG	<input checked="" type="checkbox"/>	
18	25/06/18 14:38	General View					Load JPG	<input checked="" type="checkbox"/>	
19	25/06/18 14:38	General View					Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
20	25/06/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
21	25/06/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
22	25/06/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
23	25/06/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
24	25/06/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
25	25/06/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
26	14/11/18 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	14/11/18 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	14/11/18 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	14/11/18 11:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	14/11/18 11:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	14/11/18 11:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	14/11/18 11:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	14/11/18 11:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	14/11/18 11:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	13/06/18 15:16	Sketch Plan <small>[Linked Accident Report Documents]</small>	 Load TIF	
2	13/06/18 15:16	CI,IC,DL <small>[Linked Accident Report Documents]</small>	 Load TIF	
3	19/06/18 15:56	E-filed GIA report	 Load PDF	
4	17/10/18 18:16	Copy of Supplier's Invoice	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/06/18 14:35	ESTIMATE	 Load PDF	
2	25/06/18 14:39	AUDATEX	 Load PDF	
3	09/11/18 13:42	SUPPLEMENTARY LIST	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	13/06/18 16:14	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	13/06/18 15:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	13/06/18 15:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	13/06/18 15:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	13/06/18 15:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	13/06/18 15:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	13/06/18 15:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	13/06/18 15:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	13/06/18 15:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	13/06/18 15:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	13/06/18 15:16	Sketch Plan	 Load TIF	
2	13/06/18 15:16	CI,IC,DL	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT18011178/T1QD3E2

Date: 16/11/2018

REFERENCE

Insured/Claimant: FUN WUN FAI ANDREW Policy No: DMPCSN1711821801
Date of Loss: 09/06/2018 Nature of Claim: OD Claim No: SNM18D02969C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL552T**
Make & Model: MERCEDES-BENZ GLA180, 1.6 (A) Engine No: 27091031056490
Reg. Date: 13/02/2017 (Man. Year: 2016) Chassis No: WDC1569422J289480
Colour: Grey Odometer: 38555 km
Engine Capacity: 1595 cc
Market Value/New Car Price: S\$123,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,059.00	2,513.00	2,546.00	50.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,047.16	921.16	126.00	12.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,106.16	3,434.16	2,672.00	43.76
- Excess (S\$)	0.00	1,000.00	-1,000.00	
(S\$)	6,106.16	2,434.16	3,672.00	60.14
+ GST 7.00/7.00% (S\$)	427.43	170.39	257.04	60.14
Nett Amount (S\$)	6,533.59	2,604.55	3,929.04	60.14

INSPECTION

Date of Assignment: 19/06/2018 Present Location: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected: 22/06/2018 Inspected At: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Blk 3 Pioneer Road North, #01-18
Singapore 628457
Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2018)
Parts:	M1-SUV	MERCEDES-BENZ GLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL552T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*FRT DOOR TRIMBOARD	Not Necessary	20.00 F	*- F
2	1	NA	*L/F DOOR LOCK	Not Necessary	165.00 F	*- F
3	1	NA	*L/F DOOR MODULE	Not Necessary	350.00 F	*- F
4	1	NA	*L/F DOOR SEAL	Necessary	145.00 F	*145.00 F
5	1	NA	*L/F DOOR TRIM	Not Necessary	550.00 F	*- F
6	1	NA	*L/F DOOR TRIM REAR	Not Necessary	65.00 F	*- F
7	1	NA	*L/F LWR DOOR SPEAKER	Not Necessary	88.00 F	*- F
8	1	NA	*L/F OUT WINDOW SEAL	Not Necessary	98.00 F	*- F
9	1	NA	*L/F WINDOW MOTOR	Not Necessary	285.00 F	*- F
10	1	NA	*L/R CHANNEL SEAL	Not Necessary	35.00 F	*- F
11	1	NA	*L/R DOOR	Bent	980.00 F	*1,000.00 F
12	1	NA	*L/R DOOR MODULE	Not Necessary	350.00 F	*- F
13	1	NA	*L/R DOOR SEAL	Necessary	145.00 F	*145.00 F
14	1	NA	*L/R DOOR TRIM FRONT	Not Necessary	75.00 F	*- F
15	1	NA	*L/R DOOR WINDOW SEAL	Not Necessary	105.00 F	*- F
16	1	NA	*L/R LOWER DOOR HINGE	Not Necessary	55.00 F	*- F
17	1	NA	*L/R UPPER DOOR HINGE	Not Necessary	55.00 F	*- F
18	1	NA	*L/R WINDOW MOTOR	Not Necessary	300.00 F	*- F
19	1	NA	*LEFT FRONT DOOR	Bent	850.00 F	*880.00 FS
20	1	NA	*SPECIALIST FENDER GLASS SEALANT	Necessary	40.00 F	*40.00 FS
21	1	NA	*SUNDRY PARTS	Necessary	100.00 F	*100.00 FS
Supplementary #1						
22	1		*L/R PROTECTION FOIL	Necessary	20.00 F	*20.00 F
23	1		*RIVET(FRT&RR LH)X15	Necessary	33.00 F	*33.00 F
24	1		*SPECIALIST DIAGNOSE & CLEAR CODE	Necessary	150.00 FS	*150.00 FS
Total Parts (\$\$)					5,059.00	2,513.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Paint Labour	New	365.40	365.40
2	Total Paint Materials	New	152.56	152.56
3	Total Panel/Mechanical Labour	New	529.20	403.20
Gross Labour Cost (S\$)			1,047.16	921.16

Report was unsubmitted during this print-out.

< END OF ESTIMATES >