

ASS. REC. BY:

REF: CS/EG1801183/USD3 | n2

Special Instruction:

Surveyor: MARCUS

ASSIGNMENT (Office)

From (Person): Yee Pei Li

of

EG1

Date/Time: 20/6/18 @ 1:53pm

Estimated Cost:

Bill to:

OD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FT 3155R

Insured: GBG 6711 G

at Workshop m/s: Erofia Motor

Tel: 6752 7740

of 1 kaki Bukit Ave 6 # 02-02 Autobay

Policy No:

Claim No: DSM CV1801150

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 06/06/2018

CA / REV / REP. / REV 24 HRS ^{up}

H.O.D. Endorsement:

Date/Time: 1:56pm @ 20/6/18

Person Contacted:

Lee Lee

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	FT 3155R-CC4/ASM18010832/pb3 DOA: 06/06/18
	GBG 6711G-CC4/ASM18010832/pb3 DOA: 06/06/18
21/06/18 @ 15:42 p.m.	revised PA to Pei Li via email.

ERI/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD: TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: F73155R
 at Workshop m/s: Enfu
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 56%
 IDAG Accident Rpt: _____ Consistent? : Yes or No
 GA + PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 3.13/2021
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: F73155R Yr Regn: 4, 01
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda CB400 s/c 399
 Colour: Silver/Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 30335 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: NC391021198
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 120/60ZR17
 R: 160/60ZR17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 6/6/18 D.O.I. 20/6/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
At, 015 304
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>23/7/18</u>	<u>LTA 475 net 4525</u> <u>conf. m/s #2900 with MR Leo.</u> <u>(\$3702.50 Red - 56%)</u>

RECEIVED 25 JUL 2018

Date/Time, File Pass to? 25/07/18
 1) Tyast
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: 4
 Resurvey No. of Trip: 2

Report Format : _____
 Lump Sum / I.B.I: (\$ 2,900.00 L/S)

Add Fee: Site Insp (\$ _____)
 Interview (\$ _____)
 Tech. Invs (\$ _____)
 Weekend (\$ _____)

Survey Fee:	
Transportation:	
Photos	
Others	<u>250</u>
TOTAL	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18011183/Usd3	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 20-06-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBG 6711G	Veh. Inspected	FT 3155R
Policy No.		Coverage (\$)	0.00
Claim No.	DSMCV1801150	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	20/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	06/06/2018	Inspection Date	20/06/2018
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DSMCV1801150

Date: 21 June 2018

Our Ref: CS/EGH18011183/Usd3

The Motor Claims Department
ERGO INSURANCE PTE LTD

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. FT 3155R

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/06/2018 at the premises of M/s Erofia Motor Trading Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 6,449.50</u>
Revised Estimate Amount	: <u>S\$ 2,468.40</u>
"Check" Items Amount	: <u>S\$ 819.00</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:

The vehicle sustained damages at the front portion & o/s body.



Comments/ Present Status:

Damages Consistent.
Repair days: 4 Days

Yours faithfully,
Marcus Chua
Automotive Assessor

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 21 June 2018 3:42 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: Admin-D (LKKAuto)
Subject: RE: GBG6711G / TP : FT3155R/LKK / DOA : 06.06.2018
Attachments: FT 3155R - Preli Advise.pdf

Dear Pei Li,

Enclosed preliminary revised for FT 3155R.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Wednesday, 20 June 2018 2:00 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: "SUR" <sur@lkkauto.com>; 'Yee Pei Li' <peili.yee@ergo.com.sg>
Subject: RE: GBG6711G / TP : FT3155R/LKK / DOA : 06.06.2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Wednesday, 20 June 2018 1:53 PM
To: admin-d@lkkauto.com
Subject: OI : GBG6711G / TP : FT3155R/LKK / DOA : 06.06.2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **EROFIA MOTOR TRADING PTE LTD**.

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 20 June 2018 1:53 PM
To: admin-d@lkkauto.com
Subject: OI : GBG6711G / TP : FT3155R/LKK / DOA : 06.06.2018
Attachments: GBG6711G - SAS.pdf; FT3155R - SAS.pdf; TP SGP996J - SAS.pdf; FT3155R -PRS FORM.pdf; RE: (DSMCV1801150) PRI request for accident involving GBG6711G and FT315... (12.7 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **EROFIA MOTOR TRADING PTE LTD**,

ADDRESS : 1 KAKI BUKIT AVE 6
#02-62 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

PERSON TO CONTACT : LEELEE TAN @ 6752 7740

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and third party SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Fax: 65 6829 9247
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 20.06.2018
Our Reference: DSMCV1801150/RH/pl
Your Reference: FT 3155R

Sent via Fax

or

Email erofia@singnet.com.sg

To: EROFIA MOTOR TRADING PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: FT 3155R
Insured's Vehicle: GBG 6711G
Date Of Accident: 06.06.2018

We acknowledge receipt of your request for PRS on: 19.06.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- Your request for inspection does not have your client's GIA report, kindly forward a copy.
- We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- Our Insured's driver has not reported the accident to us todate.
- Others: OFFICER-IN-CHARGE - ROHAINI

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Honda CB400 Super 4 Spec 1

Listing Type	Paid Ad
Brand	Honda (/listing/usedbike/brand/honda/)
Model	Honda CB400 Super 4 Spec 1 (/listing/usedbike/model/honda-cb400-super-4-spec-1/)
Engine Capacity	399cc
Classification	2A
Registration Date	27/12/2001
COE Expiry Date	30/09/2021 (3 years 3 months left)
Mileage	-
No. of owners	-
Type of Vehicle	Street Bikes (/listing/usedbikes/listing/?bike_type=7)

Price: SGD\$6000

DETAILS

Honda Super 4 Spec 1 for Sale. Eligible for NEA Cash Incentive of \$3500. Interested parties are welcome to Neg. Trade/Loan available. Do visit us at Wing Fuat @ Sims Place! No Early Settlement Fee.

[SIMILAR BIKES](#)

[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](/LISTING/USEDBIKES/LISTING/)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1992C
Vehicle Details	
Vehicle No.:	FT3155R
Vehicle to be Exported:	No
Intended De-registration Date:	20 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	CB400S.F.H.V
Primary Colour:	Silver
Manufacturing Year:	2001
Engine No.:	NC23E2021199
Chassis No.:	NC391021198
Maximum Power Output:	-
Open Market Value:	\$8,150.00
Original Registration Date:	17 Apr 2001
First Registration Date:	17 Apr 2001
Transfer Count:	2
Actual ARF Paid:	\$1,223.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2021
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,711.00
COE Rebate Amount:	\$475.00
Total Rebate Amount:	\$475.00
Message	
<p>Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.</p> <p>This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.</p>	

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2531992C



Name
TENG KAM CHOY



Race
CHINESE

Date of Birth
12-03-1961

Sex
M

Country of Birth
BRUNEI

S2531992C

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number
S2531992C

Name
TENG KAM CHOY



Birth Date
12 Mar 1961

Issue Date
04 Oct 2003

000874027K

0 0 5 7 1 0 8



NVIC No. **S2531992C**



Blood Group
AB+

Date of issue
25-08-1991

Address
**APT BLK 203 BISHAN STREET 23
 #09-441
 SINGAPORE 2057**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	12 May 1989
Class 2A	Motorcycles between 201 cc and 400 cc	03 Apr 1995
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	13 Nov 1979
Class 4	Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kilograms	02 Oct 1985
Class 5	Motor Vehicles which are not constructed themselves to carry any load and the weight of which unladen exceeds 7250 kilograms	27 Nov 1985

Licence No. S2531992C



NP 428A

AXA INSURANCE PTE LTD

8 Shenton Way, #24-01

AXA Tower, Singapore 068811

Customer Service Centre #B1-01

Tel:(65)63387288 Fax:(65)63382522

Website:www.axa.com.sg

GST Registration Number: 199903512M

customer.service@axa.com.sg



CERTIFICATE OF INSURANCE

■ Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) ■ Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 ■ Road Transport Act, 1987 (Malaysia) ■ Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO. : VMO/P0385183 Account No. : 03375
 Coverage : Third Party Only
 Sum Insured : NIL
 Name of Policy Holder : TENG KAM CHOY
 Vehicle Registration No. : FT3155R
 Period of Insurance : From 17/04/2018 To 16/04/2019 (Both Dates Inclusive)

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

- (a) The Policyholder
 (b) 1. TENG KAM CHOY

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and in connection with the Policyholder's business or profession

The Policy does not cover:

- a) Use for hire and reward
 b) Use for racing, pace-making, reliability trial or speed-testing
 c) Use for the carriage of goods (other than samples) in connection with any trade or business
 d) Use for any purpose in connection with the Motor Trade

(11)

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD


 Authorized Signature

Issued by - SGRAN09 on 12/03/2018

IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189)).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

AXA INSURANCE AGENCIES PTE LTD

(CUSTOMER SERVICE DEPARTMENT)

150 Raffles Place

Singapore 048548

Tel: 654 2288 Fax: 6453 4466

Email: thomson@anda.com.sg

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

CHINA

Name : Teng Kam Choy

Accident Date : 6-Jun-18

Vehicle No : FT 3155 R

Vehicle Model : Honda CB400

Estimated Repair Costs

<u>Qty</u>	<u>Description</u>	<u>Amount S(\$)</u>
	<u>List Items</u>	
1	Front fender <i>cut</i>	\$ 196.00 <i>—</i>
1	Headlamp <i>RD</i>	\$ 380.00 <i>—</i>
1	Headlamp bracket <i>cut</i>	\$ 65.00 <i>—</i>
2	Fork inner tubes <i>R</i>	\$ 620.00 <i>x</i>
2	Front brake discs	\$ 910.00 <i>2/pc</i>
1	Front rim shaft <i>11</i>	\$ 68.00 <i>x</i>
1	Meter <i>11</i>	\$ 880.00 <i>x</i>
1	Handle bar <i>cut</i>	\$ 145.00 <i>—</i>
2	Handle bar ends <i>11</i>	\$ 60.00 <i>x</i>
2	Side mirrors <i>2/SSCA</i>	\$ 190.00 <i>1/pc</i>
1	Clutch lever <i>11</i>	\$ 58.00 <i>x</i>
1	Brake lever <i>11</i>	\$ 65.00 <i>x</i>
2	Front signals <i>0/5 7/1</i>	\$ 170.00 <i>1/pc</i>
1	Front footrest -R/H <i>11</i>	\$ 75.00 <i>x</i>
1	Front footrest bracket -R/H <i>11</i>	\$ 245.00 <i>x</i>
1	Brake pedal <i>11</i>	\$ 98.00 <i>x</i>
1	Rear footrest -R/H <i>11</i>	\$ 70.00 <i>x</i>
1	Exhaust pipe <i>RD</i>	\$ 865.00 <i>—</i>
1	Exhaust pipe bracket <i>1/2C</i>	\$ 55.00 <i>—</i>
1	Rear signal -R/H <i>11</i>	\$ 85.00 <i>x</i>
1	Rear tailboard <i>R</i>	\$ 335.00 <i>x</i>
2	Horns <i>11</i>	\$ 160.00 <i>x</i>
		\$ 5,795.00
	Less 10%	\$ 579.50
		\$ 5,215.50

*not added
work*

*2/2 S
4 day
take photo. At the repair*

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Teng Kam Choy

Accident Date : 6-Jun-18

Vehicle No : FT 3155 R

Vehicle Model : Honda CB400

Estimated Repair Costs

<u>Special Nett Items</u>			
1	Number plate (1 set)	\$ 54	28.00 10
2	Fork oils	\$ 24	30.00 /
2	Fork oil seals	\$ 24	56.00 /
1	Steering cone (1 set)	\$ 24	80.00 /
1	Crash bar (1 set)	\$ 207	250.00 /
		\$	444.00

<u>S/No.</u>	<u>Labour</u>		
1	To provide towing service.	\$ 35	50.00
2	To remove, refit and align front fork tubes.	\$ 60	180.00
3	To check wiring and reset headlamp focusing.	\$ 17x	80.00
4	To provide labour.	\$ 250	480.00
		\$	790.00

Grand Total

\$ 6,449.50

Dollars: Six Thousand Four Hundred Forty-Nine And Fifty Cents Only.


EROFIA MOTOR TRADING PTE LTD

Accepted by: Robby

Accepted by: [Signature]

- To display (damage) part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Accepted by: Repairer

Signature: _____

Date: _____

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

CHINA

Name : Teng Kam Choy

Accident Date : 6-Jun-18

Vehicle No : FT 3155 R

Vehicle Model : Honda CB400

Estimated Repair Costs

Qty	Description	Amount S(\$)
List Items		
1	Front fender <i>cut</i>	\$ 196.00 <i>—</i>
1	Headlamp <i>DD</i>	\$ 380.00 <i>—</i>
1	Headlamp bracket <i>cut</i>	\$ 65.00 <i>—</i>
2	Fork inner tubes <i>2</i>	\$ 620.00 <i>x</i>
2	Front brake discs <i>0/5 set 428</i>	\$ 910.00 <i>ipc</i>
1	Front rim shaft <i>11</i>	\$ 68.00 <i>x</i>
1	Meter <i>272/cno</i>	\$ 880.00 <i>✓</i>
1	Handle bar <i>cut</i>	\$ 145.00 <i>—</i>
2	Handle bar ends <i>11</i>	\$ 60.00 <i>x</i>
2	Side mirrors <i>0/5 set</i>	\$ 190.00 <i>ipc</i>
1	Clutch lever <i>11</i>	\$ 58.00 <i>x</i>
1	Brake lever <i>11</i>	\$ 65.00 <i>x</i>
2	Front signals <i>0/5 set</i>	\$ 170.00 <i>ipc</i>
1	Front footrest -R/H <i>11</i>	\$ 75.00 <i>x</i>
1	Front footrest bracket -R/H <i>11</i>	\$ 245.00 <i>x</i>
1	Brake pedal <i>11</i>	\$ 98.00 <i>x</i>
1	Rear footrest -R/H <i>11</i>	\$ 70.00 <i>x</i>
1	Exhaust pipe <i>DD</i>	\$ 865.00 <i>—</i>
1	Exhaust pipe bracket <i>12C</i>	\$ 55.00 <i>—</i>
1	Rear signal -R/H <i>11</i>	\$ 85.00 <i>x</i>
1	Rear tailboard <i>12</i>	\$ 335.00 <i>x</i>
2	Horns <i>11</i>	\$ 160.00 <i>x</i>

Head lamp Bracket (R) \$90 set *Repair* Less 10%
 Head lamp Bracket inner \$80 set *—*

not added
2/b \$2900/1
4 day
take photo. At the repair

\$ 5,795.00
 \$ 579.50

 \$ 5,215.50
5,368.50
3271
2943.9

EROFIA MOTOR TRADING PTE LTD

No 1, Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Teng Kam Choy

Accident Date : 6-Jun-18

Vehicle No : FT 3155 R

Vehicle Model : Honda CB400

Estimated Repair Costs

<u>Special Nett Items</u>			
1	Number plate (1 set)	\$ 34	28.00 10
2	Fork oils	\$ 24	30.00 /
2	Fork oil seals	\$ 26	56.00 /
1	Steering cone (1 set)	\$ 26	80.00 /
1	Crash bar (1 set)	\$ 247	250.00 /
		\$	444.00

<u>S/No.</u>	<u>Labour</u>		
1	To provide towing service.	\$ 35	50.00
2	To remove, refit and align front fork tubes.	\$ 60	180.00
3	To check wiring and reset headlamp focusing.	\$ 17x	80.00
4	To provide labour.	\$ 250	480.00
		\$	790.00

Grand Total

\$ 6,449.50

6,602.50

3714.9
2971.92

Dollars: Six Thousand Four Hundred Forty-Nine And Fifty Cents Only.


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EG18011183/Usd3n2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 01-08-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBG 6711G	Veh. Inspected	FT 3155R
Policy No.		Coverage (\$)	0.00
Claim No.	DSMCMV1801150/RH/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	20/06/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA CB400	c.c	399
Engine No.	HIDDEN	Year of Reg.	2001
Chassis No.	NC391021198	Colour	SILVER / BLUE
Odometer	30335	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/60 ZR17	PIRELLI	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	160/60 ZR17	PIRELLI	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/06/2018	Inspection Date	20/06/2018
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FT 3155R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER	CUT	196.00	196.00
1	HEADLAMP	DENTED	380.00	380.00
1	HEADLAMP BRACKET	BENT	65.00	65.00
2	FORK INNER TUBES	TO REPAIR SEE LABOUR	620.00	-
2	FRONT BRAKE DISCS	O/S BENT	910.00	425.00
1	FRONT RIM SHAFT	NOT NECESSARY	68.00	-
1	METER	DAMAGED / CRACKED	880.00	880.00
1	HANDLE BAR	BENT	145.00	145.00
2	HANDLE BAR ENDS	NOT NECESSARY	60.00	-
2	SIDE MIRRORS	O/S SCRATCHED	190.00	95.00
1	CLUTCH LEVER	NOT NECESSARY	58.00	-
1	BRAKE LEVER	NOT NECESSARY	65.00	-
2	FRONT SIGNALS	O/S TWISTED	170.00	85.00
1	FRONT FOOTREST-R/H	NOT NECESSARY	75.00	-
1	FRONT FOOTREST BRACKET-R/H	NOT NECESSARY	245.00	-
1	BRAKE PEDAL	NOT NECESSARY	98.00	-
1	REAR FOOTREST-R/H	NOT NECESSARY	70.00	-
1	EXHAUST PIPE	DENTED	865.00	865.00
1	EXHAUST PIPE BRACKET	NECESSARY	55.00	55.00
1	REAR SIGNAL-R/H	NOT NECESSARY	85.00	-
1	REAR TAILBOARD	TO REPAIR SEE LABOUR	335.00	-
2	HORNS	NOT NECESSARY	160.00	-
1	SET HEAD LAMP BRACKET R/L	TO REPAIR SEE LABOUR	90.00	-
1	HEAD LAMP BRACKET INNER	BENT	80.00	80.00
	LESS 10% DISCOUNT		-596.50	-327.10
			5,368.50	2,943.90
SPECIAL NETT ITEMS				
1	SET NUMBER PLATE (SN)	BENT	28.00	10.00

Report Ref No. CS/EGI18011183/Usd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FORK OILS (SN)	NECESSARY	30.00	30.00
2	FORK OIL SEALS (SN)	NECESSARY	56.00	56.00
1	SET STEERING CONE (SN)	NECESSARY	80.00	80.00
1	SET CRASH BAR (SN)	CUT	250.00	250.00
			444.00	426.00
	LABOUR			
	TO PROVIDE TOWING SERVICE.		50.00	35.00
	TO REMOVE,REFIT AND ALIGN FRONT FORK TUBES.		180.00	60.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR,INCLUSIVE OF THE REPAIR OF FORK INNER TUBES,REAR TAILBOARD AND SET HEAD LAMP BRACKET R/L.		480.00	250.00
			790.00	345.00
GRAND TOTAL			6,602.50	3,714.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,900.00

Report Ref No. CS/EGI18011183/Usd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.