

Surveyor:

Amk

DOI:

19-6-18

Date / Time:

19-6-18

Registered in. Merimen:

Pre-assign / CCU / FTE

GBA 8256 Y



Insured Vehicle No.:

Claim No.:

SNM18003108002

Name of Insured:

86 MOBILE ACCESSORIES

Policy No.:

DMV SN3008101800

Insured Tel No.:

HP:

Make / Model:

T. by N/A

Excess Sec II :SS

D.O.A.:

18/6-18

Place of Accident:

WOODLAND AVE 12 & AVE 5

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TAN HAN MENG

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

9634 2315

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SHC 3998 R



INSRS:

WSP:

Tel:

Liability:

RMKS:

COE 100g.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

19/6/18

SHC 3998 R - 05/10/18 18354 / Agbhl ; 05/10/18

GBA 8256 Y X

19/6/18

called OAD No response

21/6/18

Receive TP video. send to CT2

21/6/18

send letter to O2

RECEIVED 05 OCT 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

20/6

Sent By:

Amk

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

3/10/18

Confirm with

William

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS

856.00

Loss of Rental (LOR):

SS

172.50

(

1.5

days)

x 115.00

Loss of Use (LOU):

SS

75.00

(\$

50

x 1.5

days)

Loss of Income (LOI):

SS

-

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

7.49

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

1110.99

Global Sum SS:

1100.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

1100.00

Name 1:

Comfortdelgro engineering Pte Ltd

Payee 2 (Strike if N.A.)

SS

Name 2:

Payee 3 (Strike if N.A.)

SS

Name 3:

Kalin

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No _____

Claims No _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

2 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: _____

SHC3998R

Yr Regn: _____

2 Apr 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / T 6 / Prime Mover /

Truck / Trailer or

Make: _____

Hyundai Ix35

C.C

165

Colour: _____

Blue

A/C

Insured / Std / NI / NA

Sp. Reading: _____

56 6631

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

KMHLDX14MAY067891

Gen. Cond: 6 / Fair / Poor / BurntSteering: 6 / Jammed / Leaked / Burnt orBrake: 6 / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD 6 Rim or

Tyre Size: _____

F: _____

205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / QHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal. _____

7

mm

R/Bal. _____

7

mm

L/Bal. _____

7

mm

L/Bal. _____

7

mm

D.O.A. _____

18/6/12

D.O.I. _____

19/6/12

Survey held at _____

CDHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/6/12

Check 455800/ 2hrs

CTI
45

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS: \$

) Photos:

) Others:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

Report Format :

(red) \$716.18
47.1)

Mei Kwan (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Wednesday, 4 July, 2018 1:04 PM
To: Mei Kwan (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GBA8256Y (OI : CTI - SNM18D03108C02) and SHC3998R (TP : LKK REF - CC3/CTI18011184/K1wa3) on 18/06/2018
Attachments: MCHM18083646-GBA8256Y.pdf
Categories: HMK

Dear Sirs,

As requested, kindly refer to the above attachment.

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, 4 July, 2018 12:07 PM
To: Claims Dept of CTI
Cc: Irene Tay; Lucas Lee; Vivian Lau (LKKAUTO); Thin Thin (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving GBA8256Y (OI : CTI - SNM18D03108C02) and SHC3998R (TP : LKK REF - CC3/CTI18011184/K1wa3) on 18/06/2018

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHC 3998R at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Tel: 6389 6111 Fax: 6222 1033

Website: www.sg.cntaiping.com

Co. Reg. No. 200208384E

Our Reference: **SNM18D03108/C01/6**

Date : **22 JUNE 2018**

via Ordinary & Registered Mail

**8G MOBILE ACCESSORIES
BLK 412 WOODLANDS STREET 41
#05-53
SINGAPORE 730412**

Dear Sir / Madam

**ACCIDENT INVOLVING GBA8256Y AND SHC3998R ON 18 JUNE 2018
ALONG WOODLANDS AVE 12 & WOODLANDS AVE 5**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHC3998R**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will soon contact you for more information about the accident. Kindly render your assistance and co-operation accordingly.

We understand that you or your driver has not filed an accident report within 24 hours as per Motor Claims Framework. We would urge you to comply with the condition to file your accident report with your vehicle (whether damaged or not) to us IMMEDIATELY through **LKK Auto Consultants Pte Ltd** or any of our **authorized workshops**. You may log onto our website www.sg.cntaiping.com for location of the respective workshops.

We regret to advice that we and/or **LKK Auto Consultants Pte Ltd** will not be handling the third party claim and your NO CLAIM DISCOUNT will be penalized upon renewal of your policy if you fail to comply with the condition of reporting.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : VIVIAN
Ref : CC3/CT18011184/K1WA3
Contact No : 68418625
via Email : VIVIAN@LKKAUTO.COM

CC : Agent - (AN0582A) - COSMO INSURANCE AGENCY PTE LTD

F02/LKKDSANR-2013

Date/Time: 19.06.2018 14:47

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO305177342

OMER

REGN NO:

SHC3998R

MILEAGE

IS COMFORT TRANSPORTATION PTE LTD

OMER NO 7010045

IESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

1-40

DATE/TIME IN 19.06.2018 11:25

YR OF MANU

02.04.2015

TARGET DATE

CHASSIS CODE

KMHLE41UMFU067891

COMPLETION DATE/TIME

JUNT CARD NO.

JOB DESCRIPTION

cident Date: 18.06.2018

ATURE: 3P 18.06.18

NO

LABOR CODE

DESCRIPTION

OKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.: SHC3998R

LIMITS

Vehicle No.:

SHC3998R

f Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

Date: 19.06.2018

REPAIR ESTIMATE

Time: 14:52:18

Page: 1/2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305177342
 REGN NO : SHC3998R
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 02.04.2015
 DATE/TIME IN : 19.06.2018 11:25
 ACCIDENT DATE : 18.06.2018

China Taiping
HS

Lxx kalvin

TS

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	REAR BUMPER	1	603.60	20.00	482.88	✓
0002 04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	225.00	20.00	180.00	X
0003 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	✓
0004 09-01-9999-0068-A	REVERSE SENSOR	1	135.70	2.00	135.70	X
0005 04-01-0103-1150-A	REAR BUMPER MAT	1	50.00	0.20	50.00	✓

SUB-TOTAL : 866.18

JOB NATURE

0000 20-05	Rear Bumper Adv.Sticker	50.00	✓
0001 L	PANEL BEATING	280.00 200	
0002 23-502	SPRAYPAINT ON AFFECTED AREA	200.00 180	
0003 L	R/I REVERSE SENSOR	120.00 30	

SUB-TOTAL : 650.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 19.06.2018

Time: 14:52:18

REPAIR ESTIMATE

China Taiping CLS

Page: 2/2

IS

LKK - kalvin

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305177342
REGN NO : SHC3998R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 02.04.2015
DATE/TIME IN : 19.06.2018 11:25
ACCIDENT DATE : 18.06.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,516.18

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

Kalvin LKK
19/6/18 1520 hrs.
2 hrs
L/s
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 19.06.2018

Time: 14:52:18

Page: 1/2

China Taiping
US

Lkk talvin

TS

COMPANY: THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS: COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305177342
 REGN NO : SHC3998R
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 02.04.2015
 DATE/TIME IN : 19.06.2018 11:25
 ACCIDENT DATE : 18.06.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	REAR BUMPER	1	603.60	20.00	482.88	—	Phil
0002 04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	225.00	20.00	180.00	X	see
0003 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	—	see
0004 09-01-9999-0068-A	REVERSE SENSOR	1	135.70	2.00	135.70	X	see
0005 04-01-0103-1150-A	REAR BUMPER MAT	1	50.00	0.00	50.00	—	see

SUB-TOTAL : 866.18

JOB NATURE

0000 20-05	Rear Bumper Adv.Sticker	50.00	—	see
0001 L	PANEL BEATING	280.00	200	
0002 23-502	SPRAYPAINT ON AFFECTED AREA	200.00	180	
0003 L	R/I REVERSE SENSOR	120.00	30	

SUB-TOTAL : 650.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 19.06.2018

REPAIR ESTIMATE

China Taiping (CTS)

Time: 14:52:18

Page: 2/2

IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS : COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

LKK - kalvin

JOB NO : 305177342
REGN NO : SHC3998R
MILEAGE : 000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 02.04.2015
DATE/TIME IN : 19.06.2018 11:25
ACCIDENT DATE : 18.06.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,516.18

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Kalvin LKK
19/6/18 1520 hrs.
2 hrs
L/s
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental items must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305177342

Date : 20/06/18

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN ANG

Vehicle Reg No. : SHC3998R

Date of Accident : 18-Jun-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA TAIPING --- GBA8256Y

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20% \$800.00


Final Lumpsum Repair cost \$800.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature 

Name : KALVIN

Date : 20/6/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees	-----			
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18011184/K1wa3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 11-10-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 8256Y	Veh. Inspected	SHC 3998R
Policy No.	DMCVSN3008101800	Coverage (\$)	0.00
Claim No.	SNM18D03108C02	Excess (\$)	0.00
Assign From		Assign Date	19/06/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KMHLB41UMFU067891	Colour	BLUE
Odometer	566631	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	7 mm
L/H Front Tyre	205/60 R16	HANKOOK	7 mm
R/H Rear Tyre	205/60 R16	HANKOOK	7 mm
L/H Rear Tyre	205/60 R16	HANKOOK	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	18/06/2018	Inspection Date	19/06/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3998R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	603.60	603.60
1	REAR BUMPER UNDER COVER	SERVICEABLE	225.00	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-170.12	-125.12
			680.48	500.48
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	SERVICEABLE	135.70	-
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER ADV STICKER (SN)	NECESSARY	50.00	50.00
			235.70	100.00
<u>LABOUR</u>				
	PANEL BEATING.		280.00	200.00
	SPRAYPAINT ON AFFECTED AREA.		200.00	180.00
	R/I REVERSE SENSOR.		120.00	30.00
			600.00	410.00
GRAND TOTAL			1,516.18	1,010.48
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				800.00

Report Ref No. CC3/CTI18011184/K1wa3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.