



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MR SIM HOCK CHUAN BLK 564 ANG MO KIO AVE 3 #07-3471 SINGAPORE 560564 Contact No Mobile: 98581155	Cust No/Name	/MR SIM HOCK CHUAN
	Reg No/Reg Date	SLF3942M / 25/08/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AHH001117
	Engine No	3A92UDG7533
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	18/06/2018/ 22:05		465 / Tay Jian Ye	27360

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 TO RENEW FRT BUMPER , HOOD				1100 1650.00
E PNT98000 PAINT WORK SPRAY FRT BUMPER , HOOD				840 1260.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30 50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00
M SUNDRY TO APPLY ANTI COROSSION				40 80.00
M SUNDRY TO APPLY BODY SEALANT				40 80.00
M SUNDRY SUNDRIES				20 50.00
M FACE,FR BUMPER	1.00	696.00	00.00	DE 696.00
M MARK,THREE-DIA	1.00	51.00	00.00	na 51.00
M GRILLE,RADIATOR	1.00	548.00	00.00	cut 548.00
M CLIP,FR BUMPER	10.00	3.00	00.00	na 30.00
M HOOD	1.00	722.00	00.00	W 722.00

SURVEYOR NAME:

Rasul - Hp 90010068

SURVEYOR SIGNATURE:

R

DATE:

14/08/18 @ 1415

REMARKS:

4 days

Resury b4 paint

Confirm & accepted by	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	7% GST on	Nett 5417.00	5,417.00 379.19
Authorized signatory and company stamp			Total Payable	5,796.19

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.