

INSURANCE: Marinos DOI: 20/6/18 Date / Time: 20/6/18 Registered in Merimen: 20/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.: SHC 30617
 Name of Insured: CPK
 Insured Tel No.: _____ HP: _____
 Excess Sec II :SS _____ D.O.A: 20/6/18
 Is driver the owner? (YES / NO) Nature of Accident : _____
 If NO, Driver Name / Age: Chen Ming Hong
 Driver Tel No.: 9474863 (V/L: YES / NO)

Claim No.: MU18060605
 Policy No.: MUM0015
 Make / Model : H. Sonata
 Place of Accident : Bulevarway 7 C'menth Dr.

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
 Insured Liability: % Final ? Yes / No



INSRS: Charmador
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____

Date/ Time		STAGE	DATE / PIC
<u>20/6/18</u>	<u>605970 Y. x</u>	Non-Reporting ltr (1st):	
<u>20/6/18</u>	<u>SHC30617. call in / 6012103 / 11195. 20/6/18</u>	Non-Reporting ltr (2nd):	
<u>26/6/18</u>	<u>old ree-order tp.</u>	Non-Reporting ltr (Final):	
<u>26/6/18</u>	<u>seek 100% liability.</u>	Notification ltr (if non-pickup):	
<u>27/6/18</u>	<u>TP ✓ W/L.</u>	Call OI:	
<u>27/6/18</u>	<u>Email TP: DS.</u>	After call ltr to OI:	
<u>9/7/18</u>	<u>File pass to Marinos to finalise</u>	Documentation Check List: Handler Typist	
<u>26/7/18</u>	<u>Prepass to type material</u>	Notification ltr (if non-pickup):	
<u>27/7/18</u>	<u>File pass to Merimen to close</u>	After call ltr to OI:	
	<u>* DV - rounded by correction tape.</u>	Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE		Date/Time: _____	Sent By: _____
FINALIZATION		Date/Time: _____	Confirm with: _____
Repair Cost:	SS _____	(_____ days) Reduction:	% _____
FINAL SETTLEMENT		Date/Time: <u>27/7/18</u>	Confirm with: <u>Jason</u>
Final Liability:	% <u>100</u>	(Agreed / Assessed) BOLA S/N No.:	<u>27</u>
Repair Cost:	SS <u>4500.00</u>		
Loss of Rental (LOR):	SS _____	(_____ days)	
Loss of Use (LOU):	SS <u>320.00</u>	(<u>\$80</u> x <u>4</u> days)	
Loss of Income (LOI):	SS _____	(\$ _____ x _____ days)	
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search	SS _____		
Medical:	SS _____		
Disbursement:	SS _____	(e.g. Tow/ Independent)	
Legal Cost	SS _____		
Total:	SS <u>4820.00</u>	Global Sum SS:	
FINAL PAYMENT		Date/Time: <u>27/7/18</u>	Confirm with: <u>Jason</u>
Payee 1:	SS <u>4820.00</u>	Name 1:	<u>Choo Motor Spray Painter</u>
Payee 2: (Strike if N.A.)	SS _____	Name 2:	
Payee 3: (Strike if N.A.)	SS _____	Name 3:	

(08/11/13) waf

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 63D59704

at Workshop m/s Choo m/s

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 30 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

01/8N

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 63D59704 Yr Regn: 1 / 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: Toyota Dyna C.C. 2982

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 66333 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFA 735 Y JOK 204035

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195-R15

R: 155-R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal. 6 mm

R/Bal. 6/6 mm

L/Bal. 6 mm

L/Bal. 6/6 mm

D.O.A.

D.O.I. 20/6/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/7/18 hme h/a 27A 39912
confirmed L/S \$4500 with Alu.

(Reel \$650 / 59%)

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CC6/III18011195/Upa3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 20-06-2018	
			Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3061T		Veh. Inspected	GBD 5970Y
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	20/06/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/06/2018		Inspection Date	20/06/2018
Survey held at	CHOO MOTOR SPRAY PAINTER 1 KAKI BUKIT AVENUE 6 #01-39 AUTOBAY@KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SINGAPORE 417883

Date _____

Not Affected
all
2/s # 4500
4 dy.
20/6/18

1 PCS

REAR LICENCE PLATE INNER 'L' BRACKET

TO PUTTY & SPRAY PAINTING

(25)

\$6,301.00

2

nm

\$20.00 ~~110~~

1,000.00 657

\$11,081.00

5637.72

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0118N
Vehicle Details	
Vehicle No.:	GBD5970Y
Vehicle to be Exported:	No
Intended De-registration Date:	20 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	1KD2468316
Chassis No.:	JTFAT35Y80K204035
Maximum Power Output:	-
Open Market Value:	\$27,856.00
Original Registration Date:	06 Jan 2015
First Registration Date:	06 Jan 2015
Transfer Count:	0
Actual ARF Paid:	\$1,393.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Jan 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$61,000.00
COE Rebate Amount:	\$39,912.00
Total Rebate Amount:	\$39,912.00

The information contained herein is correct as at 20 Jun 2018

OK

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD![Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Altis 1.6A



\$2500 Downpayment Monthly
From \$588 Onwards.
GV Credit Pte Ltd StarAd



Browse by Category ▼

Sort by

12 vehicles

Toyota Dyna

Advanced

Make Model Price Depreciation Reg Date Eng Cap Mileage

Search Selection

Toyota Dyna

Any

Any

2015

Any



Toyota Dyna 150

\$52,800

\$7,100 /yr

24-Nov-2015

2,982 cc

63

Fuel Type: Diesel

The Japanese Workhorse For Your Company Needs. Low Maintenance And Low Fuel Consumption. Highest Trade-in Value. Flexible Loan Of Up To 90% Available! 1x Free Servicing At Our A...

Dynamic Motoring

Posted: 19-Jun-2018 Tags: 2015 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota



Toyota Dyna 150

\$50,888

\$7,140 /yr

04-Aug-2015

2,982 cc

13

Fuel Type: Diesel

The Most Reliable Brand For Your Business Use. Under Utilised Vehicle, Super Low Mileage At 14000Km Only! 3 Days Delivery. Low Diesel Consumption. Comes With Half Canopy, Hurry Com...

Net Link Partners Pte Ltd

Posted: 18-Jun-2018 Tags: 2015 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota



Toyota Dyna 150

\$50,888

\$7,140 /yr

03-Aug-2015

2,982 cc

Fuel Type: Diesel

Please Call To Arrange For Viewing, Thanks.

Posted: 14-Jun-2018 Tags: 2015 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota



Toyota Dyna 150

\$53,800

\$7,290 /yr

06-Nov-2015

2,982 cc

68

Fuel Type: Diesel

Low Miles, Super Good Condition, Warranty Provided, Well Maintenance By Previous Owner, Price Can Negotiate, High Loan Value Available, High Trade In Value, Call Now!

ABWIN Bus Pte Ltd

Posted: 08-Jun-2018 Tags: 2015 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

[Compare](#)[Car Selling](#)[Car Ownership](#)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0118N
Vehicle Details	
Vehicle No.:	GBD5970Y
Vehicle to be Exported:	No
Intended De-registration Date:	20 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	1KD2468316
Chassis No.:	JTFAT35Y80K204035
Maximum Power Output:	-
Open Market Value:	\$27,856.00
Original Registration Date:	06 Jan 2015
First Registration Date:	06 Jan 2015
Transfer Count:	0
Actual ARF Paid:	\$1,393.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Jan 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$61,000.00
COE Rebate Amount:	\$39,912.00
Total Rebate Amount:	\$39,912.00

The information contained herein is correct as at 20 Jun 2018

OK

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	20 Jun 2018 15:42	Clim Veh Model Changed	(204575) TOYOTA DYNA 150 3.0 D (M).	[A] HOW MEI KWAN
2	20 Jun 2018 15:42	Clim Created	Reg No: GBD5970Y, Acct Date: 2018/06/20, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), Workshop: Choo Motor Spray Painter (HQ)	[A] HOW MEI KWAN
3	20 Jun 2018 15:42	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
4	20 Jun 2018 15:42	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/29	[A] HOW MEI KWAN
5	20 Jun 2018 15:42	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
6	20 Jun 2018 15:42	Label Added	(30653):Direct Settlement.	[A] HOW MEI KWAN
7	20 Jun 2018 15:42	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] HOW MEI KWAN
8	21 Jun 2018 15:54	TP Ins Updated	TPInsurer:[None] -> Great American Insurance Company (HQ).	[A] HOW MEI KWAN
9	21 Jun 2018 15:54	Clim Registration Modified	Acct Time:00:00:00->11:00:00.	[A] HOW MEI KWAN
10	21 Jun 2018 15:55	Clim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] HOW MEI KWAN
11	21 Jun 2018 15:55	Clim Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD. Claimant's ID: -> 199303821R.	[A] HOW MEI KWAN
12	21 Jun 2018 17:45	TP Ins Updated	TPPolNo:[None] -> MOMVC000002394-01-000.	[A] HOW MEI KWAN
13	26 Jun 2018 14:21	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% Remarks: Insured driver rear-ended third party.	[A] CHEW HSIAO TONG
14	27 Jun 2018 10:16	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/29	[I] Zuhaidah Bte Samsuri
15	27 Jun 2018 10:16	Adj Mandate Set	Approved:0.00.	[I] Zuhaidah Bte Samsuri
16	31 Jul 2018 13:57	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
17	31 Jul 2018 13:57	Clim Dtl Modified	JPJ Reg. Date: -> 2015/01/06.	[A] JOANNE LEE KHANG MIN
18	31 Jul 2018 13:57	Clim Details Notified		[A] JOANNE LEE KHANG MIN
19	03 Aug 2018 09:48	Adj Mandate Request	Cur.Req:4950.00:PODS Liability: 100% Quantum: (a)COR:\$4,500.00 + (b)LOU(5days x \$90.00): \$450.00 = Total:\$4,950.00 Vehicle Model: Toyota Dyna (2982cc). For your approval pls.	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1874534	31/07/2018	Motor	LKK Auto	LKK Auto	GBD5970Y	SHC3061T	10.70

8/3/2018

Merimen e-Claims

13:57

Consultants Pte
Ltd

Consultants Pte
Ltd (HQ)

Print Received Message

This mail is associated with :

***GBD5970Y (MCT18060605)**
[SHC3061T]

TP

ARC FLOOR PTE LTD

Jun 20 2018 11:00AM

[COMFORT TRANSPORTATION PTE LTD]

Choo Motor Spray Painter

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 03/08/2018 10:18 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4950.00) - GBD5970Y - Claim Handler: Zuhaidah Bte Samsuri

Approved:4950.00.

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Monday, 6 August 2018 9:39 AM
To: Jason Fastech Auto (jason@fastechauto.com.sg)
Subject: Your Ref: GBD 5970Y *Our Ref: CC6/III18011195/Upa3 [ACCIDENT INVOLVING SHC 3061T(III) & GBD 5970Y ON 20/06/2018]

Your Ref: **GBD 5970Y**
Our Ref: CC6/III18011195/Upa3

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SHC 3061T(III) & GBD 5970Y ON 20/06/2018

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair	\$ 4,500.00
2. Loss of Use (4days x \$80.00)	\$ 320.00
TOTAL	<u>\$ 4,820.00</u>

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Jason Fastech Auto <jason@fastechauto.com.sg>
Sent: Monday, 6 August 2018 11:13 AM
To: Hsiao Tong (LKKAUTO)
Subject: RE: Your Ref: GBD 5970Y *Our Ref: CC6/III18011195/Upa3 [ACCIDENT INVOLVING SHC 3061T(III) & GBD 5970Y ON 20/06/2018]

Without Prejudice

Dear Hsiao Tong,

We are pleased to accept your offer of \$ 4,820.00 all in.

Thank you.

Best Regards

Tang Jun Zhong
Choo Motor Spray Painter
1 Kaki Bukit Ave 6
#01-39 AutoBay
Singapore 417883
Tel: 6746 8443
ChooMotorClaim@gmail.com

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Monday, August 6, 2018 9:39 AM
To: Jason Fastech Auto (jason@fastechauto.com.sg) <jason@fastechauto.com.sg>
Subject: Your Ref: GBD 5970Y *Our Ref: CC6/III18011195/Upa3 [ACCIDENT INVOLVING SHC 3061T(III) & GBD 5970Y ON 20/06/2018]

Your Ref: **GBD 5970Y**
Our Ref: CC6/III18011195/Upa3

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SHC 3061T(III) & GBD 5970Y ON 20/06/2018

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair	\$ 4,500.00
2. Loss of Use (4days x \$80.00)	\$ 320.00
TOTAL	<u>\$ 4,820.00</u>

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Co. Reg No: 22736900M

Tel No: 67452063 / 67467158 Fax No: 67458520

Date 13.07.2018

India International Insurance Pte Ltd

64 Cecil Street

#04-05 IOB Building

Singapore 049711

Attn: Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING VEHICLE: GBD5970Y AND SHA3061T ON 20.06.2018

We are the authorized repair workshop for the owner of motor vehicle no: GBD5970Y, which was involved in the captioned accident with your insured vehicle: SHC3061T. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

01) Cost of Repair	\$	4,500.00
02) Loss Of Use (4days + 1sun x \$120)	\$	600.00
	\$	5,100.00

We enclosed herewith the following documents to support the claims:-

- | | |
|------------------------------------|----------------------------------|
| a) Final Repair Bill | b) Vehicle Registration Log Card |
| c) GIA Report | d) I/C & Driving Licence |
| e) Insurance Certificate | f) GIA Search Fee |
| g) Letter of Authorisation, etc... | |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.

Yours faithfully,



For Choo Motor Spray Painter

Jason Tang

DATE : 20th June 2018

TO : India International Insurance Pte Ltd

RE : ACCIDENT INVOLVING VEHICLE NO. GBD 5970Y & SHC30617

ALONG Queenway Road towards Adam Road
ON 20/6/2018

I/We, ARC Floor Pte Ltd
of (NRIC No./ROC No.) 198600118N
of BIK 16 Hougang Ave 3 #02-12T S530016
owner of vehicle no. GBD 5970Y in consideration of M/s CHOO MOTOR SPRAY
PAINTER repairing my/our vehicle GBD 5970Y at my/our instruction and hereby
authorise M/s CHOO MOTOR SPRAY PAINTER to demand claim settlement whatever
amount settled/payable by the Insurance Company and/or third party or to commence legal
proceedings, if necessary, under my name, for the cost of repairs, car rental and/or loss of use,
etc. and to their appointing solicitor to act for me/us in respect of the said accident/claim and
all claimed and/or settled shall belong to them absolutely.

I/We further agree and undertake to indemnify them against the above-mentioned claim cost
which may arisen therewith.



Signature of Owner : _____

Name of Owner : ARC FLOOR PTE LTD

EXPRESS SETTLEMENT

DISCHARGE VOUCHER

III- Direct Settlement (PODS)

India Ref: MCT18060605
Claimant Ref: GBD 59704

We/I, Choo Motor Spray Painter (the workshop) hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 4500.00 (repair cost), S\$ 320.00 (loss of use/rental), S\$ — (search fee), vehicle no. GBD59704 that was damaged pursuant to the accident which occurred on 20/6/18 (date) at Queensway Road, twi & Adam Rd (location) involving vehicle no. SHC3061T (insured vehicle). This is pursuant to the inspection conducted on 20/6/18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner ARC Floor Pte Ltd ("the third party claimant") of vehicle no. GBD59704 to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to GBD59704 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 4820.00 to Choo Motor Spray Painter.

Dated this 07 day of Aug 20 18.

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

Signed by "the workshop" (with chop)

CHOO MOTOR SPRAY PAINTER

22736900M

1 KAKI BUKIT AVE 6

#01-39 AUTOBAY S 417883

—

—

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

Signed by appointed Surveyor

LKK Auto Consultants Pte Ltd

199607198R

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park 01408933

—

—

TAX INVOICE

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Co. Reg No: 22736900M

Tel No: 67452063 / 67467158 Fax No: 67458520

India International Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Attn : Motor Claim Department

Invoice : 20357

Date: 13.07.2018
Vehicle No: GBD5970Y
Make/Model: TOYOTA DYNA
Chassis/Eng# :
Accident Date: 20.06.2018
Claim No : 0618-20357
Reference :
Policy No :

	Amount
To proceed on lump sum repair	S\$ 4,500.00

E. & O. E.

Total : S\$ 4,500.00

Amount Due : S\$ 4,500.00



CHOO MOTOR SPRAY PAINTER

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jun 2018 Edit Reg		20 Jun 2018 00:00 Edit Adj Rpt	S\$4,500.00 Edit Estimates	S\$4,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	ARC FLOOR PTE LTD, Co. Reg. No.: 198600118N		
Vehicle Reg. No.:	GBD5970Y	Date of Loss:	20/06/2018 11:00 - :59 [41 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18060605	Policy/Cover Note No.:	MCDM0015
Vehicle Reg. No. (Insured):	SHC3061T	Policy No. (Claimant):	MOMVC000002394-01-000
		Excess:	
Repairer:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 67453897		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]		
Claimant's Insurer:	Great American Insurance Company (HQ) - Tel: 6804 6047		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 29/06/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)




































- III_SG (03/08/2018): Alert - Adj Mandate Approved (S\$4950.00) - GBD5970Y - Claim Handler: Zuhaidah Bt...
- III_SG (27/06/2018): Alert - Adj Mandate Approved (S\$0.00) - GBD5970Y - Claim Handler: Zuhaidah Bte S...

















































ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)





Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBD5970Y (MCT18060605)
[SHC3061T]
TP
ARC FLOOR PTE LTD
Jun 20 2018 11:00AM
[COMFORT TRANSPORTATION PTE LTD]
Choo Motor Spray Painter

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	03/08/18 09:43	Chassis Number		 Load JPG	<input checked="" type="checkbox"/>			
2	03/08/18 09:43	Odometer Reading		 Load JPG	<input checked="" type="checkbox"/>			
3	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
4	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
5	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
6	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
7	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
8	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
9	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
10	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
11	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
12	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
13	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
14	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
15	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
16	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
17	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
18	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
19	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
20	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
21	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
22	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
23	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
24	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
25	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
26	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
27	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
28	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
29	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
30	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
31	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
32	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
33	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
34	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
35	03/08/18 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>			
36	03/08/18 09:43	General View		Load JPG	<input checked="" type="checkbox"/>			
37	03/08/18 09:43	General View		Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	03/08/18 09:43	General View	 Load JPG	<input checked="" type="checkbox"/>
39	03/08/18 09:43	General View	 Load JPG	<input checked="" type="checkbox"/>
40	03/08/18 09:43	General View	 Load JPG	<input checked="" type="checkbox"/>
41	03/08/18 09:43	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/08/18 09:43	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/08/18 09:43	General View	 Load JPG	<input checked="" type="checkbox"/>
44	03/08/18 09:43	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/08/18 09:43	General View	 Load JPG	<input checked="" type="checkbox"/>
46	03/08/18 09:43	General View	 Load JPG	<input checked="" type="checkbox"/>
47	03/08/18 09:43	General View	 Load JPG	<input checked="" type="checkbox"/>
48	03/08/18 09:43	General View	 Load JPG	<input checked="" type="checkbox"/>
49	03/08/18 09:43	General View	 Load JPG	<input checked="" type="checkbox"/>
50	03/08/18 09:43	General View	 Load JPG	<input checked="" type="checkbox"/>
51	03/08/18 09:43	General View	 Load JPG	<input checked="" type="checkbox"/>
52	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	03/08/18 09:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/06/18 17:44	TP GIA REPORT	 Load PDF	
2	31/07/18 14:10	WORKSHOP INVOICE	 Load PDF	
3	31/07/18 14:10	LOD	 Load PDF	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
4	03/08/18 09:46	TP ESTIMATE_MARKED	 Load PDF	
5	13/08/18 08:15	DISCHARGE VOUCHER	 Load PDF	
6	13/08/18 08:15	AUTHORISATION TO ACT FORM	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	21/06/18 08:40	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18011195/UPA3Q2

Date: 13/08/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
Claimant Vehicle GBD5970Y **Insured Vehicle No :** SHC3061T
No :
 Date of Loss: 20/06/2018 Nature of Claim: TP Claim No: MCT18060605

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD5970Y**
 Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2468316
 Reg. Date: 06/01/2015 (Man. Year: 2014) Chassis No: JTFAT35Y80K204035
 Colour: White Odometer: 86333 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 155 R12 (D)
 Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6/6 mm
 Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,141.00	4,047.72	4,093.28	50.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	1,590.00	1,350.00	45.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,081.00	5,637.72	5,443.28	49.12
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	11,081.00	4,500.00	6,581.00	59.39
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
Nett Liability (S\$)		4,820.00		

INSPECTION

Date of Assignment: 20/06/2018
 Date Inspected: 20/06/2018 Inspected At: Choo Motor Spray Painter (HQ)
 1 Kaki Bukit Avenue 6, #01-39 AutoBay @
 Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 Jul 2018)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD5970Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented / Bent	1,885.10 F	*1,615.10 FL
2	1		*TAILGATE TOYOTA STICKER	Not fitted	176.50 F	*- FL
3	1		*TAILGATE LOWER MEMBER	Bent	848.20 F	*545.10 FL
4	2		*TAILGATE LOCK LACTCHS	Repair	238.60 F	*- FL
5	1		*TAILGATE LOWER L PANEL N/S	Repair	90.50 F	*- FL
6	1		*TAILGATE LOWER L PANEL STOPPER N/S	Not Necessary	62.30 F	*- FL
7	2		*TAILLAMPS	Cracked	570.60 F	*570.60 FL
8	2		*TAILLAMPS BRACKETS	Bent	238.40 F	*238.40 FL
9	1		*REAR LICENCE PLATE BRACKET	Bent	119.50 F	*119.50 FL
10	1		*REAR SPARE TYRE BRACKET & CHAIN	Twisted / Jammed	392.40 F	*392.40 FL
11	1		*REAR EXHAUST	Bent / Twisted	585.20 F	*585.20 FL
12	1		*REAR EXHAUST MOUNTING	Twisted	112.00 F	*112.00 FL
13	1		*REAR SPARE TYRE BRACKET & CHAIN TOP MEMBER	Not Necessary	866.20 F	*- FL
14	1		*REAR LICENCE PLATE INNER L BRACKET	Repair	115.50 F	*- FL
15	1		*TAILGATE 70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
16	1		*REAR LICENCE PLATE	Bent	20.00 FS	*14.00 FS
17	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
18	1		*REAR DYNA STICKER	Necessary	80.00 FS	*30.00 FS
19	1		*SET REAR TAILGATE CORORATE STICKER	Necessary	520.00 FS	*350.00 FS
20	1		*REAR SPARE TYRE & RIM REAR	Not Necessary	200.00 FS	*- FS
21	1		*REAR SPARE TYRE & RIM FRONT	Not Necessary	200.00 FS	*- FS
22	1		*TAILGATE LOWER STEP PANEL	Bent	500.00 FS	*300.00 FS
23	1		*TAILGATE 13 PAX STICKER	Necessary	20.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,141.00	5,092.30
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,044.58
Total Parts (\$\$)	8,141.00	4,047.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO REPAIR & REALIGN CHASSIS MEMBER	New	680.00	0.00
3	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	60.00
4	TO SPRAY RUST PROOFING	New	80.00	50.00
5	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,000.00	800.00
6	TO PUTTY & SPRAY PAINTING	New	1,000.00	650.00
Gross Labour Cost (S\$)			2,940.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >