

1/20/18

INS. CASE OWNER

CC 6 / AUG 1801 1706, Kpong

LKK

IDAC

Surveyor:

Kenneth

DOI:

ASSIGNMENT

Date / Time:

12/6/18

Registered in Merimen:

20/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLF 97264

Name of Insured:

UP

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

15/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO. Driver Name / Age:

THW HAW LEONG

Driver Tel No.:

(VIL: YES / NO)

Claim No.:

845737456554

Policy No.:

14444444

Make / Model:

MINI COOPER

Place of Accident:

WOODLANDS AVE 7 TUKANGA TO WOODLANDS AVE 2

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

% Final? Yes / No

SLV 29770



INSRS:

WSP:

Tel:

Liability:

RMKS:

OPTIMA



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

22/6/18
JAY

SLV 29770 - X

SLV 29770 - X

OI HIT IP FROM REAR

STAGE	DATE / PIC
Non-Reporting Itr (1st):	
Non-Reporting Itr (2nd):	
Non-Reporting Itr (Final):	
Notification Itr (if non-pickup):	
Call OI:	20/6/18
After call Itr to OI:	
Documentation Check List: Handler Typist	
Notification Itr (if non-pickup):	<input checked="" type="checkbox"/>
After call Itr to OI:	<input checked="" type="checkbox"/>
Authorisation To Act:	<input checked="" type="checkbox"/>
Release Voucher:	<input checked="" type="checkbox"/>
Final Repair Bill:	<input checked="" type="checkbox"/>
Car Rental Invoice:	<input checked="" type="checkbox"/>
Towing Invoice:	<input checked="" type="checkbox"/>
LTA / GIA:	<input checked="" type="checkbox"/>
Medical Bill:	<input checked="" type="checkbox"/>
PIR:	<input checked="" type="checkbox"/>
Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
LOI:	<input checked="" type="checkbox"/>
Payment Breakdown Form:	<input checked="" type="checkbox"/>
Post-Repair Photos:	<input checked="" type="checkbox"/>
Others:	<input checked="" type="checkbox"/>

L 28-1-19 LOD IN. FOR MANDATE

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	SS	(days) Reduction:	%
FINAL SETTLEMENT		Date/Time:	Confirm with:
Final Liability:	%	(Assessed) BOLA S/N No.:	27
Repair Cost:	SS	9,210.39	18 days
Loss of Rental (LOR):	SS	1,926	100
Loss of Use (LOU):	SS	(\$ x days)	
Loss of Income (LOI):	SS	(\$ x days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/> [Tick only one]		
GIA/LTA Search	SS	7.45	
Medical:	SS		
Disbursement:	SS		(e.g. Tow/ Independent)
Legal Cost	SS		
Total:	SS	11,143.84	Global Sum SS: 11,000.XX
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	SS	11,000.XX	Name: OPTIMA WERKZ PTE LTD
Payee 2: (Strike if N.A.)	SS	X	Name 2: X
Payee 3: (Strike if N.A.)	SS		Name 3: X

COPY SENT

ASS. REC. BY:

REF:

AIGI

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

12-14 days

Res.: Yes or No

Lum Sum:

1. B. 1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLV 39770

Yr Regn:

12, 17

Type:

M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda FIT

c.c.

1317

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

10205

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GK3

1304928

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

15/6/18

D.O.I.

19/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/6 File pass to Catherine

24-9-18 \$ 8,607.84

R (A6, 117.68/429)

Date/Time, File Pass to?

☐

Prell. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Fixes

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I.: (\$

TOTAL

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 18 JUNE 2018

Third Party Insurer: AIG

Vehicle No: SLV3977D

Third Party Veh No: SLF9726G

Model: HONDA FIT

Date of Accident: 15 JUNE 2018

Chassis: GK3-1304928

Not Authorized
Recovery 34 point
ESTIMATE

\$ 8607.84

14 days

QTY	DESCRIPTION	UNIT	SS	AMOUNT	SS
1	REAR TAILGATE			<i>By</i>	\$844.20 ✓
1	REAR TAILGATE WINDSCREEN			<i>By</i>	\$970.70 X
1	REAR TAILGATE WINDSCREEN MOULDING			<i>By</i>	\$105.20 ✓
1	REAR TAILGATE LOGO EMBLEM			<i>By</i>	\$24.60 ✓
1	REAR TAILGATE FIT EMBLEM			<i>By</i>	\$34.60 ✓
1	REAR TAILGATE OUTER GARNISH			<i>By</i>	\$194.70 ✓
4	REAR TAILGATE OUTER GARNISH CLIPS		\$5.80	<i>By</i>	\$23.20 ✓
2	REAR TAILGATE NUMBER LAMP LH/RH		\$46.80	<i>By</i>	\$93.60 X
2	REAR TAILGATE REFLECTOR LH/RH		\$242.10	<i>By</i>	\$484.20 X
1	REAR TAILGATE INNER TRIM BOARD			<i>By</i>	\$114.30 ✓
10	REAR TAILGATE INNER TRIM BOARD CLIPS		\$5.80	<i>By</i>	\$58.00 ✓
1	REAR TAILGATE MECHANISM LOCK			<i>By</i>	\$204.10 ✓
1	REAR TAILGATE WEATHER STRIP			<i>By</i>	\$109.10 ✓
1	REAR TAILGATE INNER HANDLE			<i>By</i>	\$16.80 X
1	REAR LH TAILLAMP				\$403.10 ✓
2	REAR LH TAILLAMP CLIPS		\$5.80		\$11.60 ✓
1	REAR LH TAILLAMP INNER PANEL			<i>By</i>	\$98.90 ✓
1	REAR BUMPER			<i>By</i>	\$828.90 ✓
1	REAR BUMPER LH GARNISH			<i>By</i>	\$75.30 X
1	REAR BUMPER CENTER GARNISH			<i>By</i>	\$204.10 X
10	REAR BUMPER CLIPS		\$3.90	<i>By</i>	\$39.00 ✓
2	REAR BUMPER SIDE RETAINER LH/RH		\$37.90		\$75.80 ✓
1	REAR BUMPER LH INNER SIDE SHIELD			<i>By</i>	\$59.20 X
4	REAR BUMPER LH INNER SIDE SHIELD CLIPS		\$3.90	<i>By</i>	\$15.60 X
1	REAR LH FENDER			<i>By</i>	\$959.10 ✓
1	REAR LH FENDER GLASS MOULDING			<i>By</i>	\$28.30 ✓
1	REAR LH FENDER INNER AIR VENT			<i>By</i>	\$28.90 X
1	REAR LH FENDER INNER PANEL			<i>By</i>	\$700.80 X
1	REAR FENDER INNER UPHOLSTERY TRIM LH/RH		\$355.50		\$711.00 ✓
1	REAR FENDER INNER UPHOLSTERY TRIM CLIPS LH/RH		\$5.80		\$92.80 ✓
1	REAR LH DOOR			<i>By</i>	\$828.90 X
1	REAR LH DOOR MECHANISM LOCK			<i>By</i>	\$272.90 X
1	REAR END PANEL			<i>By</i>	\$370.10 ✓
1	REAR END PANEL INNER TOP GARNISH			<i>By</i>	\$70.70 ✓
1	REAR END PANEL LOCK STRIKER			<i>By</i>	\$22.80 ✓
1	REAR END PANEL TAILGATE ANTENA SENSOR			<i>By</i>	\$126.80 X
1	REAR END PANEL TAILGATE ANTENA SENSOR BUZZER			<i>By</i>	\$107.30 X

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 18 JUNE 2018

Third Party Insurer: AIG

Vehicle No: SLV3977D

Third Party Veh No: SLF9726G

Model: HONDA FIT

Date of Accident: 15 JUNE 2018

Chassis: GK3-1304928

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR LH SUB CHASSIS FRAME		<i>PC</i> \$581.70
1	REAR LH SUB CHASSIS FRAME TOP PANEL		<i>PC</i> \$186.50
1	REAR LH SUB CHASSIS FRAME EXTENSION		<i>PC</i> \$29.30
1	REAR WELL PANEL		<i>PC</i> \$946.70
1	REAR WELL PANEL INNER TOP UPHOLSTERY BOARD		<i>PC</i> \$236.60
1	REAR WELL PANEL INNER TOP TOOLS SPONGE		<i>PC</i> \$185.60
1	REAR WELL PANEL INSULATOR MAT		<i>PC</i> \$89.90
1	REAR SUSPENSION LH SHOCK ABSORBER		<i>PC</i> \$221.80
1	REAR SUSPENSION LH WHEEL HUB BEARING		<i>PC</i> \$332.10
SUB TOTAL			\$12,219.40
Less 20%			-\$2,443.88
PARTS TOTAL			\$9,775.52

X
X
X
X
X
X
X
X
X

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER		<i>PC</i> \$100.00
1	REAR BUMPER REVERSE SENSOR		<i>PC</i> \$280.00
1	REAR RH FENDER GLASS SEALANT WITH PRIMER		<i>PC</i> \$80.00
S/N TOTAL			\$460.00

40sn
200sn
30sn

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 18 JUNE 2018

Third Party Insurer: AIG

Vehicle No: SLV3977D

Third Party Veh No: SLF9726G

Model: HONDA FIT

Date of Accident: 15 JUNE 2018

Chassis: GK3-1304928

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,600.00	140d
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$1,500.00	110d
TO TUFF KOTE / ANTI-RUST	\$80.00	✓
TO CHECK WIRING, LIGHTING & WATER LEAKAGE	\$60.00	2d
TO REMOVE AND REFIT REAR RH FENDER QUARTER GLASS	\$120.00	5d
TO DISMANTLE & REINSTALL REAR INTERIOR CARPET COMPONENT TO FACILITATE REPAIR	\$250.00	120d
TO DISMANTLE REAR EXHAUST SILENSER BOX	\$150.00	6d
TO DISMANTLE & REFIX REAR TAILGATE REVERSE CAMERA	\$60.00	5d
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$60.00	5d
TO REMOVE AND REFIT REAR WINDSCREEN PERFORM	\$150.00	12d
TO DISMANTLE & REPLACED REAR LH UNDER CARRIAGE COMPONENT TO FACILITATE REPAIR	n~\$180.00	X
TO MOUNT VEHICLE ONTO 3D COMPUTERISE CAR 'O' LINER TO CALIBRATE SUB CHASSIS FRAME & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$280.00	25d

LABOUR TOTAL \$4,490.00

TOTAL \$14,725.52

WINSON

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 3



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/LCR18011206/Kjb3		
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 20-06-2018		
		Code : LCR		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLF 9726G	Veh. Inspected	SLV 3977D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	20/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/06/2018	Inspection Date	19/06/2018	
Survey held at	OPTIMA WERKZ PTE LTD 6, KUNG CHONG ROAD SINGAPORE 159143			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 18 JUNE 2018

Third Party Insurer: AIG

Vehicle No: SLV3977D

Third Party Veh No: SLF9726G

Model: HONDA FIT

Date of Accident: 15 JUNE 2018

Chassis: GK3-1304928

Not Authorised
Resony B4 paint
ESTIMATE

QTY	DESCRIPTION	UNIT	S\$	AMOUNT S\$
1	REAR TAILGATE			<i>R</i> \$977.40
1	REAR TAILGATE WINDSCREEN			\$970.70
1	REAR TAILGATE WINDSCREEN MOULDING			<i>m</i> \$125.20
1	REAR TAILGATE LOGO EMBLEM			\$24.60
1	REAR TAILGATE FIT EMBLEM			<i>m</i> \$34.60
1	REAR TAILGATE OUTER GARNISH			\$185.60
4	REAR TAILGATE OUTER GARNISH CLIPS		\$5.50	\$22.00
2	REAR TAILGATE NUMBER LAMP LH/RH		\$46.80	<i>m</i> \$93.60
2	REAR TAILGATE REFLECTOR LH/RH		\$262.10	\$524.20
2	REAR TAILGATE HINGE LH/RH		\$45.50	<i>R</i> \$91.00
2	REAR TAILGATE DAMPER LH/RH		\$138.50	<i>m</i> \$277.00
1	REAR TAILGATE INNER TRIM BOARD			\$164.30
10	REAR TAILGATE INNER TRIM BOARD CLIPS		\$5.50	\$55.00
1	REAR TAILGATE MECHANISM LOCK			<i>Ref/m</i> \$234.10
1	REAR TAILGATE WEATHER STRIP			\$119.10
1	REAR TAILGATE INNER HANDLE			\$26.70
2	REAR TAILLAMP LH/RH		\$493.30	\$986.60
4	REAR TAILLAMP CLIPS LH/RH		\$5.80	\$23.20
1	REAR TAILLAMP LH INNER PANEL			\$109.70
1	REAR BUMPER			<i>R</i> \$803.60
1	REAR BUMPER LH GARNISH			
1	REAR BUMPER CENTER GARNISH			
10	REAR BUMPER CLIPS		\$6.80	<i>m</i> \$95.20
2	REAR BUMPER SIDE RETAINER LH/RH		\$25.50	\$51.00
1	REAR BUMPER LH INNER SIDE SHIELD			<i>m</i> \$49.20
4	REAR BUMPER LH INNER SIDE SHIELD CLIPS		\$6.80	\$27.20
1	REAR LH FENDER			<i>Bu</i> \$859.10
1	REAR LH FENDER GLASS MOULDING			<i>m</i> \$28.80
1	REAR LH FENDER INNER AIR VENT			\$28.90
1	REAR LH FENDER INNER UPHOLSTERY TRIM			\$194.70
4	REAR LH FENDER INNER UPHOLSTERY TRIM CLIPS		\$5.80	\$23.20
1	REAR LH FENDER INNER PANEL			\$680.80
1	REAR LH DOOR			<i>R</i> X
1	REAR LH DOOR MECHANISM LOCK			<i>R</i> X
1	REAR LH DOOR BLACK FRAME STICKER			<i>m</i> X
1	REAR LH DOOR WEATHER STRIP			<i>m</i> X
1	REAR LH DOOR LOCK STRIKER			<i>R</i> X

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 18 JUNE 2018

Third Party Insurer: AIG

Vehicle No: SLV3977D

Third Party Veh No: SLF9726G

Model: HONDA FIT

Date of Accident: 15 JUNE 2018

Chassis: GK3-1304928

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR END PANEL		3 \$370.10
1	REAR END PANEL INNER TOP GARNISH		\$98.60
4	REAR END PANEL INNER TOP GARNISH CLIPS	\$5.50	\$22.00
1	REAR END PANEL LOCK STRIKER		\$25.80
1	REAR LH SUB CHASSIS FRAME		12 \$581.70
1	REAR LH SUB CHASSIS FRAME TOP PANEL		
1	REAR WELL PANEL		
1	REAR WELL PANEL INNER TOP UPHOLSTERY BOARD		\$286.00
1	REAR WELL PANEL INNER TOP TOOLS SPONGE		\$185.60
1	REAR SUSPENSION LH SHOCK ABSORBER	Sm	
1	REAR SUSPENSION LH WHEEL HUB BEARING	Sm	
SUB TOTAL			\$9,456.10
Less 20%			-\$1,891.22
PARTS TOTAL			\$7,564.88

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER		\$100.00
1	REAR TAILGATE REVERSE CAMERA	Sm	\$450.00
1	REAR BUMPER REVERSE SENSOR	Ref	\$280.00
1	REAR RH FENDER GLASS SEALANT WITH PRIMER	me	\$80.00
S/N TOTAL			\$910.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 18 JUNE 2018

Third Party Insurer: AIG

Vehicle No: SLV3977D

Third Party Veh No: SLF9726G

Model: HONDA FIT

Date of Accident: 15 JUNE 2018

Chassis: GK3-1304928

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

Tacca, fin
\$1,600.00 7

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

\$1,500.00 1100

TO TUFF KOTE / ANTI-RUST

\$80.00 ✓

TO CHECK WIRING, LIGHTING & WATER LEAKAGE

\$60.00 20

TO REMOVE AND REFIT REAR RH FENDER QUARTER GLASS

\$120.00 50

TO DISMANTLE & REINSTALL REAR INTERIOR CARPET COMPONENT TO FACILITATE REPAIR

\$250.00 120

TO DISMANTLE REAR EXHAUST SILENSER BOX

\$150.00 60

TO DISMANTLE & REFIX REAR TAILGATE REVERSE CAMERA

\$60.00 50

TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR

\$60.00 50

TO REMOVE AND REFIT REAR WINDSCREEN PERFORM

\$150.00 120

TO DISMANTLE & REINSTALL ROOF TOP INNER LINING ASSEMBLY

\$250.00 X

TO DISMANTLE & REPLACED REAR LH UNDER CARRIAGE COMPONENT TO FACILITATE REPAIR

\$180.00 7

TO MOUNT VEHICLE ONTO 3D COMPUTERISE CAR 'O' LINER TO CALIBRATE SUB CHASSIS FRAME & CAR BODY BACK TO MANUFACTURING SPECIFICATION

\$280.00 ?

LABOUR TOTAL \$4,740.00

WINSON

TOTAL \$13,214.88

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 1144C

Vehicle Details

Vehicle No.: SLV3977D
Vehicle to be Exported: No
Intended De-registration Date: 16 Jun 2018
Vehicle Make: HONDA
Vehicle Model: FIT 1.3GF CVT
Primary Colour: Silver
Manufacturing Year: 2017
Engine No.: L13B1405302
Chassis No.: GK31304928
Maximum Power Output: 73.0 kW (97 bhp)
Open Market Value: \$14,484.00
Original Registration Date: 28 Dec 2017
First Registration Date: 28 Dec 2017
Transfer Count: 0
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Dec 2027
PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 27 Dec 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$38,200.00
COE Rebate Amount: \$36,402.00
Total Rebate Amount: \$40,152.00

The information contained herein is correct as at 16 Jun 2018

OK

Our Ref : SLV3977D / TP#669
Your Ref : SLF9726G

WITHOUT PREJUDICE

Date : 25 September 2018

AIG ASIA PACIFIC INSURANCE PTE. LTD.
AIG BUILDING
78 Shenton Way #07-16
Singapore 079120

Attention: Motor Claims Department

**ACCIDENT INVOLVING SLV3977D & SLF9726G ON 15/06/2018
ALONG WOODLANDS AVE 7 SLIP ROAD TO WOODLANDS AVE 2**

We refer to the above captioned.

We are claiming the below followings :

- Cost of Repair (incl. of GST)	S\$9,210.39
- Loss of Rental (incl. of GST)	S\$2,846.20 (\$149.80 x 19 days)
- LTA/GIA Search Fee	S\$7.45

Grand Total	<u>S\$12,064.04</u>
--------------------	----------------------------

If you have any enquiries, please contact our representative, Ms. Sharon Ten & Ms. Lily at 64849919 or email sharon@ow.sg / lily.loi@ow.sg

All payment is to be issued direct to **Optima Werkz Pte Ltd.**

Your prompt attention is most grateful and look forward to your speedy settlement.

Yours faithfully

OPTIMA WERKZ PTE LTD

Encl.

This is a computer generated printout and no signature is required.

Print Received Message

This mail is associated with :

***SLV3977D (8457574565SG)
[SLF9726G]**

TP
AZMAN BIN KASSIM
Jun 15 2018 11:00AM
[LCRF Pte Ltd]
Optima Werkz Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 28/01/2019 18:26 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$11143.84) - SLV3977D - Claim Handler: Tan, Wilson-KL

Approved:11143.84.

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Monday, 2 July 2018 9:24 AM
To: Eileen Yap
Cc: Admin A; Vivian Lau (LKKAuto); Hsiao Tong (LKKAuto)
Subject: ACCIDENT INVOLVING SLF 9726G (LCR) & SLV 3977D ON 15/06/2018 (11:30) ALONG WOODLANDS AVE 7 SLIP RD TO WOODLANDS AVE 2

02 July 2018

LCRF PTE LTD

Policy Holder

Your Ref: SLF 9726G
Our Ref: CC4/LCR18011206/Kjb3

Dear Sir/Madam,

ACCIDENT INVOLVING SLF 9726G (LCR) & SLV 3977D ON 15/06/2018 (11:30) ALONG WOODLANDS AVE 7 SLIP RD TO WOODLANDS AVE 2

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from **SLV 3977D** against your insurance policy.

Based on the information on hand, we are of the opinion that both drivers were giving conflicting of versions in cutting lane. We cannot be fully absolved from liability unless evidence proves our driver's version. As such, we will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to provide evidence, kindly send us a copy within 10 days from the date of this letter.

Please call us within 10 days from this letter, if you wish to further discuss on the matter prior to our negotiations and settlement.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender


AUTHORISATION TO ACT

I/We Azman Bin Kassim ("the third party claimant") of Blk 752
Woodlands Circle #04-534(S) 730⁷⁵² (address), owner of SLV39770 (vehicle
no.) hereby authorize Optima Werkz Pte Ltd ("the workshop")
to act for me with respect to my claim for repair costs and/or rental and/or loss of use
("claim") for my vehicle no. SLV39770 that was damaged pursuant to the accident which
occurred on 15/06/18 (date) along Woodlands Ave 7 Slip Rd to Woodlands Ave 2
(location) involving vehicle no/s SLF9726G ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they
deem fit and the workshop is further authorized to receive payment further to settlement of
my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a
without prejudice and without admission of liability basis insofar as the driver/owner/insurers
of the other vehicle/s is concerned.

Dated this 16th (day) of June (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, OPTIMA WERKZ PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$11,000.00 (Global Sum) for vehicle no. SLV 3977D that was damaged pursuant to the accident which occurred on 15/06/2018 (date) along WOODLANDS AVE 7 (location) involving vehicle no/s SLF 9726G. This is pursuant to the inspection conducted on 19/06/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner AZMAN BIN KASSIM ("the third party claimant") of vehicle no. SLV 3977D make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLV 3977D (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 14 (day) of February (month) 2018 (year)



KSL

Signed by appointed surveyor



Signed by "the workshop" (with chop)

Without Prejudice

"The contents of this document apply to property damages claim only. All personal injuries and damages arising therefore are not included from the ambit and application of this document."

Optima Werkz Pte Ltd

9A Serangoon North Avenue 5, Singapore 554500
Tel (+65) 6484 9919 Fax: (+65) 6481 1101
Co Reg & GST No: 201212455W

TAX INVOICE

To: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Tel 64191000
Fax: 68357416

INV NO. : 121806183
INVOICE DATE : 25/09/2018
REF : TP#669
VEH NO. : SLV3977D
CAR MODEL : FIT 1.3GF
CURRENT MILEAGE:
ADVISOR : WINSON
TERMS : COD

DESCRIPTION	QTY	UOM	U.PRICE SGD	AMOUNT SGD
REAR TAILGATE	1	PC	675.36	675.36
REAR TAILGATE WINDSCREEN MOULDING	1	PC	84.16	84.16
REAR TAILGATE LOGO EMBLEM	1	PC	19.68	19.68
REAR TAILGATE FIT EMBLEM	1	PC	27.68	27.68
REAR TAILGATE OUTER GARNISH	1	PC	155.76	155.76
REAR TAILGATE OUTER GARNISH CLIPS	4	PCS	4.64	18.56
REAR TAILGATE INNER TRIM BOARD	1	PC	91.44	91.44
REAR TAILGATE INNER TRIM BOARD CLIPS	10	PCS	4.64	46.40
REAR TAILGATE MECHANISM LOCK	1	PC	163.28	163.28
REAR TAILGATE WEATHER STRIP	1	PC	87.28	87.28
REAR LH TAILLAMP	1	PC	322.48	322.48
REAR LH TAILLAMP CLIPS	1	PC	4.64	4.64
REAR LH TAILLAMP INNER PANEL	1	PC	79.12	79.12
REAR BUMPER	1	PC	663.12	663.12
REAR BUMPER CLIPS	10	PCS	3.12	31.20
REAR BUMPER SIDE RETAINER LH/RH	1	PC	30.32	30.32
REAR LH FENDER	1	PC	767.28	767.28
REAR LH FENDER GLASS MOULDING	1	PC	22.64	22.64
REAR FENDER INNER UPHOLSTERY TRIM LH/RH	1	PC	284.40	284.40
REAR FENDER INNER UPHOLSTERY TRIM CLIPS LH/RH	8	PCS	4.64	37.12
REAR END PANEL	1	PC	296.08	296.08
REAR END PANEL INNER TOP GARNISH	1	PC	56.56	56.56
REAR END PANEL LOCK STRIKER	1	PC	18.24	18.24
REAR LH SUB CHASSIS FRAME TOP PANEL	1	PC	149.20	149.20
REAR WELL PANEL	1	PC	757.36	757.36
REAR WELL PANEL INNER TOP TOOLS SPONGE	1	PC	148.48	148.48
REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER	1	PC	40.00	40.00
REAR BUMPER REVERSE SENSOR	1	PC	200.00	200.00
REAR RH FENDER GLASS SEALANT WITH PRIMER	1	PC	30.00	30.00
TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	1	JOB	1,400.00	1,400.00
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	1	JOB	1,100.00	1,100.00
TO TUFF KOTE / ANTI-RUST	1	JOB	80.00	80.00
TO CHECK WIRING, LIGHTING & WATER LEAKAGE	1	JOB	20.00	20.00
TO REMOVE AND REFIT REAR RH FENDER QUARTER GLASS	1	JOB	50.00	50.00
TO DISMANTLE & REINSTALL REAR INTERIOR CARPET COMPONENT TO FACILITATE REPAIR	1	JOB	120.00	120.00

Optima Werkz Pte Ltd

9A Serangoon North Avenue 5, Singapore 554500
Tel (+65) 6484 9919 Fax: (+65) 6481 1101
Co Reg & GST No: 201212455W

TAX INVOICE

To: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Tel 64191000
Fax: 68357416

INV NO. : 121806183
INVOICE DATE : 25/09/2018
REF : TP#669
VEH NO. : SLV3977D
CAR MODEL : FIT 1.3GF
CURRENT MILEAGE:
ADVISOR : WINSON
TERMS : COD

DESCRIPTION	QTY	UOM	U.PRICE SGD	AMOUNT SGD
TO DISMANTLE REAR EXHAUST SILENSER BOX	1	JOB	60.00	60.00
TO DISMANTLE & REFIX REAR TAILGATE REVERSE CAMERA	1	JOB	50.00	50.00
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	1	JOB		50.00
TO REMOVE AND REFIT REAR WINDSCREEN PERFORM	1	JOB	120.00	120.00
TO MOUNT VEHICLE ONTO 3D COMPUTERISE CAR 'O' LINER TO CALIBRATE SUB CHASSIS FRAME & CAR BODY BACK TO MANUFACTURING SPECIFICATION	1	JOB	250.00	250.00

Remarks: DOA: 15/06/18 @ 1130 HRS
CLAIMANT NAME: AZMAN BIN KASSIM
NRIC NO: S1481144C
TP VEHICLE: SLF9726G

Singapore Dollars: Nine Thousand Two Hundred Ten And Cent Thirty-Nine Only

Name: _____

NRIC No.: _____

Signature: _____

SUB TOTAL	SGD	8,607.84
GST 7.00%	SGD	602.55
GRAND TOTAL	SGD	9,210.39

I/We confirm that I/We incurred the repair costs herein and will observe my/our agreement with the repairs.
I/We declare the repairs for above vehicle have been completed to my/our satisfaction.

- 1) New parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of one (1) year or mileage up to 30,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.
- 2) Recon Parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of six (6) months or mileage up to 10,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.
- 3) Goods sold are not refundable/returnable.

Original Invoice is only valid when the payment is acknowledge receipt by Optima Werkz Pte Ltd. Interest of 2% per month will be charged on any outstanding amount.

for Optima Werkz Pte Ltd

AUTHORISED SIGNATURE(S)

Optima Werkz Pte Ltd

9A Serangoon North Avenue 5, Singapore 554500
Tel (+65) 6484 9919 Fax: (+65) 6481 1011
Co Reg & GST No: 201212455W

TAX INVOICE

To: AZMAN BIN KASSIM

BLK 752 WOODLANDS CIRCLE
#04-534
SINGAPORE 730752

Tel 9384 0494
Fax:

INV NO. : 121804303
INVOICE DATE : 07/07/2018
REF : TP#669 - CR
VEH NO. : SLV3977D
MAKE : HONDA
MODEL : FIT 1.3GF
CURRENT MILEAGE:
ADVISOR : TP/OD
TERMS : COD

#	DESCRIPTION	QTY	UOM	U/P SGD	AMT SGD
1	CAR RENTAL CHARGES RENTAL AGREEMENT NQ 100887 VEHICLE NO: SLG5112Z MODEL: HONDA SHUTTLE 1.5G CVT ABS D/AIRBAG 2WD 5DF FROM 16-06-2018 TO 04-07-2018	19	DAYS	140.00	2,660.00

Remarks: DOA: 15/06/2018

Singapore Dollars: Two Thousand Eight Hundred Forty-Six And Cent Twenty Only

Name: _____

NRIC No.: _____

Signature: _____

SUB TOTAL SGD 2,660.00
GST 7.00% SGD 186.20
TOTAL SGD 2,846.20
Outstanding SGD 2,846.20

We confirm that We incurred the repair costs herein and will observe my/our agreement with the repairs.
We declare the repairs for above vehicle have been completed to my/our satisfaction.

- 1) New parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of one (1) year or mileage up to 30,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.
- 2) Recon Parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of six (6) months or mileage up to 10,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.
- 3) Goods sold are not refundable/returnable.

Original Invoice is only valid when the payment is acknowledge receipt by Optima Werkz Pte Ltd. Interest of 2% per month will be charged on any outstanding amount.

For Optima Werkz Pte Ltd

AUTHORISED SIGNATURE(S)

Optima Werkz Pte Ltd

6 Kung Chong Rd Singapore 159143
Tel: +65 6472 1313 Fax: +65 6472 2112 Website: www.ow.sg
9A Serangoon North Ave 5 Singapore 554500
Tel: +65 6484 9919 Fax: +65 6481 1011
CO. REG NO. 201212455W

OPTIMA WERKZ



VEHICLE RENTAL AGREEMENT

No: 100887
SLV 3977 D

HIRER'S PARTICULARS Full Name: <u>MUR NARAH BIN ARMAN</u> Nric/Passport No: <u>S9032424A</u> Address: <u>752 VOYAGER'S CIRCLE</u> <u>#04-534 S 730752</u> Name & Address Employer: Occupation: Driving Exp: <u>9+</u> Driving Licence No: D/L Type: <u>3</u> Local/Int'l Issue Date: <u>18/07/2009</u> Date of Birth: <u>14/09/90</u> Contact no(s): HP:		Rental replacement Vehicle No: <u>SLG 51122</u> Vehicle No: <u>SLV 3977 D</u> Make/Model: <u>H. SHUTTLE</u> Make/Model: <u>H. SHUTTLE</u> Mileage Out: <u>32908km.</u> 1 <u>4. RT.</u> <u>33934</u> DATE OUT <u>16/06/18</u> TIME OUT <u>1310</u> AM/PM DATE IN <u>4.7.18</u> TIME IN <u>5.50</u> AM/PM Signature <u>M. NARAH</u>	
ADDITIONAL DRIVER'S PARTICULARS Full Name: Nric/Passport No: Address: Contact no(s): HP: Driving Licence No: Driving Exp: Issue Date: D/L Type: Local/Int'l Occupation: Date of Birth:		CHARGES S\$ 19 Day(s) @ S\$ 140 per day 2,660 Week(s) @ S\$ per day Month(s) @ S\$ per day Extension Delivery/Collection Charges Sub-Total Petrol Level Out E 1/4 <u>1/2</u> 3/4 F IN E 1/4 <u>1/2</u> 3/4 F MISC GST 7% 186.20 TOTAL CHARGES (Inclusive of GST) 2,846.20 Less Deposit Balance Payable/Refundable Refund received	
REMARKS: <u>INS EXCESS:</u> <u>OWN DAMAGE: \$2000/-</u> <u>THIRD PARTY: \$2000/-</u> } LOCAL. <u>M. NARAH</u>			

*IMPORTANT

- ONLY PERSON ABOVE 24 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE. AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- EXCESS - HIRER IS LIABLE TO PAY INSURANCE EXCESS/ES WHICH IS/ARE APPLICABLE UNDER THE RENTAL CAR INSURANCE POLICY IN ANY EACH ACCIDENT PLUS LOSS OF EARNINGS WHILE DAMAGED VEHICLE IS UNDER REPAIR.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY. OUR INSURANCE DOES NOT COVER IN MALAYSIA.

I HAVE READ THE TERMS AND CONDITIONS ON BOTH SIDE OF THIS RENTAL AGREEMENT AND AGREE THEREOF.
I UNDERTAKE NOT TO USE OR LET OTHERS USE THE RENTAL VEHICLE TO CARRY OUT ANY ILLEGAL OR CRIMINAL ACTS INCLUDING CARRYING OF DUTY UNPAID GOODS.

Hirer's
Signature: M. NARAH
Date:

Driver's Signature
(if different from Hirer)
Date:

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 16 Jun 2018 / 12:02:33

Receipt Date/Time : 16 Jun 2018 / 12:02:33

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180616-000344

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference, No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLF9726G				
As at 15 Jun 2018/11:30:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLF9726G			
	Enquiry Fee	7.00	0.49	7.49
	20180616120119838744			
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
Paid By				
	xxxxxxxxxxxx2799	Credit Card:		7.45
		Visa/MasterCard		
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jun 2018 Edit Reg		19 Jun 2018 00:00 Edit Adj Rpt	\$58,607.84 Edit Estimates	\$58,607.84 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LCRF Pte Ltd, Co. Reg. No.: 201624597K		
Main Claimant:	AZMAN BIN KASSIM, ID: S1481144C		
Vehicle Reg. No.:	SLV3977D	Date of Loss:	15/06/2018 11:00 - :59 [5 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8457574565SG	Policy/Cover Note No.:	0999994779 (Comprehensive)
Vehicle Reg. No. (Insured):	SLF9726G	Policy No. (Claimant):	5096969519
		Excess:	
Repairer:	Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5, 554500 Serangoon - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Wilson-KL]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 29/06/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (28/01/2019): Alert - Adj Mandate Approved (\$511143.84) - SLV3977D - Claim Handler: Tan, Wilso...

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLV3977D (8457574565SG)
[SLF9726G]
TP
AZMAN BIN KASSIM
Jun 15 2018 11:00AM
[LCRF Pte Ltd]
Optima Werkz Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown												<input type="button" value="1"/>	Edit					
Photos/Images															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	28/01/19 17:36	General View												<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>				
2	28/01/19 17:36	General View												<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>				
3	28/01/19 17:36	General View												<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>				
4	28/01/19 17:36	General View												<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>				
5	28/01/19 17:36	General View												<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>				
6	28/01/19 17:36	General View												<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>				
7	28/01/19 17:36	General View												<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>				
8	28/01/19 17:36	General View												<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>				
9	28/01/19 17:36	General View												<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>				
10	28/01/19 17:36	General View												<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>				
11	28/01/19 17:36	General View												<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>				
12	28/01/19 17:36	General View												<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>				
13	28/01/19 17:36	General View												<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>				
14	28/01/19 17:36	General View												<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>				
15	28/01/19 17:36	General View												<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>				
16	28/01/19 17:36	General View												<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>				
17	28/01/19 17:36	General View												<input type="button" value="1"/>	Load JPG	<input checked="" type="checkbox"/>				
Documentation															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	21/06/18 09:17	TP ESTIMATE- MARKED												<input type="button" value="1"/>	Load PDF					
2	21/06/18 09:17	TP GIA REPORT												<input type="button" value="1"/>	Load PDF					
3	02/07/18 09:26	LETTER TO LCRF												<input type="button" value="1"/>	Load PDF					
4	28/01/19 11:14	RENTAL RECEIPT												<input type="button" value="1"/>	Load PDF					
5	28/01/19 11:14	LTA SEARCH												<input type="button" value="1"/>	Load PDF					
6	18/02/19 14:58	WORKSHOP INVOICE												<input type="button" value="1"/>	Load PDF					
7	18/02/19 14:58	AUTHORISATION TO ACT FORM												<input type="button" value="1"/>	Load PDF					
8	18/02/19 14:58	Release Voucher												<input type="button" value="1"/>	Load PDF					
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	21/06/18 12:39	OI GIA REPORT												<input type="button" value="1"/>	Load PDF					

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

	^ v
--	--------

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLF9726G (Insd veh)	Model:	HONDA FIT 1.3 (A)
	SLV3977D (TP veh)		
Date of Accident:	15/06/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	:	\$		15,756.31
Final Repair Cost	:	\$		11,000.00
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		18 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		11,000.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown				
1)	Optima Werkz Pte Ltd	:	\$	11,000.00
2)		:	\$	
3)		:	\$	
4)		:	\$	

JOANNE LEE KHANG MIN

18 Feb
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18011206/KJB3Q2

Date: 18/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994779

Claimant Vehicle No : SLV3977D

Insured Vehicle No : SLF9726G

Date of Loss: 15/06/2018

Nature of Claim:

TP

Claim No: 8457574565SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLV3977D

Make & Model: HONDA FIT, 1.3 (A)

Reg. Date: 28/12/2017 (Man. Year: 2017)

Colour: Metallic Silver

Engine Capacity: 1317 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: L13B1405302

Chassis No: GK31304928

Odometer: 10205 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Front Left Side: Nexen 9 mm

Front Right Side: Nexen 9 mm

Rear Tyre Size: 185/60 R15

Rear Left Side: Nexen 9 mm

Rear Right Side: Nexen 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,235.52	5,307.84	4,927.68	48.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,490.00	3,300.00	1,190.00	26.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,725.52	8,607.84	6,117.68	41.54
+ GST 7.00/7.00% (S\$)	1,030.79	602.55	428.24	41.54
Nett Amount (S\$)	15,756.31	9,210.39	6,545.92	41.54
+ Car Rental (18.0 x S\$100.00/day + 7.00% GST) (S\$)		1,926.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		11,143.84		
Global Sum Settlement (S\$)		11,000.00		

INSPECTION

Date of Assignment: 19/06/2018

Date Inspected: 19/06/2018

Inspected At:

Optima Werkz Pte Ltd (HQ)
9A Serangoon North Ave 5,
554500 Serangoon

Estimated Period of Repair: 14.0 days

Adjuster: KENNETH KONG**Manager:** Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	844.20 FL	*844.20 FL
2	1		*REAR TAILGATE WINDSCREEN	Serviceable	970.70 FL	*- FL
3	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	105.20 FL	*105.20 FL
4	1		*REAR TAILGATE LOGO EMBLEM	Necessary	24.60 FL	*24.60 FL
5	1		*REAR TAILGATE FIT EMBLEM	Necessary	34.60 FL	*34.60 FL
6	1		*REAR TAILGATE OUTER GARNISH	Warped	194.70 FL	*194.70 FL
7	4		*REAR TAILGATE OUTER GARNISH CLIPS	Necessary	23.20 FL	*23.20 FL
8	2		*REAR TAILGATE NUMBER LAMP LH/RH	Serviceable	93.60 FL	*- FL
9	2		*REAR TAILGATE REFLECTOR LH/RH	Serviceable	484.20 FL	*- FL
10	1		*REAR TAILGATE INNER TRIM BOARD	Buckled	114.30 FL	*114.30 FL
11	10		*REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	58.00 FL	*58.00 FL
12	1		*REAR TAILGATE MECHANISM LOCK	Dented / Jammed	204.10 FL	*204.10 FL
13	1		*REAR TAILGATE WEATHERSTRIP	Dented	109.10 FL	*109.10 FL
14	1		*REAR TAILGATE INNER HANDLE	Serviceable	16.80 FL	*- FL
15	1		*REAR LH TAILLAMP	Cracked	403.10 FL	*403.10 FL
16	1		*REAR LH TAILLAMP CLIPS	N/S Necessary	11.60 FL	*5.80 FL
17	1		*REAR LH TAILLAMP INNER PANEL	Bent	98.90 FL	*98.90 FL
18	1		*REAR BUMPER	Bent	828.90 FL	*828.90 FL
19	1		*REAR BUMPER LH GARNISH	Serviceable	75.30 FL	*- FL
20	1		*REAR BUMPER CENTER GARNISH	Serviceable	204.10 FL	*- FL
21	10		*REAR BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
22	1		*REAR BUMPER SIDE RETAINER LH/RH	N/S Distorted	75.80 FL	*37.90 FL
23	1		*REAR BUMPER LH INNER SIDE SHIELD	Serviceable	59.20 FL	*- FL
24	4		*REAR BUMPER LH INNER SIDE SHIELD CLIPS	Not Necessary	15.60 FL	*- FL
25	1		*REAR LH FENDER	Buckled	959.10 FL	*959.10 FL
26	1		*REAR LH FENDER GLASS MOULDING	Necessary	28.30 FL	*28.30 FL
27	1		*REAR LH FENDER INNER AIR VENT	Serviceable	28.90 FL	*- FL
28	1		*REAR LH FENDER INNER PANEL	Repair	700.80 FL	*- FL
29	1		*REAR FENDER INNER UPHOLSTERY TRIM LH/RH	N/S Deformed	711.00 FL	*355.50 FL
30	16		*REAR FENDER INNER UPHOLSTERY TRIM CLIPS LH/RH	N/S Necessary (8 PCS ONLY)	92.80 FL	*46.40 FL
31	1		*REAR LH DOOR	Repair	828.90 FL	*- FL
32	1		*REAR LH DOOR MECHANISM LOCK	Repair	272.90 FL	*- FL
33	1		*REAR END PANEL	Bent	370.10 FL	*370.10 FL
34	1		*REAR END PANEL INNER TOP GARNISH	Distorted	70.70 FL	*70.70 FL
35	1		*REAR END PANEL LOCK STRIKER	Distorted	22.80 FL	*22.80 FL
36	1		*REAR END PANEL TAILGATE ANTENA SENSOR	Serviceable	126.80 FL	*- FL
37	1		*REAR END PANEL TAILGATE ANTENA SENSOR BUZZER	Serviceable	107.30 FL	*- FL
38	1		*REAR LH SUB CHASSIS FRAME	Repair	581.70 FL	*- FL
39	1		*REAR LH SUB CHASSIS FRAME TOP PANEL	Bent	186.50 FL	*186.50 FL
40	1		*REAR LH SUB CHASSIS FRAME EXTENSION	Repair	29.30 FL	*- FL
41	1		*REAR WELL PANEL	Bent	946.70 FL	*946.70 FL
42	1		*REAR WELL PANEL INNER TOP UPHOLSTERY BOARD	Serviceable	236.60 FL	*- FL
43	1		*REAR WELL PANEL INNER TOP TOOLS SPONGE	Deformed	185.60 FL	*185.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*REAR WELL PANEL INSULATION MAT	Serviceable	89.90 FL	*- FL
45	1		*REAR SUSPENSION LH SHOCK ABSORBER	Serviceable	221.80 FL	*- FL
46	1		*REAR SUSPENSION LH WHEEL HUB BEARING	Serviceable	332.10 FL	*- FL
47	1		*REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER	Necessary	100.00 FS	*40.00 FS
48	1		*REAR BUMPER REVERSE SENSOR	Dented	280.00 FS	*200.00 FS
49	1		*REAR RH FENDER GLASS SEALANT WITH PRIMER	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,679.40	6,567.30
- List Item Discount on L Items 20.00/20.00% (S\$)	2,443.88	1,259.46
Total Parts (S\$)	10,235.52	5,307.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	New	1,600.00	1,400.00
2	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	New	1,500.00	1,100.00
3	TO TUFF KOTE/ANTI-RUST	New	80.00	80.00
4	TO CHECK WIRING ,LIGHTING & WATER LEAKAGE	New	60.00	20.00
5	TO REMOVE AND REFIT REAR RH FENDER QUARTER GLASS	New	120.00	50.00
6	TO DISMANTLE & REINSTALL REAR INTERIOR CARPET COMPONENT TO FACILITATE REPAIR	New	250.00	120.00
7	TO DISMANTLE REAR EXHAUST SILENSER BOX	New	150.00	60.00
8	TO DISMANTLE & REFIX REAR TAILGATE REVERSE CAMERA	New	60.00	50.00
9	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	New	60.00	50.00
10	TO REMOVE AND REFIT REAR WINDSCREEN PERFORM	New	150.00	120.00
11	TO DISMANTLE & REPLACED REAR LH UNDER CARRIAGE COMPONENT TO FACILITATE REPAIR	New	180.00	0.00
12	TO MOUNT VEHICLE ONTO 3D COMPUTERISE CAR O LINER TO CALIBRATE SUB CHASSIS FRAME & CAR BODY BACK TO MANUFACTURING SPECIFICATION	New	280.00	250.00
Gross Labour Cost (S\$)			4,490.00	3,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >