

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE		<i>Bz</i> \$977.40
1	REAR TAILGATE WINDSCREEN		\$970.70
1	REAR TAILGATE WINDSCREEN MOULDING		<i>u</i> \$125.20
1	REAR TAILGATE LOGO EMBLEM		\$24.60
1	REAR TAILGATE FIT EMBLEM		<i>u</i> \$34.60
1	REAR TAILGATE OUTER GARNISH		\$185.6
4	REAR TAILGATE OUTER GARNISH CLIPS	\$5.50	\$22.00
2	REAR TAILGATE NUMBER LAMP LH/RH	\$46.80	<i>Pu</i> \$93.60
2	REAR TAILGATE REFLECTOR LH/RH	\$262.10	\$524.20
2	REAR TAILGATE HINGE LH/RH	\$45.50	<i>R</i> \$91.00
2	REAR TAILGATE DAMPER LH/RH	\$138.50	<i>su</i> \$277.00
1	REAR TAILGATE INNER TRIM BOARD		\$164.30
10	REAR TAILGATE INNER TRIM BOARD CLIPS	\$5.50	\$55.00
1	REAR TAILGATE MECHANISM LOCK		<i>Red / Pu</i> \$234.10
1	REAR TAILGATE WEATHER STRIP		\$119.10
1	REAR TAILGATE INNER HANDLE		\$26.70
2	REAR TAILLAMP LH/RH <i>nl / su</i>	\$493.30	\$986.60
4	REAR TAILLAMP CLIPS LH/RH <i>nl / su</i>	\$5.80	\$23.20
1	REAR TAILLAMP LH INNER PANEL		\$109.70
1	REAR BUMPER		<i>Bz</i> \$803.60
1	REAR BUMPER LH GARNISH		
1	REAR BUMPER CENTER GARNISH		
10	REAR BUMPER CLIPS	\$6.80	<i>u</i> \$95.20
2	REAR BUMPER SIDE RETAINER LH/RH <i>nl / dir</i>	\$25.50	\$51.00
1	REAR BUMPER LH INNER SIDE SHIELD		<i>su</i> \$49.20
4	REAR BUMPER LH INNER SIDE SHIELD CLIPS	\$6.80	<i>u</i> \$27.20
1	REAR LH FENDER		<i>Bz</i> \$859.10
1	REAR LH FENDER GLASS MOULDING		<i>u</i> \$28.80
1	REAR LH FENDER INNER AIR VENT		\$28.90
1	REAR LH FENDER INNER UPHOLSTERY TRIM		\$194.70
4	REAR LH FENDER INNER UPHOLSTERY TRIM CLIPS	\$5.80	\$23.20
1	REAR LH FENDER INNER PANEL		\$680.80
1	REAR LH DOOR <i>R X</i>		
1	REAR LH DOOR MECHANISM LOCK <i>R X</i>		
1	REAR LH DOOR BLACK FRAME STICKER <i>u X</i>		
1	REAR LH DOOR WEATHER STRIP <i>su X</i>		
1	REAR LH DOOR LOCK STRIKER <i>R X</i>		

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 18 JUNE 2018

Third Party Insurer: AIG

Vehicle No: SLV3977D

Third Party Veh No: SLF9726G

Model: HONDA FIT

Date of Accident: 15 JUNE 2018

Chassis: GK3-1304928

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR END PANEL		3 \$370.10
1	REAR END PANEL INNER TOP GARNISH		\$98.60
4	REAR END PANEL INNER TOP GARNISH CLIPS	\$5.50	\$22.00
1	REAR END PANEL LOCK STRIKER		\$25.80
1	REAR LH SUB CHASSIS FRAME		12 \$581.70
1	REAR LH SUB CHASSIS FRAME TOP PANEL		
1	REAR WELL PANEL		
1	REAR WELL PANEL INNER TOP UPHOLSTERY BOARD		\$286.00
1	REAR WELL PANEL INNER TOP TOOLS SPONGE		\$185.60
1	REAR SUSPENSION LH SHOCK ABSORBER		
1	REAR SUSPENSION LH WHEEL HUB BEARING		
SUB TOTAL			\$9,456.10
Less 20%			-\$1,891.22
PARTS TOTAL			\$7,564.88

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER		\$100.00
1	REAR TAILGATE REVERSE CAMERA		Sn \$450.00
1	REAR BUMPER REVERSE SENSOR		Net \$280.00
1	REAR RH FENDER GLASS SEALANT WITH PRIMER		nr \$80.00
S/N TOTAL			\$910.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 18 JUNE 2018

Third Party Insurer: AIG

Vehicle No: SLV3977D

Third Party Veh No: SLF9726G

Model: HONDA FIT

Date of Accident: 15 JUNE 2018

Chassis: GK3-1304928

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

Zuccafin
\$1,600.00 ?

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

\$1,500.00 *1100*

TO TUFF KOTE / ANTI-RUST

\$80.00 ✓

TO CHECK WIRING, LIGHTING & WATER LEAKAGE

\$60.00 *200*

TO REMOVE AND REFIT REAR RH FENDER QUARTER GLASS

\$120.00 *500*

TO DISMANTLE & REINSTALL REAR INTERIOR CARPET COMPONENT TO FACILITATE REPAIR

\$250.00 *1200*

TO DISMANTLE REAR EXHAUST SILENSER BOX

\$150.00 *600*

TO DISMANTLE & REFIX REAR TAILGATE REVERSE CAMERA

\$60.00 *500*

TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR

\$60.00 *500*

TO REMOVE AND REFIT REAR WINDSCREEN PERFORM

\$150.00 *1200*

TO DISMANTLE & REINSTALL ROOF TOP INNER LINING ASSEMBLY

\$250.00 X

TO DISMANTLE & REPLACED REAR LH UNDER CARRIAGE COMPONENT TO FACILITATE REPAIR

\$180.00 ?

TO MOUNT VEHICLE ONTO 3D COMPUTERISE CAR 'O' LINER TO CALIBRATE SUB CHASSIS FRAME & CAR BODY BACK TO MANUFACTURING SPECIFICATION

\$280.00 ?

LABOUR TOTAL \$4,740.00

WINSON

TOTAL \$13,214.88