

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9317L**AAD1806-133**

Not Notarized
11 Sep @ 3950p

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9317L

KL1LA69RJBB066862

CHEVROLET

EPICA 2.0

15.6.2018

AIG**PART****LIST**

1	1	Front Bumper	\$	CN 1,202.00 ✓
2	1	Front Bumper Lower Absorber	\$	SL 180.00 X
3	1	Front Bumper Reinforcement	\$	N 356.00 X
4	1	Front Bumper Retainer RH	\$	DIT 102.00 ✓
5	1	Front Bumper Retainer LH	\$	SL 102.00 X
6	1	Front Bumper Lower Grille	\$	SL 78.00 X
7	1	Front Bumper Lower Stiffener	\$	N 134.37 X
8	1	Front Bumper Bracket LH	\$	N 10.00 X
9	1	Front Bumper Bracket RH	\$	N 10.00 X
10	1	Bumper Fog Lamp Cover RH	\$	N 32.40 ✓
11	1	Bumper Fog Lamp Cover LH	\$	SL 32.40 X
12	1	Headlamp RH	\$	CU 816.00 ✓
13	1	Headlamp RH inner panel	\$	N 611.16 X
14	1	Front Fender RH	\$	Bu 837.60 ✓
15	1	Front Fender Liner RH	\$	SL 47.00 X
16	1	Front Fender Inner Wheel House Panel RH	\$	N 1,437.00
17	1	Front Shock Absorber Assy RH	\$	SL 216.17
18	1	Front Shock Absorber Top Mounting RH	\$	SL 48.32
19	1	Front Lower Arm RH	\$	SL 283.00
20	1	Front Knuckle Arm RH	\$	SL 230.00
21	1	Front Hub Unit	\$	SL 376.00
22	1	Front Disc Brake RH	\$	SL 157.55
23	1	Front Strut Bar Bracket RH	\$	SL 235.01
24	1	Front Stabilizer Bar	\$	SL 234.00
25	1	Front Stabilizer Bar Link RH	\$	SL 51.79
26	1	Front Stabilizer Bar Bracket RH	\$	N 105.75
27	1	Front Stabilizer Bar Bush RH	\$	SL 66.00
28	1	Front Beam A - Impact RH	\$	N 214.00
29	1	Bonnet Panel	\$	Bu 1,250.00 ✓

Trans-cab Auto Services Pte Ltd

AAD1806-133

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9317L

30	1	Horn Unit (Low Tone)	\$	53.46	} X
31	1	Horn Unit (High Tone)	\$	53.46	
32	1	Front Support Panel Assy	\$	1,222.32	
33	1	Front brace panel	\$	134.37	
34	1	Windscreen Washer Tank (Reservoir A-W/Shield)	\$	62.00	
35	1	Windscreen Washer Tank Motor (Pump Wswa)	\$	51.00	
36	1	TANK, WIPER HOSE	\$	21.00	
37	1	Radiator Assembly (Radiator A	\$	618.00	
38	1	Front Door RH	\$	1,133.00	

TOTAL	\$	12,804.13
10%	\$	1,280.41
	\$	11,523.72

Specical Nett

1	1 Set	Front Fender Liner clip LH	\$	30.00	} X
2	1 Set	Louver Cowl Top clip	\$	30.00	
3	1	Front right tyre rim	\$	380.00	
4	1	Front right tyre	\$	300.00	
5	2	Bonnet stopper	\$	15.00	
6	6	Bonnet under weatherstrip seal clips	\$	30.00	
7	10	Bonnet insulator clip	\$	30.00	
8	1	Front right fender advertisement sticker	\$	250.00	
9	1	Front right door advertisement sticker	\$	300.00	

TOTAL	\$	1,365.00
--------------	-----------	-----------------

TOTAL PARTS	\$	12,888.72
--------------------	-----------	------------------

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00 200
---	----	------------

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00 5000
---	----	---------------

Trans-cab Auto Services Pte Ltd

AAD1806-133

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9317L

Putty and spray painting of the affected portion.	\$	3,200.00	6001
To Remove And Refit Front And Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	~ 440.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	~ 380.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	~ 380.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	~ 170.00	X
To Transfer Of Bonnet Fittings, Attachments And Perform Water Seepage Test.	\$	~ 170.00	X

TOTAL	\$	8,790.00
--------------	-----------	-----------------

Over All Total	\$	21,678.72
-----------------------	-----------	------------------

Repair Days

10 DAYS

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: