



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJZ267S

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

24490
SJZ267S / 28/06/2017
/ 0
WDD2221622A320961
27682430576975
MB/MB S 320 L SEDAN (V222)
021 197 Obsidian B1/ 048 801 Nappa Leath

| Account No | Terms | Date/Time Printed | CSE | Operator |
|------------|--------|-------------------|-----|------------------------|
| WI000576 | Credit | 19/06/2018/ 16:30 | AQ | 305 / Alan Quek Ai Lun |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|---|------|------------|-------|-------------|
| M BPNSUN POLICY NO/ACC DATE : 170020439 // 18-06-2018 DRIVE IN: 19-06-2018 // TP CAR NO: SHA2951S (INDIA INTERNATIONAL INS) DATE IN/DATE SURVEY: BY/AUTHORIZED ON : | | | | |
| A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT | | | | 480.00 |
| A BPILAB REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH. | | | | 960 1440.00 |
| A BPIRES RESPRAY REAR BUMPER | | | | 600 720.00 |
| M REAR BUMPER | 1.00 | 2040.41 | 00.00 | 2040.41 |
| M LH/R BUMPER GARNISH | 1.00 | 109.57 | 00.00 | 109.57 |
| M RH/R BUMPER GARNISH | 1.00 | 109.57 | 00.00 | 109.57 |
| M CT/R PARKING SENSOR | 4.00 | 172.07 | 00.00 | 688.28 |
| M CT/R PARKING SENSOR SEAL | 4.00 | 6.42 | 00.00 | 25.68 |
| M CT/R BASIC MOUNTING FOR BUMPER | 1.00 | 119.90 | 00.00 | 119.90 |
| M LH/R BASIC MOUNTING FOR BUMPER | 1.00 | 75.66 | 00.00 | 75.66 |
| M REAR CROSS MEMBER | 1.00 | 1093.57 | 00.00 | 1093.57 |

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarrage.com.sg

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Confirmed & accepted by
Third party survey is on a "Without Prejudice" basis
No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

Date:

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg