



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJZ267S

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

Vehicle & Document Information
WIP No **24490**
Reg No/Reg Date **SJZ267S / 28/06/2017**
Date In/Mileage **/ 0**
Chassis No **WDD2221622A320961**
Engine No **27682430576975**
Make/Model **MB/MB S 320 L SEDAN (V222)**
Colour/Trim **021 197 Obsidian Bl/ 048 801 Nappa Leath**

Account No	Terms	Date/Time Printed	CSE	Operator
WI000576	Credit	19/06/2018/ 16:30	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :170020439 // 18-06-2018 DRIVE IN:19-06-2018 // TP CAR NO:SHA2951S (INDIA INTERNATIONAL INS) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT				480.00
A BPILAB REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.				1440.00
A BPIRES RESPRAY REAR BUMPER				720.00
M REAR BUMPER	1.00	2040.41	00.00	2040.41
M LH/R BUMPER GARNISH	1.00	109.57	00.00	109.57
M RH/R BUMPER GARNISH	1.00	109.57	00.00	109.57
M CT/R PARKING SENSOR	4.00	172.07	00.00	688.28
M CT/R PARKING SENSOR SEAL	4.00	6.42	00.00	25.68
M CT/R BASIC MOUNTING FOR BUMPER	1.00	119.90	00.00	119.90
M LH/R BASIC MOUNTING FOR BUMPER	1.00	75.66	00.00	75.66
M REAR CROSS MEMBER	1.00	1093.57	00.00	1093.57

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on **Nett 6,902.64**
483.18

Authorized signatory and company stamp

Total Payable 7,385.82

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS