

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

*not Adm
Hk
20/6/18
d/s
To be able to the 12 dy.*

M/S : ECICS LIMITED
7 TEMASEK BOULEVARD #10-01
SUNTEC TOWER ONE
SINGAPORE 038987
TEL: 6337 4779 FAX: 6338 9267
ATTN: Motor Claim Department
Your Ref No: 18/EC/TP-123 (06)
Claim Type: Third Party

Estimate No: EST0004182
Date: 19 Jun 2018
Policy No: P10040784R00
Veh Reg No: SLV6903Y
Make/Model: MITSUBISHI LANCER

Reg. Date: 27/02/2008

Estimate Repair Cost to Vehicle No :SLV6903Y

Description	U/Price	Quantity	Cost	Amount
			SS	SS
Parts				
1 REAR BOOT <i>d/suc</i>		1 PC	280.00	✓
2 REAR BOOT LOGO <i>neu</i>		1 PC	32.00	✓
3 REAR BOOT EMBLEM 'LANCER' <i>neu</i>		1 PC	20.00	✓
4 REAR BOOT EMBLEM 'GLX' <i>neu</i>		1 PC	20.00	✓
5 REAR BOOT OUTER GARNISH		1 PC	160.00	?
6 REAR BOOT LOCK <i>twi</i>		1 PC	42.00	✓
7 REAR BOOT INNER RUBBER <i>twi</i>		1 PC	110.00	✓
8 REAR BUMPER <i>d/s</i>		1 PC	400.00	✓
9 REAR BUMPER RETAINER <i>neu</i>		2 PC	64.00	✓
10 REAR BUMPER CLIP <i>neu</i>		10 PC	20.00	✓
11 REAR BUMPER BEAM		1 PC	120.00	?
12 REAR TAIL LAMP <i>o/sone</i>		2 PC	520.00	1 PC @ 160
13 REAR END PANEL <i>3 o/sone</i>		1 PC	280.00	✓
14 END PANEL TOP GARNISH <i>twi</i>		1 PC	130.00	✓
15 REAR SPARE TYRE FLOOR PANEL <i>crumpled/suc</i>		1 PC	460.00	✓
16 REAR SPARE TYRE CARDBOARD <i>70.0</i>		1 PC	150.00	✓
17 REAR FENDER RH <i>R</i>		1 PC	500.00	X
18 REAR FEDER AIR DUCT RH <i>11</i>		1 PC	40.00	X
19 REAR FENDER INNER COWLING RH		1 PC	40.00	?
20 REAR FENDER INNER COWLING CLIP		10 PC	20.00	?
21 REAR WINDSCREEN MOULDING <i>11</i>		1 PC	40.00	X
22 REAR BUMPER SPOILER <i>d/s</i>		1 PC	500.00	✓
23 REAR EXHAUST BOX		1 PC	320.00	?
24 REAR EXHAUST BOX RUBBER HOLDER		2 PC	70.00	?
25 REAR CHASSISMEMBER RH <i>R</i>		1 PC	210.00	X
26 FRT BONNET <i>d/suc</i>		1 PC	380.00	✓
27 FRT BONNET LOCK <i>twi</i>		1 PC	36.00	✓
28 FRT GRILLE		2 PC	120.00	?
29 FRT GRILLE CLIP <i>neu</i>		4 PC	8.00	✓
30 FRT GRILLE LOGO <i>neu</i>		1 PC	18.00	✓
31 FRT GRILLE OUTER GARNISH		1 PC	110.00	✓
32 FRT BUMPER <i>d/s</i>		1 PC	400.00	✓
33 FRT BUMPER RETAINER <i>neu</i>		2 PC	56.00	✓
34 FRT BUMPER CLIP <i>neu</i>		10 PC	20.00	✓
35 FRT BUMPER LOWER OUTER GARNISH		2 PC	70.00	?
36 FRT NUMBER PLATE GARNISH <i>70.0</i>		1 PC	40.00	✓
37 HEADLAMP SUPPORT PANEL		1 PC	400.00	?
38 AIRCON CONDENSER		1 PC	300.00	?
39 RADIATOR <i>11</i>		1 PC	300.00	X

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST:201119451E RCB NO:201119451E

M/S : ECICS LIMITED

7 TEMASEK BOULEVARD #10-01

SUNTEC TOWER ONE

SINGAPORE 038987

TEL: 6337 4779

FAX: 6338 9267

ATTN: Motor Claim Department

Your Ref No: 18/EC/TP-123 (06)

Claim Type: Third Party

Estimate No: EST0004182

Date: 19 Jun 2018

Policy No: P10040784R00

Veh Reg No: SLV6903Y

Make/Model: MITSUBISHI LANCER

Reg. Date: 27/02/2008

Estimate Repair Cost to Vehicle No :SLV6903Y

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
40 HORN 1 1		1 PC	60.00 X	
41 HEADLAMP		2 PC	560.00 ?	
			7,426.00	
	Add 10%		742.60	8,168.60

Special Net

42 FRT NUMBER PLATE 3.21	1 PC	40.00 ✓	
43 REAR NUMBER PLATE 1.1	1 PC	40.00 X	
44 REAR REVERSE SENSOR 5.00	1 PC	250.00 200	
45 REAR WINDSCREEN GUM 1.1	1 PC	60.00 X	
			390.00

Labour

46 WIRE CHECKING	1 UNIT	20.00 ✓	
47 REMOVE & REFIX REAR WINDSCREEN 1.1	1 UNIT	120.00 X	
48 TRANSFER REAR BOOT COMPONENT FROM OLD TO NEW	1 UNIT	100.00 60	
49 REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	1 UNIT	100.00 80	
50 CAVITY PROTECTION ON ALL AFFECTED AREA	1 UNIT	100.00 ✓	
51 REMOVE & REFIX EXHAUST BOX	1 UNIT	150.00 60	
52 REMOVE & REFIX CUSHION AND SEAT	1 UNIT	150.00 80	
53 TOWING	1 UNIT	100.00 50	
54 LABOUR CHARGE	1 UNIT	2,600.00 1500	
55 SPRAY PAINTING	1 UNIT	1,500.00 1480	
			4,940.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S : ECICS LIMITED
7 TEMASEK BOULEVARD #10-01
SUNTEC TOWER ONE
SINGAPORE 038987

TEL: 6337 4779 FAX: 6338 9267

ATTN: Motor Claim Department

Your Ref No: 18/EC/TP-123 (06)

Claim Type: Third Party

Estimate No: EST0004182

Date: 19 Jun 2018

Policy No: P10040784R00

Veh Reg No: **SLV6903Y**

Make/Model: MITSUBISHI LANCER

Reg. Date: 27/02/2008

Estimate Repair Cost to Vehicle No :SLV6903Y

Amount Before Excess	S\$ 13,498.60
Add GST @ 7%	944.90
Total Amount payable	<u>S\$ 14,443.50</u>

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND FOUR HUNDRED FORTY THREE AND CENTS FIFTY ONLY

For SME Motor Pte Ltd

AUTHORISED SIGNATURE