

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Estimate No: EST1800183

Date: 18 Jun 2018

TEL: 63896111

FAX: 62247175

Veh Reg No: SJU2929D

ATTN: Motor Claim Department

Make/Model: M.BENZ C200
KOMPRESSOR

Xiao Tony

Chasis No: WDD2040412A095314

Claim Type: Third Party

Reg. Date: 24/01/2018

Accident Date: 28/05/2018

Your Ref No: SLV2850S

TP Veh Reg No: SLV2850S

Estimate Repair Cost to Vehicle No :SJU2929D

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC FRONT R/H DOOR <i>Refect</i>	2,106.00 ✓	
2	1 PC FRONT R/H DOOR RUBBER <i>m</i>	282.00 ✓	
3	1 PC FRONT R/H DOOR INNER BOTTOM RUBBER <i>m</i>	124.00 ✓	
4	1 PC FRONT R/H DOOR LOCK <i>2nd</i>	386.00 ✓	
5	1 PC FRONT R/H DOOR OUTER CHROME MOULDING <i>the m</i>	244.00 +	
6	1 PC FRONT R/H DOOR MOULDING <i>m</i>	90.00 ✓	
7	1 PC FRONT R/H DOOR GLASS CHANNEL <i>Heu</i>	199.00 x	
8	1 PC FRONT R/H DOOR GLASS REGULATORE ASSY <i>meu</i>	659.00 +	
9	1 PC FRONT R/H DOOR GLASS CHANNEL PILLAR <i>meu</i>	68.00 +	
10	1 PC FRONT R/H DOOR TRIM <i>cracked outer</i>	2,668.00 x 950	
11	1 PC REAR R/H DOOR <i>Dislnd</i>	2,099.00 ✓	
12	2 PCS REAR R/H DOOR DOOR HINGES <i>3 me</i>	250.00 ✓	
13	1 PC REAR R/H DOOR DOOR CHECK	78.00 ✓	
14	1 PC REAR R/H DOOR OUTER CHROME MOULDING <i>meu</i>	211.00 x	
15	1 PC REAR R/H DOOR MOULDING <i>meu</i>	89.00 ✓	
16	1 PC REAR R/H DOOR RUBBER <i>m</i>	282.00 ✓	
17	1 PC REAR R/H DOOR DOOR BOTTOM AND RUBBER <i>inner m</i>	116.00 ✓	
18	1 PC REAR R/H DOOR GLASS CHANNEL <i>meu</i>	182.00 x	
19	1 PC REAR R/H DOOR LOCK <i>meu</i>	387.00 +	
20	1 PC REAR R/H FENDER <i>Dislnd</i>	2,038.00 ✓	
21	1 PC REAR R/H FENDER COWLING <i>Dislnd</i>	162.00 ✓	
22	1 PC R/H SIDE SKIRT <i>Dislnd</i>	526.00 ✓	
23	1 PC REAR R/H DOOR TRIM <i>cracked</i>	2,026.00 1045	
24	1 PC REAR W/S GLASS <i>meu</i>	2,251.00 962	
25	1 PC REAR R/H LOWER ARM <i>set</i>	699.00 ✓	
26	1 PC REAR TRAILING ARM <i>meu</i>	587.00 x	
27	1 PC REAR R/H SHOCK ABSORBER <i>Best neu</i>	518.00 +	
28	1 PC REAR R/H WHEEL HUB <i>Dislnd</i>	452.00 ✓	
29	1 PC REAR R/H BEARING <i>m</i>	274.00 ✓	
1pc	rear door glass regulator <i>2nd</i>	629.00 ✓	
1pc	rear door " " motor	540.00 x	
1pc	" " " " ECU	418.00 +	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST1800183
Date: 18 Jun 2018
Veh Reg No: SJU2929D
Make/Model: M.BENZ C200
KOMPRESSOR
Chasis No: WDD2040412A095314
Reg. Date: 24/01/2018
Your Ref No: SLV2850S

Claim Type: Third Party
Accident Date: 28/05/2018
TP Veh Reg No: SLV2850S

Estimate Repair Cost to Vehicle No :SJU2929D

Quantity	Description	List Price	Amount
		S\$	S\$
30	1 PC REAR R/H THRUST ARM <i>2</i>	107.00 <i>+</i>	
31	1 PC REAR R/H TIE ROD <i>Best NH</i>	224.00 <i>+</i>	
32	1 PC REAR R/H STRUT ARM <i>1</i>	194.00 <i>+</i>	
33	1 PC REAR R/H CUMBER ARM <i>Men</i>	779.00 <i>+</i>	
34	1 PC REAR R/H KNUCKLE ARM <i>Dump</i>	1,669.00 <i>+</i>	
1 PC	Front glass regulator motor .599.00 <i>Men</i>	23,026.00	
1 PC	" " " " ECU 464.00 <i>Less 10%</i>	2,302.60	20,723.40
	Special Net		
35	1 SET REAR R/H FENDER COWLING CLIPS <i>Men</i>	60.00 <i>30</i>	
36	1 PC REAR W/S GUM <i>2</i>	80.00 <i>30</i>	
37	1 PC REAR W/S SEAL <i>3</i>	80.00 <i>30</i>	
38	1 SET SIDE SKIRT CLIPS <i>Men</i>	40.00 <i>✓</i>	
39	1 PC REAR R/H SPORTS RIM <i>Lot</i>	1,000.00 <i>800</i>	
		1,260.00	1,260.00
	Labour		
40	1 TO CHECK WIRING	50.00 <i>30</i>	
41	1 TO REMOVE AND REFIT FRONT R/H DOOR GLASS <i>fitting</i>	120.00 <i>80</i>	
42	1 TO REMOVE AND REFIT REAR R/H DOOR GLASS <i>fitting</i>	120.00 <i>80</i>	
43	1 TO REMOVE AND REFIT FUEL TANK	200.00 <i>80</i>	
44	1 TO REMOVE AND REFIT W/S GLASS	120.00 <i>100</i>	
45	1 TO REMOVE AND REFIT UNDERCARRIAGE	600.00 <i>220</i>	
46	1 TO CHECK WHEEL ALIGNMENT	120.00 <i>80</i>	
47	1 TO SPRAY UNDERSEAL	200.00 <i>60</i>	
48	1 TO SPRAY PAINT DAMAGED PORTION, INCLUDING SUPPLY OF PAINT MATERIALS	1,500.00 <i>1000</i>	
49	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,000.00 <i>1000</i>	
50	1 REMOVE AND REFIT SEAT CUSHION	350.00 <i>120</i>	
		2850	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST1800183
Date: 18 Jun 2018

Veh Reg No: SJU2929D
Make/Model: M.BENZ C200
KOMPRESSOR
Chasis No: WDD2040412A095314
Reg. Date: 24/01/2018
Your Ref No: SLV2850S

Claim Type: Third Party
Accident Date: 28/05/2018
TP Veh Reg No: SLV2850S

Estimate Repair Cost to Vehicle No :SJU2929D

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		5,380.00	5,380.00
		Total	S\$ 27,363.40
		Add GST @ 7%	1,915.44
		Total Amount Payable	<u>S\$ 29,278.84</u>

TOTAL: SINGAPORE DOLLAR TWENTY NINE THOUSAND TWO HUNDRED SEVENTY EIGHT AND CENTS EIGHTY FOUR ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

total: 17557.2 For Kang Car Repairers Pte Ltd
L/s: 14K.
AUTHORISED SIGNATURE

Adrian King
L/s 19/06/18.

009 Peng.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: