Thin Thin (LKKAuto)

From: Thin Thin (LKKAuto)

Sent: Tuesday, 9 October 2018 3:50 PM

To: 'nip one'

Subject: RE: ACCIDENT INVOLVING SJZ 6041L AND SHD 3957D ON 17/06/2018

Dear Ms Pin Pin,

We refer to the below matter.

Please be inform that we have requested video footage from Third Party. Based on the footage provided by Third Party, Third Party vehicle was travelling in front of your vehicle.

Therefore, we will proceed to negotiate and settle at best with Third Party in order to avoid the further escalation.

Please call us if you have further queries.

Yours faithfully,

Best Regards,

Thin Thin Hlaing | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: <u>thinthin@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: nip one <nipone2002@yahoo.com>
Sent: Monday, 24 September 2018 4:14 PM
To: Thin Thin (LKKAuto) <thinthin@lkkauto.com>

Subject: Re: ACCIDENT INVOLVING SJZ 6041L AND SHD 3957D ON 17/06/2018

Dear Thin Thin,

Please find the report made after the accident with Lai Huat Auto.

I do have some photos of the accidents. They are attached to this email. Based on what I could recall, I was in the right of way with no car in front of me in the one way lane. I was on the right hand side looking out for traffic coming on my right and when there was no car, I turned left. That was when my left side made contact with the right side of the taxi (who probably squeezed past). The taxi driver initially indicated that he did not want to make a report and told me to leave the matter as it is. I went to Lai Huat Auto to file a report but did not make any claims as it was very minor.

Thank you for your assistance.

Pic 1: The single lane where the accident occurs. It is a wide lane and possible for 2 cars to be side-by-side.



Pic 2: Based on the following photos, you would see where my car made contact with the taxi. If I am behind him, then I would have made contact with him on the back of his taxi and not at the side.

