

ECICS

DOA: 18.06.18

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHD3090D
MAKE : HYUNDAI
MODEL : i40

Date: 19.06.2018

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Front Bumper <i>X repair</i>			\$ 1,052.20
10	Front Bumper Clips <i>X 11</i>		\$2.20	\$ 22.00
1	Front Bumper Top Bracket - RH <i>X su</i>			\$ 22.40
1	Front Bumper Bracket - RH <i>X su</i>			\$ 24.60
1	Headlamp <i>X su</i>			\$ 1,388.00
1	Headlamp Support Panel <i>X su</i>			\$ 1,067.50
	<i>Front RH Fender X repair</i>			
	SUB TOTAL			\$ 3,576.70
	LESS 20%			715.34
	DISCOUNTED TOTAL			\$ 2,861.36
	Labour Charge			
1	Panel Beating			\$ 500.00 ²⁰⁰
1	Spray Painting Charge			\$ 500.00 ⁴⁰⁰
1	Wiring Charge			\$ 50.00 ^{X 11}
1	Tuff Kote			\$ 80.00 ^{X 11}
	TOTAL LABOUR			\$ 1,130.00
	ESTIMATE TOTAL			\$ 3,991.36

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Ka/ur 16/6/18

Page 1 of 1

20/6/18 1405hrs
2 by
PIP
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- Parts prices are subject to final survey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: