

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

20-Jun-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6099 R

1 pc	Front o/s door ✓	\$	761.00
2 pcs	Front o/s door hinges @ \$34.00 ✗	\$	68.00
1 pc	Rear o/s door ✗ repair	\$	791.00
2 pcs	Rear o/s door hinges @ \$34.00 ✗	\$	68.00
1 pc	Front o/s fender inner shield @ \$120.00 ✗	\$	120.00
1 pc	Front o/s wheel cover @ \$116.00 ✓	\$	116.00
1 pc	o/s rocker panel garnish @ \$286.00 ✗ repair	\$	286.00
		\$	2,210.00
Less 10%		\$	221.00
		\$	1,989.00

### S/NETT

1 pc	Front o/s fender sticker ✗	\$	30.00
1 pc	Front o/s fender inner shield clips ✗	\$	28.00
1 pc	o/s door sticker ✓	\$	100.00
Sundry		\$	<del>50.00</del> 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	<del>180.00</del> ✗
To dismantle and refit the inner component of front o/s door into new shell door		\$	<del>150.00</del> 50
To dismantle and refit the inner component of rear o/s door into new shell door		\$	<del>150.00</del> ✗
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front bumper, front o/s fender, front o/s door, o/s rocker panel garnish, etc.		\$	<del>800.00</del> 400
To putty and spray painting on front bumper, front o/s fender, o/s side mirror, front o/s door, rear o/s door, o/s rocker panel garnish ✗		\$	<del>1200.00</del> 900
To apply rustproofing on the repaired and replaced panels.		\$	<del>150.00</del> 20
		\$	4,827.00

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahar ellay  
20/6/18 1015h  
3 May  
U/s  
Atte Rep'r pht