

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

LUMENS AUTO PTE LTD
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

TP China
Joy

19th JUNE 2018

ZVW 506102005

Accident date: 18th JUNE 2018

Estimated repair cost for vehicle no: SLV4775M Toyota PRIUS '18

S/n	Qty	Items	U/price	Amount
1	1	Front head lamp -LH <i>cauled.</i>		\$1,885.00 ✓
2	1	Front bumper <i>Deland</i>		\$1,050.00 ✓
3	2	Front bumper side bracket <i>LH m</i>	\$121.00	\$242.00 77
4	1	Front bumper clips <i>new</i>		\$30.00 ✓
5	1	Front bumper fog lamp <i>2 new</i>		\$385.00 X
6	1	Front bumper fog lamp cover		\$155.00 X
7	1	Front bumper reinforcement		\$635.00 X
8	1	Front grille <i>Crack</i>		\$420.00 ✓
9	1	Front grille clips <i>m</i>		\$50.00 20

Front Bumper Sponge *and* 172.40
Front Bumper Lower Grille *and* 165. ✓

Subtotal :- \$4,852.00

labour charges

To Check Wiring System

3819.4

~~\$80.00~~ 30

Tuff Kote

2864.55

~~\$120.00~~ X

Panel beating

480

~~\$800.00~~ 200

Spray painting

~~\$800.00~~ 250

Subtotal :- \$1,800.00

Total :- \$6,652.00

total 3344.55

c/s 2650

03/11/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: