

15/5/2010

INS. CASE OWNER:

CC 6/CTI1801

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

20/6/18

Date / Time:

20/6/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLV 7711H

Name of Insured:

bati Enkai

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A:

18/6/18

Is driver the owner?

(YES) (NO)

Nature of Accident:

If NO, Driver Name / Age:

ng mul Hoonh LHERYL

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SAMY 800007600 ✓

Policy No.:

DMP LSW 208770700

Make / Model:

TOYOTA

Place of Accident:

SERVICE KIP PASSENGER BRP
OFF @ BISHAW JUNE 8

OI GIA REPORT YES / NO:

TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SLV 4775m

INSRS:
WSP:
Tel:
Liability:
RMKS:Green
ForestINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

28/6/18
JAY

1-8-18 @ 1057

W/OID. OI IS HER
HUSBAND. CONFIRMED
ACC. AWARE OF CAR
& AWARE NCD LIVE.

1-8-18

FOR MANDATE.

RECEIVED 27 AUG 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

3-8-18

Confirm with:

CHARIS

Email ☐ Call ☐

Final Liability:

%

100

(Agreed)

Assessed)

BOLA S/N No.:

NIL

If NO or B 28. Ass. Lia:

Repair Cost:

S\$

2,835.50

Loss of Rental (LOR):

S\$

300

(S

x

days)

Loss of Use (LOU):

S\$

(S

x

days)

Loss of Income (LOI):

S\$

(S

x

days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

3,135.50

Global Sum S\$:

Email ☐ Call ☐

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

S\$

3,135.50

Name 1:

GREEN FOREST AUTOMOBILE PTE LTD

Payee 2: (Strike if N.A.)

S\$

X

Name 2:

X

Payee 3: (Strike if N.A.)

S\$

X

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

OID REVERSED &

HIT PARKED TP

CLAIM

REF:

ASS. REC. BY: Adrian King**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : **Yes** or No

GIA / PR Seen:

Consistent? : **Yes** or No

Est. Repairs:

3

days

Res.: **Yes** or No

Lum Sum:

%

3 Val.: **Yes** or No

CA / REV / REP. / 24 HRS

Vehicle: **IN** / OUT

Date:

Person Contacted:

Veh No:

SLV4775MYr Regn: **2017, Dec**Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota PriusC.C. **1797**

Colour:

GreyA/C: **Insured / Std / NI / NA**

Sp. Reading

30512T/Radio: **Insured / Std / NI / NA**

Eng/No:

C/No:

ZVWS06102005Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: **Nil** / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/65R15**185/65R15**BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

20/06/18

Survey held at

Green ForestDes. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or**Fr**

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Claim**L/S \$2,650****R (\$4,002/60%)****6961K**

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS. SI

) Photos:

) Others:

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18011232/Ajb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 20-06-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLU 7711H	Veh. Inspected	SLV 4775M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	18/06/2018	Inspection Date	20/06/2018
Survey held at	GREEN FOREST AUTOMOBILE 8 KAKI BUKIT AVENUE 4 #05-25 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Shu Pei (LKKAuto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 27 June 2018 2:43 PM
To: Shu Pei (LKKAuto)
Cc: Admin A; Joy Irene (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving SLU7711H (OI : CTI - TBA) and SLV4775M (TP : LKK REF - CC6/CTI18011232/jb3) on 18.06.2018 / OUR REF: SNM18D03073C02
Attachments: INSD REPORT.PDF

Dear Shu Pei,

Pls find Insured report.

Thank you.

Regards,

Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 20 June, 2018 8:13 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Angie Foo <angie.foo@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Subject: Direct Settlement - Accident Involving SLU7711H (OI : CTI - TBA) and SLV4775M (TP : LKK REF - CC6/CTI18011232/jb3) on 18.06.2018

WITHOUT PREJUDICE

Dear Boon Sen,

We refer to the above matter.

This is a TP direct settlement case from M/s Green Forest Automobile.

Enclosed for your perusal is:

- TP GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

LUMENS AUTO PTE LTD
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

TP' China
Joy.

19th JUNE 2018

ZVW 506107005

Accident date: 18th JUNE 2018
Estimated repair cost for vehicle no: SLV4775M Toyota PRIUS '18

S/n	Qty	Items	U/price	Amount
1	1	Front head lamp -LH <i>cracked.</i>		\$1,885.00 ✓
2	1	Front bumper <i>delivered</i>		\$1,050.00 ✓
3	2	Front bumper side bracket <i>LH m</i>	\$121.00	\$242.00 77
4	1	Front bumper clips <i>new</i>		\$30.00 ✓
5	1	Front bumper fog lamp <i>2 new</i>		\$385.00 x
6	1	Front bumper fog lamp cover		\$155.00 x
7	1	Front bumper reinforcement		\$635.00 x
8	1	Front grille <i>cracked</i>		\$420.00 ✓
9	1	Front grille clips <i>m</i>		\$50.00 20

Front Bumper Sponge *auto* 172.40
Front Bumper Lower Grille *delivered* 165. ✓

Subtotal :- \$4,852.00

labour charges

To Check Wiring System

3819.4

~~\$80.00~~ 30

Tuff Kote

2864.55

\$120.00 x

Panel beating

480

~~\$800.00~~ 200

Spray painting

~~\$800.00~~ 250

Subtotal :- \$1,800.00

Total :- \$6,652.00

6989.40

total 3344.55

c/s 2650

03hnp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 6961K

Vehicle Details

Vehicle No.: SLV4775M
Vehicle to be Exported: Yes
Intended De-registration Date: 20 Jun 2018
Vehicle Make: TOYOTA
Vehicle Model: PRIUS HYBRID 1.8S CVT
Primary Colour: Grey
Manufacturing Year: 2017
Engine No.: 2ZR8263120
Chassis No.: ZVW506102005
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$24,933.00
Original Registration Date: 29 Dec 2017
First Registration Date: 29 Dec 2017
Transfer Count: 0
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Dec 2027
PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 28 Dec 2027
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period (Years): 10
QP Paid: \$53,711.00
COE Rebate Amount: \$42,968.00
Total Rebate Amount: \$46,718.00

The information contained herein is correct as at 20 Jun 2018

OK

no estimate



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18011232/Ajb3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 29-08-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLU 7711H	Veh. Inspected	SLV 4775M
Policy No.	DMPCSN3087701700	Coverage (\$)	0.00
Claim No.	SNM18D03073C02	Excess (\$)	0.00
Assign From		Assign Date	20/06/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZVW506102005	Colour	GREY
Odometer	30512	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	DUNLOP	6 mm
L/H Front Tyre	195/65R15	DUNLOP	6 mm
R/H Rear Tyre	195/65R15	DUNLOP	6 mm
L/H Rear Tyre	195/65R15	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/06/2018	Inspection Date	20/06/2018
Survey held at	GREEN FOREST AUTOMOBILE 8 KAKI BUKIT AVENUE 4 #05-25 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 4775M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT HEAD LAMP -LH	CRACKED	1,885.00	1,885.00
1	FRONT BUMPER	DEFORMED	1,050.00	1,050.00
2	FRONT BUMPER SIDE BRACKET @\$121.00	N/S NECESSARY	242.00	77.00
1	FRONT BUMPER CLIPS	NECESSARY	30.00	30.00
1	FRONT BUMPER FOG LAMP	NOT NECESSARY	385.00	-
1	FRONT BUMPER FOG LAMP COVER	NOT NECESSARY	155.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	635.00	-
1	FRONT GRILLE	CRACKED	420.00	420.00
1	FRONT GRILLE CLIPS	NECESSARY	50.00	20.00
1	FRONT BUMPER SPONGE	CRACKED	172.40	172.40
1	FRONT BUMPER COVER GRILLE	DEFORMED	165.00	165.00
	LESS 25% DISCOUNT		-	-954.85
			5,189.40	2,864.55
<u>LABOUR</u>				
	TO CHECK WIRING SYSTEM.	NOT NECESSARY	80.00	30.00
	TUFF KOTE.		120.00	-
	PANEL BEATING.		800.00	200.00
	SPRAY PAINTING.		800.00	250.00
			1,800.00	480.00
GRAND TOTAL			6,989.40	3,344.55
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,650.00

Report Ref No. CC6/CTI18011232/Ajb3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.