

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKR5245C

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST SLS1794T - MSIG		
2	ZZ/001	CONDUCT TP CLAIM MSIG LOCATION:MARINA BOULEVARD TO BAYFRONT AVE DATE:04/06/2018 TIME:0815HRS		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER AND PANEL	1680.00	560.00
4	ZZ/003	RESPRAY REAR BUMPER AND PANEL	1260.00	840.00
5	ZZ/004	TO CONDUCT WATER SEEPAGE TEST	100.00	.00
6	ZZ/005	TO CONDUCT REAR LIGHTING TEST	50.00	20.00
7	ZZ/006	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	300.00	.00
8	ZZ/007	SUNDRIES	100.00	20.00
9	ZZ/008	REMOVE AND REFLX EXHAUST (SUPP)	150.00	150.00 A
TOTAL LABOUR CHARGES			3640.00	1590.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKR5245C

		DAMAGED PARTS & PRICES			S/LIST REMARKS
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	
1 GASKET A (SUPP)	44011AE010	16.00			<i>na</i> OK A —
2 EXH PIPE ASSY R (SUPP)	44200FJ110	684.00			<i>B1</i> OK A —
3 MUFFLER AY (SUPP)	44300FJ040	576.00			<i>B1</i> OK A —
4 REAR END PANEL	52401FJ0009P	252.00			X
5 BUMPER FACE R XUV	57704FJ041	594.00			OK
6 BRKT RRH BUMP	57707FJ160	14.40			OK
7 BRKT RLH BUMP	57707FJ170	14.40			X
8 BEAM COMPL R EU	57711FJ0229P	259.20			OK
9 COVER-REAR BUMPER	57731FG010E1	14.40			X
10 EXHAUST COVER REAR (SUPP)	59024FJ000	72.00			<i>na</i> OK A —
11 REFLEX AY RH	84281FG000	21.60			X
12 RELFLEX ASSY LH	84281FG010	21.60			X
13 LENS & BODY-FOG LIGHT,REAR	84913FG420	102.00			X
SUB TOTAL		2215.60	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		443.12	0.00	0.00	0.00
GRAND TOTAL		1772.48	0.00	0.00	0.00
OVERALL TOTAL		1772.48			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED