



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18011253/Ajb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 21-06-2018	
Code : AIG			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLT 7149L	Veh. Inspected	SLP 893M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	18/06/2018	Inspection Date	20/06/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

Alig. Adnan

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TP AIG. JMYSRCY2A94003964
Joy.

18/06/2018

Accident date: 17/06/2018

Estimated repair cost for vehicle no: SLP893M MITSUBISHI LANCER 1.5 A '09

S/n	Qty	Items	U/price	Amount
1	1	Front L/H Door <i>Dented</i>		\$1,075.00
2	2	Front L/H Door Frame Sticker <i>new</i>	\$36.00	\$72.00
3	1	Front L/H Door Inner Lock <i>new</i>		\$287.00
4	1	Rear L/H Door <i>Dented</i>		\$1,008.00
5	2	Rear L/H Door Frame Sticker <i>new</i>	\$36.00	\$72.00
6	1	Rear L/H Door Inner Lock <i>new</i>		\$287.00
7	1	Rear L/H Door Inner Rubber <i>new</i>		\$148.00
8	1	Rear L/H Door Inner Trim Board <i>new</i>		\$568.00
9	1	Rear L/H Door Gear Motor Assy <i>Dented</i>		\$363.00
10	1	Rear L/H Fender <i>Key</i>		\$988.00
11	1	Rear L/H Rim <i>ht</i>		\$650.00
12	1	Rear L/H Tyre <i>new</i>		\$350.00
13	1	Rear L/H Lower Arm <i>Best</i>		\$221.00
14	1	Rear L/H Lower Arm Inner new <i>Not new</i>		\$126.00
15	1	Rear L/H Knuckle Arm <i>Best</i>		\$420.00
16	1	Rear L/H Knuckle Arm Bearing <i>new</i>		\$397.00
17	1	Rear L/H Trailing Arm <i>new</i>		\$399.00
18	1	Rear L/H Shock Absorber new <i>new</i>		\$254.00
19	1	Rear Bumper <i>Behind</i>		\$815.00
20	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00
21	1	Rear L/H Bumper Mud Shield <i>new</i>		\$38.00
22	4	Rear L/H Bumper Mud Shield Clip <i>new</i>	\$6.50	\$26.00
23	1	Rear Windscreen Moulding <i>new</i>		\$65.00
24	1	L/H Rocker Panel Skirt <i>Behind</i>		\$708.00
25	10	L/H Rocker Panel Skirt Clip <i>new</i>	\$6.50	\$65.00

6319
5687.10

Subtotal :- \$9,454.00

Labour charges

To remove & refit reverse sensor	\$100.00 50
To remove & refit petrol tank	\$280.00 +
To remove & refit rear windscreen	\$120.00 +
Gum	211 \$50.00 +
To remove & refit front & rear L/H door, gear motor, rubber, lock, trim board & frame sticker	\$380.00 160
To remove & refit rear L/H undercarriage	\$380.00 220
To check wheel alignment	\$150.00 80
To check wiring	\$100.00 30
Tuff kote	2240 \$150.00 x
Panel beating	\$1,400.00 700
Spray painting	\$1,400.00 1000

Subtotal :- \$4,510.00

Total:- \$13,964.00

Adrian Lij
1/2 20/06/18
OG Pumps

total: 7527.10

n/s: 6.3K

6.3K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NEW HOCK TECK MOTOR PTE LTD

Our Ref : NPI1807-0143 / SLP893M
Your Ref : SLT7149L
Date : 25th July 2018

1 Kaki Bukit Avenue 6
Blk C #01-43 Autobay@KB
Singapore 417883

AIG ASIA Pacific Insurance Pte Ltd
78 Shenton Way,
AIG Building, #09-16
Singapore 079120

WITHOUT PREJUDICE

Dear Sirs,

RE: ACCIDENT INVOLVING SLP893M & SLT7149L AT PARKWAY PARADE MSCP LEVEL P3 ON 18.06.2018, 13:45HRS

We are instructed by **ORANGE SAPPHIRE SOLUTION PTE LTD** to claim damages and losses against you in connection with the above captioned road traffic accident which our client's vehicle **SLP893M** was damaged by vehicle **SLT7149L** driven by your insured at the material time.

We are instructed that the said accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

1) Repair Costs	\$ 6,300.00
2) Loss of Use for 07 days (6 + 1 Weekend)	\$ 420.00
3) LTA Search Fees	\$ 7.45
	<u>\$ 6,727.45</u>

A copy each of the following supporting document is enclosed:

- 1) Final Repair Bill
- 2) LTA Receipt

Please let us have your cheque for the sum **\$6,727.45** made payable to us, **NEW HOCK TECK MOTOR PTE LTD** in the next 14 days.

Yours faithfully,

NEW HOCK TECK MOTOR PTE LTD



Assignment

To: New Hock Teck Motor Pte Ltd (Workshop)

In consideration for your agreement to repair my motor vehicle registration no. SLP893M and to defer demanding for payment of the cost of repair, I/we the undersigned do hereby irrevocably assign absolutely to you all the proceeds of my/our claim(s) including damages, interest, costs and expenses (including legal costs / disbursements payable on a party and party basis which are to be paid to the parties so entitled including solicitors, vehicle appraisers and other experts / consultants).

I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this 20 day of 06 2018.

Signature : 
Name : SOLUTION
ID No. : _____
Address : PTE LTD
Witness Signature : 
Witness Name : Chew Yee Yim
Witness ID : SPR266184
Witness Address : 1 Kaki Bukit Avenue 6 #01-43
Singapore 417883

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	22 Jun 2018 Edit Reg		20 Jun 2018 00:00 Edit Adj Rpt	S\$6,300.00 Edit Estimates	S\$6,300.00 View Rpt		Pending for Survey Report Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	VERONICA GOH WEE CHIA , ID: S8318366G, Tel: +6588185509		
Main Claimant:	ORANGE SAPPHIRE SOLUTION PTE LTD , Co. Reg. No.: 2014005519D		
Vehicle Reg. No.:	SLP893M	Date of Loss:	18/06/2018 13:00 - :59 [112 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / 5164952761SG	Policy/Cover Note No.:	1700075550 (Comprehensive)
Vehicle Reg. No. (Insured):	SLT7149L	Policy No. (Claimant):	5092071938
		Excess:	
Repairer:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Bk C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 02/07/2018]		
Driver/Custodian (Insured):	VERONICA GOH WEE CHIA (), NRIC: S8318366G, Tel: +6588185509		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLP893M (5164952761SG)
[SLT7149L]**

TP

ORANGE SAPPHIRE SOLUTION PTE LTD

Jun 18 2018 1:00PM

**[VERONICA GOH WEE CHIA]
New Hock Teck Motor Pte Ltd**

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View	View in Browser ▾
Video			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	14/08/18 08:41	Video - Accident VIDEO FROM OI		Load MP4
Letters/Correspondences			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit
Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
2	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
3	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
4	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
5	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
6	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
7	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
8	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
9	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
10	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
11	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
12	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
13	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
14	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
15	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
16	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
17	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
18	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
19	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
20	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
21	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
22	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
23	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
24	06/08/18 11:38	General View		Load JPG <input checked="" type="checkbox"/>
25	06/08/18 11:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
26	06/08/18 11:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
27	06/08/18 11:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
28	06/08/18 11:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
29	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
30	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
31	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
32	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
33	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
34	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
35	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
36	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
37	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
38	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
39	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
40	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
41	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
42	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
43	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
44	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
45	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
46	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
47	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
48	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
49	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
50	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
51	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
52	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
53	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
54	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
55	06/08/18 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
56	06/08/18 11:39	Reinspection Photo		<input checked="" type="checkbox"/>
57	06/08/18 11:39	Reinspection Photo		<input checked="" type="checkbox"/>
58	06/08/18 11:39	Reinspection Photo		<input checked="" type="checkbox"/>
59	06/08/18 11:39	Reinspection Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/06/18 19:49	TP GIA REPORT		<input checked="" type="checkbox"/>
2	14/09/18 16:46	AUTHORISATION TO ACT		<input checked="" type="checkbox"/>
3	14/09/18 16:46	LETTER TO OI		<input checked="" type="checkbox"/>
4	14/09/18 16:46	LTA SEARCH		<input checked="" type="checkbox"/>
5	14/09/18 16:46	RELEASE VOUCHER		<input checked="" type="checkbox"/>
6	14/09/18 16:46	WORKSHOP INVOICE		<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	22/06/18 13:15	OI GIA REPORT		<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLT7149L (Insd veh)	Model:	MITSUBISHI LANCER 1.5 MIVEC GLS 4A/T (A)
	SLP893M (TP veh)		
Date of Accident:	18/06/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	13,964.00
Final Repair Cost	:	\$	6,655.00
Loss of Use	:	\$	7.00 days at \$50.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	6,655.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown

1)	New Hock Teck Motor Pte. Ltd.	:	\$	6,655.00
2)		:	\$	
3)		:	\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

14 Sep
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18011253/AJB3S2
Date: 14/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700075550
Claimant Vehicle No : SLP893M **Insured Vehicle No :** SLT7149L
 Date of Loss: 18/06/2018 Nature of Claim: TP Claim No: 5164952761SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP893M**
 Make & Model: MITSUBISHI LANCER, 1.5 MIVEC GLS 4A/T (A) Engine No: 4A910122429
 Reg. Date: 18/02/2009 (Man. Year: 2009) Chassis No: JMYSRCY2A9U003964
 Colour: Red Odometer: 190277 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
 Front Left Side: Sincera 6 mm Rear Left Side: Sincera 6 mm
 Front Right Side: Sincera 6 mm Rear Right Side: Sincera 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,504.00	5,687.10	3,816.90	40.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,460.00	2,240.00	2,220.00	49.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,964.00	7,927.10	6,036.90	43.23
Approved Total (Overridden) (S\$)		6,300.00		
Nett Amount (S\$)	13,964.00	6,300.00	7,664.00	54.88
+ Loss of Use (7.0 x S\$50.00/day) (S\$)		350.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,657.45		
Global Sum Settlement (S\$)		6,655.00		

INSPECTION

Date of Assignment: 20/06/2018
 Date Inspected: 20/06/2018 Inspected At: New Hock Teck Motor Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 6.0 days

9/14/2018

Adjuster Report

Adjuster: ADRIAN LING

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT L/H DOOR	Dented	1,075.00 F	*1,075.00 FL
2	2		*FRONT L/H DOOR FRAME STICKER	Necessary	72.00 F	*72.00 FL
3	1		*FRONT L/H DOOR INNER LOCK	Not Necessary	287.00 F	*- FL
4	1		*REAR L/H DOOR	Dented	1,008.00 F	*1,008.00 FL
5	2		*REAR L/H DOOR FRAME STICKER	Necessary	72.00 F	*72.00 FL
6	1		*REAR L/H DOOR INNER LOCK	Not Necessary	287.00 F	*- FL
7	1		*REAR L/H DOOR INNER RUBBER	Not Necessary	148.00 F	*- FL
8	1		*REAR L/H DOOR INNER TRIM BOARD	Cracked	568.00 F	*458.00 FL
9	1		*REAR L/H DOOR GEAR MOTOR ASSY	Damaged	363.00 F	*363.00 FL
10	1		*REAR L/H FENDER	Repair	988.00 F	*- FL
11	1		*REAR L/H RIM	Cut	650.00 F	*650.00 FL
12	1		*REAR L/H TYRE	Not Necessary	350.00 F	*- FL
13	1		*REAR L/H LOWER ARM	Bent	221.00 F	*221.00 FL
14	1		*REAR L/H LOWER ARM INNER	Not Necessary	126.00 F	*- FL
15	1		*REAR L/H KNUCKLE ARM	Bent	420.00 F	*420.00 FL
16	1		*REAR L/H KNUCKLE ARM BEARING	Necessary	397.00 F	*397.00 FL
17	1		*REAR L/H TRAILING ARM	Not Necessary	399.00 F	*- FL
18	1		*REAR L/H SHOCK ABSORBER	Not Necessary	254.00 F	*- FL
19	1		*REAR BUMPER	Deformed	815.00 F	*815.00 FL
20	8		*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
21	1		*REAR L/H BUMPER MUD SHIELD	Not Necessary	38.00 F	*- FL
22	4		*REAR L/H BUMPER MUD SHIELD CLIP	Not Necessary	26.00 F	*- FL
23	1		*REAR WINDSCREEN MOULDING	Not Necessary	65.00 F	*- FL
24	1		*L/H ROCKER PANEL SKIRT	Deformed	708.00 F	*708.00 FL
25	10		*L/H ROCKER PANEL SKIRT CLIP	Necessary	65.00 F	*30.00 FL
26	1		*GUM	Not Necessary	50.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	9,504.00	6,319.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	631.90
Total Parts (\$\$)	9,504.00	5,687.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT REVERSE SENSOR.	New	100.00	50.00
2	TO REMOVE & REFIT PETROL TANK.	New	280.00	0.00
3	TO REMOVE & REFIT REAR WINDSCREEN.	New	120.00	0.00
4	TO REMOVE & REFIT FRONT & REAR L/H DOOR, GEAR MOTOR, RUBBER, LOCK, TRIM BOARD & FRAME STICKER.	New	380.00	160.00
5	TO REMOVE & REFIT REAR L/H UNDERCARRIAGE.	New	380.00	220.00
6	TO CHECK WHEEL ALIGNMENT.	New	150.00	80.00
7	TO CHECK WIRING.	New	100.00	30.00
8	TUFF KOTE.	New	150.00	0.00
9	PANEL BEATING.	New	1,400.00	700.00
10	SPRAY PAINTING.	New	1,400.00	1,000.00
Gross Labour Cost (S\$)			4,460.00	2,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >