

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD  TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLF 5723R  
 at Workshop m/s: Sum  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: 15500  
 I/PAC Accident Rpt: 2 Consistent?: Yes or No  
 GA / PR Seen: 2 Consistent?: Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
26/2/2019  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLF 5723R Yr Regn: 27/2 09  
 Type:  M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or CA/  
 Make: Honda crossroad c.c 1799  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 177080 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: RT11008198  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Good / Jammed / Leaked / Burnt or  
 Brake: Good / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 225/65R18  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front 6 mm Rear 6 mm  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 16/6/18 D.O.I. 21/6/18  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
Rear N/S  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>AKA LTA 9678 dep 9500 Amb. nett 5825</u>
	<u>L/S 25800</u>
	<u>* independent report</u>
<b>RECEIVED 23 JUL 2018</b>	

Date/Time, File Pass to? 03/07/18  
 : Preli. Report  
 : Final Report  
 1) Typist  
 Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: 5  
 Resurvey No. of Trip: 2

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee:	<u>170</u>
Transportation:	<u>50</u>
\$ + RS, \$	<u>50+50</u>
Photos	<u>93</u>
Others	<u>80</u>
<b>TOTAL</b>	<b><u>493</u></b>

Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I. (\$) 5,200.00 HS

Ref. No : <u>CS/TP18011255/usb02</u>	Res. Date: <u>22/6/18</u>	Date Received:
Veh. No : <u>SLZ5723A</u>	SP: _____	WKSP: <u>B...</u>
C/No :		
<b>Action/Instruction:</b>		
1. File	2. Submit Photo?	YES / NO
3. Indicate Res. Date On Photo Page?		YES / NO
If No, due to	a) No authorisation	b) Days of repair
others:		
Final Re-inspection	or	Progress Photos
		Inspected By: <u>[Signature]</u>

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	1154B
<b>Vehicle Details</b>	
Vehicle No.:	SLF5723R
Vehicle to be Exported:	No
Intended De-registration Date:	21 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	CROSSROAD TYPE-18L A
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	R18A3011158
Chassis No.:	RT11008198
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$18,684.00
Original Registration Date:	27 Feb 2009
First Registration Date:	27 Feb 2009
Transfer Count:	1
Actual ARF Paid:	\$18,684.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Feb 2019
PARF Rebate Amount:	\$9,342.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	26 Feb 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$5,889.00
COE Rebate Amount:	\$333.00
<b>Total Rebate Amount:</b>	<b>\$9,675.00</b>

The information contained herein is correct as at 21 Jun 2018

OK



### Post an Advertisement

Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Altis 1.6A



\$2500 Downpayment Monthly  
From \$588 Onwards. Lowest  
3.68%P.A@GV Cars Financing  
GV Credit Pte Ltd [StarAd](#)





4 vehicles



Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mile
------	-------	-------	--------------	----------	---------	------

Search Selection

honda cross

Any

Any

2009

Any



**Honda Crossroad 1.8A L (New 5-yr COE)**

**\$41,800**

\$8,360 /yr

15-May-2009

1,799 cc

12

Low Down Payment Of Only \$4k! In House Financing Available, Your Unique 7-Seater SUV, Low Mileage, Well Maintained, Cheapest In The Market! Trade In Welcomed, Look No Further, Contact...

Posted: 15-Jun-2018 Tags: 2009 Honda Crossroad, Honda Crossroad, Honda, Crossroad, Used Honda



**Honda Crossroad 1.8A L (New 5-yr COE)**

**\$40,800**

\$8,160 /yr

07-May-2009

1,799 cc

14

Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only!

Boeki Auto & Marine

Posted: 04-Jun-2018 Tags: 2009 Honda Crossroad, Honda Crossroad, Honda, Crossroad, Used Honda



**Honda Crossroad 1.8A L (New 5-yr COE)**

**\$42,888**

\$8,570 /yr

23-Jan-2009

1,799 cc

81

We Are The COE Specialist, No Gimmicks, Honest Dealing! 2 Owner With Low Mileage Clocked, Car In Superb Condition, Payment Drive Away! 100% Approval! Trade In And Bank Loan A...

Posted: 01-Jun-2018 Tags: 2009 Honda Crossroad, Honda Crossroad, Honda, Crossroad, Used Honda



**Honda Crossroad 1.8A (New 10-yr COE)**

**\$63,899**

\$6,380 /yr

20-Feb-2009

1,799 cc

89

Pearl White. A Very Reliable And Low Mileage Definitely One Of The Best SUV In Town! Well Maintained By 1 Careful Owner SUV With New Paintwork, Clean And Neat Interior/Exterior...

Posted: 25-May-2018 Tags: 2009 Honda Crossroad, Honda Crossroad, Honda, Crossroad, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

Compare

Model

Price

Depreciation

Reg Date

Eng Cap

Mile

NA116078274 / National Assessment Centre Services - Ubi  
 ENTRY DATE & TIME: 18/06/2018 15:08  
 SUBMITTED BY: Low Shan Hui

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/06/2018 15:08
Date Of Accident	16/06/2018 16:00
Exact Location Of Accident	MARINE PARADE RD TWDS PARKWAY PARADE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF5723R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ONG BEE HOON
NRIC No	S1761154B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90048643
Alternative Phone No	OFFICE-90048643
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	CROSSROAD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00331284/01
Cover Note Number	-
<b>Driver</b>	
Name of Driver	ONG BEE HOON
NRIC No	S1761154B
Date Of Birth	11/10/1968
Occupation	INDOOR
Date Of Driving Pass	25/01/1989
Driving Experience	29 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90048643
Fax Number	
Contact Number	OFFICE-90048643
EMail Address	NOEMAIL

Address 1 ELIAS GREEN #12-05  
 Postcode 519959  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of Intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO


#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKB517K  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

Maine Parade road towards Parkway Parade



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time at the stated  
 place I vehicle of SLE5723R was travelling straight  
 on my right hand lane vehicle in front of me stopped  
 so I followed suit after abt 2 seconds I felt  
 a great impact on my rear portion vehicle of  
 BKR 517K collided onto the rear portion of my  
 stationary vehicle

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature -  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28  
 (Unit C) #01-28-53/55 Singapore 417883  
 Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088  
 Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg  
 Co. Reg. No.: 200704951N  
 GST Reg. No.: 200704951N

Not Added  
 all  
 1/5 = 500  
 500

SLF5723R

	Rear Tailgate	50d/500	1488.37	✓
	Rear Tailgate outer garnish	De/10m	599.20	✓
	Rear Tailgate 'H' logo	per	42.50	✓
	Rear Tailgate crossroad emblem	per	66.50	✓
	Rear Tailgate inner lock	11	260.50	X
	Rear Tailgate weatherstrip	twi	192.60	✓
	Rear Tailgate inner trim board	11	225.10	X
1set	Rear Tailgate inner trim board clips	per	50.00	✓
	Rear bumper	D/S	1150.10	✓
	Rear bumper side protector 1/5	10m	295.50	✓
	Rear bumper side protector retainer 1/5	5m	45.80	✓
	Rear bumper reflector 1/5	11	62.50	X
	Rear windscreen moulding	per	118.20	✓
	Rear bumper top retainer	5m	115.30	✓
	Rear end panel	100	699.10	✓
	Rear end panel top garnish	11	381.20	X
	Rear exhaust	but/tw/851.50	851.50	✓
2pc/1	Rear exhaust mounts @ 45.00	per	90.00	✓
			6933.97	1-604.67
			(20%)	
	S. Neft			
1set	Rear bumper reverse sensor	shut	280.00	200
	Rear windscreen sealant	per	50.00	40
1set	Rear floor panel insulator	11	300.00	X





# BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28  
 (Unit C) #01-29-53/55 Singapore 417883  
 Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088  
 Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg  
 Co. Reg. No.: 200704951N  
 GST Reg. No.: 200704951N

SLF5723R

To check wiring	S\$0.00	30
To Dismantle & replacing reverse sensor	S\$0.00	50
To Dismantle & refix rear windscreen	S\$150.00	120
To Dismantle & refix seat cushion upholstery	S\$150.00	80
To Dismantle & replacing rear exhaust	S\$100.00	60
To transfer Tailgate mechanism	S\$100.00	80
To spray rust proofing	S\$100.00	80
labour for panel beating/cut/weld/straighten & replacing parts	S\$1080.00	700
To putty & spray painting	S\$500.00	1200

TOTAL S\$10903.97

S\$1187.73

LKK Auto Consultants hence notify the Repairer of the following:  
 Signature: \_\_\_\_\_ Date: \_\_\_\_\_  
 Acknowledged by Repairer:  
 Signature: \_\_\_\_\_ Date: \_\_\_\_\_  
 To resurvey before spray painting  
 To display damaged part(s) during resurvey  
 Damaged parts are subject to condition of repair  
 Third party survey is on a "Without Prejudice" basis  
 No illegal modification(s) is allowed  
 Third party survey is on a "Without Prejudice" basis  
 Damaged part(s) must be repaired on a "Without Prejudice" basis  
 To display damaged part(s) during resurvey  
 To resurvey before repair  
 Acknowledged by Repairer:  
 Signature: \_\_\_\_\_ Date: \_\_\_\_\_  
 LKK Auto Consultants hence notify the Repairer of the following:  
 Signature: \_\_\_\_\_ Date: \_\_\_\_\_



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD Ref : CS/TP18011255/Usbn2

BLK 1 KAKI BUKIT AVE 6  
#01-28/51/53/55(MAIN OFFICE)SINGAPORE  
417883

Date : 24-07-2018



ON BEHALF OF ONG BEE HOON

Code : TP149

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SLF 5723R
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	21/06/2018

## 2. Vehicle Particulars & Condition

Make & Model	HONDA CROSSROAD (A)	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	RT11008198	Colour	BLACK
Odometer	177080	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/65 R16	YOKOHAMA	6 mm
L/H Front Tyre	225/65 R16	YOKOHAMA	6 mm
R/H Rear Tyre	225/65 R16	YOKOHAMA	6 mm
L/H Rear Tyre	225/65 R16	YOKOHAMA	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	16/06/2018	Inspection Date	21/06/2018
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 5723R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR TAILGATE	BADLY DENTED	1,488.37	1,488.37
1	REAR TAILGATE OUTER GARNISH	DEFORMED / TORN	599.20	599.20
1	REAR TAILGATE "H" LOGO	NECESSARY	42.50	42.50
1	REAR TAILGATE CROSSROAD EMBLEM	NECESSARY	66.50	66.50
1	REAR TAILGATE INNER LOCK	NOT NECESSARY	260.50	-
1	REAR TAILGATE WEATHERSTRIP	TWISTED	192.60	192.60
1	REAR TAILGATE INNER TRIM BOARD	NOT NECESSARY	425.10	-
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER	DISTORTED	1,150.10	1,150.10
1	REAR BUMPER SIDE PROTECTOR N/S	TORN	295.50	295.50
1	REAR BUMPER SIDE PROTECTOR RETAINER N/S	BENT	45.80	45.80
1	REAR BUMPER REFLECTOR N/S	NOT NECESSARY	62.50	-
1	REAR WINDSCREEN MOULDING	NECESSARY	118.20	118.20
1	REAR BUMPER TOP RETAINER	BENT	115.30	115.30
1	REAR END PANEL	DENTED	699.10	699.10
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	381.20	-
1	REAR EXHAUST	BENT / TWISTED	851.50	851.50
2	REAR EXHAUST MOUNTINGS @\$45.00	NECESSARY	90.00	90.00
	LESS 20% DISCOUNT		-	-1,160.94
			<b>6,933.97</b>	<b>4,643.73</b>
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	300.00	-
			<b>630.00</b>	<b>240.00</b>
<b><u>LABOUR</u></b>				
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		150.00	80.00
	TO DISMANTLE & REPLACING REAR EXHAUST.		100.00	60.00
	TO TRANSFER TAILGATE MECHANISM.		100.00	80.00
	TO SPRAY RUST PROOFING.		100.00	80.00

Report Ref No. CS/TP18011255/Usbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS.		1,080.00	700.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,200.00
			3,340.00	2,400.00
	<b>GRAND TOTAL</b>		<b>10,903.97</b>	<b>7,283.73</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,800.00</b>

Report Ref No. CS/TP18011255/Usbn2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.