

(INSUR)

INS. CASE OWNER:

Hosiah

CC6 / AIG1801

1257

AIG

LKK:

IDAC:

Surveyor:

Adnan

DOE:

ASSIGNMENT

20/6/18

Date / Time:

Pohkin / 20/6/18

Registered in Merit:

21/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SCU 1801C

Name of Insured:

TAN TAN LOO

Insured Tel No.:

HP: 97784643

Excess Sec II :\$5

D.O.A.: 16/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

677764W1054

Policy No.:

700758776-02000

Make / Model:

MERCEDES

Place of Accident:

JUNE OF BLAIR RD SPIT (SWOOD) PARK RD

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT (YES / NO) TP GIA REPORT (YES / NO)

Insured Liability: % Final? Yes / No

SLR 38815

INSRS:
WSP:
Tel:
Liability:
RMKS:Success
UnitedINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA & GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

5/4/2018

CPIK

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5 17,350.00

(12 days) Reduction:

54

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

4

Repair Cost:

\$5 19,564.50

(A/B instructions)

Loss of Rental (LOR):

\$5 1,400.00

(14 days) X \$100.00

Loss of Use (LOU):

\$5

-

(\$

x

days)

Loss of Income (LOI):

\$5

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GLA/TA Search

\$5

200

Medical:

\$5

-

Disbursement:

\$5

-

(e.g. Tow / Independent)

Legal Cost:

\$5

-

Total:

\$5 19,966.50

Global Sum \$5:

19,950.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

19,950.00

Name 1:

Success United M/Ltd

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

If NO or B 28, Ass. Lia:

OI (write out from Minor (stop line) Road

n/2/19

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4,500.00 + \$200

REF:

INS. REC BY Adrian King

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.: Yes or No

Lum Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLR3881S

Yr Regn:

2017, August

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle

c.c 1496

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading:

1894/

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GK81103309

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/45 R17

R: 205/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

06

mm

R/Bal:

06

mm

L/Bal:

06

mm

L/Bal:

06

mm

D.O.A.

D.O.I.

29/06/18

Survey held at

Success United

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP ALG.

MV: 80K
RV: A4K
Nett: 36K

L/S. \$ 17,600.00

(Red) + 21,044.02 / 54%

Date/Time, File Pass in?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return in?

2)

Report Format

Lump Sum / L.B.L. (3)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp. (\$)

☐

Interview (\$)

☐

Tech. Ins. (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

) \$ x R.S. 10

) Fides

) Other

TOTAL




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18011257/Afb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 21-06-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SCU 1801C	Veh. Inspected	SLR 3881S	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	21/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	16/06/2018	Inspection Date	20/06/2018	
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



聯成汽車維修

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921

Tel: 6746 1515 / 6747 1787 Fax: 6748 5015

www.successunited.com.sg Co. / GST Reg: 200402570G

Estimate : TP/18-076

M/s AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120

Date : 20th June 2018

Vehicle No : SLR 3881S
Make/ Model : Honda Shuttle
Chassis No : GK81103309
Acc. Date : 16.06.18
Policy No :

Attn : Motor Claim

Tel: 64191053
Fax: 68357416

Your Ref : SCU 1801C

S/n.	Qty	Particulars	Unit Price	Amount
<u>Materials</u>				
1	1 pc	Bonnet <i>Defted</i>	\$	988.20 ✓
2	1 pc	Bonnet Weatherstrip <i>Not New</i>	\$	45.20 x.
3	1 pc	Bonnet Mechanism Lock <i>Not New</i>	\$	79.70 x.
4	1 pc	Frt Bumper Assy <i>Distorted</i>	\$	1,050.50 ✓
5	10 pc	Frt Bumper Clips <i>New</i>	\$ 4.20	\$ 42.00 <i>30</i>
6	2 pc	Frt Bumper Side Holder L/R <i>New</i>	\$ 28.40	\$ 56.80 ✓
7	1 pc	Frt Bumper Under Shield <i>Deformed</i>	\$	87.60 ✓
8	1 pc	Frt Bumper Lower Air Grille <i>Deformed</i>	\$	160.00 ✓
9	1 pc	Frt Bumper Foglamp Cover LH <i>Deformed</i>	\$	65.30 ✓
10	1 pc	Frt Bumper Reinforcement <i>Best</i>	\$	462.90 ✓
11	1 pc	Frt Bumper Tow Hook Cover <i>Not New</i>	\$	25.70 x.
12	2 pc	Frt Bumper Bracket L/R <i>Not New</i>	\$ 37.80	\$ 75.60 x.
13	2 pc	Frt Fender Liner L/R <i>Deformed</i>	\$ 138.73	\$ 277.46 ✓
14	12 pc	Frt Fender Liner Clips <i>New</i>	\$ 4.20	\$ 50.40 ✓
15	2 pc	Headlamp Assy L/R <i>Distorted</i>	\$ 2,250.00	\$ 4,500.00 <i>2250</i>
16	1 pc	Frt Grille Assy <i>nt</i>	\$	435.10 ✓
17	1 pc	Frt Grille Honda Logo <i>New</i>	\$	32.50 ✓
18	1 pc	Frt Grille Chrome Moulding <i>Cracked</i>	\$	420.10 ✓
19	1 pc	Frt Bumper Lower Rubber Trim <i>nt</i>	\$	143.63 ✓
20	1 pc	Radiator Support Panel Assy <i>Distorted</i>	\$	874.50 ✓
21	1 pc	Radiator Assy <i>Best</i>	\$	1,350.60 ✓
22	1 pc	A/C Condenser <i>Best</i>	\$	1,050.00 ✓
23	1 pc	Engine Lower Cross Member <i>Not New</i>	\$	820.10 x.
24	1 pc	Frt Fender RH <i>Distorted</i>	\$	543.00 ✓
25	1 pc	Frt Fender Quarter Glass RH <i>Not New</i>	\$	290.70 x.
26	1 pc	Frt Fender Glass Moulding RH <i>New</i>	\$	58.40 ✓
27	1 pc	Frt Door Pillar RH <i>Repair</i>	\$	1,150.60 x.
28	1 pc	Frt Door RH <i>Distorted</i>	\$	978.21 ✓
29	1 pc	Frt Door Weatherstrip RH <i>Best</i>	\$	163.00 ✓
30	1 pc	Frt Door Channel Rubber RH	\$	66.50 ✓
31	2 pc	Frt Door Hinge (top/lower) RH <i>Best</i>	\$ 51.46	\$ 102.92 ✓
32	1 pc	Frt Door Center Checker RH	\$	53.80 ✓
33	1 pc	Frt Door Wing Mirror Assy RH <i>Distorted</i>	\$	575.20 ✓
34	1 pc	Frt Door Wing Mirror Cover RH <i>Missing</i>	\$	50.10 ✓



聯成汽車維修

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921

Tel: 6746 1515 / 6747 1787 Fax: 6748 5015

www.successunited.com.sg

Co. / GST Reg: 200402570G

35	1 pc	Frt Door Wing Mirror Glass RH <i>Not New</i>	\$	78.40	+
36	1 pc	Frt Door Black Matt Sticker <i>New</i>	\$	68.70	✓
37	1 pc	Frt Door Mechanism Lock RH <i>Joined</i>	\$	298.30	✓
38	1 pc	Frt Door Glass Outer Moulding RH <i>Deformed</i>	\$	89.70	✓
39	1 pc	Frt Door Glass <i>Shattered</i>	\$	498.40	✓
40	1 pc	Frt Door Glass Regulator Gear Assy RH <i>Not New</i>	\$	413.80	X
41	1 pc	Frt Door Outer Moulding RH <i>Not New</i>	\$	97.00	X
42	1 pc	Frt Door Inner Trim Board RH <i>Deformed</i>	\$	759.80	✓
43	1 pc	Frt Door Inner Handle RH <i>Joined</i>	\$	68.00	✓
44	1 pc	Frt Door Wire Harness Assy RH <i>Not New</i>	\$	1,180.30	X
45	1 pc	Frt Door Glass Control Switch RH	\$	321.90	X
46	1 pc	Frt Door Glass Channel Rubber RH <i>New</i>	\$	66.50	✓
47	1 pc	Rear Door Pillar RH <i>Deformed</i>	\$	1,150.60	✓
48	1 pc	Rear Door RH <i>Deformed</i>	\$	899.45	✓
49	1 pc	Rear Door Mechanism Lock RH <i>Not New</i>	\$	254.20	X
50	2 pc	Rear Door Hinge (top/lower) RH <i>Best</i>	\$ 49.10	\$ 98.20	✓
51	1 pc	Rear Door Center Check RH <i>Best</i>	\$	48.20	✓
52	1 pc	Rear Door Weatherstrip RH <i>Int</i>	\$	138.10	✓
53	1 pc	Rear Door Channel Rubber RH <i>New</i>	\$	75.10	✓
54	1 pc	Rear Door Glass Regulator Gear Motor Assy RH <i>Not New</i>	\$	428.90	X
55	1 pc	Rear Door Matt Sticker RH <i>New</i>	\$	50.40	✓
56	1 pc	Rear Door Glass Outer Moulding RH <i>Not New</i>	\$	64.70	X
57	1 pc	Rear Door Inner Trim Board RH <i>Not New</i>	\$	491.40	X
58	1 pc	Side Rocker Panel RH <i>Deformed</i>	\$	383.20	✓
59	1 pc	Side Rocker Skirt RH <i>Deformed</i>	\$	466.62	✓
60	1 pc	Frt Wheel House Panel RH <i>Repaired</i>	\$	395.00	X
61	1 pc	Frt Shock Absorber RH <i>Not New</i>	\$	450.80	X
62	1 pc	Frt Lower Arm RH <i>Best</i>	\$	280.92	✓
63	1 pc	Frt Knuckle Arm RH <i>Best</i>	\$	353.60	✓
64	1 pc	Frt Wheel Bearing RH <i>New</i>	\$	131.92	✓
65	1 pc	Frt Wheel Bearing Hub RH <i>Repaired</i>	\$	266.00	✓
66	1 pc	Anti-Roll Bar <i>Not New</i>	\$	292.00	X
67	1 pc	Anti-Roll Bar Linkage RH <i>Not New</i>	\$	59.80	X
68	1 pc	ABS Wire Sensor <i>Not New</i>	\$	239.80	X
69	1 pc	Frt Drive Shaft RH <i>Not New</i>	\$	927.50	X
70	1 pc	Steering Rack & Pinion <i>Not New</i>	\$	1,950.60	X
71	1 pc	Tie Rod <i>Not New</i>	\$	87.00	X
72	1 pc	Rack End	\$	88.70	X
73	1 pc	Engine Mounting <i>Not New</i>	\$	191.00	X
74	1 pc	Gearbox Mounting	\$	288.00	X
75	1 pc	Air Con Compressor <i>Not New</i>	\$	1,780.50	X
76	1 pc	Air Con Liquid Pipe <i>Not New</i>	\$	251.30	X
77	1 pc	Horn	\$	54.40	X
			\$	33,705.03	
Less 20%			\$	8,741.01	
Total			\$	26,964.02	



聯成汽車維修

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921

Tel: 6746 1515 / 6747 1787 Fax: 6748 5015

www.successunited.com.sg

Co. / GST Reg: 200402570G

<u>Special Nett</u>			
78	1 pc	Frt Door Speaker RH	\$ 420.00 +
79	1 pc	Rear Door Speaker RH	\$ 380.00 +
80	1 pc	Frt Sports Rim RH	\$ 1,180.00 -580
81	1 pc	Frt Tyre RH	\$ 350.00 -220
Special Nett :			\$ 2,330.00

<u>Labour</u>		Special Net	\$ 2,330.00
1	To remove, rearrange electrical wirings, check lightings	\$	300.00 30
2	To remove, replace & transfer door components.	\$	340.00 160
3	To remove, re instal inner trims, upholstery, dashboard to facilitate repair.	\$	450.00 80
4	To remove, replace air con parts, vacuum & refill gas.	\$	350.00 120
5	To mount car on to "O" linear.	\$	700.00 +
6	To remove, replace front suspension undercarriage parts	\$	580.00 220
7	To road test driving & reset wheel alignment.	\$	200.00 80
8	Reset SRS, ABS setting.	\$	180.00 +
9	Bleeding brake system, ABS pump etc.	\$	200.00 +
10	To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.	\$	2,400.00 2000
11	To putty and respray painting on affected area.	\$	2,800.00 1800
12	Respray tuff kote sealant.	\$	200.00 80
13	Apply ceramic coating.	\$	450.00 ✓
14	Towing Fees	\$	200.00 60
Total Labour		\$	9,350.00

Total Parts & Labour \$ 38,644.02



Success United Pte Ltd

No of Days _____

Re-Survey Before/After Paint

Part By Part/Lump Sum

LKK Auto Consultants hence notify
Surveyed By _____ of the following:
• To resurvey the damaged area painting
• To resurvey the damaged part(s) during resurvey
Date of Survey _____
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal items will be surveyed
NOTE: LUMP SUM WILL BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer _____

total 20734.74
L/S: 17.6K (15%)
17.6K
120up h/c P/P??
20/06/18
No of days: ??

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Thursday, 21 February 2019 4:41 PM
To: 'sirina@successunited.com.sg'
Subject: RE: RTA involving vehicle nos. SCU 1801C and SLR 3881S on 16/06/2018
Attachments: DV SLR 3881S.pdf
Importance: High

Dear Sirina,

Thank you for acceptance.

Please duly sign the DV attached and return to us for payment processing.

Your prompt action will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."


Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: sirina@successunited.com.sg [mailto:sirinassk@gmail.com]
Sent: Wednesday, 20 February 2019 4:48 PM
To: Poh Kin (LKKAUTO) <pohkin@lkkauto.com>
Subject: Fwd: RTA involving vehicle nos. SCU 1801C and SLR 3881S on 16/06/2018

Hi Poh Kin

Kindly ignore the claims for the spectacle.

Forward us the RV as agreed.

Thank You.

Poh Kin (LKKAUTO)

From: sirina@successunited.com.sg <sirinassk@gmail.com>
Sent: Wednesday, 20 February 2019 4:48 PM
To: Poh Kin (LKKAUTO)
Subject: Fwd: RTA involving vehicle nos. SCU 1801C and SLR 3881S on 16/06/2018
Attachments: Spectical Bill.jpg; Credit Note.pdf

Hi Poh Kin

Kindly ignore the claims for the spectacle.

Forward us the RV as agreed.

Thank You.

Best Regards,

Sirina Soon

Senior Claims Executive
Mobile: +65 9223 6288

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2
#01-33 / #02-29
Kaki Bukit AutoHub
Singapore 417921
Tel: 6746 1515 Fax: 6748 5015

----- Forwarded message -----

From: sirina@successunited.com.sg <sirinassk@gmail.com>
Date: Thu, Feb 14, 2019 at 5:25 PM
Subject: Fwd: RTA involving vehicle nos. SCU 1801C and SLR 3881S on 16/06/2018
To: Poh Kin (LKKAUTO) <pohkin@lkkauto.com>



SLR3881S-car cam.mp4

Thank You.

Best Regards,

Sirina Soon

Senior Claims Executive
Mobile: +65 9223 6288

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2
#01-33 / #02-29
Kaki Bukit AutoHub
Singapore 417921
Tel: 6746 1515 Fax: 6748 5015

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Thursday, 14 February 2019 2:17 PM
To: 'sirina@successunited.com.sg'
Cc: Admin A
Subject: RTA involving vehicle nos. SCU 1801C and SLR 3881S on 16/06/2018

Importance: High

Our Ref: CC6/AIG18011257/Afb3
Your Ref: SLR 3881S

Dear Sirina,

We refer to the above matter

As spoken, the COR readjusted to **L/S \$17,350.00** (before GST).

Purely towards an amicable settlement, we have instruction to offer settlement at global sum of **\$19,950.00(all in)** on this matter.

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Print Received Message

This mail is associated with :

***SLR3881S (6797642810SG)**
[SCU1801C]
TP
LOH YU IAN
Jun 16 2018 12:00PM
[TAN YAN LOO]
Success United Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 08/02/2019 09:53 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$19966.50) - SLR3881S - Claim Handler: MdNoor, Norsiah

Approved:19966.50.

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Friday, 28 September 2018 9:35 AM
To: 'Norsiah.MdNoor@aig.com'
Cc: Hsiao Tong (LKKAuto)
Subject: <seek mandate> ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SCU 1801C (OI) & SLR 3881S (TP) ON 16/06/2018

Importance: High

Your Ref: 6797642810SG
Our Ref: CC6/AIG18011257/Afb3

Dear Norsiah,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SCU 1801C (OI) & SLR 3881S (TP) ON 16/06/2018

We refer to the above matter.

The accident occurred when our insured collided into third party vehicle while moving straight along minor road(with stop line) and TP is moving straight along Main road. Liability is down against our insured as per BOLA 4(a). We did clarify with insured (Mdm Tan) the nature of the accident and she agreed to settle and aware NCD (if any) is affected.

We seek your approval to offer to Third Party repairer, "Success United Pte Ltd" is as follows: -

	<u>Amount Claimed</u>	<u>Amount Revised</u>
1. Cost of Repair (w/gst)	\$ 41,349.10(\$38,644.02 + 7%gst)	\$ 18,832.00 (\$17,600.00 + 7% GST)
2. Loss of Use	\$ 1,680.00 (14 days x \$ 120.00)	\$ 1,400.00 (\$14 days x \$100.00)
3. GIA search fee	\$ 2.00	\$ 2.00
Total	\$ 43,031.10	\$ 20,234.00

Total amount of claim (Liability 100%)

\$20,234.00

***Recommended 12 repair days

Market Value	\$80,000.00 (est)
Parf Rebate	\$44,000.00(est)
Nett Loss	\$36,000.00(est)

All the relevant documents had been uploaded in Merimen for your perusal.



聯成汽車維修

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921

Tel: 6746 1515 / 6747 1787 Fax: 6748 5015

www.successunited.com.sg

Co. / GST Reg. 200402570C

Your Ref: SCU 1801C

4th July 2018

M/s. AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120

Attn: Motor Claims

Dear Sir

Re: Acc Invlg SLR 3881S & SCU 1801C on 16.06.18

We refer to the above accident which was caused due to the negligence of your insured driver of Veh No. SCU 1801C

We are claiming for the following costs and losses incurred:

1)	Cost of Repairs (Inc. 7% GST)	\$ 18,832.00
2)	Car Rental (\$120 x 14 days)	\$ 1,680.00
3)	Search Fees	\$ 2.00
Total:		<u>\$ 20,514.00</u>

Enclosed herein the following documents for your perusal.

- 1) Tax Invoice No. SU1807-0004
- 2) Car Rental
- 3) GIA Search Fee
- 4) Letter of Authorisation

We appreciate your prompt attention and response.

Yours faithfully





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG18011257/Afa3

9th July 2018

TAN YAN LOO
42 Everton Road,
#18-01,
Singapore 089394.

Dear Sir/Madam,

**ROAD TRAFFIC ACCIDENT INVOLVING SCU 1801C AND SLR 3881S ALONG
JUNCTION OF SPOTTISWOODE PARK ROAD AND EVERTON ROAD ON
16.06.2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Poh Kin, Chong
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: pohkin@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

LETTER OF AUTHORISATION

To: Success United Pte Ltd
Singapore

RE: ACCIDENT INVOLVING VEHICLE NOS: SLR 3881S & SCU 1801C
ALONG Junc Of Spottiswoode Park Rd And Everton Rd ON 16.06.18

I/We, Loh Yu lan Co's Rgn/NRIC No. S7925927F
of BLK 110 Spottiswoode Park Rd 89 S081110
the owner of vehicle no. SLR 3881S hereby authorise you to commence repair to the said
vehicle forthwith. In consideration of you repairing my/our vehicle at my/our request:

- a) I/We hereby irrevocably authorise you to demand claim settle receive whatever amount settled/payable by the insurance and/or third party or to commence legal proceeding, if necessary, in my name, for the costs of repair and loss of use, etc and to you appointing any Solicitor to act for me in respect of the accident claim and all and any amount claimed, received and/or settled shall belong absolutely to you. I/We agree to assign the whole proceeds of my/our third party claim to you and my/our Solicitors (to be appointed by you on my/our behalf) shall accept this as my/our irrevocable authorisation to pay the amount compensated direct to you after deduction of their costs on a Solicitor & Client basis. I/We undertake to co-operate fully with you and my/our Solicitors to see the claim to a successful conclusion.
- b) If the third party claim is unsuccessful or in your discretion inappropriate for any reason, I/we hereby instruct and authorise you to claim direct from my/our insurance company on my/our behalf for all monies due to you. I undertake to pay you for the Excess applicable under my policy and to reimburse you all costs, fees and expenses incurred by you in pursuing the claim on my behalf.
- c) If the own insurers' claim is not applicable and/or the third party claim fails and/or either of the aforesaid is inadequate, I/we undertake to pay you for your expenses, costs and fees immediately.

I/We also irrevocably authorise you to sign all discharge vouchers/indemnity forms and all necessary papers in connection with the above claim in my/our absence. I/We irrevocable authorise you to appoint such a firm of Solicitors on my/our behalf as you shall deem fit for the purpose of the third party/own insurer's claim.

I/We undertake to inform you and/or the Solicitors appointed by you on my behalf in the event the third party's insurance company communicate with me/us directly, orally or in writing and I/we further undertake not to accept any monies or offer of settlement from the third party's insurers without first communicating with you and obtaining your consent.

Upon settlement of the third party claim and in case the settlement monies was sent to me/us by the third party's insurers, I/we undertake to pay you and my/our solicitor the cost of repairs settled and related expenses and disbursement incurred.

My/Our insurer is/are Direct Asia Insurance Ptd Ltd
Policy No. MT/00406291

Expiry Date: 0/1/1900

Date: 18.06.18

Excess: 0

Owner's Signature/Co's stamp

Loh Yu lan

NRIC No: S7925927F

Witness Signature/Name

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, Success United Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$19,950.00 (Global Sum) for vehicle no. SLR 3881S that was damaged pursuant to the accident which occurred on 16/06/2018 (date) along Spottiswoods Park Road (location) involving vehicle no/s SCU 1801C. This is pursuant to the inspection conducted on 20/06/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LOH YU IAN ("the third party claimant") of vehicle no. SLR 3881S make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLR 3881S (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 21st (day) of February (month) 2019 (year)

LWP (LKK)

Signed by appointed surveyor

Success United Pte Ltd

Signed by "the workshop" (with chop)



聯成汽車維修

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921

Tel: 6746 1515 / 6747 1787 Fax: 6748 5015

www.successunited.com.sg Cc: GST Reg: 200402370C

Tax Invoice : SU1807-0004

M/s. AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120
Attn: Motor Claims

Date : 11th July 2018

Vehicle No : **SLR 3881S**
Make/ Model : Honda Shuttle
Chassis No : GK81103309
Date of Acc. : 16.06.18

Tel : 64191053
Fax : 68357416

Your Ref. : SCU 1801C

S/n.	Qty	Particulars	Unit Price	Amount
		To provide material, labour and respray painting.		
		LUMP SUM REPAIRS		\$ 17,600.00



for Success United Pte Ltd

Sub Total :	\$	17,600.00
Add GST 7% :	\$	1,232.00
TOTAL DUE :	\$	18,832.00



WIN WIN RENT-A-CAR PTE LTD

Invoice

SLR3881S
LUO YU LAN
BLK 110 SPOTTISWOODE PARK ROAD
#02-89
S(081110)

Invoice No : WPLIN0002099
Invoice Date : 3/7/2018
Due Date : 3/7/2018
VHA No : 2532
Referral ID : S014

Description :	Amount
Rental for 14 Day/s @ \$120 per Day	\$1,680

Vehicle No : SJY8510S

Vehicle Description : Toyota Altis 1.6A

Rental Period : 18/06/2018 to 02/07/2018

Total Amount Payable : \$1,680

WIN WIN RENT-A-CAR PTE LTD8 Kaki Bukit Ave 4 #06-04 Premier@Kaki Bukit Singapore 415875
Tel: 6315 8479 H/P: 9833 0807

VHA No: 2532

Invoice No: INPLIN 2099

Hirer's Vehicle No:

UEN: 201505115E

VEHICLE RENTAL AGREEMENT**HIRER'S PARTICULARS**Name: (as in I/C) Mr. H. L. TanNRIC / FIN No: 757925927FAddress (Res): Blk 110 Spottwood ParkEA 402-87 (081110)

Name & Address of Employer:

Occupation: Driving Exp:

Singapore Driving Licence No:

Issue Date: Date of Birth:

Tel: (O) (R) HP: 97547571**ADDITIONAL DRIVER'S PARTICULARS**

Name: (as in I/C)

NRIC / FIN No:


Address (Res):

Occupation: Driving Exp:

Singapore Driving Licence No:

Issue Date: Date of Birth:

Tel: (O) (R) H/P:

VEHICLE CHECK LISTINDICATE:
D - DENTS
S - SCRATCHES
A - ACCIDENTS**MISSING / FAULTY ACCESSORIES / PARTS**

REMARKS:

Vehicle No: TY85105 Replace Veh No:Mileage Out: 75004 Mileage In:Make & Model: TOYOTA ALTIS Auto / ManualOut : Date 18/06/2018 Time: 16.42

HIRE / PERIOD EXPIRY Time:

NON-WAIVER EXCESS=\$ 2000**CHARGES**Daily 14 @ \$ 170 per day 71650

Weekly @ \$ per week

Monthly @ \$ per month

Hours @ \$ per hour

Extension @ \$

Delivery/Collection Service

SUB-TOTAL \$**PETROL LEVEL**

Out E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F

In E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F

Fuel

Traffic / Parking Fines

TOTAL CHARGES \$

Hirer's Signature

Additional Driver's Signature

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given WIN WIN RENT-A-CAR PTE LTD in connection with this agreement is true.

***IMPORTANT**

1. VEHICLE IS STRICTLY PROHIBITED FOR "HIRE FOR REWARDS" USAGE SUCH AS USER / GRABCAR / GRABSHARE ETC.
2. ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORIZED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
3. ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
4. THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF COW AND/OR PAI WHERE APPLICABLE.
5. IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
6. VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY WIN WIN RENT-A-CAR PTE LTD.

RETURN OF VEHICLE: THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO WIN WIN RENT-A-CAR PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
<u>2018</u>	<u>18/06</u>	<u>75004</u>	<u>PM</u>	<u>75004</u>	



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-093472
Date of Request: 19/06/2018

Your Ref No: Online Purchase

Success United Pte Ltd
2 Kaki Bukit Ave 2 #01-33
Kaki Bukit AutoHub
Singapore 417921

Dear Sir/Madam,

Enquiry Date: 19/06/2018
Enquiry By: Sirina Soon
TP Vehicle No: SCU1801C
Accident Date: 16/06/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SCU1801C	AIG Asia Pacific Insurance Pte. Ltd.	09/07/2017-08/07/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-093472

Date of Request: 19/06/2018

Your Ref No:

Online Purchase

Success United Pte Ltd
2 Kaki Bukit Ave 2 #01-33
Kaki Bukit AutoHub
Singapore 417921

Dear Sir/Madam,

Enquiry Date 19/06/2018
Enquiry By Sirina Soon
TP Vehicle No. SCU1801C
Accident Date 16/06/2018

DESCRIPTION	AMOUNT (\$S)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jun 2018 Edit Reg		20 Jun 2018 00:00 Edit Adj Rpt	S\$17,350.00 Edit Estimates	S\$17,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	TAN YAN LOO, ID: S1181451D		
Main Claimant:	LOH YU IAN, ID: S7925927F		
Vehicle Reg. No.:	SLR3881S	Date of Loss:	16/06/2018 12:00 - :59 [10 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 6797642810SG	Policy/Cover Note No.:	2100378776 (Comprehensive) Coverage: 09/07/2017 - 08/07/2018
Vehicle Reg. No. (Insured):	SCU1801C	Policy No. (Claimant):	MT/00406291
	Excess:		
Repairer:	Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub, 417921 Kaki Bukit - Tel: 6746 1515		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 02/07/2018]		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

- AIG_SG_EXPRESS (08/02/2019): Alert - Adj Mandate Approved (S\$19966.50) - SLR3881S - Claim Handler: MdNoor, No...
- AIG_SG_EXPRESS (03/01/2019): Alert - Adj Mandate Maintained - SLR3881S - Claim Handler: MdNoor, Norsiah
- AIG_SG_EXPRESS (20/11/2018): Alert - Adj Mandate Maintained - SLR3881S - Claim Handler: MdNoor, Norsiah
- AIG_SG_EXPRESS (26/10/2018): Alert - Adj Mandate Approved (S\$20234.00) - SLR3881S - Claim Handler: MdNoor, No...
- AIG_SG_EXPRESS (26/10/2018): Alert - Adj Mandate Approved (S\$20234.00) - SLR3881S - Claim Handler: MdNoor, No...


















































ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

















































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR3881S (6797642810SG)
[SCU1801C]
TP
LOH YU IAN
Jun 16 2018 12:00PM
[TAN YAN LOO]
Success United Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1		Edit			
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	11/07/18 13:42		General View												1		Load JPG			
2	11/07/18 13:42		General View												1		Load JPG			
3	11/07/18 13:42		General View												1		Load JPG			
4	11/07/18 13:42		General View												1		Load JPG			
5	11/07/18 13:42		General View												1		Load JPG			
6	11/07/18 13:42		General View												1		Load JPG			
7	11/07/18 13:42		General View												1		Load JPG			
8	11/07/18 13:42		General View												1		Load JPG			
9	11/07/18 13:42		General View												1		Load JPG			
10	11/07/18 13:42		General View												1		Load JPG			
11	11/07/18 13:42		General View												1		Load JPG			
12	11/07/18 13:42		General View												1		Load JPG			
13	11/07/18 13:42		General View												1		Load JPG			
14	11/07/18 13:42		General View												1		Load JPG			
15	11/07/18 13:42		General View												1		Load JPG			
16	11/07/18 13:42		General View												1		Load JPG			
17	11/07/18 13:42		General View												1		Load JPG			
18	11/07/18 13:42		General View												1		Load JPG			
19	11/07/18 13:42		General View												1		Load JPG			
20	11/07/18 13:42		General View												1		Load JPG			
21	11/07/18 13:42		General View												1		Load JPG			
22	11/07/18 13:42		General View												1		Load JPG			
23	11/07/18 13:42		General View												1		Load JPG			
24	11/07/18 13:42		General View												1		Load JPG			
25	11/07/18 13:42		General View												1		Load JPG			
26	11/07/18 13:42		General View												1		Load JPG			
27	11/07/18 13:42		General View												1		Load JPG			
28	11/07/18 13:42		General View												1		Load JPG			
29	11/07/18 13:42		General View												1		Load JPG			
30	11/07/18 13:42		General View												1		Load JPG			
31	11/07/18 13:42		General View												1		Load JPG			
32	11/07/18 13:42		General View												1		Load JPG			
33	11/07/18 13:42		General View												1		Load JPG			
34	11/07/18 13:42		General View												1		Load JPG			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
36	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
37	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
38	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
39	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
40	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
41	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
42	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
43	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
44	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
45	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
46	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
47	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
48	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
49	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
50	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
51	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
52	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
53	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
54	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
55	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
56	11/07/18 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
57	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	11/07/18 13:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/06/18 18:35	TP GIA REPORT	 Load PDF	

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
		LKK Auto Consultants Pte Ltd (HQ)			
2	30/07/18 18:02	OI Traffic police report		Load PDF	
3	31/07/18 08:32	TP Estimate-Marked		Load PDF	
4	27/09/18 08:27	GIA SEARCH		Load PDF	
5	27/09/18 08:27	RENTAL RECEIPT		Load PDF	
6	27/09/18 08:27	LETTER TO OI		Load PDF	
7	28/09/18 09:25	PRAF and COE rebate form		Load PDF	
8	25/02/19 12:25	WORKSHOP INVOICE		Load PDF	
9	25/02/19 12:25	AUTHORISATION TO ACT FORM		Load PDF	
10	25/02/19 12:25	Release Voucher		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	22/06/18 12:17	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SCU1801C (Insd veh)	Model:	HONDA SHUTTLE 1.5 G CVT
	SLR3881S (TP veh)		(A)
Date of Accident:	16/06/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	41,349.10
Final Repair Cost	:	\$	19,950.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	14 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	19,950.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____ 100 _____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Success United Pte Ltd	:	\$ 19,950.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

25 Feb
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18011257/AFB3Q2

Date: 25/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100378776
Claimant Vehicle No : SLR3881S **Insured Vehicle No :** SCU1801C
 Date of Loss: 16/06/2018 Nature of Claim: TP Claim No: 6797642810SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR3881S**
 Make & Model: HONDA SHUTTLE, 1.5 G CVT (A) Engine No: L15B5003892
 Reg. Date: 14/08/2017 (Man. Year: 2017) Chassis No: GK81103309
 Colour: Silver Odometer: 18941 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R17 Rear Tyre Size: 205/45 R17
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,294.02	15,654.74	13,639.28	46.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,350.00	5,080.00	4,270.00	45.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,644.02	20,734.74	17,909.28	46.34
Approved Total (Overridden) (S\$)		17,350.00		
(S\$)	38,644.02	17,350.00	21,294.02	55.10
+ GST 7.00/7.00% (S\$)	2,705.08	1,214.50	1,490.58	55.10
Nett Amount (S\$)	41,349.10	18,564.50	22,784.60	55.10
+ Car Rental (14.0 x S\$100.00/day) (S\$)		1,400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		19,966.50		
Global Sum Settlement (S\$)		19,950.00		

INSPECTION

Date of Assignment: 20/06/2018
 Date Inspected: 20/06/2018 Inspected At:

Success United Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit
AutoHub
Singapore 417921

Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING

Manager: Chong Poh Kin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	988.20 FL	*988.20 FL
2	1		*BONNET WEATHERSTRIP	Not Necessary	45.20 FL	*- FL
3	1		*BONNET MECHANISM LOCK	Not Necessary	79.70 FL	*- FL
4	1		*FRT BUMPER ASSY	Distorted	1,050.50 FL	*1,050.50 FL
5	10		*FRT BUMPER CLIPS	Necessary	42.00 FL	*30.00 FL
6	2		*FRT BUMPER SIDE HOLDER L/R	Necessary	56.80 FL	*56.80 FL
7	1		*FRT BUMPER UNDER SHIELD	Deformed	87.60 FL	*87.60 FL
8	1		*FRT BUMPER LOWER AIR GRILLE	Deformed	160.00 FL	*160.00 FL
9	1		*FRT BUMPER FOGLAMP COVER LH	Deformed	65.30 FL	*65.30 FL
10	1		*FRT BUMPER REINFORCEMENT	Bent	462.90 FL	*462.90 FL
11	1		*FRT BUMPER TOW HOOK COVER	Not Necessary	25.70 FL	*- FL
12	2		*FRT BUMPER BRACKET L/R	Not Necessary	75.60 FL	*- FL
13	2		*FRT FENDER LINER L/R	Deformed	277.46 FL	*277.46 FL
14	12		*FRT FENDER LINER CLIPS	Necessary	50.40 FL	*50.40 FL
15	1		*HEADLAMP ASSY L/R	N/S Cracked	4,500.00 FL	*2,250.00 FL
16	1		*FRT GRILLE ASSY	Cut	435.10 FL	*435.10 FL
17	1		*FRT GRILLE HONDA LOGO	Necessary	32.50 FL	*32.50 FL
18	1		*FRT GRILLE CHROME MOULDING	Cracked	420.10 FL	*420.10 FL
19	1		*FRT BUMPER LOWER RUBBER TRIM	Cut	143.63 FL	*143.63 FL
20	1		*RADIATOR SUPPORT PANEL ASSY	Distorted	874.50 FL	*874.50 FL
21	1		*RADIATOR ASSY	Bent	1,350.60 FL	*1,350.60 FL
22	1		*A/C CONDENSER	Bent	1,050.00 FL	*1,050.00 FL
23	1		*ENGINE LOWER CROSS MEMBER	Not Necessary	820.10 FL	*- FL
24	1		*FRT FENDER RH	Distorted	543.00 FL	*543.00 FL
25	1		*FRT FENDER QUARTER GLASS RH	Not Necessary	290.70 FL	*- FL
26	1		*FRT FENDER GLASS MOULDING RH	Necessary	58.40 FL	*58.40 FL
27	1		*FRT DOOR PILLAR RH	Repair	1,150.60 FL	*- FL
28	1		*FRT DOOR RH	Distorted	978.21 FL	*978.21 FL
29	1		*FRT DOOR WEATHERSTRIP RH	Cut	163.00 FL	*163.00 FL
30	1		*FRT DOOR CORNER RUBBER RH	Cut	66.50 FL	*66.50 FL
31	2		*FRT DOOR HINGE (TOP /LOWER) RH	Bent	102.92 FL	*102.92 FL
32	1		*FRT DOOR CENTER CHECKER RH	Bent	53.80 FL	*53.80 FL
33	1		*FRT DOOR WING MIRROR ASSY RH	Distorted	575.20 FL	*575.20 FL
34	1		*FRT DOOR WING MIRROR COVER RH	Missing	50.10 FL	*50.10 FL
35	1		*FRT DOOR WING MIRROR GLASS RH	Not Necessary	78.40 FL	*- FL
36	1		*FRT DOOR BLACK MATT STICKER	Necessary	68.70 FL	*68.70 FL
37	1		*FRT DOOR MECHANISM LOCK RH	Jammed	298.30 FL	*298.30 FL
38	1		*FRT DOOR GLASS OUTER MOULDING RH	Deformed	89.70 FL	*89.70 FL
39	1		*FRT DOOR GLASS	Shattered	498.40 FL	*498.40 FL
40	1		*FRT DOOR GLASS REGULATOR GEAR ASSY RH	Not Necessary	413.80 FL	*- FL
41	1		*FRT DOOR OUTER MOULDING RH		97.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*FRT DOOR INNER TRIM BOARD RH	Not Necessary Deformed	759.80 FL	*759.80 FL
43	1		*FRT DOOR INNER HANLE RH	Damaged	68.00 FL	*68.00 FL
44	1		*FRT DOOR WIRE HARNESS ASSY RH	Not Necessary	1,180.30 FL	*- FL
45	1		*FRT DOOR GLASS CONTROL SWITCH RH	Not Necessary	321.90 FL	*- FL
46	1		*FRT DOOR GLASS CHANNEL RUBBER RH	Necessary	66.50 FL	*66.50 FL
47	1		*REAR DOOR PILLAR RH	Dented	1,150.60 FL	*1,150.60 FL
48	1		*REAR DOOR RH	Distorted	899.45 FL	*899.45 FL
49	1		*REAR DOOR MOULDING LOCK RH	Not Necessary	254.20 FL	*- FL
50	2		*REAR DOOR HINGE (TOP/LOWER) RH	Bent	98.20 FL	*98.20 FL
51	1		*REAR DOOR CENTER CHECK RH	Bent	48.20 FL	*48.20 FL
52	1		*REAR DOOR WEATHERSTRIP RH	Cut	138.10 FL	*138.10 FL
53	1		*REAR DOOR CHANNEL RUBBER RH	Necessary	75.10 FL	*75.10 FL
54	1		*REAR DOOR GLASS REGULATOR GEAR MOTOR ASSY RH	Not Necessary	428.90 FL	*- FL
55	1		*REAR DOOR MATT STICKER RH	Necessary	50.40 FL	*50.40 FL
56	1		*REAR DOOR GLASS OUTER MOULDING RH	Not Necessary	64.70 FL	*- FL
57	1		*REAR DOOR INNER TRIM BOARD RH	Not Necessary	491.40 FL	*- FL
58	1		*SIDE ROCKER PANEL RH	Dented	383.20 FL	*383.20 FL
59	1		*SIDE ROCKER SKIRT RH	Deformed	466.62 FL	*466.62 FL
60	1		*FRT WHEEL HOUSE PANEL RH	Repair	395.00 FL	*- FL
61	1		*FRT SHOCK ABSORBER RH	Not Necessary	450.80 FL	*- FL
62	1		*FRT LOWER ARM RH	Bent	280.92 FL	*280.92 FL
63	1		*FRT KNUCKLE ARM RH	Bent	353.60 FL	*353.60 FL
64	1		*FRT WHEEL BEARING RH	Necessary	131.92 FL	*131.92 FL
65	1		*FRT WHEEL BEARING HUB RH	Damaged	266.00 FL	*266.00 FL
66	1		*ANTI-ROLL BAR	Not Necessary	292.00 FL	*- FL
67	1		*ANTI-ROLL BAR LINKAGE RH	Not Necessary	59.80 FL	*- FL
68	1		*ABS WIRE SENSOR	Not Necessary	239.80 FL	*- FL
69	1		*FRT DRIVE SHAFT RH	Not Necessary	927.50 FL	*- FL
70	1		*STEERING RACK & PINION	Not Necessary	1,950.60 FL	*- FL
71	1		*TIE ROD	Not Necessary	87.00 FL	*- FL
72	1		*RACK END	Not Necessary	88.70 FL	*- FL
73	1		*ENGINE MOUNTING	Not Necessary	191.00 FL	*- FL
74	1		*GEARBOX MOUNTING	Not Necessary	288.00 FL	*- FL
75	1		*AIR CON COMPRESSOR	Not Necessary	1,780.50 FL	*- FL
76	1		*AIR CON LIQUID PIPE	Not Necessary	251.30 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
77	1		*HORN	Not Necessary	54.40 FL	*- FL
78	1		*FRT DOOR SPEAKER RH	Not Necessary	420.00 FS	*- FS
79	1		*REAR DOOR SPEAKER RH	Not Necessary	380.00 FS	*- FS
80	1		*FRT SPORTS RIM RH	Cut	1,180.00 FS	*580.00 FS
81	1		*FRT TYRE RH	Punctured	350.00 FS	*220.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	36,035.03	19,368.43
				- List Item Discount on L Items 20.00/20.00% (S\$)	6,741.01	3,713.69
				Total Parts (S\$)	29,294.02	15,654.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTINGS	New	300.00	30.00
2	TO RMEOVE,REPLACE & TRANSFER DOOR COMPONENTS	New	340.00	160.00
3	TO REMOVE,REINSTALL INNER TRIMS ,UPHOLSTERY ,DASHBOARD TO FACILITATE REPAIR	New	450.00	80.00
4	TO REMOVE,REPLACE AIR CON PARTS ,VACUUM & REFILL GAS	New	350.00	120.00
5	TO MOUNT CAR ON TO O LINER	New	700.00	0.00
6	TO REMOVE,REPLACE FRONT SUSPENSION UNDERCARRIAGE PARTS	New	580.00	220.00
7	TO ROAD TEST DRIVING & RESET WHEEL ALIGNMENT	New	200.00	80.00
8	RESET SRS ,ABS SETTING	New	180.00	0.00
9	BLEEDING BRAKE SYSTEM ,ABS PUMP ETC	New	200.00	0.00
10	TO REMOVE,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	2,400.00	2,000.00
11	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	2,800.00	1,800.00
12	RESPRAY TUFF KOTE SEALANT	New	200.00	80.00
13	APPLY CERAMIC COATING	New	450.00	450.00
14	TOWING FEES	New	200.00	60.00
Gross Labour Cost (S\$)			9,350.00	5,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >