

2/03/2007

ASS. REC. BY:

REF: es/FCI18011264/Ksd3n2 Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

of

FCI

Date/Time: 20/6/18 @ 5:48 pm

Estimated Cost:

Bill to:

OD ☒ TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SJQ 9785B

Insured:

SHA 4647H

at Workshop m/s

Ah Lim Motor

Tel:

6483 1244

of

No. 10 AMK Ind. Park 2A #01-09

Policy No:

Claim No:

D18004806MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/06/2018

CA / REV / REP. / REV 24 HRS DS

21/06/18 @ 1:30 pm.

H.O.D. Endorsement:

Date/Time:

21/06/18 @ 9:20 am

Person Contacted:

Zila

Vehicle:

☒ IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJQ 9785B - x

SHA 4647H - CC3/AIG10002776/Cwg/n

DOA: 08/02/2010

22/06/18 @ 16:38 p.m. received PA to Joanne via email.

2018 81061-60 Cabana

REF: FCL

ASSIGNMENT

From:

Date: 21-06-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJQ 9785B

at Workshop m/s

Ah Lim Motor

of

Blk 10 AMK Ind Park 2A

Insured:

#01-09

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

1:30pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

872k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lump Sum:

1-B.1 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJQ 9785B

Yr Regn:

05 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra

1591

Colour:

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

27139

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KM140841CMTJ 464358

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

8 mm

R/Bal.

8 mm

L/Bal.

8 mm

L/Bal.

8 mm

D.O.A.

15/6/18

D.O.I.

21/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/6 File per 1/2 Catherin

(\$363.55 Red - 45%)

RECEIVED 20 AUG 2018

Date/Time, File Pass In?

20/08/18

1)

Typist

Date/Time, File Return to?

2)



Prel. Report



Final Report

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

1) S-RS: 9

2) Photos:

3) Other:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech Invs (\$)



Weekend (\$)

Report Format:

Lump Sum / L.B.I: (\$ 1,061.60 P/P)

TOTAL

100
50
50
13

213



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18011264/Ksd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 21-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4647H	Veh. Inspected	SJQ 9785B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004806MFSH	Excess (\$)	0.00	
Assign From	CWS (JOANNE YONG)	Assign Date	21/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/06/2018	Inspection Date	21/06/2018	
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004806MFSH

Date: 22 June 2018

Our Ref: CS/FCI18011264/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJO 9785B

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/06/2018 at the premises of M/s Ah Lim Motor Company and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,925.15</u>
Revised Estimate Amount	: S\$ <u>1,047.60</u>
"Check" Items Amount	: S\$ <u>221.10</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 2 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 22 June 2018 4:38 PM
To: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: "SUR"; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18004806MFSH/1
Attachments: SJQ 9785B - Preli Advise.pdf

Dear Joanne,

Enclosed preliminary revised for SJQ 9785B.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 21 June 2018 8:42 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; "SUR" <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004806MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 20 June 2018 5:46 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004806MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

MOTOR SURVEY ASSIGNMENT

Date	18-06-2018	Our Ref No. D18004806MFSH
Accident Date	15-06-2018	Claim Type. Third Party
Insured Vehicle	SHA4647H	Third Party Vehicle. SJQ9785B
Survey Location	NO. 10 ANG MO KIO IND PARK 2A #01-09 AMK AUTOPOINT	
Contact Person.	EILEEN CHUA	
Contact No.	64831244/ 0	Fax No. 64836170
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AH LIM MOTOR COMPANY	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241538)



PRI Documents



Close



PRI Header Details

Claim No	D18004806MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & AH LIM M
Workshop Name	AH LIM MOTOR COMPANY (Contact Person : EILEEN CHUA)	Survey Location & Contact Details	NO. 10 ANG MO KIO IND PARK 2A #01-09 AMK AUTO PC Mobile: 0 , Phone: 64831244 , Fax: 64836170 EmailId: AHLIMMC@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA4647H	TP Vehicle No	SJQ9785B
PRI Recieved Date	19-06-2018 10:02:07 PM	Surveyor Appointed Date	20-06-2018 05:46:57 PM	Surveyor Accept Date	20-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	20-06-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4816E

Vehicle Details

Vehicle No.: SJQ9785B
Vehicle to be Exported: Yes
Intended De-registration Date: 16 Jun 2018
Vehicle Make: HYUNDAI
Vehicle Model: ELANTRA AD 1.6 GLS AT
Primary Colour: Silver
Manufacturing Year: 2017
Engine No.: G4FGHU120796
Chassis No.: KMHD841CMJU464358
Maximum Power Output: 93.8 kW (125 bhp)
Open Market Value: \$13,099.00
Original Registration Date: 31 May 2017
First Registration Date: 31 May 2017
Transfer Count: 0
Actual ARF Paid: \$13,099.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 30 May 2027
PARF Rebate Amount: \$9,824.00

Intended COE Rebate Details

COE Expiry Date: 30 May 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$46,489.00
COE Rebate Amount: \$37,191.00
Total Rebate Amount: \$47,015.00

The information contained herein is correct as at 16 Jun 2018

OK

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S7504816E**

Name: **TAN CHER ANN (CHEN ZI'AN)**

Birth Date: **10 Feb 1975**

Issue Date: **06 Nov 2003**

1000987591H




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7504816E**



Name: **TAN CHER ANN (CHEN ZI'AN)**

陈子安

Race: **CHINESE**

Date of Birth: **10-02-1975**

Country of Birth: **SINGAPORE**

Sex: **M**

S7504816E



Hp: 9797 6277

Email: cherannff@yahoo.com

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE
27 Nov 1998

NP 428A



A0054977

NRIC No: **S7504816E**



Blood Group: **O+** Date of Issue: **20-08-2001**

**3 SENGKANG EAST AVENUE #10-07
RIVERSOUND RESIDENCE SINGAPORE 544813**

NRIC No: **S7504816E** Date: **25/06/2016**

Tan Li See (F)

~~Chia Puay Sang~~

Chia Puay Sang (F)

Rain
wef

hp: 9797

Car: Yes

Total: 3



CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2018-00006370 (Comprehensive - Classic Plan)

Car plate number: SJQ9785B

Your name (As the policyholder): Tan Cher Ann

Coverage start date: 31/05/2018

Coverage end date: 30/05/2019

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

- (a) You; and
- (b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: Maybank Singapore

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 10/05/2018

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN CHER ANN
3 SENGKANG EAST AVENUE
#10-07
SINGAPORE 544813

Estimate No: MC0913185
Date: 16 Jun 2018
Policy No: PNPV2018-00006370
Veh Reg No: SJQ9785B
Make/Model: HYUNDAI ELANTRA
AD 1.6 GLS AT

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 15/06/2018
TP Veh Reg No: SHA4647H

Not Authorized
Per survey B4 party
2 days

Estimate Repair Cost to Vehicle No :SJQ9785B

Description	Quantity	List Price SS	Amount SS
SPARE PARTS			
1 REAR BUMPER LOWER	1 PC	250.10	✓
2 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	88.60	x
3 REAR BUMPER CLIPS X 15	15 PC	30.00	✓
4 REAR BUMPER REINFORCEMENT	1 PC	294.80	x
	20%	663.50	
	Less 25%	165.88	497.63
5 REAR BUMPER TOP	1 PC	459.40	✓
		459.40	
	Less 20%	91.88	367.52
Special Nett			
6 REVERSE SENSOR X 2	2 PC	200.00	x
		200.00	200.00
LABOUR			
7 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	50
8 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR END PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00	200
9 TO SPRAY REAR BUMPER TOP, END PANEL	1 PC	400.00	220
		860.00	860.00
Total			SS 1,925.15
Add GST @ 7%			134.76
Total Amount Payable			SS 2,059.91

TOTAL: SINGAPORE DOLLAR TWO THOUSAND FIFTY NINE AND CENTS NINETY ONE ONLY

Please arrange this vehicle to be surveyed soonest possible
Thank You

LKK Auto Consultants hence notify
the Repairer of the following:

- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

1958.32



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18011264/Ksd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 21-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4647H	Veh. Inspected	SJQ 9785B	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18004806MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	20/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHD841CMJU464358	Colour	METALLIC GREY	
Odometer	27139	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	NEXEN	8 mm	
L/H Front Tyre	195/65 R15	NEXEN	8 mm	
R/H Rear Tyre	195/65 R15	NEXEN	8 mm	
L/H Rear Tyre	195/65 R15	NEXEN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/06/2018	Inspection Date	21/06/2018	
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJQ 9785B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER LOWER	DENTED / CUT	250.10	250.10
2	REAR BUMPER SIDE RETAINERS LH & RH	SERVICEABLE	88.60	-
15	REAR BUMPER CLIPS	NECESSARY	30.00	30.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	294.80	-
1	REAR BUMPER TOP	DENTED	459.40	459.40
	LESS 20% DISCOUNT		-224.58	-147.90
			898.32	591.60
	SPECIAL NETT ITEMS			
2	REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
			200.00	-
	LABOUR			
	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.		60.00	50.00
	TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR END PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		400.00	200.00
	TO SPRAY REAR BUMPER TOP, END PANEL.		400.00	220.00
			860.00	470.00
	GRAND TOTAL		1,958.32	1,061.60
	RECOMMENDED COST OF REPAIRS			1,061.60

Report Ref No. CS/FCI18011264/Ksd3n2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.