

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST #04-05 IOB BUILDING

049711

Attention : Motor Claim Department

Contact : 6223 8122

Estimate : ES000185

Date : 21/06/2018

Vehicle Num. : SLJ 6325D (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 20/06/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR DOOR - LH ✓ <i>DMG</i>		1,200.00
2.	1	REAR DOOR HINGE LH UPPER ✕		120.00
3.	1	REAR DOOR HINGE LH LOWER ✕		120.00
4.	1	REAR DOOR CHECKER LH ✕		180.00
5.	1	REAR DOOR GLASS REGULATOR MOTOR LH ✕		430.00
6.	1	REAR DOOR INNER LOCK LH ?		300.00
7.	1	REAR FENDER LH ✓ <i>Deform</i>		1,100.00
8.	1	REAR FENDER UNDERDUST COVER LH ✓ <i>Deform</i>		110.00
9.	1	SIDE SKIRT LH ✓ <i>CUT</i>		430.00
10.	1	REAR TYRE LH ?		230.00
11.	1	REAR STEEL RIM LH R		280.00
List Total S\$:				4,500.00
20.00% Discount S\$:				900.00
				3,600.00

SPECIAL NETT ITEMS :				
1.	1	REAR WHEEL CAP LH ✓ <i>SCR</i>		190.00 100
Special Nett Total S\$:				190.00
LABOUR :				
TRANSFER DOOR MECHANISM				180.00 100
REMOVE & REPLACE FENDER 1/4 GLASS				180.00 100
WIRINGS CHECK AND RECTIFY WHERE NECESSARY				180.00 ✕

Sathya Sai

21/6/2018

Sathya Sai @ lkkauto.com

98072012

- Part by Part Repair
- Question mark item photo
- Photo before paint

5 days

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST #04-05 IOB BUILDING

049711

Attention : Motor Claim Department

Contact : 6223 8122

Estimate : ES000185

Date : 21/06/2018

Vehicle Num. : SLJ 6325D (LCR

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 20/06/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE REAR UPHOLSTERY IN ORDER TO FACILITATE REPAIRS AND REFIT BACK SAME		280.00 120
		LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.		1,600.00 900
		TO REMOVE AND INSTALL HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS.		380.00 200
		TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS.		380.00 150
		PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)		1,200.00 200
		Labour Total S\$:		4,380.00

E. & O.E.

Total S\$:

8,170.00

=====

for WORLD AUTO PTE LTD