

Soon Seng Company (SG) Pte Ltd

160 Sin Ming Drive

#04-05

Sin Ming Autocity

S575722

Not Authorized
L1 Lmp @ 3150h
Resurvey After Paint
Kenneth
6 days

Our client SGF9309L

TP claim against INDIA INTERNATIONAL Insurance (Your insured: SH90115)

Repairer's estimate

Parts

1	Rear bumper	489.90	n	1	750	B	750
2	Rear End Panel	530.80	n	1	656	B	656
3	Bumper clips			10	3	n	30
4	Bumper retainers	038.4	n	2	90	D1	180
5	Reverse sensors (set of 2)		sn	1	250		250
6	Rear bumper reflectors			2	95		190
7	Boot lid	810.00		1	1210	B	1,210
8	Rear logo	32.40	n	1	90	n	90
9	Rear emblem	32.40	n	1	90	n	90
10	Rear boot inner board cover		n	1	420	nsp	420
11	Boot lock	98.50		1	238	n	238
12	Boot latch			1	143	n	143
13	Rear End panel bracket	049	n	2	170	B	340
14	Boot inner garnish	45.0	n	1	287	n	287
15	Boot inner rubber	48.00	n	1	233	n	233
16	Rear RH and LH Tail lights		n	2	380	C	760
17	Rear boot RH and LH inner light			2	240	n	480
18	Rear reinforcement bar			1	500	nsp	500
19	Rear exhaust muffler			1	1410	n	1,410
20	Rear boot hinge		n	2	120	n	240
21	Rear bumper corner panel	080.70		2	190	B	380
Parts Total:							\$ 8,877.00

Labor

1	Check wiring and system function	1	480	480
2	Rust proofing on affected areas	1	420	420
3	Labor to remove and refit rear bumper, boot, reverse sensors, end panel, rear exhaust and 2 inner and outer tail lights. Include pulling out frame of rear undercarriage	1	1800	1,800
4	To respray damaged and refitted parts (rear bumper, 2 rear fenders, boot, interior of rear boot frame)	1	1400	1,400
Labor Total:				\$ 4,100.00

TOTAL: \$12,977.00

*Supplementary items would be included if noticed during the course of repair

Contact:

Mr Chai - 96250518

James - 92960289

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Co.

Acknowledged by Repairer

Signature:

Date: