




Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 20.06.2018

FWD Singapore Pte Ltd
6 Temasek Boulevard #18-01
Suntec Tower Four
Singapore 038986

Attn: Motor Claims Dept



RE: ESTIMATE COST OF REPAIR TO VEHICLE HONDA GRACE SLZ7031K (2017)

To Supply

- 1) 1pc Front bumper
- 2) 1pc Front bumper clip
- 3) 1pc Front bumper left side retainer
- 4) 1pc Left front fender
- 5) 1pc Left front fender cowl
- 6) 1pc Left front fender cowl clip
- 7) 1pc Left side mirror assy
- 8) 1pc Left side mirror cover

Repair
Hp 9000000
4 days
L/S or p/p
21/06/18 @ 1035

	\$	921.00	<i>Repair</i>
	\$	30.00	<i>new</i>
	\$	40.00	<i>?</i>
	\$	370.60	<i>Repair</i>
	\$	69.55	<i>?</i>
	\$	30.00	<i>?</i>
	\$	588.60	<i>scr</i>
	\$	85.00	<i>scr</i>

Repair by or after repair

Sub total Parts	\$	2,134.75
Less: 20% discount	\$	426.95
	\$	1,707.80

L/charges

- 1) To tuff kote \$ ~~50.00~~ 30
- 2) To remove front bumper & left side mirror, left front fender. Replace front bumper & left front fender. Align & adjust front bumper \$ ~~500.00~~ 300
- 3) To putty respray painting front bumper, left front fender & left side mirror cover. To polish \$ ~~600.00~~ 500

Sub total L/charges	\$	1,150.00
Estimate total	\$	2,857.80