

ASS. REC. BY:

REF

CS/GAI(80)1280 U.S.D.302

● Global Infrastructure

Surveyor

MAFUS

ASSIGNMENT (Office)

From (Person):

Kelvynq Ngran

GAI

Date/Time:

21/06/18 @ 10:46am

Estimated Cost:

Bill to:

① TP/WS/TP RES/OD RES/EVA/INV/MY?CS

To inspect Vehicle No.

YP 4105A

Injured

at Workshop m/

Hack Wah Motor

Tel

6441 5655

city

Blk 3011 Bedok North Ave 4 # 01-2008

Policy No:

Claim No.

CLMOMVC06063305

Sum Insured

Excess

~~\$1100.00~~ \$600/-

Make of Veh

(Client's Record)

DOA

13/06/2018

(Client's Record) if consistent

CA 14 CONSISTENT / REV / REP. / REV 24 HRS

H.O.D. Enforcement

DateTime

11:19am @ 2/6/18

Perron Contacted

Anicia

Vehicle IN (OUT)

[illegible]

ASSIGNMENT

From: _____ Date: _____

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

YP 4105A

at Workshop mis

lockwood

of

1/2m

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

4100

(Client's Record)

600 + 3500

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

68

IDAC Accident Report:

Consistent? : Yes or No

☒ GIK / PR Seen:

L

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

1.81

%

3 Val.:

Yes or No

L7A 3964
☒ CA REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

YP 4105A

Yr Regn:

9 16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(M)

Make:

m. f. center FEB 21 2998

Colour:

white

A/C:

Insured / Std / Nil / NA

Sp. Reading:

14/304

T/Radio:

Insured / Std / Nil / NA

Eng/No:

Cr/No:

FEB 21 EA 20971

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Worder / Jammed / Leaked / Burnt or

Brake:

Worder / Jammed / Leaked / Burnt or

Mod:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195 / 65 R15 35

SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

6

Rear:

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

13/6/18

D.O.I.

22/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Lf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Inspection

27/7/18 confirmed - final fig \$8418.50 with Anyse
Anyse said excess only \$600
(\$5,548.25 Red - 40%)

RECEIVED 30 JUL 2018

Date/Time, File Pass to?

30/7/18
☐

Prel. Report

1)

Typist
☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

350

Transportation:

\$ = RS. \$

Photos

Others

TOTAL

-20
330

Report Format:

 Lump Sum / I.B.I: (\$ 8,418.50 r/p)

(08/11/13) waf

ASS REC. BY: Marcus

REF:

GA1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: YP 4105Aat Workshop n/a lockwoodof 11/20

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 4100(Client's Record) 600 + 3500

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 68

IDAC Accident Report: _____ Consistent? : Yes or No

GIR / PR Seen: T Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: 1.34 % 3 Vel.: Yes or No

CA REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: YP 4105A Yr Regn: 9.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)Make: M. F. Canter FEB 21 2998Colour: white A/C: Insured / Std / NI / NASp. Reading: 14/304 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FEB21EA 20971Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModi: All / R/Rim / STD A/Rim or

Tyre Size: F: _____

R: 19.5 / 45-18 35

FS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6/6 mmL/Bal. 6 mm L/Bal. 6/6 mmD.O.A. _____ D.O.I. 22/6/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

L1.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 3964

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days of Repair: _____

Resurvey No. of Trip: _____

Report Format: _____

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS \$1

Photos

Others

TOTAL

Shirley Hiew (LKK Auto)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Friday, 27 July 2018 2:38 PM
To: Nivitha (LKK Auto); ASSIGNMENTS@LKKAUTO.COM
Cc: "SUR"
Subject: RE: RE: CLMOMVC000003305 OD CLAIM_YP4105A_DOA:13/06/2018

Hi Shirley

As spoken, excess for this case will be \$600

Thanks
Kelvyna

From: Nivitha (LKK Auto) <admin-d@lkkauto.com>
Sent: Thursday, June 21, 2018 11:32 AM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; ASSIGNMENTS@LKKAUTO.COM
Cc: "SUR" <sur@lkkauto.com>
Subject: [External] RE: CLMOMVC000003305 OD CLAIM_YP4105A_DOA:13/06/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ngian, Kelvyna [<mailto:Kelvyna.Ngian@sg.gaig.com>]
Sent: Thursday, 21 June 2018 10:46 AM
To: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: CLMOMVC000003305 OD CLAIM_YP4105A_DOA:13/06/2018

Hi team

OD survey, excess \$4100 (\$600 plus additional \$3500 young/inexperienced driver). Authorize if consistent

Thanks
Kelvyna

From: Ngian, Kelvyna
Sent: Thursday, June 21, 2018 10:42 AM
To: 'motor@hockwah.com.sg' <motor@hockwah.com.sg>
Subject: RE: OD CLAIM_YP4105A_DOA:13/06/2018

Nivitha (LKK Auto)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Thursday, 21 June 2018 10:46 AM
To: Catherine Chong (LKK Auto); SUR
Subject: CLMOMVC000003305 OD CLAIM_YP4105A_DOA:13/06/2018
Attachments: YP4105A.pdf; GBB913G.pdf

Hi team

OD survey, excess \$4100 (\$600 plus additional \$3500 young/inexperienced driver). Authorize if consistent.

Thanks
Kelvyna

From: Ngian, Kelvyna
Sent: Thursday, June 21, 2018 10:42 AM
To: 'motor@hockwah.com.sg' <motor@hockwah.com.sg>
Subject: RE: OD CLAIM_YP4105A_DOA:13/06/2018

Hi Mavis

LKK will survey

Thanks
Kelvyna

From: Hock Wah Motor Pte Ltd <motor@hockwah.com.sg>
Sent: Wednesday, June 20, 2018 4:53 PM
To: General Claims <GeneralClaims@sg.gaig.com>
Subject: [External] OD CLAIM_YP4105A_DOA:13/06/2018

Dear Sir/Madam

Attached herewith our client's GIA report that claim Own Damage Claim.

Please make necessary arrangement with Bedok workshop.

Thank you.

Best Regards
Mavis Er
Customer Service Executive
Hock Wah Motor Workshop Pte Ltd
Blk 3011 Bedok North Avenue 4 | #01-2008/2010/2012/2014 | Singapore 489977
Tel: 6441 5655 | Fax: 6243 8121 | Website: www.hockwah.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18011280/Usd3

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 21-06-2018



Code : GAI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	YP 4105A
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC00003305	Excess (\$)	4,100.00
Assign From	KELVYNA NGIAN	Assign Date	21/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	13/06/2018	Inspection Date	
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	7904N

Vehicle Details

Vehicle No.:	YP4105A
Vehicle to be Exported:	No
Intended De-registration Date:	22 Jun 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER4SDEB
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	4P10C35286
Chassis No.:	FEB21EA20971
Maximum Power Output:	-
Open Market Value:	\$35,365.00
Original Registration Date:	20 Sep 2016
First Registration Date:	20 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$1,769.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	19 Sep 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$4,809.00
COE Rebate Amount:	\$3,964.00
Total Rebate Amount:	\$3,964.00

The information contained herein is correct as at 22 Jun 2018

OK

> Back to OneMotoring -

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 7904N

Vehicle Details

Vehicle No.: YP4105A
Vehicle to be Exported: No
Intended De-registration Date: 22 Jun 2018
Vehicle Make: MITSUBISHI
Vehicle Model: CANTER FEB21ER4SDEB
Primary Colour: White
Manufacturing Year: 2016
Engine No.: 4P10C35286
Chassis No.: FEB21EA20971
Maximum Power Output: -
Open Market Value: \$35,365.00
Original Registration Date: 20 Sep 2016
First Registration Date: 20 Sep 2016
Transfer Count: 0
Actual ARF Paid: \$1,769.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 19 Sep 2026
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
PQP Paid: \$4,809.00
COE Rebate Amount: \$3,964.00
Total Rebate Amount: \$3,964.00

The information contained herein is correct as at 22 Jun 2018

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more.

sgCARMART

CONNECT

RELIABLE BUYERS & SELLERS

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Nissan X-Trail 2.0 Premium 'Adventure Series' 7-Seat.



Mint Condition. Selling Because

I'm Leaving SG. You Can't Afford

To Miss This

Direct Owner - Shinkit



click here to view

our PRISTINE USED CARS

at GREAT PRICES

Browse by Category

Sort by Date Posted

20 results/page

14 vehicles

Mitsubishi Feb21

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mitsubishi Feb21		Any	Any	2016	Any	Any	Any	Available
	Mitsubishi	Fuso Canter FEB21	\$64,800	\$8,570 /yr	13-Jan-2016	2,998 cc	-	Truck	Available
Fuel Type: Diesel Lower Depreciation In Market. Class 3 Can Drive. No Need VPC. Condition Like New. Call Now To Negotiate. ABWIN (1994) Pte Ltd Posted: 22-Jun-2018 Tags: 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi									
	Mitsubishi	Fuso Canter FEB21	\$92,800	\$11,470 /yr	25-Jul-2016	2,998 cc	-	Truck	Available
Fuel Type: Diesel High Trade In For Your Old Vehicle. High Loan Is Possible. We Can Quote Your Insurance For You. Hurry While Stock Last. KSL Automotive Pte Ltd Posted: 22-Jun-2018 Tags: 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi									
	Mitsubishi	Fuso Canter FEB21	\$69,800	\$9,170 /yr	29-Jan-2016	2,998 cc	60,000 km	Truck	Available
Fuel Type: Diesel 1 Owner! 100% Accident Free! Can Choose To Have Sliding Box. Low Mileage Done At 60000Km Well Maintained By Fussy Previous Owner. Cheaper Than New Unit Yet Condition Like New. Yet Come With New Paintw... Car (S) Pte Ltd Posted: 21-Jun-2018 Tags: 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi									
	Mitsubishi	Fuso Canter FEB21	\$68,800	\$9,100 /yr	13-Jan-2016	2,998 cc	18,800 km	Truck	Available
Fuel Type: Diesel As Good As New! 1 Owner, New Paintwork, Super Low Mileage Done At 9,000Km Yearly, Good Condition, Easy In House Loan Available, Class 3 Can Drive, No VPC Needed, Call Now. Posted: 15-Jun-2018 Tags: 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi									
Car Buying Car Selling Car Ownership Buying a pre-owned car, but Unsure of its Condition? Car Aftermarket On The Move Lifestyle Get STA Car Evaluation									
	Mitsubishi	Fuso Canter FEB21	\$69,800	\$8,910 /yr	21-Apr-2016	2,998 cc	33,000 km	Truck	Available
Fuel Type: Diesel Very Rare Auto 14 Foot Lorry With Retractable Canopy, Vehide Like New Condition, In House Loan Available, Trade In Are Welcome, Door Step Viewing Can Be Arranged. Call Now Before It's Gone To Avoid D... ABWIN (1994) Pte Ltd Posted: 13-Jun-2018 Tags: 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi									
	Mitsubishi	Fuso Canter FEB21	\$66,900	\$8,570 /yr	12-Apr-2016	2,998 cc	45,000 km	Truck	Available
Fuel Type: Diesel Look No Further, Ideal Workhorse For Your Business Use. Direct Owner's April 2016 White Mitsubishi Fuso Canter FEB21 With Comfortable Fabric Upholstery Owned By 1 Logistic Company Selling Due To Under... Posted: 07-Jun-2018 Tags: 2016 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi									

Compare

http://www.sgcarmart.com/used_cars/listing.php?MOD=Mitsubishi+Feb21&PRC=0&DEP=0&RGD=20... 22-Jun-18

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/06/2018 15:53
Date Of Accident	13/06/2018 06:30
Exact Location Of Accident	EUNOS LINK BEFORE JUNC BEDOK RESERVOIR RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP4105A
Insured/Policyholder	
Name Of Registered Owner	DC CONTRACTORS PTE LTD
Co Reg No	199607904N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67156948

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER FEB21ER4SDEB
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MOMVC000005591-00-000
Cover Note Number	

Driver

Name of Driver	THIRUGNANAM BABU
Passport No/FIN	G7104510U
Date Of Birth	20/04/1977
Occupation	OUTDOOR
Date Of Driving Pass	14/06/2017
Driving Experience	0 YEAR AND 11 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81609194
Fax Number	
Contact Number	OFFICE-81609194
Email Address	NOEMAIL

Address	8 JURONG TOWN HALL ROAD #30-04 THE JTC SUMMIT
Postcode	609434
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : HOSSAIN BABU GENDER: : MALE
Passenger 2	NAME: : MD EBRAHIM GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB913G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SUNDARAMOORTHY JAYARAJ
NRIC/Passport Number	G2251912W
Contact Number	
Address	
Postcode	

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Accident Sketch Plan

17/02/2017

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be submitted by the Policyholder and/or the Authorized Driver.
3. Information provided must be as prompt and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. For JKR involvement, refer to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consistent with the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

Accident Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was travelling along Eunos Link before Bedok Reservoir Road . When the traffic light turned from green to amber , vehicle B suddenly stopped . Hence , I could not brake in time and I accidentally collided onto vehicle B's rear portion of the vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Submittal: 10/05/2014

THIRUGANAN BABA

License No: G7104510U

DOB: 20 Apr 1977

Valid Till: 31/01/2023

Barcode: 002844755C

THIRUGANAN BABA

Operations Supervisor

License No: G7104510U

Valid Till: 31/01/2023

Barcode: 002844755C

L7738853

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSSES

CLASS	VEHICLE CLASS	EXPIRY DATE
Class 1	Motor vehicles up to 3.5t CC	11 Nov 2023
Class 2	Motor vehicles up to 3.5t CC with a 7 speed gearbox, with a valid license	11 Nov 2023
Class 3	Motor vehicles up to 3.5t CC with a 7 speed gearbox, with a valid license	11 Nov 2023

CHIRAN

S / No: 9000270837

License No: G7104510U

10/4/2023

THIRUGANAN BABA

Multiple Journey Visa Issued

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU

Barcode: 002844755C

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

TO: 199607904N

GREAT AMERICAN INSURANCE COMPANY
NO 3 TEMASEK AVENUE
16-01 CENTENNIAL TOWER
SINGAPORE 039190
TEL: 6804 6000 FAX: 6235 2616
PH:
ATTN:

Approved
Take photo Before painting.
Excess 4100
5 day.
22/6/18
9/12/18

ESTIMATE BILL

Number: EB00004858
Date: 20/06/2018
Case No: AD00009795
Vehicle No: YP4105A
Chassis: FEB21EA20971
Year of Mfr: 2016
Policy No: MOMVC000005591-00
Model: MITSUBISHI
CANTER

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	FRONT BUMPER <i>DD</i>	1.0	575.00	(10)	632.50
2	FRONT BUMPER BRACKET LH <i>11</i>	1.0	110.00	(10)	121.00
3	FRONT BUMPER BRACKET RH <i>311</i>	1.0	110.00	(10)	121.00
4	FRONT BUMPER SIDE COVER GARNISH LH	1.0	185.00	(10)	203.50
5	FRONT BUMPER SIDE COVER GARNISH RH	1.0	185.00	(10)	203.50
6	FRONT GRILLE <i>CR</i>	1.0	575.00	(10)	632.50
7	FRONT GRILLE EMBLEM - CANTER <i>211</i>	1.0	60.00	(10)	66.00
8	FRONT GRILLE EMBLEM - STAR <i>211</i>	1.0	45.00	(10)	49.50
9	FRONT PANEL OUTER <i>Bush 10</i>	1.0	640.00	(10)	704.00
10	FRONT PANEL INNER <i>NS</i>	1.0		(10)	
11	FRONT PANEL EMBLEM - FUSO <i>211</i>	1.0	70.00	(10)	77.00
12	FRONT GRILLE CLIPS	5.0	4.50	(10)	24.75
13	FRONT WIPER PANEL GARNISH <i>100/CR</i>	1.0	300.00	(10)	330.00
14	FRONT WIPER MOTOR <i>11</i>	1.0	400.00	(10)	440.00
15	HEADLAMP LH	1.0	310.00	(10)	341.00
16	HEADLAMP RH	1.0	310.00	(10)	341.00
17	FRONT SIGNAL LAMP LH	1.0	180.00	(10)	198.00
18	FRONT SIGNAL LAMP RH <i>3120</i>	1.0	180.00	(10)	198.00
19	HEADLAMP SIDE COVER LAMP LH	1.0	110.00	(10)	121.00
20	HEADLAMP SIDE COVER LAMP RH	1.0	110.00	(10)	121.00
21	FRONT WINDSCREEN RUBBER	1.0	210.00	(10)	231.00
22	FRONT HEAD MOUNTING CABIN BRACKET RH	1.0	530.00	(10)	583.00
23	FRONT HEAD MOUNTING CABIN BRACKET LH	1.0	530.00	(10)	583.00
24	FRONT HEAD MOUNTING CABIN BUSH LH	1.0	165.00	(10)	181.50
25	FRONT HEAD MOUNTING CABIN BUSH RH	1.0	165.00	(10)	181.50
26	FRONT GRILLE CENTER BRACKET	1.0	50.00	(10)	55.00
27	FRONT HORN	1.0	80.00	(10)	88.00
28	AIR CON SUCTION HOSE <i>11</i>	1.0	420.00	(10)	462.00
29	AIR CON DISCHARGE HOSE <i>11</i>	1.0	465.00	(10)	511.50
30	AIR CON LIQUID HOSE <i>11</i>	1.0	350.00	(10)	385.00
31	AIR INTAKE BOX	1.0	650.00	(10)	715.00
32	AIR CON COIL HOUSING WITH HEATER HOUSING	1.0	1,950.00	(10)	2,145.00
Nett Price - Parts Sub Total					11,046.75

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
 BEDOK NORTH AVE 4,
 #01-2008/10/12 SINGAPORE 489977
 TEL: 6441 5655 FAX: 6441 5355/6243 8121
 R.O.C No: 200104141D GST Reg. No. 20-0104141-D

TO: 199607904N
 GREAT AMERICAN INSURANCE COMPANY
 NO 3 TEMASEK AVENUE
 16-01 CENTENNIAL TOWER
 SINGAPORE 039190
 TEL: 6804 6000 FAX: 6235 2616
 PH:
 ATTN:

ESTIMATE BILL

Number: EB00004858
 Date: 20/06/2018
 Case No: AD00009795
 Vehicle No: YP4105A
 Chassis: FEB21EA20971
 Year of Mfr: 2016
 Policy No: MOMVC000005591-00
 Model: MITSUBISHI
 CANTER

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
33	FRONT NUMBER PLATE <i>5-2-1</i>	1.0	30.00	0	30.00
34	FLOOR PANEL - REPAIR <i>2</i>	1.0			
35	FRONT DOOR RH - REPAIR <i>2</i>	1.0			
Special Nett Price - Parts Sub Total					30.00
Parts Total					11,076.75
36	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,000.00	0	1,000.00
37	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,000.00	0	1,000.00
38	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
39	TO SERVICE & TOP-UP AIR-CON GAS	1.0	250.00	0	250.00
40	WIRING	1.0	80.00	0	80.00
41	TO REMOVE & REFIT DASHBOARD	1.0	380.00	0	380.00
Labour 1 Sub Total					2,890.00
SINGAPORE DOLLARS: FOURTEEN THOUSAND NINE HUNDRED FORTY-FOUR AND CENTS FORTY-TWO ONLY					
Less Excess					0.00
SUBTOTAL					13,966.75
GST 7.00%					977.67
TOTAL					14,944.42

Date of accident: 13/06/2018 06:30 AM. Place: EUNOS LINK BEFORE JUNC BEDOK RESERVOIR RD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4.
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

Authored
Take photo before painting.
Express 4109
5 day.
22/6/18
p/p

TO : 199607904N

GREAT AMERICAN INSURANCE COMPANY
NO 3 TEMASEK AVENUE
16-01 CENTENNIAL TOWER
SINGAPORE 039190
TEL : 6804 6000 FAX : 6235 2616
PH:
ATTN:

ESTIMATE BILL

Number : EB00004858
Date : 20/06/2018
Case No : AD00009795
Vehicle No : YP4105A
Chassis : FEB21EA20971
Year of Mfr : 2016
Policy No : MOMVC000005591-00
Model : MITSUBISHI
CANTER

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT BUMPER <i>DD</i>	1.0	575.00	(10)	632.50
2	FORNT BUMPER BRACKET LH <i>11</i>	1.0	110.00	(10)	121.00
3	FRONT BUMPER BRACKET RH <i>311</i>	1.0	110.00	(10)	121.00
4	FRONT BUMPER SIDE COVER GARNISH LH <i>11</i>	1.0	185.00	(10)	203.50
5	FRONT BUMPER SIDE COVER GARNISH RH <i>10.1</i>	1.0	185.00	(10)	203.50
6	FRONT GRILLE <i>cue</i>	1.0	575.00	(10)	632.50
7	FRONT GRILLE EMBLEM - CANTER <i>cue</i>	1.0	60.00	(10)	66.00
8	FRONT GRILLE EMBLEM - STAR <i>cue</i>	1.0	45.00	(10)	49.50
9	FRONT PANEL OUTER <i>311/SD</i>	1.0	640.00	(10)	704.00
10	FRONT PANEL INNER <i>cue</i>	1.0		(10)	
11	FRONT PANEL EMBLEM - FUSO <i>cue</i>	1.0	70.00	(10)	77.00
12	FRONT GRILLE CLIPS <i>11</i>	5.0	4.50	(10)	24.75
13	FRONT WIPER PANEL GARNISH <i>10/cue</i>	1.0	300.00	(10)	330.00
14	FRONT WIPER MOTOR <i>11</i>	1.0	400.00	(10)	440.00
15	HEADLAMP LH <i>11</i>	1.0	310.00	(10)	341.00
16	HEADLAMP RH <i>cue</i>	1.0	310.00	(10)	341.00
17	FRONT SIGNAL LAMP LH <i>cue</i>	1.0	180.00	(10)	198.00
18	FRONT SIGNAL LAMP RH <i>311</i>	1.0	180.00	(10)	198.00
19	HEADLAMP SIDE COVER LAMP LH <i>11</i>	1.0	110.00	(10)	121.00
20	HEADLAMP SIDE COVER LAMP RH <i>cue</i>	1.0	110.00	(10)	121.00
21	FRONT WINDSCREEN RUBBER <i>11</i>	1.0	210.00	(10)	231.00
22	FRONT HEAD MOUNTING CABIN BRACKET RH <i>cue</i>	1.0	530.00	(10)	583.00
23	FRONT HEAD MOUNTING CABIN BRACKET LH <i>11</i>	1.0	530.00	(10)	583.00
24	FRONT HEAD MOUNTING CABIN BUSH LH <i>11</i>	1.0	165.00	(10)	181.50
25	FRONT HEAD MOUNTING CABIN BUSH RH <i>cue</i>	1.0	165.00	(10)	181.50
26	FRONT GRILLE CENTER BRACKET <i>11</i>	1.0	50.00	(10)	55.00
27	FRONT HORN <i>11</i>	1.0	80.00	(10)	88.00
28	AIR CON SUCTION HOSE <i>11</i>	1.0	420.00	(10)	462.00
29	AIR CON DISCHARGE HOSE <i>11</i>	1.0	465.00	(10)	511.50
30	AIR CON LIQUID HOSE <i>11</i>	1.0	350.00	(10)	385.00
31	AIR INTAKE BOX <i>11</i>	1.0	650.00	(10)	715.00
32	AIR CON COIL HOUSING WITH HEATER HOUSING <i>cue</i>	1.0	1,950.00	(10)	2,145.00
Nett Price - Parts Sub Total					11,046.75

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

1-5985+10%

6583.50

p/p 8418.50

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 199607904N

GREAT AMERICAN INSURANCE COMPANY
NO 3 TEMASEK AVENUE
16-01 CENTENNIAL TOWER
SINGAPORE 039190
TEL : 6804 6000 FAX : 6235 2616
PH :
ATTN :

ESTIMATE BILL

Number : EB00004858
Date : 20/06/2018
Case No : AD00009795
Vehicle No : YP4105A
Chassis : FEB21EA20971
Year of Mfr : 2016
Policy No : MOMVC000005591-00
Model : MITSUBISHI
CANTER

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
33	FRONT NUMBER PLATE <i>sent</i>	1.0	30.00	0	30.00
34	FLOOR PANEL - REPAIR <i>2</i>	1.0			
35	FRONT DOOR RH - REPAIR <i>2</i>	1.0			
Special Nett Price - Parts Sub Total					30.00
Parts Total					11,076.75
36	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,000.00	0	1,000.00
37	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,000.00	0	1,000.00
38	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
39	TO SERVICE & TOP-UP AIR-CON GAS	1.0	250.00	0	250.00
40	WIRING	1.0	80.00	0	80.00
41	TO REMOVE & REFIT DASHBOARD	1.0	380.00	0	380.00
Labour 1 Sub Total					2,890.00
					1835
SINGAPORE DOLLARS : FOURTEEN THOUSAND NINE HUNDRED FORTY-FOUR AND CENTS FORTY-TWO ONLY					
Less Excess					0.00
SUBTOTAL					13,966.75
GST 7.00%					977.67
TOTAL					14,944.42

Date of accident : 13/06/2018 06:30 AM. Place : EUNOS LINK BEFORE JUNC BEDOK RESERVOIR RD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 406710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 190307741M



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

HOCK WAH MOTOR WORKSHOP PTE LTD
3011 BEDOK INDS PARK E
#01-2008
[NEED PO]
SINGAPORE 489977
TEL : 64415655 FAX : 62438121
ATTN : (SMALL ITEM PASS TO COUNTER) GUAN 98633934

TAX INVOICE : AR201807-05013
DATE : 10/07/2018
CUSTOMER ID : HOC001
VEH REG. NO. : YP4105A
TERMS : 30 days
PO NO. : PO00026703
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	MC978516	FR BUMPER	MO	1	575.00	575.00
	FEB21 FEB71		3N1			
2	MK618511	FR BUMPER STAY BRACKET RH	MO	1	110.00	110.00
			2H8			
3	MC978571	FR GRILLE ASSY	MO	1	575.00	575.00
			3N1			
4	MK675497	MARK_EMBLEM (CANTER)	MO	1	60.00	60.00
			2N16			
5	MK546616	MARK_EMBLEM (STAR)	MO	1	45.00	45.00
			II11			
6	MK707621	FR CAB PANEL	MO	1	640.00	640.00
			3N1			
7	MK546617	MARK_EMBLEM (FUSO)	MO	1	70.00	70.00
			2A26			
8	MC978995	FR WIPER GARNISH	MO	1	300.00	300.00
			2B19			
9	MK580528	FR SIGNAL LAMP RH	MO	1	180.00	180.00
			2D10			

At

AD 9795

SUB-TOTAL : 2,555.00
ADD GST 7.00 % 178.85

E & O E TOTAL AMOUNT SGD : 2,733.85

[P] 10/07/2018 10:02:08AM

[B] 10/07/2018 9:59:55AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : EDWARD



This is computer generated document.

No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Dept Direct: 6417 9791 / 9746 8636



Dept Direct: 6302 9610



Dept Direct: 6306 9611



Dept Direct: 6417 9792



Dept Direct: 6417 9793



Dept Direct: 6417 9794

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

HOCK WAH MOTOR WORKSHOP PTE LTD
3011 BEDOK INDS PARK E

#01-2008

[NEED PO]

SINGAPORE 489977

TEL : 64415655 FAX : 62438121

ATTN : (SMALL ITEM PASS TO COUNTER) GUAN 98633934

TAX INVOICE : AR201807-05082
DATE : 10/07/2018
CUSTOMER ID : HOC001
VEH REG. NO. : YP4105A
TERMS : 30 days
PO NO. : PO00026839
PAGE NO. : Page 1 of 1
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	MK580552	HEADLAMP ASSY,RH	CC CC11-C-06D	1	310.00	310.00
2.	MK580527	FR SIGNAL LAMP LH	CC CC11-C-07C	1	180.00	180.00
3.	MK622528	CUSHION,CAB FR MTG	CC CC11-A-03C	1	165.00	165.00

(Handwritten signature)

AD 9795

SUB-TOTAL : 655.00
ADD GST 7.00 % 45.80

E. & O.E TOTAL AMOUNT SGD: 700.80

[P] 10/07/2018 10:40:57AM

[E] 10/07/2018 10:38:03AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: EDWARD

This is computer generated document.

No signature is required.



* A R 2 0 1 8 0 7 - 0 5 0 8 2 *

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Dept Direct: 6417 8791 / 8743 9639

Arrange By

Driver

DEBER?



Dept Direct: 6205 9810



Dept Direct: 6205 9811



Dept Direct: 6417 8792



Dept Direct: 6417 8793



Dept Direct: 6417 8794



Dept Direct: 6417 8795



Dept Direct: 6417 8796



Dept Direct: 6417 8797



Dept Direct: 6417 8798



Dept Direct: 6417 8799



Dept Direct: 6417 8796



Dept Direct: 6417 8796



Dept Direct: 6417 8796



Dept Direct: 6417 8796



Dept Direct: 6417 8796



Dept Direct: 6417 8796



Dept Direct: 6417 8796



Dept Direct: 6417 8796



Dept Direct: 6417 8796

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

HOCK WAH MOTOR WORKSHOP PTE LTD

3011 BEDOK INDS PARK E

#01-2008

[NEED PO]

SINGAPORE 489977

TEL : 64415655 FAX : 62438121

ATTN : (SMALL ITEM PASS TO COUNTER) GUAN 98633934

TAX INVOICE : AR201807-05085

DATE : 10/07/2018

CUSTOMER ID : HOC001

VEH REG. NO. : YP4105A

TERMS : 30 days

PO NO. : PO00026839

PAGE NO. : Page 1 of 1

CURR : SGD

SO STOCK ID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1 MK580530	FR SIDE GARNISH RH	PA PL3-N1-10A	1	110.00	110.00
2 MK622457	BRKT,CAB FR MTG C/MBR,RH	PA PL3-N1-04A	1	530.00	530.00

A

SUB-TOTAL : 640.00

ADD GST 7.00 % 44.80

E & O E

TOTAL AMOUNT SGD : 684.80

[P] 10/07/2018 10:44:07AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 10/07/2018 10:39:28AM

JAE Auto Pte. Ltd.

Sales Executive: EDWARD

This is computer generated document.

No signature is required.



AR201807-05085

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司
JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

PROUDLY SERVED BY
Dept Direct: 6417 8091 / 6417 8092



Wiper blade: NWB (Nippon Wiper blade), Siper (Made in Korea)
Forch (Made in Germany)

===== GST REG NO: M2-0118201-3 CG REG NO: 100307741M =====
HOCK WAH MOTOR WORKSHOP PTE LTD
3011 BEDOK INDS PARK E
#01-2008
[NEED PO]
SINGAPORE 489977
TEL : 64415655 FAX : 62438121
ATTN : (SMALL ITEM PASS TO COUNTER) GUAN 98633934

TAX INVOICE : AR201807-05813
DATE : 11/07/2018
CUSTOMER ID : HOC001
VEH REG. NO. : YP4105A
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
✓	MK583365	HEATER ASSY	MO	1	1950.00	1,950.00
	FEB21 FEB71		2RFRT			

580

SUB-TOTAL : 1,950.00
ADD GST 7.00 % 136.50

E. & O.E TOTAL AMOUNT SGD : 2,086.50

[P] 11/07/2018 10:19:28AM

[E] 11/07/2018 10:16:53AM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : NIN



Goods Received in Good Order

This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9636



Dept Direct: 6308 9610

Dept Direct: 6308 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Bilpar (Made in Korea),
Forn (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

HOCK WAH MOTOR WORKSHOP PTE LTD

3011 BEDOK INDS PARK E

#01-2008

[NEED PO]

SINGAPORE 489977

TEL : 64415655 FAX : 62438121

ATTN : (SMALL ITEM PASS TO COUNTER) GUAN 98633934

TAX INVOICE : AR201807-06227

DATE : 11/07/2018

CUSTOMER ID : HOC001

VEH REG. NO. : YP4105A

TERMS : 30 days

PO NO. : JS00058912

PAGE NO. : Page 1 of 1

CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	MK618527 FEB21 FEB71	FR BUMPER COVER RH	CC CC11-C-06D	1	185.00	185.00

Handwritten signature/initials

Handwritten initials

SUB-TOTAL : 185.00
ADD GST 7.00 % 12.95

E. & O. E

TOTAL AMOUNT SGD : 197.95

[P] 11/07/2018 3:13:05PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 11/07/2018 3:09:52PM

JAE Auto Pte. Ltd.

Sales Executive: NIN

This is computer generated document.
No signature is required.



* AR201807-06227 *

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18011280/Usd3e2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 13-08-2018



Code : GAI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	YP 4105A
Policy No.	Coverage (\$)	0.00
Claim No. CLMOMVC00003305	Excess (\$)	600.00
Assign From KELVYNA NGIAN	Assign Date	21/06/2018

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI CANTER FEB21ER4SDEB (M)	c.c	2998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	FEB21EA20971	Colour	WHITE
Odometer	141304	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/85 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195/85 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195/85 R15 (D)	BRIDGESTONE	6/6 mm
L/H Rear Tyre	195/85 R15 (D)	BRIDGESTONE	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/06/2018	Inspection Date	22/06/2018
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		

5a. Remarks

A)THE MARKET VALUE IS S\$68,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 4105A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DENTED	575.00	575.00
1	FRONT BUMPER BRACKET LH	NOT NECESSARY	110.00	-
1	FRONT BUMPER BRACKET RH	BENT	110.00	110.00
1	FRONT BUMPER SIDE COVER GARNISH LH	NOT NECESSARY	185.00	-
1	FRONT BUMPER SIDE COVER GARNISH RH	TORN	185.00	185.00
1	FRONT GRILLE	CRACKED	575.00	575.00
1	FRONT GRILLE EMBLEM - CANTER	NECESSARY	60.00	60.00
1	FRONT GRILLE EMBLEM - STAR	NECESSARY	45.00	45.00
1	FRONT PANEL OUTER	BADLY DENTED	640.00	640.00
1	FRONT PANEL INNER (NPA)	NO SUCH PARTS	-	-
1	FRONT PANEL EMBLEM - FUSO	NECESSARY	70.00	70.00
1	FRONT GRILLE CLIPS	NOT NECESSARY	22.50	-
1	FRONT WIPER PANEL GARNISH	DENTED / CRACKED	300.00	300.00
1	FRONT WIPER MOTOR	NOT NECESSARY	400.00	-
1	HEADLAMP LH	NOT NECESSARY	310.00	-
1	HEADLAMP RH	CRACKED	310.00	310.00
1	FRONT SIGNAL LAMP LH	CRACKED	180.00	180.00
1	FRONT SIGNAL LAMP RH	BROKEN	180.00	180.00
1	HEADLAMP SIDE COVER LAMP LH	NOT NECESSARY	110.00	-
1	HEADLAMP SIDE COVER LAMP RH	CRACKED	110.00	110.00
1	FRONT WINDSCREEN RUBBER	NOT NECESSARY	210.00	-
1	FRONT HEAD MOUNTING CABIN BRACKET RH	TWISTED	530.00	530.00
1	FRONT HEAD MOUNTING CABIN BRACKET LH	NOT NECESSARY	530.00	-
1	FRONT HEAD MOUNTING CABIN BUSH LH	NOT NECESSARY	165.00	-
1	FRONT HEAD MOUNTING CABIN BUSH RH	TWISTED	165.00	165.00
1	FRONT GRILLE CENTER BRACKET	NOT NECESSARY	50.00	-
1	FRONT HORN	NOT NECESSARY	80.00	-
1	AIR CON SUCTION HOSE	NOT NECESSARY	420.00	-
1	AIR CON DISCHARGE HOSE	NOT NECESSARY	465.00	-
1	AIR CON LIQUID HOSE	NOT NECESSARY	350.00	-
1	AIR INTAKE BOX	NOT NECESSARY	650.00	-
1	AIR CON COIL HOUSING WITH HEATER HOUSING	CRACKED	1,950.00	1,950.00

Report Ref No. CS/GAI18011280/Usd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	COST PLUS 10%		1,004.25	598.50
			11,046.75	6,583.50
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	BENT	30.00	15.00
1	FLOOR PANEL (NPA) (SN)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR RH (NPA) (SN)	TO REPAIR SEE LABOUR	-	-
			30.00	15.00
	<u>LABOUR</u>			
	LABOUR TO REMOVE & REFIT NECESSARY PARTS. INCLUSIVE OF THE REPAIR OF FLOOR PANEL AND FRONT DOOR RH.		1,000.00	700.00
	SPRAY PAINT ON THE AFFECTED AREAS.		1,000.00	700.00
	TO REMOVE & REFIT WINDSCREEN.		180.00	100.00
	TO SERVICE & TOP-UP AIR-CON GAS.		250.00	100.00
	WIRING.		80.00	20.00
	TO REMOVE & REFIT DASHBOARD.		380.00	200.00
			2,890.00	1,820.00
GRAND TOTAL			13,966.75	8,418.50
RECOMMENDED COST OF REPAIRS				8,418.50

Report Ref No. CS/GAI18011280/Usd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.